




Arley Street Car Park Works

Road and Pavement Dilapidation Survey




EB – East bound along Arley – leaving site (existing Car Park)
heading to Walmersley Road A56

Photo/location reference	Approx Chainage	Description	Photos as per 12 July 2023
EB001-002	0m site access gates 15m	Pavement and kerbs all ok Gully operating ok	 
EB003-004	15m – 25m	Speed 'hump' in good condition Recent repairs to gully and drop kerb in front of property	 
EB005-006	25m-40m	Junction of Copse Drive Gully nearside and top surface all ok Junction line making worn Gully far side blocked on day of survey	 
EB007-008	40m-70m	Road surface in fair condition Pavement with broken flags in area of drop kerb No central line marking visible	 
EB008-009	70m-85m	Surface course missing along kerb line Vegetation growing along kerb line Road surface in fair condition Junction with Seedfield Rd (right)	 


Arley Street Car Park Works

Road and Pavement Dilapidation Survey



EB010-	85m-	Road Surface ok No line markings present	
EB011- EB012	100m 140m	Patched repairs to nearside pavement Road surface patched central	 
EB013- 014	140m- 150m	Previous patched repair nearside Far side tarmac surface ok	 
EB015- 016 017 018	150m- 200m	Previous patched repair far side Central line marking not visible Double yellow lines and speed limit painted clear	   

Location of photo evidence



Survey Details

Survey carried out on 12/07/2023 by J Clegg.

Conditions were wet at the time of the survey drainage could be seen in operation.

Certain road gully's are free running some were blocked and overflowing

Road surface in fair condition, line markings not viable in places.

Pavements consist of bitmac an PC concrete flags damaged areas shown