

Window W3 facing west :



External



Internal

Outer frame	Remove weldmesh and securing bolts. Robust frame, requires sanding and painting.
Glazing bars	Beading missing. Add/replace beading where required, sand and paint.
Glazing	Glazing satisfactory on lower 4 panes. Upper semi-circular light is boarded using plywood – sand and paint.

Window W4 facing west :



External



Internal

Outer frame	Remove weldmesh and securing bolts. Robust frame, requires sanding and painting.
Glazing bars	Beading missing. Add/replace beading where required, sand and paint.
Glazing	Glazing satisfactory on lower 3 panes. 1 pane to be replaced. Upper semi-circular light is boarded using plywood – sand and paint.

Window W5 facing west :



External



Internal

Outer frame	Remove weldmesh and securing bolts. Robust frame, requires sanding and painting.
Glazing bars	Beading missing. Add/replace beading where required, sand and paint.
Glazing	Glazing satisfactory on lower 3 panes. 1 pane to be replaced. Upper semi-circular light is boarded using plywood – sand and paint.

Window W6 facing south :



External



Internal

Outer frame	Remove vegetation from around the window. Remove weldmesh and securing bolts. Robust frame, requires sanding and painting.
Glazing bars	Beading missing. Add/replace beading where required, sand and paint.
Glazing	Glazing appears to be satisfactory. Upper semi-circular light is boarded using plywood – sand and paint.

Should you require anything further please do not hesitate to contact the writer.

Yours faithfully,

Gary Dearden