

PLOT 17

PLOT 17



PROT

17

PLOT

17



PLOT 17









Gas Protection - Validation Record Sheet

One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

2 PLOT 19 (Block 6) NEW CHURCH STREET RADCLIFFE

Inspection date:	8-11-17	Weather:	DRY / SUNNY	Inspected by:	ANDY LOUGDEN	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2 - FLOOR SLAB					
2.2	Condition of sub-grade & underside of gas membrane	FLOOR SCRAPPED & BRUSHED, PERIMETER MEMBRANE CLEANED, ALL TAPES APPLIED WELL, SEALED TO A GOOD QUALITY					
2.3	Gas membrane type	RADBAR BLACK					
2.4	Gas membrane condition and coverage	SEALED ON ALL 4 SIDES - ALL GOOD					
2.5	Jointing tape product	DOUBLE SIDED RADBAR TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	VISIBLE OVERLAPS - ALL GOOD					
2.8	Number and condition of service entry seals	3 rd TOP HATS FITTED AROUND DRAINAGE/WATER, JUBILEE CLIPS + TAPED ALL GOOD					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples			I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance.				
3.1	Internal Venting Pipes Spacing	☒	Signed:  Dated: 8-11-17				
3.2	External Cranked Vents Spacing	☒					
3.3	Sub Floor Void	☒	Photographs witnessed and approved by Coopers:				
3.4	Membrane Overview	☒					
3.5	Overlaps	☒	Signed:  Dated: 9/11/17				
3.6	Corners	☒					
3.7	Services	☒					
3.8	Product Types/Labels	☒					

For Residential Development at New Church Street, Radcliffe.







PILOT
19










Gas Protection - Validation Record Sheet

One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

Plot 20 (Block 6) New Church Street, Radcliffe

Inspection date:	8-11-17	Weather:	DRY / SUNNY	Inspected by:	ANDY LONGDEN	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2 - FLOOR SLAB					
2.2	Condition of sub-grade & underside of gas membrane	FLOOR SCRAPPED & BRUSHED, PERIMETER MEMBRANE CLEANED, ALL TAPES APPLIED WELL. SEALED TO A GOOD QUALITY.					
2.3	Gas membrane type	RADBAR BLACK					
2.4	Gas membrane condition and coverage	SEALED ON ALL FOUR SIDES - ALL GOOD					
2.5	Jointing tape product	DOUBLE SIDED RADBAR TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	VISIBLE OVERLAPS - ALL GOOD					
2.8	Number and condition of service entry seals	3 NO TOP HATS FITTED AROUND DRAINAGE / WATER, TAPED + JUBILEE CLIPPED					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples		I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance.					
3.1	Internal Venting Pipes Spacing	—					
3.2	External Cranked Vents Spacing	=					
3.3	Sub Floor Void	=					
3.4	Membrane Overview	✓					
3.5	Overlaps	✓					
3.6	Corners	✓					
3.7	Services	✓					
3.8	Product Types/Labels	✓					
		Signed: 		Dated: 8-11-17			
		Photographs witnessed and approved by Coopers:		Signed: 		Dated: 9/11/17	

For Residential Development at New Church Street, Radcliffe.



Plot 20













Gas Protection - Validation Record Sheet

One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

6654:- PLOT 22 (PLOT 7) NEW CHURCH STREET, RADCLIFFE

Inspection date:	27-10-17	Weather:	COLD/DRY/SUNNY	Inspected by:	ANDY LONGDEN	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2 FLOOR SLAB					
2.2	Condition of sub-grade & underside of gas membrane	FLOOR SCRAPED & BRUSHED, PERIMETER MEMBRANE CLEANED, ALL TAPES APPLIED WELL, SEALED TO A GOOD QUALITY					
2.3	Gas membrane type	RADBAR BLACK					
2.4	Gas membrane condition and coverage	SEALED ON ALL FOUR SIDES - ALL GOOD					
2.5	Jointing tape product	DOUBLE SIDED RADBAR TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	VISIBLE OVERLAPS - ALL GOOD					
2.8	Number and condition of service entry seals	3 RD TOP HATS FITTED AROUND DRAINAGE/WATER, JUBILEE CLIPS STAPED - ALL GOOD					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples			I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance.				
3.1	Internal Venting Pipes Spacing	—	Signed: 		Dated: 27-10-17		
3.2	External Cranked Vents Spacing	—					
3.3	Sub Floor Void	—	Photographs witnessed and approved by Coopers:				
3.4	Membrane Overview	✓					
3.5	Overlaps	✓	Signed: 				
3.6	Corners	✓					
3.7	Services	✓	Dated: 30/10/17				
3.8	Product Types/Labels	ALL AS					

PREVIOUSLY SUPPLIED

For Residential Development at New Church Street, Radcliffe.



















One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

6654 - PLOT 21 (Block 7) NEW CHURCH STREET, RADCLIFFE

Inspection date:	27-10-17	Weather:	COLD/DRY/SUNNY	Inspected by:	ANDY LONGDEN	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2 - FLOOR SLAB					
2.2	Condition of sub-grade & underside of gas membrane	FLOOR SCRAPED & BRUSHED, PERIMETER MEMBRANE CLEANED, ALL TAPES APPLIED WELL, SEALED TO A GOOD QUALITY					
2.3	Gas membrane type	RADBAR BLACK					
2.4	Gas membrane condition and coverage	SEALED ON ALL FOUR SIDES - ALL GOOD					
2.5	Jointing tape product	DOUBLE SIDED RADBAR TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	VISIBLE OVERLAPS - ALL GOOD					
2.8	Number and condition of service entry seals	3 NO TOP HATS FITTED AROUND DRAINAGE/WATER, JUBILEE CLIPS & TAPED - ALL GOOD					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples		I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance.					
3.1	Internal Venting Pipes Spacing	—					
3.2	External Cranked Vents Spacing	—					
3.3	Sub Floor Void	—					
3.4	Membrane Overview	—					
3.5	Overlaps	✓					
3.6	Corners	✓					
3.7	Services	✓					
3.8	Product Types/Labels	ALL AS					
		Signed: <i>[Signature]</i>				Dated: 27-10-17	
		Photographs witnessed and approved by Coopers:					
		Signed: <i>[Signature]</i>				Dated: 30/10/17	

PREVIOUSLY SUPPLIED

For Residential Development at New Church Street, Radcliffe.

22















Gas Protection - Validation Record Sheet



One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

... PLOT 24, Block 8

Inspection date:	12/9/17	Weather:	DRY, OVERCAST	Inspected by:	DAVE GARNES	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2 – FLOOR SLAB					
2.2	Condition of sub-grade & underside of gas membrane	FLOOR BRUSHED AND ALL TAPES APPLIED WELL. SEALED TO A GOOD QUALITY					
2.3	Gas membrane type	RADBAR – Black					
2.4	Gas membrane condition and coverage	GOOD, SEALED ON ALL FOUR SIDES					
2.5	Jointing tape product	DOUBLE SIDED RADBAR TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	ALL GOOD, VISIBLE OVERLAPS					
2.8	Number and condition of service entry seals	3 NO. TOPHATS WITH JUBILEE CLIPS – TAPES CHECKED, ALL OK					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples		I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance.					
3.1	Internal Venting Pipes Spacing	—		Signed: <u>DS Barnes</u>		Dated: <u>12/9/17</u>	
3.2	External Cranked Vents Spacing	—					
3.3	Sub Floor Void	✓					
3.4	Membrane Overview	✓					
3.5	Overlaps	✓		Photographs witnessed and approved by Coopers:			
3.6	Corners	✓		Signed: <u>DS</u>		Dated: <u>25/9/17</u>	
3.7	Services	✓					
3.8	Product Types/Labels	✓					

For Residential Development at New Church Street, Radcliffe.



Plot 24

PLOT 24



910724





R10524



Plot 24



Gas Protection - Validation Record Sheet



One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

Plot 25, Block 9

Inspection date:	18/8/17	Weather:	SUNNY + SHOWERS	Inspected by:	DAVE BARNES	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2 – FLOOR SLAB					
2.2	Condition of sub-grade & underside of gas membrane	ALL TAPES APPLIED WELL + SEALED TO A GOOD QUALITY. FLOOR BRUSHED					
2.3	Gas membrane type	BLACK RADBAR					
2.4	Gas membrane condition and coverage	GOOD AND SEALED ON ALL FOUR SIDES					
2.5	Jointing tape product	DOUBLE SIDED RADBAR TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	VISIBLE OVERLAPS, ALL APPEAR GOOD					
2.8	Number and condition of service entry seals	3 NO TOPHATS WITH SUBILEE CLIPS (PICTURED). TAPES CHECKED, ALL OK					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples			I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance.				
3.1	Internal Venting Pipes Spacing	—	Signed: <u>DS Barnes</u>		Dated: <u>18/9/17</u>		
3.2	External Cranked Vents Spacing	—					
3.3	Sub Floor Void	✓	Photographs witnessed and approved by Coopers:				
3.4	Membrane Overview	✓					
3.5	Overlaps	✓	Signed: <u>[Signature]</u>				
3.6	Corners	✓					
3.7	Services	✓					
3.8	Product Types/Labels	✓					
			Dated: <u>25/9/17</u>				

For Residential Development at New Church Street, Radcliffe.

PLOT 25



PLOT 25









Gas Protection - Validation Record Sheet

One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

Plot 26, Block 9

Inspection date:	18/9/17	Weather:	DRY + OVERCAST	Inspected by:	DAVE BARNES	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2 – FLOOR SLAB					
2.2	Condition of sub-grade & underside of gas membrane	ALL TAPES APPLIED WELL AND SEALED TO A GOOD QUALITY, WITH THE FLOOR FINISHED					
2.3	Gas membrane type	BLACK RADBAR					
2.4	Gas membrane condition and coverage	SEALED ON ALL SIDES AND IN GOOD CONDITION					
2.5	Jointing tape product	RADBAR DOUBLE SIDED TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	ALL GOOD, WITH VISIBLE OVERLAPS					
2.8	Number and condition of service entry seals	3 NO. TO PLUMBS WITH SUBILKE CLIPS – ALL TAPES CHECKED AND OK					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples			I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance.				
3.1	Internal Venting Pipes Spacing	—	Signed: <u>DS Barnes</u>		Dated: <u>18/9/17</u>		
3.2	External Cranked Vents Spacing	—					
3.3	Sub Floor Void	✓					
3.4	Membrane Overview	✓					
3.5	Overlaps	✓	Photographs witnessed and approved by Coopers:				
3.6	Corners	✓	Signed: <u>STH</u>		Dated: <u>25/9/17</u>		
3.7	Services	✓					
3.8	Product Types/Labels	✓					

For Residential Development at New Church Street, Radcliffe.



KIER

PLOT 26



PILOT 26

STOP AT 1000



910726







PLOT 26



One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

Plot 27, Block 9

Inspection date:	18/9/17	Weather:	OVERCAST, DRY	Inspected by:	DAVE BARNES	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2 – FLOOR INSPECTION ON SLAB					
2.2	Condition of sub-grade & underside of gas membrane	SEALED TO A GOOD QUALITY. FLOOR BRUSHED AND ALL TAPES APPLIED WELL					
2.3	Gas membrane type	BLACK RADBAR					
2.4	Gas membrane condition and coverage	SEALED ON ALL FOUR SIDES AND IN GOOD CONDITION					
2.5	Jointing tape product	RADBAR DOUBLE SIDED TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	VISIBLE OVERLAPS AND ALL GOOD					
2.8	Number and condition of service entry seals	3 NO. TOPHATS WITH JUBILEE CLIPS – TAPES CHECKED AND ALL OK					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples		I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance.					
3.1	Internal Venting Pipes Spacing	—	Signed: DS Barnes		Dated: 18/9/17		
3.2	External Cranked Vents Spacing	—					
3.3	Sub Floor Void	✓					
3.4	Membrane Overview	✓					
3.5	Overlaps	✓					
3.6	Corners	✓					
3.7	Services	✓					
3.8	Product Types/Labels	✓					
			Photographs witnessed and approved by Coopers:				
			Signed: S.M.S.		Dated: 25/9/17		

For Residential Development at New Church Street, Radcliffe.







910727



01-12-08 10:20:14







06-42 05 10 2016



ROT 27

Gas Protection - Validation Record Sheet

One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

Plot 29, Block 10

Inspection date:	18/8/17	Weather:	SUNNY + SHOWERS	Inspected by:	ANDY LONGDEN	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	FLOOR SLAB - STAGE 2					
2.2	Condition of sub-grade & underside of gas membrane	FLOOR BRUSHED, ALL TAPES APPLIED WELL AND SEALED TO A GOOD QUALITY					
2.3	Gas membrane type	BLACK RADBAR					
2.4	Gas membrane condition and coverage	GOOD, SEALED ON ALL FOUR SIDES					
2.5	Jointing tape product	RADBAR DOUBLE-SIDED TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	VISIBLE OVERLAPS, ALL GOOD					
2.8	Number and condition of service entry seals	ALL OK, 3 N° TOPHATS WITH JUBILEE CLIPS - ALL TAPES CHECKED					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples		I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance. Signed:  Dated: 18/8/17 Photographs witnessed and approved by Coopers: Signed:  Dated: 18/8/17					
3.1	Internal Venting Pipes Spacing	—					
3.2	External Cranked Vents Spacing	—					
3.3	Sub Floor Void	✓					
3.4	Membrane Overview	✓					
3.5	Overlaps	✓					
3.6	Comers	✓					
3.7	Services	✓					
3.8	Product Types/Labels	✓					

For Residential Development at New Church Street, Radcliffe.



KIER

PLOT 29







PLOT 29







PLOT
29



Gas Protection - Validation Record Sheet

One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

Plot 30, Block 10

Inspection date:	18/8/17	Weather:	SUNNY + SHOWERS	Inspected by:	ANDREW LONGDEN	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	FLOOR SLAB - STAGE 2					
2.2	Condition of sub-grade & underside of gas membrane	FLOOR BRUSHED, ALL TAPES APPLIED WELL AND SEALED TO A GOOD QUALITY					
2.3	Gas membrane type	BLACK RADBAR					
2.4	Gas membrane condition and coverage	GOOD, SEALED ON ALL FOUR SIDES					
2.5	Jointing tape product	RADBAR DOUBLE-SIDED TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	ALL GOOD, VISIBLE OVERLAPS					
2.8	Number and condition of service entry seals	3 NO TOPHATS WITH SUBILEE CLIPS - ALL TAPES CHECKED AND OK					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples			I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance. Signed:  Dated: 18/8/17				
3.1	Internal Venting Pipes Spacing	—					
3.2	External Cranked Vents Spacing	—	Photographs witnessed and approved by Coopers: Signed:  Dated: 18/8/17				
3.3	Sub Floor Void	✓					
3.4	Membrane Overview	✓					
3.5	Overlaps	✓					
3.6	Corners	✓					
3.7	Services	✓					
3.8	Product Types/Labels	✓					

For Residential Development at New Church Street, Radcliffe.

The KIER logo, featuring a stylized 'K' in blue and red followed by the word 'KIER' in black capital letters.

PLOT 30



Plot
30



PLOT
30

HAWAII
Sample 3000
10/1/10









Gas Protection - Validation Record Sheet

One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

Plot 31, Block 10

Inspection date:	18/8/17	Weather:	SUNNY + SHOWERS	Inspected by:	ANDY LONGDEN	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2, FLOOR SLAB					
2.2	Condition of sub-grade & underside of gas membrane	ALL TAPES APPLIED WELL AND SEALED TO A GOOD QUALITY – FLOOR BRUSHED					
2.3	Gas membrane type	BLACK RADBAR					
2.4	Gas membrane condition and coverage	GOOD, SEALED ON ALL FOUR SIDES					
2.5	Jointing tape product	RADBAR DOUBLE-SIDED TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	VISIBLE OVERLAPS, ALL GOOD					
2.8	Number and condition of service entry seals	ALL OK, 3 NO TOPWATS WITH SUBILEE CLIPS – ALL TAPES CHECKED					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples		I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance. Signed:  Dated: 18/8/17 Photographs witnessed and approved by Coopers: Signed:  Dated: 18/8/17					
3.1	Internal Venting Pipes Spacing						
3.2	External Cranked Vents Spacing	✓					
3.3	Sub Floor Void	✓					
3.4	Membrane Overview	✓					
3.5	Overlaps	✓					
3.6	Corners	✓					
3.7	Services	✓					
3.8	Product Types/Labels	✓					

For Residential Development at New Church Street, Radcliffe.



PLOT 31









PLOT
31











One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

Plot 32, Block 11

Inspection date:	1/8/17	Weather:	DRY, OVERCAST	Inspected by:	DAVE BARNES	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2 – FLOOR SLAB					
2.2	Condition of sub-grade & underside of gas membrane	GOOD QUALITY, BRUSHED FLOOR, TAPE APPLIED WELL AND SEALED					
2.3	Gas membrane type	BLACK RADBAR					
2.4	Gas membrane condition and coverage	GOOD SEALED ON ALL FOUR SIDES					
2.5	Jointing tape product	RADBAR DOUBLE-SIDED TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE					
2.7	Condition of joints/seals	GOOD – OVERLAP VISIBLE					
2.8	Number and condition of service entry seals	GOOD, TAPE CHECKED, ALL JUBILEE CLIPS VISIBLE – 3 N. TOP HATS					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples		I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance.					
3.1	Internal Venting Pipes Spacing	—		Signed: <i>DS Barnes</i>		Dated: 1/8/17	
3.2	External Cranked Vents Spacing	—					
3.3	Sub Floor Void	—					
3.4	Membrane Overview	✓		Photographs witnessed and approved by Coopers:			
3.5	Overlaps	✓					
3.6	Corners	✓		Signed: <i>SJS</i>			
3.7	Services	✓		Dated: 4-8/17			
3.8	Product Types/Labels	✓					

For Residential Development at New Church Street, Radcliffe.



566499
MANCHESTER NORTH

ROCKWOOL
ROCKWOOL

PLOT 32

Plot 32





PLOT 32



Plot 32



P10632



One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

Plot 34, Block 11

Inspection date:	1/8/17	Weather:	DRY, OVERCAST	Inspected by:	DAVE BARNES	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2, FLOOR SLAB					
2.2	Condition of sub-grade & underside of gas membrane	GOOD, FLOOR BRUSHED AND TAPES APPLIED WELL AND SEALED					
2.3	Gas membrane type	BLACK RADBAR					
2.4	Gas membrane condition and coverage	GOOD, SEALED ON ALL SIDES					
2.5	Jointing tape product	RADBAR DOUBLE-SIDED TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	GOOD, OVERLAPS VISIBLE					
2.8	Number and condition of service entry seals	ALL GOOD, 3 NO TOP HATS WITH SUBILEE CLIPS. TAPES CHECKED.					
2.9	Membrane steps/corner seals	NONE					
2.10	Repairs or Corrections:	NONE VISIBLE.					
3) Photograph Check List – Tick to Confirm – Refer to Examples		I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance.					
3.1	Internal Venting Pipes Spacing	—	Signed: <u>DS Barnes</u>		Dated: <u>1/8/17</u>		
3.2	External Cranked Vents Spacing	—					
3.3	Sub Floor Void	✓					
3.4	Membrane Overview	✓	Photographs witnessed and approved by Coopers:				
3.5	Overlaps	✓					
3.6	Corners	✓	Signed: <u>SS</u>				
3.7	Services	✓	Dated: <u>4/8/17</u>				
3.8	Product Types/Labels	✓					

For Residential Development at New Church Street, Radcliffe.



Plot 34

Plot 34

Plot 34

Plot 34







One record sheet to be completed for each plot

This Record sheet is only applicable to block and beam floor slabs for Characteristic Situation 2 gas protection systems

Plot 35, Block 11

Inspection date:	1/2/17	Weather:	DRY, OVERCAST	Inspected by:	DAVE BARNES	Company:	KIER LIVING
1) Sub Floor Venting System		Comments:					
1.1	Internal Wall Venting Pipes – size and spacing	—					
1.2	External Wall Venting – cranked vent spacing	—					
2) Gas Membrane Inspection		Comments:					
2.1	Inspection Stage:	STAGE 2, FLOOR SLAB					
2.2	Condition of sub-grade & underside of gas membrane	GOOD QUALITY, BRUSHED FLOOR, TAPE APPLIED WELL AND SEALED.					
2.3	Gas membrane type	BLACK RADBAR					
2.4	Gas membrane condition and coverage	GOOD, SEALED ON ALL FOUR SIDES.					
2.5	Jointing tape product	RADBAR DOUBLE-SIDED TAPE					
2.6	Lapping tape product	RADBAR ULTRA LAPPING TAPE (SILVER)					
2.7	Condition of joints/seals	GOOD, OVERLAPS VISIBLE					
2.8	Number and condition of service entry seals	ALL GOOD, 3 NO. TOP HATS WITH RUBBER CLIPS, TAPES CHECKED.					
2.9	Membrane steps/corner seals	NONE.					
2.10	Repairs or Corrections:	NONE VISIBLE					
3) Photograph Check List – Tick to Confirm – Refer to Examples		I confirm I have independently inspected and verified the gas membrane installation has been completed in accordance with construction details and manufacturers guidance.					
3.1	Internal Venting Pipes Spacing	—		Signed: 	Dated: 1/2/17		
3.2	External Cranked Vents Spacing	—					
3.3	Sub Floor Void	✓		Photographs witnessed and approved by Coopers:	Dated: 4/8/17		
3.4	Membrane Overview	✓					
3.5	Overlaps	✓		Signed: 			
3.6	Corners	✓					
3.7	Services	✓					
3.8	Product Types/Labels	✓					

For Residential Development at New Church Street, Radcliffe.



Plot 33