








proposed section




existing ground floor plan



proposed ground floor plan



proposed roof plan



proposed PILED foundation plan

Proposed	
Roof Tiles	Ridge
Brickwork	Mortar
SVP	Gutters
Ramp	
Rafters - 100 x 50mm @ 400ccs	
Ceiling Joists - 100 x 50mm @ 400ccs	
Flat Roof Joists - 150 x 50mm @ 400 cts	
Hipped Rafters - 100 x 50mm @ 400ccs	
Purins - 100 x 50mm @ 400ccs	
Hangers and Binders - 100 x 50mm	
Ridge Size - 150 x 50mm	
Ground Floor Joists - 100 x 50mm @ 400ccs	
First Floor Joists - 100 x 50mm @ 400ccs	
Internal Stairs - 100 x 50mm @ 400ccs	
Fascias & Soffits	
	Existing Switch
	Proposed New Switch
	Existing Pull Cord Switch
	Proposed Pull Cord Switch
	Existing Pendant
	Existing Single Double Power Point
	Proposed Single Double Power Point
	Existing Ceiling Light/Fixture/Flow
	Proposed Ceiling Light/Fixture/Flow
	Mains Downlight - Flush
	Shower Downlight - Flush
	Proposed New Heat Blind Smoke Detector
	Existing Spur
	Proposed Spur
	Existing Cooler Power Point
	Proposed Cooler Power Point
	Proposed Under Cupboard Tri-Lite
	Devices a High Level Power Point
	Devices a Low Level Power Point
	Existing Extractor in Ceiling
	Proposed Extractor in Ceiling
	Existing Extractor Through Wall
	Proposed Extractor Through Wall
	New TV Point
	New Tap Position
	New Shower Position
	New Stop Tap Position
	New Cold Water Tap Position
	Existing Radiator
	New Radiator
	New Straight Towel Radiator
	New Curved Towel Radiator
Radiator Pipe Diameter - 15mm	
Skirting - ??	Architrave - ??
SKIP LOCATION - MATERIALS - PORTALOO -	????????? ?????????
During the construction process of carrying out loft conversions and alteration works to existing properties there is a risk that cracks may appear in existing ceilings. Additionally 'mud gaps' (which is the detachment of plaster from the existing wall heads) can also be experienced. Adamson Construction Ltd will take all reasonable precautions to prevent such occurrences and will carry out reasonable repairs to such cracks. However, the company cannot be held responsible for defects in the ceilings, such as existing ceilings which are out of level or are already cracked. Adamson Construction Ltd suggest that the Customer arranges for the removal of all carpets adjacent to the proposed works for the duration of the contract. Whilst we will undertake reasonable protection measures we can not be held responsible for any removal or clearing of carpets left in situ.	
The company does not undertake external painting, landscaping or steps. The company will not be liable for any decoration works to new or existing ceilings, walls & woodwork. This drawing is the copyright of Adamson Construction Limited and any reproduction in whole or part is strictly forbidden. Adamson Construction reserve the right to modify and make necessary alterations dependent on site conditions. Piled on 05/02/2018	
Current Continuation of Order Book	
THIS DRAWING HAS BEEN EXAMINED AND APPROVED AND I AM AWARE THAT ANY CHANGES WILL BE CHARGEABLE. DATE	
APPROVED BY CUSTOMER	
E	
D	
C	
B	
A	
DRAWN	JDJ
SCALE	1:50
DATE	May 2022
CUSTOMER	
Mr Crump	
PROJECT	
Extension to the rear	
LOCATION	
13 Brookfield Road, Bury, BL9 5LA	
Adamson Home Care Ltd, Oldfield, Chester SK10 4DE Telephone: 01276 336189 Fax: 01276 336191	
JOB No.	7844 - 01
REV.	