



Photograph 1. Hillside Avenue adjoining George Street



Photograph 2. Recently formed roadway and footpath surfacing



Photograph 3. Kerbing is stained and marked on both sides of the roadway



Photograph 4. Kerbing is stained and marked on both sides of the roadway



Photograph 5. Localised impact damage to the kerbs



Photograph 6. Staining the kerbing



Photograph 7. Staining to the kerbing



Photograph 8. Staining to the kerbing



Photograph 9. Localised indentations to footpath areas



Photograph 10. Localised indentations to footpath areas



Photograph 11. Minor erosion to the surfacing at the junction with George Street.



Photograph 12. Roadway directly adjacent to the site entrance area



Photograph 13. Tarmacadam surfacing to the footpath



Photograph 14. Localised damage and settlement to the concrete kerbs



Photograph 15. Norwood located directly to the north of the site entrance



Photograph 16. Localised reinstatement of road surfacing to Norwood junction slightly eroded



Photograph 17. Localised reinstatement of road surfacing to Norwood junction slightly eroded



Photograph 18. Localised reinstatement of road surfacing to Norwood junction slightly eroded



Photograph 19. Damaged and uneven kerbs to Norwood junction



Photograph 20. Localised cracking to road surface



Photograph 21. Uneven and damaged kerb to George Street



Photograph 22. Uneven and damaged kerb to George Street



Photograph 23. Uneven and damaged kerb to George Street



Photograph 24. Reinstatement to inspection chamber cracked and eroding



Photograph 25. Localised erosion to surfacing



Photograph 26. Reinstated area of surfacing damaged and eroded



Photograph 27. Reinstated area of surfacing damaged and eroded



Photograph 28. Localised indentations to road surfacing



Photograph 29. Adjoining footpath in reasonable condition



Photograph 30. Localised erosion to surfacing



Photograph 31. Localised erosion to surfacing



Photograph 32. Erosion to road surfacing near to site entrance on George Street



Photograph 33. Localised erosion to surfacing



Photograph 34. Localised erosion to surfacing



Photograph 35. Line marking eroding



Photograph 36. Cracking to surfacing



Photograph 37. Erosion of wearing coat of surfacing



Photograph 38. Badly eroded and cracked surfacing



Photograph 39. Badly eroded and cracked surfacing.



Photograph 40. Badly eroded and cracked surfacing.



Photograph 41. Damaged and uneven kerbing.



Photograph 42. Uneven kerbing.



Photograph 43. Localised erosion to surfacing.



Photograph 44. Cracking to surfacing to centre of roadway.



Photograph 45. Cracking to surfacing to centre of roadway.



Photograph 46. Cracking to surfacing to centre of roadway.



Photograph 47. Localised erosion to surfacing.



Photograph 48. Cracking and erosion to surfacing.



Photograph 49. Cracking and erosion to surfacing.



Photograph 50. Cracking and erosion to surfacing.



Photograph 51. Cracking and erosion to surfacing.



Photograph 52. Uneven kerbs



Photograph 53. Cracking to surfacing



Photograph 54. Footpath in reasonable condition



Photograph 55. Footpath in reasonable condition



Photograph 56. Footpath in reasonable condition



Photograph 57 Surfacing in reasonable condition.



Photograph 58. Surfacing in reasonable condition.



Photograph 59. Erosion to central section of roadway



Photograph 60. Localised damage to kerbing



Photograph 61. Minor erosion to surfacing



Photograph 62. Erosion to footpath surfacing of junction to business premises



Photograph 63. Erosion to footpath surfacing of junction to business premises



Photograph 64. Erosion to footpath surfacing of junction to business premises



Photograph 65. Localised reinstatement to footpath



Photograph 66. Localised reinstatement to footpath



Photograph 67. Erosion to footpath



Photograph 68. Erosion to footpath



Photograph 69. Cracking to surfacing



Photograph 70. Erosion to footpath



Photograph 71. Road surfacing in reasonable condition



Photograph 72. Footpath in reasonable condition



Photograph 73. Road surfacing in reasonable condition



Photograph 74. Uneven kerbs to footpath



Photograph 75. Road surfacing in reasonable condition



Photograph 76. Road surfacing in reasonable condition



Photograph 77. Localised cracking to surfacing.



Photograph 78. Localised cracking to surfacing.



Photograph 79. Junction to industrial estate.



Photograph 80. Junction to industrial estate.



Photograph 81.Exposed joint to centre of roadway



Photograph 82. Localised cracking to road surfacing.



Photograph 83. Localised erosion to footpath



Photograph 84. Localised erosion to footpath.



Photograph 85. Localised reinstatement of road surfacing.



Photograph 86. Erosion to surfacing around inspection chamber.



Photograph 87. Reinstatement of road surfacing.



Photograph 88. Erosion to line marking.



Photograph 89. Localised erosion to surfacing



Photograph 90. Localised erosion to surfacing.



Photograph 91. Junction with industrial estate to the east of George Street