



GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
9/ 50



TS01 - Timber-clad within the eastern part of the excavation



TS01 - Reinstated





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
10/ 50



TS01 - Reinstated





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
11 / 50



TS02 - Prior to excavation looking northeast



TS02 - Excavation to a depth of 1.15 m looking northeast





Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
12/ 50



TS02 - Excavation to a depth of 1.15 m looking northwest - no services encountered



TS02 - Closer view of the pit





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
13/ 50



TS02 - Reinstated





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
14/ 50



TS03 - Prior to excavation looking northeast



TS03 - Excavation to a depth of 1.30 m looking southeast





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
15/ 50



TS03 - Excavation to a depth of 1.30 m looking southeast



TS03 - Excavation to a depth of 1.30 m looking southeast






Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
16/ 50



TS03 - Excavation to a depth of 1.30 m looking northeast



TS03 - Cast iron pipe at base of the excavation





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs


Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
17 / 50



TS03 - Reinstated





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
18/ 50



TS04 - Prior to excavation looking northeast



TS04 - Excavation to a depth of 1.80 m looking southeast - drainage pipe encountered





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
19/ 50



TS04 - Excavation to a depth of 1.80 m looking northwest - drainage pipe encountered



TS04 - Closer view of drainage pipe





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
20/ 50



TS04 - Reinstated





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
21/ 50



TS05 - Prior to excavation looking southwest



TS05 - Excavation to a depth of 1.30 m looking northwest - low voltage electric and BT ducts encountered





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
22/ 50



TS05 - Excavation to a depth of 1.30 m looking northwest - low voltage electric and BT ducts encountered



TS05 - Excavation to a depth of 1.30 m looking southwest - low voltage electric and BT ducts encountered





Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
23/ 50



TS05 - Closer view of low voltage electric duct



TS05 - Closer view of BT duct





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
24/ 50



TS05 - Spoil



TS05 - Spoil





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
25/ 50



TS05 - Reinstated





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
26/ 50



TS06 - Prior to excavation looking northwest



TS06 - Excavation to a depth of 0.30 m looking northwest - concrete encountered





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
27 / 50



TS06 - Excavation to a depth of 0.30 m looking northwest - concrete encountered



TS06 - Excavation to a depth of 0.30 m looking southwest - concrete encountered





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
28/ 50



TS06 - Excavation to a depth of 0.30 m looking southwest - concrete encountered



TS06 - Reinstated





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
29/ 50



TS07 - Prior to excavation looking northwest



TS07 - Electric supply against exterior wall





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
30/ 50



TS07 - Excavation to a depth of 1.20 m looking northwest - no services encountered



TS07 - Excavation to a depth of 1.20 m looking southwest - no services encountered





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
31/ 50



TS07 - View beneath kerb



TS07 - Spoil





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
32/ 50



TS07 - Reinstated





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs


Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
33/ 50



TS08 - Prior to excavation looking northeast



TS08 - Excavation to a depth of 2.00 m looking northwest - no services encountered





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
34/ 50



TS08 - Excavation to a depth of 2.00 m looking northwest - no services encountered



TS08 - Excavation to a depth of 2.00 m looking southwest - no services encountered





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
35/ 50



TS08 - Spoil



TS08 - Spoil





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
36/ 50



TS08 - Reinstated





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
37 / 50



TS09 - Prior to excavation looking northeast



TS09 - Excavation to a depth of 0.30 m looking northeast - concrete encountered





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
38/ 50



TS09 - Excavation to a depth of 0.30 m looking northeast - concrete encountered



TS09 - Excavation locally to a depth of 0.60 m looking northeast





Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
39/ 50



TS09 - Excavation to a depth of 0.30 m looking northwest - concrete encountered



TS09 - Excavation locally to a depth of 0.60 m looking northwest





GEA

Geotechnical & Environmental Associates
www.gea-ltd.co.uk

Service Trench Photographs

Site Prestwich North Car Park, Fairfax Road, Prestwich, Manchester, M25 1BT

Client The Prestwich Regeneration LLP

Engineer Civic Engineers

Job Number
J23254A

Sheet
40/ 50



TS09 - Spoil



TS09 - Reinstated

