




P3 Inside main section, unlined roof



P4 Board lining over stalls



P5 Interior breeze block



P6 Corrugated rear open section



P7 Next door building obstructing rear of affected stables