

DILAPS SURVEY

The following photographs taken 21 October show state of footway and surrounding carriageway at that date.



South east site boundary. Footway cracking, edgings required, kerbs misaligned/broken.



Junction back Walmersley Rd with Chesham Rd, badly deteriorated road markings, poor carriageway reinstatement and damage to carriageway.



Gulley sunk and blocked Chesham Rd



Footway on Chesham Rd showing relatively recent reinstatements and historical cracking.



Chesham Rd footway looking east



Looking east, reinstatement following LC installation.



Looking east from LC



Footway near telegraph/BRSK(?) pole.





From TP to Hilton St





Hilton St junction



Damaged flags on Hilton St



Hilton St



Edging required on Hilton St



carriageway at Chesham St/Hilton St