

Conservation

The amendments are satisfactory so no objection from a heritage conservation viewpoint.

Just one small point. The rooflights on the opposite roof slope to the dormers I think are quite large and given they are to the first floor bedrooms where the dormers are, could the rooflights be reduced in size to mitigate their visual impact as a contemporising feature in the CA?