

There are changes because it's a demolition and re-build. However, there is no north side elevation (I've sent you the southern side) because it is right up against the existing neighbouring building. Similarly at the rear, there is no access to the building so the rear elevation (solid brick with no windows) cannot be seen. Therefore, there is no point in having the elevations.

Many thanks

Rev'd Prof Bob May FRTPI
Director