

in the event of a lack of ventilation to extract the fumes; this is usually the result of an extract fan mechanical or electrical failure.

The NCSP complies with *BS6173 – 2001* for Commercial Kitchens, where all Gas appliances are fitted with *flame failure devices*.

- The panel is suitable for Pressure sensing (preferred) or current sensing
- The Panel is suitable for use with any 1 Phase or 3 Phase Extract or Supply fan
- An Emergency Stop Button is mounted on the fascia
- The Panel has no fan electrical connections
- Different coloured lamps mounted on the fascia indicate