




CDM HIGH RISK ASSESSMENT	
ITEM	RECOMMENDATION
Roof Windows and Glazing	To prevent falls scaffolding or boarding of gable and frame cladding required. (See schedule for details)
Roofing / Cladding / Scaffolding / Boarding	To prevent falls scaffolding required.
Windows / Glass Panels	To prevent falls scaffolding required.
Windows / Glass Panels	To prevent falls scaffolding required.
Plumbing in Loft	Scaffolding/Boarding required.
Plumbing in Loft	Scaffolding/Boarding required.
Roofs / Cladding	Mechanical measures as appropriate
Roofs / Cladding	Low Mechanical Equipment, for main lift area (see schedule for details) (See schedule for details)
Collapses	Temporary propping required
Health	Provide CDMH Assessment



bpd Architecture

CIAT Registered practice

Stichstone, Brown House Lane, Higher Wheelton,
Chorley, Lancashire PR8 8HR
Tel: 01257 220510
web: www.betterplan.co.uk
email: info@betterplan.co.uk



Chartered Institute of
Architectural Technologists

Registered Practice

Project

**62 Starling Road, Ainsworth,
BURY M26 4LN**

Title

**Complete property remodel
Site sections/streetscenes**

Scale @ A1

1:100

Date

July 2023

Ref

Job 1054

Drawn

MDB

Dwg No

1091/SRA/PL4

Rev

-