

CHERY, BURY

49

Friday, 3 July 2026



ISSUE 1

Cracked paving up from the dealership



ISSUE 2

Cracked paving up from the dealership



ISSUE 3

Current condition of existing pedestrian crossing up from the dealership



ISSUE 4

Current condition of entrance into petrol station across from the dealership



ISSUE 5

Cracked tarmac in the highway up from the dealership



ISSUE 6

Existing drain outside of the petrol station across from the dealership



ISSUE 7

Existing drain pictured in issue 6



ISSUE 8

Existing highway surface next to the dealership



ISSUE 9

Cracked tarmac in the highway outside the dealership



ISSUE 10

Damaged kerbs down from the dealership



ISSUE 11

Existing footpath, kerbs and balustrade across the road from the dealership



ISSUE 12

Existing tactile paving across the road from the dealership, badly damaged



ISSUE 13

Damaged kerbs up from the dealership



ISSUE 14

Retaining wall of the petrol station across the road from the dealership



ISSUE 15

Retaining wall of the petrol station across the road from the dealership



ISSUE 16

Existing gully in the highway, blocked



ISSUE 17

Retaining wall of the petrol station across the road from the dealership and footpath



ISSUE 18

Retaining wall of the petrol station across the road from the dealership and footpath



ISSUE 19

Damaged kerbs down from the dealership



ISSUE 20

Existing paving next to the petrol station across from the dealership



ISSUE 21

Existing paving next to the petrol station across from the dealership



ISSUE 22

Existing paving next to the petrol station across from the dealership, partly damaged



ISSUE 23

Damaged kerb up from the dealership



ISSUE 24

Existing footpath up from the dealership



ISSUE 25

Existing footpath and manholes up the road from the dealership



ISSUE 26

Damaged kerbs up the road from the dealership at the bus stop



ISSUE 27

Damaged kerbs up from the dealership outside the bus stop



ISSUE 28

Existing paving around the bus stop, up from the dealership



ISSUE 29

Existing kerbs up from the dealership



ISSUE 30

Cracks in the tarmac in the highway, up from the dealership



ISSUE 31

Damaged kerbs up from the dealership



ISSUE 32

Damaged kerbs up from the dealership



ISSUE 33

Existing paving up from the dealership outside of the park, partly damaged



ISSUE 34

Damaged kerbs up from the dealership, outside of the park



ISSUE 35

Damaged kerbs outside of the dealership



ISSUE 36

Existing gully in the highway, blocked



ISSUE 37

Damaged kerbs up from the dealership outside the park




ISSUE 38

Existing kerbs up from the dealership outside the park, partly damaged



ISSUE 39

Damaged kerbs down from the dealership



ISSUE 40

Existing gully in the highway, blocked



ISSUE 41

Damaged kerbs down from the dealership



ISSUE 42

Damaged kerbs outside the dealership



ISSUE 43

Existing footpath down from the dealership



ISSUE 44

Existing tactile paving and footpath down from the dealership



ISSUE 45

Existing gully in the highway, as well as damaged kerbs



ISSUE 46

Damaged tactile paving down from the dealership



ISSUE 47

Existing retaining wall down from the dealership



ISSUE 48

Existing retaining wall down from the dealership



ISSUE 49

Existing retaining wall down from the dealership



ISSUE 50

Damaged kerbs down from the dealership




ISSUE 51

Damaged kerbs outside the dealership




ISSUE 52

Existing kerbs outside the dealership



ISSUE 53

Damaged kerbs outside the dealership



ISSUE 54

Damaged kerbs outside the dealership



ISSUE 55

Damaged paving up from the dealership



ISSUE 56

Damaged paving up from the dealership



ISSUE 57

Existing gully outside the dealership, which is blocked and tarmac is cracked around it