

MASSEY FOUNDATIONS & PILING LTD

Specialist Mini Piling, Structural Repair & Underpinning Contractors
Building Contractors

Toft Smithy
Toft Road
Knutsford
Cheshire
WA16 9PA



Tel: 01565 750066
Fax: 01565 750077

E-mail: info@masseyfoundations.co.uk

Mr Anton Lally
Sock Construction Ltd

PHN/RE 2726.RAMS Addendum

31st January 2023

By email only to: ael23@icloud.com

Dear Mr Lally,

Re: Butterstile Close, Hilton Lane, Prestwich

ADDENDUM TO METHOD STATEMENT / RISK ASSESSMENT of 25 Jan 2023

We confirm that the steel-cased driven piles in all cases did not breach the clay layer into the sandstone.

Using borehole CP201 as a reference, we can confirm that the tips of the piles were a minimum of 1.70 metres above the base of the clay stratum. The majority were probably 2.00 metres above the base of the clay layer.

Yours sincerely,
for MASSEY FOUNDATIONS & PILING LTD

P H Nelson
Director