


General


 Specified Site  Specified Buffer(s)  Bearing Reference Point

Estimated Soil Chemistry Arsenic

Arsenic Concentrations mg/kg



Estimated Soil Chemistry Arsenic - Slice A





Order Details

Order Details: 296205844_1_1
Customer Ref: 22-1127.01
National Grid Reference: 380180, 408500
Slice: A
Site Area (Ha): 1.52
Search Buffer (m): 1000

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL






General


Specified Site Specified Buffer(s) Bearing Reference Point

Estimated Soil Chemistry Cadmium

Cadmium Concentrations mg/kg



Estimated Soil Chemistry Cadmium - Slice A



Order Details

Order Details: 296205844_1_1
Customer Ref: 22-1127.01
National Grid Reference: 380180, 408500
Slice: A
Site Area (Ha): 1.52
Search Buffer (m): 1000

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL




Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk

General


 Specified Site  Specified Buffer(s)  Bearing Reference Point

Estimated Soil Chemistry Chromium

Chromium Concentrations mg/kg



Estimated Soil Chemistry Chromium - Slice A





Order Details

Order Details: 296205844_1_1
Customer Ref: 22-1127.01
National Grid Reference: 380180, 408500
Slice: A
Site Area (Ha): 1.52
Search Buffer (m): 1000

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL






General


- Specified Site
- Specified Buffer(s)
- Bearing Reference Point

Estimated Soil Chemistry Lead

Lead Concentrations mg/kg



Estimated Soil Chemistry Lead - Slice A



Order Details

Order Details: 296205844_1_1
Customer Ref: 22-1127.01
National Grid Reference: 380180, 408500
Slice: A
Site Area (Ha): 1.52
Search Buffer (m): 1000

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL




Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk

General


 Specified Site  Specified Buffer(s)  Bearing Reference Point

Estimated Soil Chemistry Nickel

Nickel Concentrations mg/kg



Estimated Soil Chemistry Nickel - Slice A





Order Details

Order Details: 296205844_1_1
Customer Ref: 22-1127.01
National Grid Reference: 380180, 408500
Slice: A
Site Area (Ha): 1.52
Search Buffer (m): 1000

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL





Groundwater Vulnerability

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Slice
- Map ID

Agency and Hydrological

Bedrock Aquifers


- High Vulnerability, Principal Aquifer
- High Vulnerability, Secondary Aquifer
- Medium Vulnerability, Principal Aquifer
- Medium Vulnerability, Secondary Aquifer
- Low Vulnerability, Principal Aquifer
- Low Vulnerability, Secondary Aquifer

Superficial Aquifers

- High Vulnerability, Principal Aquifer
- High Vulnerability, Secondary Aquifer
- Medium Vulnerability, Principal Aquifer
- Medium Vulnerability, Secondary Aquifer
- Low Vulnerability, Principal Aquifer
- Low Vulnerability, Secondary Aquifer

- Unproductive Aquifer
- Soluble Rock

Site Sensitivity Context Map - Slice A



Order Details


Order Number: 296205844_1_1
 Customer Ref: 22-1127.01
 National Grid Reference: 380180, 408500
 Slice: A
 Site Area (Ha): 1.52
 Search Buffer (m): 1000

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL



Tel: 0844 844 9952
 Fax: 0844 844 9951
 Web: www.envirocheck.co.uk



© Crown Copyright. All Rights Reserved. License Number 100022432.



Superficial Aquifer Designation

General


- △ Specified Site
- Specified Buffer(s)
- X Bearing Reference Point
- Slice
- 8 Map ID

Agency and Hydrological

Geological Classes

- Principal Aquifer
- Secondary A Aquifer
- Secondary B Aquifer
- Secondary Undifferentiated
- Unproductive Strata
- Unknown
- Unknown (Lakes and Landslip)

Site Sensitivity Context Map - Slice A



Order Details


Order Number: 296205844_1_1
 Customer Ref: 22-1127.01
 National Grid Reference: 380180, 408500
 Slice: A
 Site Area (Ha): 1.52
 Search Buffer (m): 1000

Site Details


Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL



Tel: 0844 844 9952
 Fax: 0844 844 9951
 Web: www.envirocheck.co.uk



© Crown Copyright. All Rights Reserved. License Number 100022432



© Crown Copyright. All Rights Reserved. License Number 100022432.



BGS Flood GFS Data


General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Slice

Agency and Hydrological (Flood)

- Limited Potential for Groundwater Flooding to Occur
- Potential for Groundwater Flooding of Property Situated Below Ground Level
- Potential for Groundwater Flooding to Occur at Surface

Site Sensitivity Context Map - Slice A



Order Details

Order Number: 296205844_1_1
 Customer Ref: 22-1127.01
 National Grid Reference: 380180, 408500
 Slice: A
 Site Area (Ha): 1.52
 Search Buffer (m): 1000

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL



Tel: 0844 844 9952
 Fax: 0844 844 9951
 Web: www.envirocheck.co.uk

Envirocheck[®] Report:

Mining and Ground Stability Datasheet

Order Details:

Order Number:

296205844_1_1

Customer Reference:

22-1127.01

National Grid Reference:

380180, 408500

Slice:

A

Site Area (Ha):

1.52

Search Buffer (m):

1000

Site Details:

Tesco Mobile Customer Care, Cellnet Building
Dumers Lane
BURY
BL9 9QL

Client Details:

Ms M Booth
Delta Simons
Suite 4A
One Portland Street
Manchester
M1 3BE

Report Section and Details	Page Number
Summary	-
The Summary section provides an overview of the data contained within the report, detailing the number of data set features or the existence of a data set in relation to the buffer selected. For ease of reference, the report is broken down into 4 sections of data; Mining and Natural Cavities Data, Historical Land Use Information (1:2,500), Historical Land Use Information (1:10,000) and Ground Stability Data (1:50,000).	
Mining and Natural Cavities Data	1
The Mining and Natural Cavities Data section features data sets related to the existence of mining areas and their potential hazards; and details of naturally formed cavities. Data sets within this section are not plotted, with the exception of BGS Recorded Mineral Sites and Potential Mining Areas which feature on the Historical Land Use Information (1:10,000) map.	
Historical Land Use Information (1:2,500)	2
The Historical Land Use Information (1:2,500) section contains data captured from analysis carried out by Landmark of 1:1,250 and 1:2,500 scale historical Ordnance Survey mapping, identifying areas where, historically, the land uses were potentially contaminative. For the purpose of this Envirocheck module, only historical data relating to mining and ground stability has been included and plotted on the corresponding Historical Land Use Information (1:2,500) map. This section also includes the Subterranean Features data set, which details various man-made and man-used underground spaces obtained from the Subterranea Britannica society.	
Historical Land Use Information (1:10,000)	4
The Historical Land Use (1:10,000) section covers data captured from the systematic analysis carried out by Landmark of 1:10, 560 and 1:10,000 scale historical Ordnance Survey mapping dating back to the mid-19th century, identifying potentially contaminative past industrial land uses. For the purpose of this Envirocheck module, only data relating to mining and ground stability has been included and plotted on the accompanying Historical Land Use Information (1:10,000) map.	
Ground Stability Data (1:50,000)	7
The Ground Stability (1:50,000) section includes the BGS Geosure data suite, reporting features to 250m and plotted onto 3 separate maps. Also reported is brine subsidence, brine mining and salt mining data sets, of which Brine Pumping and Salt Mining Related Features are plotted, and subsidence insurance claims and insurance investigations data, which is not plotted.	
Historical Map List	8
The Historical Map List section details the historical mapping that has been analysed for your site, in relation to the Historical Land Use Information sections.	
Data Currency	9
Data Suppliers	10
Useful Contacts	11

Copyright Notice

© Landmark Information Group Limited 2022. The Copyright on the information and data and its format as contained in this Envirocheck® Report ("Report") is the property of Landmark Information Group Limited ("Landmark") and several other Data Providers, including (but not limited to) Ordnance Survey, British Geological Survey, and the Environment Agency/Natural Resources Wales, and must not be reproduced in whole or in part by photocopying or any other method. The Report is supplied under Landmark's Terms and Conditions accepted by the Customer. A copy of Landmark's Terms and Conditions can be found with the Index Map for this report. Additional copies of the Report may be obtained from Landmark, subject to Landmark's charges in force from time to time. The Copyright, design rights and any other intellectual rights shall remain the exclusive property of Landmark and/or other Data providers, whose Copyright material has been included in this Report.

© Copyright Stantec UK Limited. All rights reserved.

The brine subsidence data relating to the Droitwich area as provided in this report is derived from JPB studies and physical monitoring undertaken annually over more than 35 years. For more detailed interpretation contact enquiries@jpb.co.uk. JPB retain the copyright and intellectual rights to this data and accept no liability for any loss or damage, including in direct or consequential loss, arising from the use of this data.

The Mining Instability data was obtained on licence from Ove Arup & Partners Limited (for further information, contact mining.review@arup.com). No reproduction or further use of such Data is to be made without the prior written consent of Ove Arup & Partners Limited. The supplied Mining Instability data is derived from publicly available records and other third party sources and neither Ove Arup & Partners nor Landmark warrant the accuracy or completeness of such information or data.

Report Version v53.0

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m
Mining and Natural Cavities Data					
BGS Recorded Mineral Sites					
Coal Mining Affected Areas	pg 1	Yes	n/a	n/a	n/a
Man Made Mining Cavities					
Mining Instability	pg 1	Yes	n/a	n/a	n/a
Natural Cavities					
Non Coal Mining Areas of Great Britain				n/a	n/a
Potential Mining Areas	pg 1	1		2	2
Historical Land Use Information (1:2,500)					
Extractive Industries or Potential Excavations from 1855-1909 (100m)	pg 2		1	n/a	n/a
Extractive Industries or Potential Excavations from 1893-1915 (100m)	pg 2		4	n/a	n/a
Extractive Industries or Potential Excavations from 1906-1937 (100m)	pg 2	1	3	n/a	n/a
Extractive Industries or Potential Excavations from 1924-1949 (100m)	pg 2		3	n/a	n/a
Extractive Industries or Potential Excavations from 1950-1980 (100m)	pg 3	2	2	n/a	n/a
Subterranean Features (100m)				n/a	n/a
Historical Land Use Information (1:10,000)					
Air Shafts	pg 4				1
Disturbed Ground					
General Quarrying					
Heap, unknown constituents	pg 4		1	1	1
Mineral Railway	pg 4			4	
Mining & quarrying general					
Mining of coal & lignite	pg 4				2
Quarrying of sand & clay, operation of sand & gravel pits	pg 4				1
Former Marshes					
Potentially Infilled Land (Non-Water)	pg 4				3
Potentially Infilled Land (Water)	pg 4		5	10	17
Ground Stability Data (1:50,000)					
CBSCB Compensation District			n/a	n/a	n/a
Brine Pumping Related Features					
Brine Subsidence Solution Area					
Potential for Collapsible Ground Stability Hazards	pg 7	Yes	Yes	n/a	n/a
Potential for Compressible Ground Stability Hazards	pg 7	Yes	Yes	n/a	n/a
Potential for Ground Dissolution Stability Hazards	pg 7	Yes	Yes	n/a	n/a
Potential for Landslide Ground Stability Hazards	pg 7	Yes	Yes	n/a	n/a
Potential for Running Sand Ground Stability Hazards	pg 7	Yes	Yes	n/a	n/a
Potential for Shrinking or Swelling Clay Ground Stability Hazards	pg 7	Yes	Yes	n/a	n/a
Salt Mining Related Features					



Summary

Report Version v53.0

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Coal Mining Affected Areas Description: In an area which may be affected by coal mining activity. It is recommended that a coal mining report is obtained from the Coal Authority. Contact details are included in the Useful Contacts section of this report.	A13SW (SE)	0	1	380182 408498
	Mining Instability Mining Evidence: Inconclusive Coal Mining Source: Ove Arup & Partners Boundary Quality: As Supplied	A13SW (SE)	0	2	380182 408498
	Non Coal Mining Areas of Great Britain No Hazard				
1	Potential Mining Areas Name: Bank Top Ceased Operation: 1893 Commodity: Coal; Hynes or Cannel Reference: 3001 Alternate: Cannel Name/Mine: Alternate Alternate: Hagside Name/Mine: Alternate Alternate: Openshaw Fold Name/Mine: Alternate Alternate: Reservoir Name/Mine: Custodian: Not Supplied	A13SW (SE)	0	3	380182 408498
2	Potential Mining Areas Name: Withins Lane Ceased Operation: 1887 Commodity: Coal; Five Quarter; Dow Reference: 2055 Alternate: Not Supplied Name/Mine: Custodian: Not Supplied	A12SE (W)	402	3	379698 408395
3	Potential Mining Areas Name: Withins Lane and Coney Green Ceased Operation: 1893 Commodity: Coal; Hyne or Cannel; Dow; Five Quarters Reference: 3001A Alternate: Not Supplied Name/Mine: Custodian: Not Supplied	A12SE (W)	402	3	379698 408395
4	Potential Mining Areas Name: Bank Top Ceased Operation: 1868 Commodity: Coal; Hinds Reference: Not Supplied Alternate: Openshaw Fold Name/Mine: Custodian: Divisional Engineer's Office, L.M.S. Railway Co. Ltd., Hunts Bank, Manchester.	A12NE (NW)	509	3	379702 408797
5	Potential Mining Areas Name: Bank Top Ceased Operation: Not Supplied Commodity: Coal Reference: Not Supplied Alternate: Not Supplied Name/Mine: Custodian: Not Supplied	A17NE (NW)	765	3	379705 409199

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
6	Extractive Industries or Potential Excavations from 1855-1909 Use: Reservoirs First Map Published 1893 Date: Last Map Published Not Applicable Date:	A13SE (E)	58	-	380327 408442
7	Extractive Industries or Potential Excavations from 1893-1915 Use: Aqueduct First Map Published 1910 Date: Last Map Published Not Applicable Date:	A13SE (SE)	46	-	380294 408416
8	Extractive Industries or Potential Excavations from 1893-1915 Use: Resr. First Map Published 1910 Date: Last Map Published Not Applicable Date:	A13SE (E)	62	-	380331 408438
9	Extractive Industries or Potential Excavations from 1893-1915 Use: Filter Bed First Map Published 1910 Date: Last Map Published Not Applicable Date:	A13SE (SE)	64	-	380279 408385
10	Extractive Industries or Potential Excavations from 1893-1915 Use: W First Map Published 1910 Date: Last Map Published Not Applicable Date:	A13SW (SW)	67	-	380038 408419
11	Extractive Industries or Potential Excavations from 1906-1937 Use: Unspecified Deposited Material First Map Published 1930 Date: Last Map Published Not Applicable Date:	A13SE (SE)	0	-	380263 408447
12	Extractive Industries or Potential Excavations from 1906-1937 Use: Aqueduct First Map Published 1930 Date: Last Map Published Not Applicable Date:	A13SE (SE)	48	-	380295 408415
13	Extractive Industries or Potential Excavations from 1906-1937 Use: Resr. First Map Published 1930 Date: Last Map Published Not Applicable Date:	A13SE (E)	64	-	380332 408436
14	Extractive Industries or Potential Excavations from 1906-1937 Use: Settling Tanks First Map Published 1930 Date: Last Map Published Not Applicable Date:	A13SE (SE)	65	-	380283 408385
15	Extractive Industries or Potential Excavations from 1924-1949 Use: Aqueduct First Map Published 1937 Date: Last Map Published Not Applicable Date:	A13SE (SE)	47	-	380293 408415
16	Extractive Industries or Potential Excavations from 1924-1949 Use: Settling Tanks First Map Published 1937 Date: Last Map Published Not Applicable Date:	A13SE (SE)	53	-	380275 408396

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
17	Extractive Industries or Potential Excavations from 1924-1949 Use: Resr. First Map Published 1937 Date: Last Map Published Not Applicable Date:	A13SE (E)	63	-	380331 408437
18	Extractive Industries or Potential Excavations from 1950-1980 Use: Unspecified Deposited Material First Map Published 1957 Date: Last Map Published 1957 Date:	A13SE (SE)	0	-	380208 408460
19	Extractive Industries or Potential Excavations from 1950-1980 Use: Unspecified Deposited Material First Map Published 1957 Date: Last Map Published N/A Date:	A13SW (S)	0	-	380182 408443
20	Extractive Industries or Potential Excavations from 1950-1980 Use: Aqueduct First Map Published 1957 Date: Last Map Published N/A Date:	A13SE (SE)	47	-	380295 408416
21	Extractive Industries or Potential Excavations from 1950-1980 Use: Settling Tanks First Map Published 1957 Date: Last Map Published N/A Date:	A13SE (SE)	58	-	380288 408396

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
22	Air Shafts Use: Not Supplied Date of Mapping: 1911	A12NW (W)	741	-	379375 408618
23	Heap, unknown constituents Use: Not Supplied Date of Mapping: 1910	A13NW (NW)	214	-	379961 408656
24	Heap, unknown constituents Use: Not Supplied Date of Mapping: 1931 - 1992	A13NW (NW)	368	-	379852 408780
25	Heap, unknown constituents Use: Not Supplied Date of Mapping: 1894	A12NW (W)	805	-	379305 408603
26	Mineral Railway Use: Not Supplied Date of Mapping: 1894 - 1911	A12SE (W)	422	-	379698 408314
27	Mineral Railway Use: Not Supplied Date of Mapping: 1894 - 1910	A12SE (W)	423	-	379701 408302
28	Mineral Railway Use: Not Supplied Date of Mapping: 1894	A12NE (W)	447	-	379701 408658
29	Mineral Railway Use: Not Supplied Date of Mapping: 1911	A12SE (W)	476	-	379621 408457
30	Mining of coal & lignite Use: Not Supplied Date of Mapping: 1894	A12NW (W)	736	-	379376 408602
31	Mining of coal & lignite Use: Not Supplied Date of Mapping: 1850	A17NW (NW)	962	-	379465 409247
32	Quarrying of sand & clay, operation of sand & gravel pits Use: Not Supplied Date of Mapping: 1851	A18NE (N)	920	-	380428 409478
33	Potentially Infilled Land (Non-Water) Use: Unknown Filled Ground (Pit, quarry etc) Date of Mapping: 1992	A12NW (W)	736	-	379376 408602
34	Potentially Infilled Land (Non-Water) Use: Unknown Filled Ground (Pit, quarry etc) Date of Mapping: 1983	A18NE (N)	915	-	380424 409474
35	Potentially Infilled Land (Non-Water) Use: Unknown Filled Ground (Pit, quarry etc) Date of Mapping: 1992	A17NW (NW)	962	-	379465 409247
36	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A13NW (W)	169	-	379946 408528
37	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1931	A13SW (SW)	172	-	379947 408366
38	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A13NE (E)	179	-	380410 408576
39	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A13SW (SW)	187	-	379938 408352
40	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A13NE (NE)	242	-	380358 408755
41	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1894	A12SE (SW)	356	-	379787 408276
42	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A14SW (E)	370	-	380641 408425

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
43	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1851	A14SW (E)	393	-	380643 408329
44	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1851	A18SW (N)	401	-	380044 408973
45	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A14SW (E)	416	-	380659 408305
46	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1894	A18SE (N)	421	-	380319 408989
47	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1894	A7NE (SW)	444	-	379773 408147
48	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A14NW (E)	449	-	380712 408554
49	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1910	A18SE (N)	465	-	380301 409041
50	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1910	A18SE (N)	475	-	380285 409056
51	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A8NE (S)	549	-	380360 407906
52	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A8NE (S)	605	-	380390 407855
53	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1851	A18NE (N)	631	-	380238 409221
54	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A7NE (SW)	661	-	379510 408147
55	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A17SE (NW)	668	-	379620 408971
56	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1851	A18NW (N)	685	-	380096 409274
57	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1851	A14SE (E)	696	-	380956 408328
58	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1910	A17NE (NW)	744	-	379839 409258
59	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A17SE (NW)	789	-	379587 409124
60	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1910	A14SE (E)	800	-	381055 408296
61	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1911	A17SW (NW)	844	-	379434 409006
62	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1910	A18NW (N)	880	-	380036 409462
63	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1851	A18NE (N)	901	-	380204 409494

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
64	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1911	A17SW (NW)	930	-	379357 409044
65	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A9SW (SE)	965	-	380825 407665
66	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A9SE (SE)	976	-	380915 407724
67	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1851	A15SW (E)	992	-	381264 408449

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	CBSCB Compensation District The site does not fall within the brine compensation area.				
	Brine Subsidence Solution Area The site does not fall within the brine subsidence solution area.				
68	Potential for Collapsible Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (SE)	0	4	380182 408498
	Potential for Collapsible Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SW (S)	0	4	380183 408461
	Potential for Collapsible Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SW (W)	97	4	380000 408498
69	Potential for Compressible Ground Stability Hazards Hazard Potential: Moderate Source: British Geological Survey, National Geoscience Information Service	A13SW (S)	0	4	380183 408461
70	Potential for Compressible Ground Stability Hazards Hazard Potential: Moderate Source: British Geological Survey, National Geoscience Information Service	A13SW (W)	97	4	380000 408498
	Potential for Compressible Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SW (SE)	0	4	380182 408498
	Potential for Ground Dissolution Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SW (SE)	0	4	380182 408498
	Potential for Ground Dissolution Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SW (W)	97	4	380000 408498
71	Potential for Landslide Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (SE)	0	4	380182 408498
72	Potential for Landslide Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (W)	97	4	380000 408498
73	Potential for Landslide Ground Stability Hazards Hazard Potential: Low Source: British Geological Survey, National Geoscience Information Service	A13SE (SE)	239	4	380478 408339
74	Potential for Running Sand Ground Stability Hazards Hazard Potential: Low Source: British Geological Survey, National Geoscience Information Service	A13SW (S)	0	4	380183 408461
75	Potential for Running Sand Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (SE)	0	4	380182 408498
76	Potential for Running Sand Ground Stability Hazards Hazard Potential: Low Source: British Geological Survey, National Geoscience Information Service	A13SW (W)	97	4	380000 408498
77	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (S)	0	4	380183 408461
78	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (W)	97	4	380000 408498
	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SW (SE)	0	4	380182 408498

The following mapping has been analysed for Historical Land Use Information (1:2,500):

1:2,500	Mapsheet	Published Date
Lancashire And Furness	088_13	1893
Lancashire And Furness	088_13	1910
Lancashire And Furness	088_13	1930
Lancashire And Furness	088_13	1937

The following mapping has been analysed for Historical Land Use Information (1:10,000):

1:10,560	Mapsheet	Published Date
Lancashire And Furness	096_00	1848
Lancashire And Furness	087_00	1850
Lancashire And Furness	095_00	1850
Lancashire And Furness	088_00	1851
Lancashire And Furness	087_SE	1894
Lancashire And Furness	088_SW	1894
Lancashire And Furness	096_NW	1894
Lancashire And Furness	088_SW	1910
Lancashire And Furness	095_NE	1910
Lancashire And Furness	096_NW	1910
Lancashire And Furness	087_SE	1911
Lancashire And Furness	096_NW	1923
Lancashire And Furness	095_NE	1930
Lancashire And Furness	087_SE	1931
Lancashire And Furness	088_SW	1931
Ordnance Survey Plan	SD70NE	1955
Ordnance Survey Plan	SD80NW	1955
1:10,000	Mapsheet	Published Date
Ordnance Survey Plan	SD80NW	1983
Ordnance Survey Plan	SD70NE	1992

Mining and Cavities Data	Version	Update Cycle
BGS Recorded Mineral Sites British Geological Survey - National Geoscience Information Service	May 2022	Bi-Annually
Coal Mining Affected Areas The Coal Authority - Property Searches	March 2014	Annual Rolling Update
Man Made Mining Cavities Stantec UK Ltd	December 2021	Bi-Annually
Mining Instability Ove Arup & Partners	June 1998	Not Applicable
Natural Cavities Stantec UK Ltd	December 2021	Bi-Annually
Non Coal Mining Areas of Great Britain British Geological Survey - National Geoscience Information Service	May 2015	Not Applicable
Historical Land Use Information (1:2,500)	Version	Update Cycle
Subterranean Features Landmark Information Group Limited	February 2020	Bi-Annually
Ground Stability Data (1:50,000)	Version	Update Cycle
CBSCB Compensation District Cheshire Brine Subsidence Compensation Board (CBSCB) Cheshire Brine Subsidence Compensation Board (CBSCB)	August 2011 November 2020	As notified
Potential for Collapsible Ground Stability Hazards British Geological Survey - National Geoscience Information Service	April 2020	As notified
Potential for Compressible Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Ground Dissolution Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Landslide Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Running Sand Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Shrinking or Swelling Clay Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Brine Subsidence Solution Area Johnson Poole & Bloomer	December 2020	Annual Rolling Update

A selection of organisations who provide data within this report

Data Supplier	Data Supplier Logo
Ordnance Survey	
British Geological Survey	 British Geological Survey NATURAL ENVIRONMENT RESEARCH COUNCIL
The Coal Authority	
Ove Arup	
Stantec UK Ltd	
Wardell Armstrong	
Johnson Poole & Bloomer	

Contact	Name and Address	Contact Details
1	The Coal Authority - Property Searches 200 Lichfield Lane, Mansfield, Nottinghamshire, NG18 4RG	Telephone: 0345 762 6848 Fax: 01623 637 338 Email: groundstability@coal.gov.uk Website: www2.groundstability.com
2	Ove Arup & Partners Central Square, Forth Street, Newcastle upon Tyne, Tyne and Wear, NE1 3PL	Telephone: 0191 261 6080 Fax: 0191 261 7879
3	Landmark Information Group Limited Imperium, Imperial Way, Reading, Berkshire, RG2 0TD	Telephone: 0844 844 9960 Fax: 0844 844 9951 Email: customerservice@promap.co.uk Website: www.landmarkinfo.co.uk
4	British Geological Survey - Enquiry Service British Geological Survey, Environmental Science Centre, Keyworth, Nottingham, Nottinghamshire, NG12 5GG	Telephone: 0115 936 3143 Fax: 0115 936 3276 Email: enquiries@bgs.ac.uk Website: www.bgs.ac.uk
-	Landmark Information Group Limited Imperium, Imperial Way, Reading, Berkshire, RG2 0TD	Telephone: 0844 844 9952 Fax: 0844 844 9951 Email: customerservices@landmarkinfo.co.uk Website: www.landmarkinfo.co.uk

Historical Land Use Information (1:2,500)

General

- Specified Site
 ○ Specified Buffer(s)
 X Bearing Reference Point
 Map ID
 Several of Type at Location


Potentially Contaminative Industrial Uses (Extractive Industries Activity)

	Point	Line	Polygon
Extractive Industries Activity from 1855 - 1909	▲	—	■
Extractive Industries Activity from 1893 - 1915	▲	—	■
Extractive Industries Activity from 1906 - 1937	▲	—	■
Extractive Industries Activity from 1924 - 1949	▲	—	■
Extractive Industries Activity from 1950 - 1980	▲	—	■

Subterranean Features

	Point	Line	Polygon
Subterranean Features	▼	---	■

Mining and Ground Stability - Segment A13



Order Details

Order Number: 296205844_1_1
 Customer Ref: 22-1127.01
 National Grid Reference: 380180, 408500
 Slice: A
 Site Area (Ha): 1.52
 Plot Buffer (m): 100

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane,
 BURY, BL9 9QL

