



Scoreboard internal and external renovation works to provide new toilets, a members bar and a new entrance

A3 1:100




Remove existing damaged double doors, replace with new to match existing. New access to cellar / bar area

New front elevation door to be used as the main entrance into the members bar.





Brickwork on the left hand side to be take up to match higher level on the right side. New windows to match right side. Scoreboard to be removed.



Existing tiled roof to be clean front and rear, repair where needed using the same profiled tile.

Repalce windows to match existing. Existing brickwork to be cleaned.



Remove old door and brick up to match existing brick.

