

The rear brook walls were also strengthened to ensure the walls could cope with the water flow in heavy rain. The Brook walls were in a highly neglected state in September 2019 and were strengthened as a result.

Kitchen building

All works were completed on the kitchen building and rear patio by December 2021. See attached image of the completed building titled: July 2022 for reference of the completed kitchen building.

View of kitchen building

See attached image of the completed building titled: Front side of house view and back of house view for reference of the completed kitchen building.

View of the kitchen building from key vantage points surrounding property

See attached images of the kitchen building taken from:

- Rochdale Road
- Bury Old Road
- Hollins Lane
- Bleakholt Road

As can clearly be seen from the images, the kitchen building, and most of the buildings for that matter, are well hidden from public eye and do not interfere with the natural flow of the greenbelt from a visual perspective.