

Historical Land Use Information (1:10,000)

General

-  Specified Site  Specified Buffer(s)  Bearing Reference Point  Map ID
 Several of Type at Location

Potentially Contaminative Industrial Uses (Past Land Uses - Mining)

	Point	Line	Polygon
Air Shafts			
Disturbed Ground			
General Quarrying			
Heap, unknown constituents			
Mineral Railway			
Mining and Quarrying General			
Mining of Coal & Lignite			
Quarrying of Sand and Clay, Operation of Sand and Gravel Pits			


Historical Land Use

	Point	Line	Polygon
Potentially Infilled Land (Non-Water)			
Potentially Infilled Land (Water)			
Former Marsh			

Mining Data

-  Potential Mining Area
 BGS Recorded Mineral Site

Mining and Ground Stability - Slice A





Order Details

Order Number: 296205844_1_1
Customer Ref: 22-1127.01
National Grid Reference: 380180, 408500
Slice: A
Site Area (Ha): 1.52
Search Buffer (m): 1000

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL





Ground Stability Data (1:50,000)

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Slice
- Map ID

Potential for Compressible Ground Stability Hazards

- High
- Low
- Moderate
- Very Low


Potential for Collapsible Ground Stability Hazards

- High
- Low
- Moderate
- Very Low

Brine Pumping and Salt Mining

- | | Point | Polygon |
|-------------------------------|-------|---------|
| Brine Pumping Related Feature | | |
| Salt Mining Related Feature | | |

Mining and Ground Stability - Slice A



Order Details


Order Number: 296205844_1_1
 Customer Ref: 22-1127.01
 National Grid Reference: 380180, 408500
 Slice: A
 Site Area (Ha): 1.52
 Search Buffer (m): 1000

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL



Tel: 0844 844 9952
 Fax: 0844 844 9951
 Web: www.envirocheck.co.uk



Ground Stability Data (1:50,000)

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Slice
- Map ID


Potential for Landslide Ground Stability Hazards

- High
- Moderate
- Low
- Very Low

Potential for Ground Dissolution Stability Hazards

- High
- Moderate
- Low
- Very Low

Mining and Ground Stability - Slice A



Order Details


Order Number: 296205844_1_1
 Customer Ref: 22-1127.01
 National Grid Reference: 380180, 408500
 Slice: A
 Site Area (Ha): 1.52
 Search Buffer (m): 1000

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL



Tel: 0844 844 9952
 Fax: 0844 844 9951
 Web: www.envirocheck.co.uk



© Crown Copyright. All Rights Reserved. License Number 100022432.



Ground Stability Data (1:50,000)

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Slice
- Map ID


Potential for Running Sand Ground Stability Hazards

- High
- Low
- Moderate
- Very Low

Potential for Shrinking or Swelling Clay Ground Stability Hazards

- High
- Low
- Moderate
- Very Low

Mining and Ground Stability - Slice A



Order Details

Order Number: 296205844_1_1
 Customer Ref: 22-1127.01
 National Grid Reference: 380180, 408500
 Slice: A
 Site Area (Ha): 1.52
 Search Buffer (m): 1000

Site Details

Tesco Mobile Customer Care, Cellnet Building, Dumers Lane, BURY, BL9 9QL



Tel: 0844 844 9952
 Fax: 0844 844 9951
 Web: www.envirocheck.co.uk