

Appendix 1 Photographic survey (2nd March 2022)



Image 1 – View of car parking to site frontage.



Image 2 – Signage for car parking to frontage



Image 3 – View of accessible main entrance




Image 4 – CCTV installation to monitor internal & external areas



Image 5 – Signage for evening use of Day Nursery car park by Cosalea



Image 6 – Signage outside main entrance



Image 7 – Car parking signage to side elevation



Image 8 – Car parking signage to side elevation