

Dilapidation Survey

Erection of one residential dwelling at **4 Parkstone Avenue, Whitefield.**

on behalf of :

Mr Addis

Jan 2026

Contents

- 1. Introduction**
- 2. Dilapidation Survey Photos**

1. Introduction

1.1 This dilapidation survey has been produced to support an application for the discharge of conditions at the site known as **4 Parkstone Avenue, Whitefield.**

2. Dilapidation Survey

The photos were taken at the start of the project prior to the job going on hold.



Photograph 1



Photograph 2



Photograph 3

Thorp Design Services
thorpdesignservices@gmail.com

Thorp Design Services
thorpdesignservices@gmail.com