

GHG LAD Survey

20 Jan 2021 / Shajidur Rahman / Green Home grant
- LAD

Complete

Score	41.18%	Failed items	10	Actions	0
Site	Green Home grant - LAD, Green Home Grant, Green Home grant - LAD				
Conducted on	20th Jan, 2021 12:13 PM GMT				
Prepared by	Shajidur Rahman				
Location	64 Bright St Manchester England M26 2XX United Kingdom (53.56836623517197, -2.312552165242203)				

Failed Items

10 failed

Inspection / Cavity Wall Insulation

1. Is the customer interested in this measure

No

Inspection / Loft Insulation

1. Is the customer interested in this measure

No

Inspection / Under Floor Insulation

1. Is the customer interested in this measure

No

Inspection / Room in Roof Insulation

1. Is the customer interested in this measure

No

Inspection / Air Source Heat Pump

1. Is the customer interested in this measure

No

Inspection / Solar Thermal

2. Do you have the technical knowledge to carry out this technical survey

No

Inspection / Window Replacement

2. Do you have the technical knowledge to carry out this technical survey

No

Inspection / Upgrading Doors

2. Do you have the technical knowledge to carry out this technical survey

No



Photo 8



Photo 9

Inspection / Smart Heating Controls

1. Is the customer interested in this measure

No

Inspection / Solar PV

2. Do you have the technical knowledge to carry out this technical survey

No

Elevation photographs

Private & Confidential

Photographs of each elevation



Photo 1



Photo 2

Photograph of floorplan




Photo 3

Inspection

10 failed, 41.18%

External Wall Insulation

1. Is the customer interested in this measure

Yes

2. Do you have the technical knowledge to carry out this technical survey

Yes

Cavity Wall Insulation

1 failed

1. Is the customer interested in this measure

No

Loft Insulation

1 failed, 0%

1. Is the customer interested in this measure

No

Under Floor Insulation

1 failed, 0%

1. Is the customer interested in this measure

No

Room in Roof Insulation

1 failed, 0%

1. Is the customer interested in this measure

No

Air Source Heat Pump

1 failed, 0%

1. Is the customer interested in this measure

No

Solar Thermal

1 failed, 80%

1. Is the customer interested in this measure

Yes

2. Do you have the technical knowledge to carry out this technical survey

No

3. How is the hot water heated

From Boiler

3. Is there an existing water tank




Photo 4

5. Is there adequate space for a cylinder (600mm x 600mm x 1500mm)

Yes

6. Is there a S/SE/SW facing roof area with 6m2

Yes

7. Is there a shower




Photo 5

Window Replacement

1 failed, 33.33%

1. Is the customer interested in this measure

Yes

2. Do you have the technical knowledge to carry out this technical survey

No

Window/s Sizes added (all SINGLE GLAZED windows)

Window/s Sizes added (all SINGLE GLAZED windows) 1

Window Opening (in mm)

4000

Photo of window



Photo 6

Window/s Sizes added (all SINGLE GLAZED windows) 2

Window Opening (in mm)

800

Photo of window



Photo 7

Upgrading Doors

1 failed, 50%

1. Is the customer interested in this measure

Yes

2. Do you have the technical knowledge to carry out this technical survey

No



Photo 8



Photo 9

3. Front door dimensions in mm	3000
--------------------------------	------

4. Rear door dimensions in mm	
-------------------------------	--

5. Side door dimensions in mm	2000
-------------------------------	------

6. Other door dimensions in mm	
--------------------------------	--

Smart Heating Controls

1 failed, 0%

1. Is the customer interested in this measure	No
---	----

Solar PV

1 failed, 50%

1. Is the customer interested in this measure	Yes
---	-----

2. Do you have the technical knowledge to carry out this technical survey	No
---	----

3. What is the orientation of the proposed roof?	South East
--	------------

Take clear photo of roof



Photo 10

4. What is the location of the Electricity meter?	Living room
---	-------------

Photograph of electricity meter




Photo 11

5. What is the location of the Electricity Consumer Unit?	Living room
---	-------------

Photograph of electricity consumer unit




Photo 12






Photo 5



Photo 7



Photo 8



Photo 10




Photo 12

Photo 9




Photo 11