

Envirocheck[®] Report:

Datasheet

Order Details:

Order Number:

287800372_1_1

Customer Reference:

5237

National Grid Reference:

380600, 410570

Slice:

A

Site Area (Ha):

1.89

Search Buffer (m):

1000

Site Details:

Bury Market
Murray Road
BURY
BL9 0BJ

Client Details:

Dr B Rice-Birchall
iD GeoEnvironmental Ltd
Caledonian House
Tatton Street
Knutsford
Cheshire
WA16 6AG

Report Section	Page Number
Summary	-
Agency & Hydrological	1
Waste	35
Hazardous Substances	51
Geological	52
Industrial Land Use	53
Sensitive Land Use	-
Data Currency	100
Data Suppliers	105
Useful Contacts	106

Introduction

The Environment Act 1995 has made site sensitivity a key issue, as the legislation pays as much attention to the pathways by which contamination could spread, and to the vulnerable targets of contamination, as it does the potential sources of contamination. For this reason, Landmark's Site Sensitivity maps and Datasheet(s) place great emphasis on statutory data provided by the Environment Agency/Natural Resources Wales and the Scottish Environment Protection Agency; it also incorporates data from Natural England (and the Scottish and Welsh equivalents) and Local Authorities; and highlights hydrogeological features required by environmental and geotechnical consultants. It does not include any information concerning past uses of land. The datasheet is produced by querying the Landmark database to a distance defined by the client from a site boundary provided by the client. In this datasheet the National Grid References (NGRs) are rounded to the nearest 10m in accordance with Landmark's agreements with a number of Data Suppliers.

Copyright Notice

© Landmark Information Group Limited 2021. The Copyright on the information and data and its format as contained in this Envirocheck® Report ("Report") is the property of Landmark Information Group Limited ("Landmark") and several other Data Providers, including (but not limited to) Ordnance Survey, British Geological Survey, the Environment Agency/Natural Resources Wales and Natural England, and must not be reproduced in whole or in part by photocopying or any other method. The Report is supplied under Landmark's Terms and Conditions accepted by the Customer. A copy of Landmark's Terms and Conditions can be found with the Index Map for this report. Additional copies of the Report may be obtained from Landmark, subject to Landmark's charges in force from time to time. The Copyright, design rights and any other intellectual rights shall remain the exclusive property of Landmark and /or other Data providers, whose Copyright material has been included in this Report. © Environment Agency & United Kingdom Research and Innovation 2021. © Natural Resources Wales & United Kingdom Research and Innovation 2021.

Natural England Copyright Notice

Site of Special Scientific Interest, National Nature Reserve, Ramsar, Special Protection Area, Special Conservation Area, Marine Nature Reserve data (derived from Ordnance Survey 1:10000 raster) is provided by, and used with the permission of, Natural England who retain the copyright and Intellectual Property Rights for the data.

Scottish Natural Heritage Copyright

Contains SNH information licensed under the Open Government Licence v3.0.

Ove Arup Copyright Notice

The Mining Instability data was obtained on licence from Ove Arup & Partners Limited (for further information, contact mining.review@arup.com). No reproduction or further use of such Data is to be made without the prior written consent of Ove Arup & Partners Limited. The supplied Mining Instability data is derived from publicly available records and other third party sources and neither Ove Arup & Partners nor Landmark warrant the accuracy or completeness of such information or data.

Stantec Copyright Notice

The cavity data presented has been extracted from the PBA (now Stantec UK Ltd) enhanced version of the original DEFRA national cavity databases. Stantec UK Ltd retain the copyright & intellectual property rights in the data. Whilst all reasonable efforts are made to check that the information contained in the cavity databases is accurate we do not warrant that the data is complete or error free. The information is based upon our own researches and those collated from a number of external sources and is continually being augmented and updated by Stantec UK Ltd. In no event shall Stantec UK Ltd or Landmark be liable for any loss or damage including, without limitation, indirect or consequential loss or damage arising from the use of this data.

Radon Potential dataset Copyright Notice

Information supplied from a joint dataset compiled by The British Geological Survey and Public Health England.

Natural Resources Wales Copyright Notice

Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Contains Ordnance Survey Data. Ordnance Survey Licence number 100019741. Crown Copyright and Database Right. Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Some features of this information are based on digital spatial data licensed from the Centre for Ecology & Hydrology © NERC (CEH). Defra, Met Office and DARD Rivers Agency © Crown copyright. © Cranfield University. © James Hutton Institute. Contains OS data © Crown copyright and database right 2021. Land & Property Services © Crown copyright and database right.

Report Version v53.0

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Agency & Hydrological					
BGS Groundwater Flooding Susceptibility	pg 1	Yes	Yes	Yes	n/a
Contaminated Land Register Entries and Notices					
Discharge Consents	pg 2			4	26
Prosecutions Relating to Controlled Waters			n/a	n/a	n/a
Enforcement and Prohibition Notices					
Integrated Pollution Controls	pg 9				3
Integrated Pollution Prevention And Control	pg 10				2
Local Authority Integrated Pollution Prevention And Control					
Local Authority Pollution Prevention and Controls	pg 10		1	9	14
Local Authority Pollution Prevention and Control Enforcements	pg 14			1	
Nearest Surface Water Feature	pg 14		Yes		
Pollution Incidents to Controlled Waters	pg 14			2	12
Prosecutions Relating to Authorised Processes	pg 16				2
Registered Radioactive Substances					
River Quality	pg 16				4
River Quality Biology Sampling Points					
River Quality Chemistry Sampling Points	pg 17				2
Substantiated Pollution Incident Register	pg 18				2
Water Abstractions	pg 19				7 (*37)
Water Industry Act Referrals					
Groundwater Vulnerability Map	pg 30	Yes	n/a	n/a	n/a
Groundwater Vulnerability - Soluble Rock Risk			n/a	n/a	n/a
Bedrock Aquifer Designations	pg 30	Yes	n/a	n/a	n/a
Superficial Aquifer Designations	pg 30	Yes	n/a	n/a	n/a
Source Protection Zones					
Extreme Flooding from Rivers or Sea without Defences				n/a	n/a
Flooding from Rivers or Sea without Defences				n/a	n/a
Areas Benefiting from Flood Defences				n/a	n/a
Flood Water Storage Areas				n/a	n/a
Flood Defences				n/a	n/a
OS Water Network Lines	pg 30			1	35

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Waste					
BGS Recorded Landfill Sites	pg 35			2	
Historical Landfill Sites	pg 35		1	5	1
Integrated Pollution Control Registered Waste Sites					
Licensed Waste Management Facilities (Landfill Boundaries)					
Licensed Waste Management Facilities (Locations)	pg 36				33
Local Authority Landfill Coverage	pg 43	1	n/a	n/a	n/a
Local Authority Recorded Landfill Sites					
Registered Landfill Sites	pg 43			1	3
Registered Waste Transfer Sites	pg 45				3
Registered Waste Treatment or Disposal Sites	pg 46		1		8
Hazardous Substances					
Control of Major Accident Hazards Sites (COMAH)	pg 51				2
Explosive Sites					
Notification of Installations Handling Hazardous Substances (NIHHS)	pg 51				2
Planning Hazardous Substance Consents	pg 51				1
Planning Hazardous Substance Enforcements					
Geological					
BGS 1:625,000 Solid Geology	pg 52	Yes	n/a	n/a	n/a
BGS Recorded Mineral Sites					
CBSCB Compensation District			n/a	n/a	n/a
Coal Mining Affected Areas	pg 52	Yes	n/a	n/a	n/a
Mining Instability	pg 52	Yes	n/a	n/a	n/a
Man-Made Mining Cavities	pg 52				1
Natural Cavities					
Non Coal Mining Areas of Great Britain				n/a	n/a
Potential for Collapsible Ground Stability Hazards	pg 52	Yes		n/a	n/a
Potential for Compressible Ground Stability Hazards				n/a	n/a
Potential for Ground Dissolution Stability Hazards				n/a	n/a
Potential for Landslide Ground Stability Hazards	pg 52	Yes		n/a	n/a
Potential for Running Sand Ground Stability Hazards	pg 52	Yes		n/a	n/a
Potential for Shrinking or Swelling Clay Ground Stability Hazards	pg 52		Yes	n/a	n/a
Radon Potential - Radon Affected Areas			n/a	n/a	n/a
Radon Potential - Radon Protection Measures			n/a	n/a	n/a

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Industrial Land Use					
Contemporary Trade Directory Entries	pg 53	3	29	88	425
Fuel Station Entries	pg 99		2	3	1
Gas Pipelines					
Underground Electrical Cables					
Sensitive Land Use					
Ancient Woodland					
Areas of Adopted Green Belt					
Areas of Unadopted Green Belt					
Areas of Outstanding Natural Beauty					
Environmentally Sensitive Areas					
Forest Parks					
Local Nature Reserves					
Marine Nature Reserves					
National Nature Reserves					
National Parks					
Nitrate Sensitive Areas					
Nitrate Vulnerable Zones					
Ramsar Sites					
Sites of Special Scientific Interest					
Special Areas of Conservation					
Special Protection Areas					
World Heritage Sites					

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13NW (W)	0	1	380550 410573
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NE (E)	0	1	380650 410573
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NE (E)	0	1	380598 410573
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13NW (W)	92	1	380400 410573
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding to Occur at Surface	A13NE (E)	119	1	380800 410650
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	158	1	380400 410400
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding to Occur at Surface	A13SE (S)	187	1	380600 410300
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SE (SE)	204	1	380850 410450
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13SW (SW)	266	1	380350 410300
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A14SW (SE)	316	1	380950 410400
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A14NW (E)	321	1	381000 410573
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A18SW (N)	354	1	380450 410950
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A14NW (E)	369	1	381050 410600
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A8NW (S)	437	1	380550 410050
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A9NW (SE)	439	1	380950 410200
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A8NE (SE)	444	1	380900 410150
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A8NE (SE)	459	1	380850 410100
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A14NW (E)	471	1	381150 410573
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A14SW (E)	473	1	381150 410550
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A9NW (SE)	475	1	380950 410150
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A17SE (NW)	482	1	380200 410950
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A14NW (E)	483	1	381150 410800

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A8NE (S)	486	1	380598 410000
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding to Occur at Surface	A8NE (S)	487	1	380600 410000
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A8NE (S)	491	1	380650 410000
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A12NE (W)	492	1	380000 410573
1	Discharge Consents Operator: Mr & Mrs Mark Hillon Property Type: DOMESTIC PROPERTY (SINGLE) (INCL FARM HOUSE) Location: 360-366 Manchester Rd, Walmersley, Bury, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016993231 Permit Version: 3 Effective Date: 12th November 2002 Issued Date: 12th November 2002 Revocation Date: Not Supplied Discharge Type: Sewage Discharges - Final/Treated Effluent - Not Water Company Discharge: Freshwater Stream/River Environment: Receiving Water: Trib River Irwell Status: Modified (Water Resources Act 1991, Schedule 10 as amended by Environment Act 1995) Positional Accuracy: Located by supplier to within 100m	A12SE (SW)	332	2	380200 410400
1	Discharge Consents Operator: Mr & Mrs E Hardman Property Type: DOMESTIC PROPERTY (SINGLE) (INCL FARM HOUSE) Location: 360-366 Manchester Rd, Walmersley, Bury, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016993231 Permit Version: 1 Effective Date: 20th June 1963 Issued Date: Not Supplied Revocation Date: 31st March 1997 Discharge Type: Sewage Discharges - Final/Treated Effluent - Not Water Company Discharge: Freshwater Stream/River Environment: Receiving Water: Trin River Irwell Status: Authorisation revoked Positional Accuracy: Located by supplier to within 100m	A12SE (SW)	332	2	380200 410400
1	Discharge Consents Operator: Mr & Mrs Mark Hillon Property Type: DOMESTIC PROPERTY (SINGLE) (INCL FARM HOUSE) Location: 360-366 Manchester Rd, Walmersley, Bury, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016993231 Permit Version: 2 Effective Date: 1st April 1997 Issued Date: Not Supplied Revocation Date: 11th November 2002 Discharge Type: Sewage Discharges - Final/Treated Effluent - Not Water Company Discharge: Freshwater Stream/River Environment: Receiving Water: Trib River Irwell Status: Modified (Water Resources Act 1991, Schedule 10 as amended by Environment Act 1995) Positional Accuracy: Located by supplier to within 100m	A12SE (SW)	333	2	380200 410395

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
2	Discharge Consents Operator: Mr J C Lees Property Type: FARMS (NOT HOUSE)/CROP + ANIMAL REARING/PLANT NURSERY Location: Park Farm, 206 Manchester Rd, Walmsley, Bury, Lancashire, B19 5np Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01m/779 Permit Version: 1 Effective Date: 2nd March 1956 Issued Date: 2nd March 1956 Revocation Date: Not Supplied Discharge Type: Sewage Discharges - Final/Treated Effluent - Not Water Company Discharge: Freshwater Stream/River Environment: Receiving Water: Unknown Status: Pre National Rivers Authority Legislation where issue date < 01/09/1989 Positional Accuracy: Located by supplier to within 10m	A12SE (SW)	427	2	380131 410319
3	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Tanpits Road Cso Harvard Road, Bury, ., Lancashire, B19 0nl Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016982617 Permit Version: 2 Effective Date: 9th July 2018 Issued Date: 9th July 2018 Revocation Date: Not Supplied Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: River Irwell Status: Varied under EPR 2010 Positional Accuracy: Located by supplier to within 10m	A17SE (NW)	671	2	379980 411000
4	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Tanpits Road Cso Harvard Road, Bury, ., Lancashire, B19 0nl Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01BRY0098 Permit Version: 1 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 1st January 1995 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: River Irwell Status: Consent revoked or revised: New Consent issued (Section 37(1)) Positional Accuracy: Located by supplier to within 100m	A12NW (W)	767	2	379730 410655
4	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Tanpits Road Cso Harvard Road, Bury, ., Lancashire, B19 0nl Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016982617 Permit Version: 1 Effective Date: 30th September 1994 Issued Date: Not Supplied Revocation Date: 8th July 2018 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: River Irwell Status: Post National Rivers Authority Legislation where issue date > 31/08/1989 Positional Accuracy: Located by supplier to within 100m	A12NW (W)	768	2	379730 410660

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
4	Discharge Consents Operator: United Utilities Water Limited Property Type: WWTW (NOT WATER CO) (NOT STP AT A PRIVATE PREMISES) Location: Marsden St, Bury, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01bry0014 Permit Version: 1 Effective Date: 17th September 1992 Issued Date: Not Supplied Revocation Date: 1st January 1995 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Unknown Environment: Receiving Water: Unknown Outlet; Licence Status: Revoked Status: Authorisation revoked Positional Accuracy: Located by supplier to within 10m	A12NW (W)	768	2	379730 410660
5	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Badger St, Bury, Lancashire Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01bry0015 Permit Version: 2 Effective Date: 3rd September 2010 Issued Date: 3rd September 2010 Revocation Date: 23rd March 2015 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Barn Brook Status: Surrendered under EPR 2010 Positional Accuracy: Located by supplier to within 10m	A19NW (NE)	800	2	381160 411300
5	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Badger St, Bury, Lancashire Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01BRY0015 Permit Version: 1 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 2nd September 2010 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Barn Brook Status: Varied under EPR 2010 Positional Accuracy: Located by supplier to within 100m	A19NW (NE)	800	2	381160 411300
6	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Woodfield Catchment Area, Bury, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01BRY0088 Permit Version: 2 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 14th July 2014 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: River Irwell Status: Surrendered under EPR 2010 Positional Accuracy: Located by supplier to within 100m	A17SW (NW)	813	2	379770 410940

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
6	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Woodfield Catchment Area, Bury, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01bry0088 Permit Version: 1 Effective Date: 1st July 1991 Issued Date: Not Supplied Revocation Date: 31st December 1994 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: River Irwell Status: Authorisation revoked Positional Accuracy: Located by supplier to within 10m	A17SW (NW)	813	2	379770 410940
6	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Woodfield Catchment Area, Bury, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016951239 Permit Version: 1 Effective Date: 5th February 1988 Issued Date: Not Supplied Revocation Date: 2nd July 2016 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: River Irwell Status: Pre National Rivers Authority Legislation where issue date < 01/09/1989 Positional Accuracy: Located by supplier to within 10m	A17SW (NW)	832	2	379770 410980
7	Discharge Consents Operator: Cemex Uk Materials Limited Property Type: WAREHOUSING + SUPPORT ACTIVITIES FOR TRANSPORTATION Location: Bury Readymix Plant Bridge Trading Estate, Bury/Bolton Road, Bury, Greater Manchester, B18 2aq Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 0174/11 Permit Version: 2 Effective Date: 7th March 2019 Issued Date: 1st January 1995 Revocation Date: Not Supplied Discharge Type: Trade Discharge - Process Water Discharge: Freshwater Stream/River Environment: Receiving Water: River Irwell Status: Post National Rivers Authority Legislation where issue date > 31/08/1989 Positional Accuracy: Located by supplier to within 100m	A12NW (W)	860	2	379700 410900
7	Discharge Consents Operator: Rmc Roadstone Ltd - North West Property Type: WAREHOUSING + SUPPORT ACTIVITIES FOR TRANSPORTATION Location: Bury Readymix Plant Bridge Trading Estate, Bury/Bolton Road, Bury, Greater Manchester, B18 2aq Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 0174/11 Permit Version: 1 Effective Date: 1st April 1991 Issued Date: Not Supplied Revocation Date: 6th March 2019 Discharge Type: Sewage Discharges - Final/Treated Effluent - Not Water Company Discharge: Freshwater Stream/River Environment: Receiving Water: River Irwell Status: Authorisation revoked Positional Accuracy: Located by supplier to within 100m	A12NW (W)	860	2	379700 410900

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
8	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Primrose Hill Cso School Street, ., Bury, Lancashire, B19 7ex Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01bry0022 Permit Version: 2 Effective Date: 3rd September 2010 Issued Date: 3rd September 2010 Revocation Date: 9th May 2019 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Barn Brook Status: Varied under EPR 2010 Positional Accuracy: Located by supplier to within 10m	A14SE (E)	870	2	381510 410320
8	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Primrose Hill Cso School Street, ., Bury, Lancashire, B19 7ex Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01BRY0022 Permit Version: 1 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 2nd September 2010 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Barn Brook Status: Varied under EPR 2010 Positional Accuracy: Located by supplier to within 100m	A14SE (E)	870	2	381510 410320
8	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Primrose Hill Cso School Street, ., Bury, Lancashire, B19 7ex Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01bry0022 Permit Version: 3 Effective Date: 10th May 2019 Issued Date: 10th May 2019 Revocation Date: 31st March 2022 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Barn Brook Status: Varied under EPR 2010 Positional Accuracy: Located by supplier to within 10m	A14SE (E)	875	2	381514 410314
8	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Primrose Hill Cso School Street, ., Bury, Lancashire, B19 7ex Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01bry0022 Permit Version: 4 Effective Date: 1st April 2022 Issued Date: 10th May 2019 Revocation Date: Not Supplied Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Barn Brook Status: Varied under EPR 2010 Positional Accuracy: Located by supplier to within 10m	A14SE (E)	875	2	381514 410314

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
9	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Pimhole Cso James Street, ., Bury, Lancashire, B19 7eg Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01bry0021 Permit Version: 2 Effective Date: 3rd September 2010 Issued Date: 3rd September 2010 Revocation Date: 26th June 2019 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Barn Brook Status: Varied under EPR 2010 Positional Accuracy: Located by supplier to within 10m	A9NE (SE)	880	2	381470 410180
9	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Pimhole Cso James Street, ., Bury, Lancashire, B19 7eg Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01BRY0021 Permit Version: 1 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 2nd September 2010 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Barn Brook Status: Varied under EPR 2010 Positional Accuracy: Located by supplier to within 100m	A9NE (SE)	880	2	381470 410180
9	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Pimhole Cso James Street, ., Bury, Lancashire, B19 7eg Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01bry0021 Permit Version: 3 Effective Date: 27th June 2019 Issued Date: 27th June 2019 Revocation Date: 31st March 2022 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Barn Brook Status: Varied under EPR 2010 Positional Accuracy: Located by supplier to within 10m	A9NE (SE)	881	2	381472 410182
9	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Pimhole Cso James Street, ., Bury, Lancashire, B19 7eg Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01bry0021 Permit Version: 4 Effective Date: 1st April 2022 Issued Date: 27th June 2019 Revocation Date: Not Supplied Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Barn Brook Status: Varied under EPR 2010 Positional Accuracy: Located by supplier to within 10m	A9NE (SE)	881	2	381472 410182

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
10	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Lower Woodhill Rd, Bury, Lancashire Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01bry0013 Permit Version: 2 Effective Date: 3rd September 2010 Issued Date: 3rd September 2010 Revocation Date: 14th July 2014 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Woodhill Brook Status: Surrendered under EPR 2010 Positional Accuracy: Located by supplier to within 10m	A17SW (NW)	903	2	379830 411180
10	Discharge Consents Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Lower Woodhill Rd, Bury, Lancashire Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01BRY0013 Permit Version: 1 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 2nd September 2010 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge: Freshwater Stream/River Environment: Receiving Water: Woodhill Brook Status: Varied under EPR 2010 Positional Accuracy: Located by supplier to within 100m	A17SW (NW)	903	2	379830 411180
11	Discharge Consents Operator: J.R. Crompton Ltd Property Type: MAKING OF PAPER+PAPER PRODUCTS Location: Elton Paper Mills Outlet C, Elton Paper Mill, Bury, Greater Manchester, B18 2as Authority: Environment Agency, North West Region Catchment Area: Upper Mersey Reference: 016990064 Permit Version: 1 Effective Date: 1st January 1980 Issued Date: Not Supplied Revocation Date: 1st April 1996 Discharge Type: Trade Discharge - Process Water Discharge: Freshwater Stream/River Environment: Receiving Water: River Irwell Status: Lapsed (under Environment Act 1995, Schedule 23) Positional Accuracy: Located by supplier to within 100m	A12SW (W)	907	2	379600 410400
12	Discharge Consents Operator: Antler Ltd Property Type: MAKING OF TEXTILES Location: Antler Ltd, Bury, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016992340 Permit Version: 1 Effective Date: 1st October 1996 Issued Date: 1st October 1996 Revocation Date: 18th August 2011 Discharge Type: Trade Boiler Blowdown Effluent: Unspecified Discharge: Freshwater Stream/River Environment: Receiving Water: River Roach Status: Lapsed (under Environment Act 1995, Schedule 23) Positional Accuracy: Located by supplier to within 10m	A9NE (SE)	940	2	381400 409951

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
12	Discharge Consents Operator: Antler Ltd Property Type: MAKING OF TEXTILES Location: Antler Ltd, Bury, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 0169/01/1977/47 Permit Version: 2 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 30th September 1996 Discharge Type: Trade Boiler Blowdown Effluent: Unspecified Discharge: Freshwater Stream/River Environment: Receiving Water: River Roch Status: Revoked: New Consent issued (Water Act 1989, Section 113) Positional Accuracy: Located by supplier to within 100m	A9NE (SE)	941	2	381400 409950
12	Discharge Consents Operator: Antler Ltd Property Type: MAKING OF TEXTILES Location: Antler Ltd, Bury, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 0169/01/1977/47 Permit Version: 1 Effective Date: 1st April 1991 Issued Date: Not Supplied Revocation Date: 31st December 1994 Discharge Type: Trade Boiler Blowdown Effluent: Unspecified Discharge: Not Supplied Environment: Receiving Water: Not Supplied Status: Authorisation revoked Positional Accuracy: Located by supplier to within 10m	A9NE (SE)	941	2	381400 409950
13	Discharge Consents Operator: Dorron Roller Ltd Property Type: MAKING OF BASIC METALS/IRON+STEEL/FOUNDRY/CASTING Location: Dorron Roller Ltd, 59 Bolton Road, Bury, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016990338 Permit Version: 1 Effective Date: 23rd December 1981 Issued Date: Not Supplied Revocation Date: 20th September 1991 Discharge Type: Trade Discharges - Cooling Water Discharge: Freshwater Stream/River Environment: Receiving Water: Elton Brook Status: Authorisation revoked Positional Accuracy: Located by supplier to within 100m	A12NW (W)	953	2	379600 410900
14	Integrated Pollution Controls Name: Mondi Holcombe Ltd Location: Holcombe Mill, Bridge Street, BURY, Lancashire, BL0 0BS Authority: Environment Agency, North West Region Permit Reference: BD4546 Dated: 24th November 1998 Process Type: IPC minor (non-substantial) variation to previous variation Description: 6.1 A (B) Paper and Pulp manufacturing processes within Miscellaneous Industries Status: Revoked - Now IPPC Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	983	2	381172 411510
14	Integrated Pollution Controls Name: Scandura Textiles Location: P And S Textiles, Porrit Street, BURY, Lancashire, BL9 6HJ Authority: Environment Agency, North West Region Permit Reference: BD3698 Dated: 24th November 1998 Process Type: IPC minor (non-substantial) variation to previous variation Description: 3.3 A Mineral Fibres (non-Asbestos) within the Mineral Industry Status: Authorisation revoked Positional Accuracy: Unknown	A19NW (NE)	990	2	381213 411493

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
14	Integrated Pollution Controls Name: Scandura Textiles Location: Porritt Street, BURY, Lancashire, BL9 6HJ Authority: Environment Agency, North West Region Permit Reference: AU2107 Dated: 9th July 1996 Process Type: IPC new application Description: 3.3 A Mineral Fibres (non-Asbestos) within the Mineral Industry Status: Authorisation superseded by a substantial or non substantial variation Positional Accuracy: Unknown	A19NW (NE)	994	2	381213 411498
15	Integrated Pollution Prevention And Control Name: Bury Power Limited Location: Chamberhall Street, Bury Power Limited, Chamberhall Street,,, Bury, Lancashire, BL9 0JU Authority: Environment Agency, North West Region Permit Reference: AP3031QS Original Permit Ref: Ap3031qs Effective Date: 3rd April 2020 Status: Effective Application Type: Application App. Sub Type: New Positional Accuracy: Located by supplier to within 10m Activity Code: 25B (3)(1)(a) Activity Description: Tranche B SG permitting date 1st January 2019 Primary Activity: Y	A17NE (N)	923	2	380240 411480
16	Integrated Pollution Prevention And Control Name: Vecom Sillavan Metal Treatment Ltd Location: Bury Metal Treatment Facility, Sillavan Works,Wood Street, ,, BURY, Lancashire, BL8 2SL Authority: Environment Agency, North West Region Permit Reference: UP3738ZF Original Permit Ref: Up3738zf Effective Date: 1st October 2013 Status: Superseded By Variation Application Type: Application App. Sub Type: New Positional Accuracy: Automatically positioned to the address Activity Code: 2.3 A(1) (A) Activity Description: Surface Treating Metals And Plastics; Electrolytic/Chemical Greater Than 30 Cubic Metres Primary Activity: Y Activity Code: 0.0 Associated Process Activity Description: Associated Process Primary Activity: N	A16SE (W)	1000	2	379568 410949
17	Local Authority Pollution Prevention and Controls Name: Save Service Station Location: Angeleume Way, BURY, Lancashire, BL9 0BZ Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: Ps6 Dated: Not Supplied Process Type: Local Authority Air Pollution Control Description: PG1/14 Petrol filling station Status: Authorised Positional Accuracy: Manually positioned to the road within the address or location	A13SW (S)	3	3	380573 410483
18	Local Authority Pollution Prevention and Controls Name: Wallwork Heat Treatment Ltd Location: Lord Street, Bury, BL9 0RE Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC11-01 Dated: 1st March 2012 Process Type: Local Authority Pollution Prevention and Control Description: PG1/1Waste oil burners, less than 0.4MW net rated thermal input Status: Permitted Positional Accuracy: Manually positioned to the address or location	A14SW (E)	290	3	380967 410559
18	Local Authority Pollution Prevention and Controls Name: Wallwork Heat Treatment Ltd Location: Rochdale Road, Bury, BL9 0QH Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC04-12 Dated: 1st June 2005 Process Type: Local Authority Pollution Prevention and Control Description: PG2/3 Electrical and rotary furnaces Status: Authorised Positional Accuracy: Manually positioned to the address or location	A14SW (E)	290	3	380967 410559

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
18	Local Authority Pollution Prevention and Controls Name: Wallwork Heat Treatment Ltd Location: Rochdale Road, Bury, BL9 0QH Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC04-12 Dated: 1st June 2005 Process Type: Local Authority Pollution Prevention and Control Description: PG2/4 Iron, steel and non-ferrous metal foundry processes Status: Authorised Positional Accuracy: Manually positioned to the address or location	A14SW (E)	290	3	380967 410559
19	Local Authority Pollution Prevention and Controls Name: H & J Quick Ltd Location: Derby Street, BURY, Lancashire, BL9 0NW Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: 6 Dated: 1st August 1992 Process Type: Local Authority Air Pollution Control Description: PG6/34 Respraying of road vehicles Status: Authorised Positional Accuracy: Manually positioned to the road within the address or location	A19SW (NE)	359	3	380935 410913
20	Local Authority Pollution Prevention and Controls Name: Alenco Dry Cleaners Location: 44 Bolton Street, Bury, BL9 0ll Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC06-11 Dated: 1st February 2007 Process Type: Local Authority Pollution Prevention and Control Description: PG6/46 Dry cleaning Status: Permitted Positional Accuracy: Manually positioned to the address or location	A12NE (NW)	383	3	380225 410840
21	Local Authority Pollution Prevention and Controls Name: Bury Engine Centre Location: Cook Street, Bury, BL9 0RP Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC04-16 Dated: 1st March 2006 Process Type: Local Authority Pollution Prevention and Control Description: PG1/1Waste oil burners, less than 0.4MW net rated thermal input Status: Authorised Positional Accuracy: Manually positioned to the address or location	A14SW (E)	423	3	381094 410506
22	Local Authority Pollution Prevention and Controls Name: Tesco Stores Location: Peel Way, Woodfields Retail Park, BURY, Lancashire, BL9 5BY Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC05-15 Dated: Not Supplied Process Type: Local Authority Pollution Prevention and Control Description: PG1/14 Petrol filling station Status: Authorised Positional Accuracy: Manually positioned to the address or location	A18SW (N)	439	3	380525 411070
23	Local Authority Pollution Prevention and Controls Name: Shell Uk Location: 236 Rochdale Road, BURY, Lancashire, BL9 7AX Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: Ps1 Dated: Not Supplied Process Type: Local Authority Air Pollution Control Description: PG1/14 Petrol filling station Status: Authorised Positional Accuracy: Manually positioned to the road within the address or location	A14NW (E)	459	3	381130 410755
24	Local Authority Pollution Prevention and Controls Name: Beldam Lascar Location: Tan Pits Lane, BURY, Lancashire, BL9 0LY Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: 21 Dated: 1st March 1995 Process Type: Local Authority Air Pollution Control Description: PG3/13 Asbestos processes Status: Authorised Positional Accuracy: Manually positioned to the road within the address or location	A18SW (NW)	498	3	380262 411008

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
25	Local Authority Pollution Prevention and Controls Name: Cass of Bury Location: Manor Street, BURY, BL9 7BL Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: 3 Dated: 1st May 1992 Process Type: Local Authority Air Pollution Control Description: PG2/5 Hot and cold blast cupolas Status: Authorisation revoked Positional Accuracy: Manually positioned to the road within the address or location	A14NW (NE)	613	3	381248 410893
26	Local Authority Pollution Prevention and Controls Name: Chapel Fine Furniture Location: James Street, BURY, Lancashire, BL9 7EG Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: 12 Dated: 1st April 1993 Process Type: Local Authority Air Pollution Control Description: PG6/33 Wood coating Status: Not Supplied Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	639	3	381296 410413
27	Local Authority Pollution Prevention and Controls Name: Geldards Dry Cleaners Location: 60 Walmersley Road, Bury, BL9 6dp Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC06-12 Dated: 1st January 2007 Process Type: Local Authority Pollution Prevention and Control Description: PG6/46 Dry cleaning Status: Authorised Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	729	3	380933 411343
28	Local Authority Pollution Prevention and Controls Name: Wilcox Drums Ltd Location: Tile Street, BURY, Lancashire, BL9 5BQ Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: 10 Dated: 1st March 1993 Process Type: Local Authority Air Pollution Control Description: PG6/15 Coating in drum manufacturing and reconditioning processes Status: Authorisation revoked Positional Accuracy: Manually positioned to the road within the address or location	A18NE (N)	737	3	380601 411392
29	Local Authority Pollution Prevention and Controls Name: Moorside Garage Location: Brook Street, BURY, Lancashire, BL9 6AH Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: Ps24 Dated: Not Supplied Process Type: Local Authority Air Pollution Control Description: PG1/14 Petrol filling station Status: Authorised Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	751	3	381108 411277
30	Local Authority Pollution Prevention and Controls Name: K Wood & Sons Location: Pimhole Road, BURY, BL9 7EY Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: 2 Dated: 1st February 1993 Process Type: Local Authority Air Pollution Control Description: PG2/9 Metal decontamination processes Status: Authorisation revoked Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	782	3	381461 410562
31	Local Authority Pollution Prevention and Controls Name: Cemex Uk Materials Ltd Location: Bolton Road, BURY, Lancashire, BL8 2AQ Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: Lappc03-05 Dated: 1st February 1993 Process Type: Local Authority Pollution Prevention and Control Description: PG3/1 Blending, packing, loading and use of bulk cement Status: Authorised Positional Accuracy: Manually positioned to the address or location	A12NW (W)	814	3	379689 410702

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
32	Local Authority Pollution Prevention and Controls Name: Starbreakers Location: Pimhole Lane, Bury, BL9 7gy Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC04-17 Dated: 1st August 2006 Process Type: Local Authority Pollution Prevention and Control Description: PG1/1Waste oil burners, less than 0.4MW net rated thermal input Status: Authorised Positional Accuracy: Manually positioned to the address or location	A14SE (E)	834	3	381494 410406
33	Local Authority Pollution Prevention and Controls Name: A1 Independent Landrover Specialists Limited Location: Unit 4, Fernhill Street, Bury, BL9 5bg Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC13-04 Dated: Not Supplied Process Type: Local Authority Pollution Prevention and Control Description: PG1/1Waste oil burners, less than 0.4MW net rated thermal input Status: Permitted Positional Accuracy: Located by supplier to within 10m	A18NW (N)	844	3	380559 411494
34	Local Authority Pollution Prevention and Controls Name: The Timber Centre Location: Fernhill Street, BURY, Lancashire, BL9 5BH Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: Lappc03-06 Dated: 1st August 1992 Process Type: Local Authority Pollution Prevention and Control Description: PG6/2 Manufacture of timber and wood-based products Status: Site Closed Positional Accuracy: Automatically positioned to the address	A18NW (N)	846	3	380504 411487
35	Local Authority Pollution Prevention and Controls Name: Bardon Concrete Location: Every Street, Fernhill, BURY, Lancashire, BL9 Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: Lappc03-10 Dated: 1st November 2003 Process Type: Local Authority Pollution Prevention and Control Description: PG3/1Blending, packing, loading and use of bulk cement Status: Authorisation certificate surrendered by operator Positional Accuracy: Manually positioned to the road within the address or location	A18NE (N)	908	3	380631 411566
35	Local Authority Pollution Prevention and Controls Name: Every Street Garage Location: Every Street, Fernhill, Bury, BL9 5BE Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC11-04 Dated: 1st February 2012 Process Type: Local Authority Pollution Prevention and Control Description: PG1/1Waste oil burners, less than 0.4MW net rated thermal input Status: Permitted Positional Accuracy: Manually positioned to the address or location	A23SE (N)	928	3	380620 411585
36	Local Authority Pollution Prevention and Controls Name: P & S Textiles Ltd Location: Hornby Street, Bury, BL9 5bl Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC06-18 Dated: 1st April 2007 Process Type: Local Authority Pollution Prevention and Control Description: PG6/8 Textile and fabric coating of finishing processes Status: Authorised Positional Accuracy: Located by supplier to within 100m	A23SE (N)	942	3	380700 411600
37	Local Authority Pollution Prevention and Controls Name: Milliken Industries Ltd Location: Wellington Street, BURY, BL8 2AY Authority: Bury Metropolitan Borough Council, Environmental Health Department Permit Reference: LAPPC04-10 Dated: 1st October 1992 Process Type: Local Authority Pollution Prevention and Control Description: PG6/23 Coating of metal and plastic Status: Authorisation revoked Positional Accuracy: Manually positioned to the road within the address or location	A11SE (W)	989	3	379504 410514

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
38	Local Authority Pollution Prevention and Control Enforcements Location: Rochdale Road, Bury, B19 0qh Type: Air Pollution Control Enforcement Notice Reference: LAPPC04-12 Date Issued: 23rd August 2006 Enforcement Date: Not Supplied Details: Extractive Monitoring Not Completed By Relevant Date In Permit - Complied With Positional Accuracy: Manually positioned to the road within the address or location	A14NW (E)	417	3	381086 410758
	Nearest Surface Water Feature	A13SW (SW)	160	-	380482 410348
39	Pollution Incidents to Controlled Waters Property Type: Garage Premises Location: Castlecroft Garage , BURY Authority: Environment Agency, North West Region Pollutant: Oils - Waste Oil Note: Petrol From Garage Incident Date: 8th October 1998 Incident Reference: SO981853 Catchment Area: Irwell Receiving Water: Freshwater Stream/River Cause of Incident: Blocked Sewer Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A12NE (W)	321	2	380200 410700
40	Pollution Incidents to Controlled Waters Property Type: Manufacturing: Other Manufacturing Location: Panpits Road, Greater Manchester Authority: Environment Agency, North West Region Pollutant: Contaminated Material : Fire Fighting Run Off Note: Not Supplied Incident Date: 27th September 1999 Incident Reference: 32815 Catchment Area: Irwell Receiving Water: River Stretch (Freshwater) Cause of Incident: Other Cause Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A18SW (NW)	475	2	380300 411000
41	Pollution Incidents to Controlled Waters Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: River Irwell; No Pollution Found Incident Date: 19th June 1995 Incident Reference: 95621464 Catchment Area: Irwell Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A19SW (NE)	540	2	381100 411000
42	Pollution Incidents to Controlled Waters Property Type: Private Sewage (Non-PLC): Combined Sewer Overflow Location: River Irwell, BURY Authority: Environment Agency, North West Region Pollutant: Sewage - Storm Overflow Note: Grey Liquid Incident Date: 4th June 1998 Incident Reference: SO981013 Catchment Area: Irwell Receiving Water: Freshwater Stream/River Cause of Incident: Blocked Sewer Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A17SW (NW)	734	2	379900 411000
43	Pollution Incidents to Controlled Waters Property Type: WSC Sewage, Sewerage & Supply: Southern Water Ltd Location: William Hair, Castlecroft, CASTLECROFT, Greater Manchester Authority: Environment Agency, North West Region Pollutant: Crude Sewage Note: Not Supplied Incident Date: 5th August 1999 Incident Reference: 31030 Catchment Area: Irwell Receiving Water: River Stretch (Freshwater) Cause of Incident: Climatic Conditions : Localised High Rainfall Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A17SE (NW)	803	2	380001 411201

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
44	Pollution Incidents to Controlled Waters Property Type: Not Given Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Rubble/Litter Or Solids Note: Elton Brook; Colour Incident Date: 18th May 1995 Incident Reference: 95621163 Catchment Area: Irwell Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A12NW (W)	803	2	379700 410700
45	Pollution Incidents to Controlled Waters Property Type: Not Given Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Rubble/Litter Or Solids Note: River Irwell Incident Date: 21st June 1995 Incident Reference: 95621495 Catchment Area: Irwell Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A12NW (W)	826	2	379700 410800
46	Pollution Incidents to Controlled Waters Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: Kirklees Brook; None Pollution Found Incident Date: 20th September 1995 Incident Reference: 95622368 Catchment Area: Irwell Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A17SW (NW)	874	2	379800 411100
47	Pollution Incidents to Controlled Waters Property Type: Private Sewage (Non-PLC): Sewerage Systems Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Chemicals - Paints / Dyes Note: Elton Brook Incident Date: 28th July 1995 Incident Reference: 95621905 Catchment Area: Irwell Receiving Water: Not Given Cause of Incident: Miscellaneous/Other Pollution Type Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A12SW (W)	895	2	379600 410500
48	Pollution Incidents to Controlled Waters Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: None Pollution Found Incident Date: 11th June 1996 Incident Reference: 96621261 Catchment Area: Irwell Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A17SW (NW)	903	2	379700 411000
49	Pollution Incidents to Controlled Waters Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: River Irwell; No Pollution Found Incident Date: 22nd June 1995 Incident Reference: 95621505 Catchment Area: Irwell Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A7SW (SW)	938	2	379900 409800

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
50	Pollution Incidents to Controlled Waters Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: River Roch; No Pollution Found Incident Date: 28th September 1995 Incident Reference: 95622416 Catchment Area: Roch Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A9SE (SE)	970	2	381300 409800
51	Pollution Incidents to Controlled Waters Property Type: Water Company Sewage: Storm Overflow Location: Bury Bridge Authority: Environment Agency, North West Region Pollutant: Surcharged Sewage Note: Irwell Is A Vivid Blue Colour Incident Date: 4th August 1998 Incident Reference: SO981395 Catchment Area: Irwell Receiving Water: Freshwater Stream/River Cause of Incident: Blocked Sewer Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A17SW (NW)	992	2	379600 411000
52	Pollution Incidents to Controlled Waters Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: River Irwell; No Pollution Found Incident Date: 11th April 1995 Incident Reference: 95620790 Catchment Area: Irwell Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A11SE (W)	994	2	379500 410500
53	Prosecutions Relating to Authorised Processes Location: Unit 8 Pimhole Road Business Park, Pimhole Road, Bury Prosecution Text: Operating a waste vehicle dismantling facility without the required permit Prosecution Act: Epr07 R12 & 38(1)(A) Hearing Date: 1st September 2008 Verdict: Guilty Fine: 5000 Costs: 2462 Positional Accuracy: Manually positioned to the address or location	A14SE (E)	752	2	381376 410286
54	Prosecutions Relating to Authorised Processes Location: Pimhole Lodge, Pimhole Road, Bury, B19 Prosecution Text: Allowing the transport of asbestos waste Prosecution Act: Epa90 S34 Hearing Date: 17th March 2006 Verdict: Guilty Fine: 9000 Costs: 1800 Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	817	2	381490 410488
	River Quality Name: Irwell GQA Grade: River Quality C Reach: Chest Wheel Bridge To Roch Estimated Distance (km): 10.3 Flow Rate: Flow less than 5 cumecs Flow Type: River Year: 2000	A17SE (NW)	740	2	380040 411152
	River Quality Name: Elton Bk GQA Grade: River Quality D Reach: Qsl At Dow Lane To Irwell Estimated Distance (km): 1.9 Flow Rate: Flow less than 0.31 cumecs Flow Type: River Year: 2000	A12SW (W)	828	2	379682 410394

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	River Quality Name: Kirklees Bk GQA Grade: River Quality C Reach: Olives Paper Mill To Irwell Estimated Distance (km): .7 Flow Rate: Flow less than 0.31 cumecs Flow Type: River Year: 2000	A17SW (NW)	879	2	379827 411141
	River Quality Name: Roch GQA Grade: River Quality C Reach: Rochdale Stw To Irwell Estimated Distance (km): 15.2 Flow Rate: Flow less than 20 cumecs Flow Type: River Year: 2000	A9NE (SE)	924	2	381419 410003
55	River Quality Chemistry Sampling Points Name: Kirklees Brook Reach: Olives Paper Mill To Irwell Estimated Distance: 0.70 Objective: Not Supplied Positional Accuracy: Located by supplier to within 10m Year: 1990 GQA Grade: River Quality Chemistry GQA Grade C - Fairly Good Compliance: Not Supplied Year: 1993 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 1994 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 1995 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 1996 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 1997 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 1998 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 1999 GQA Grade: River Quality Chemistry GQA Grade B - Good Compliance: Not Supplied Year: 2000 GQA Grade: River Quality Chemistry GQA Grade B - Good Compliance: Not Supplied Year: 2001 GQA Grade: River Quality Chemistry GQA Grade B - Good Compliance: Not Supplied Year: 2002 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 2003 GQA Grade: River Quality Chemistry GQA Grade B - Good Compliance: Not Supplied Year: 2004 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 2005 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 2006 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 2007 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 2008 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied Year: 2009 GQA Grade: River Quality Chemistry GQA Grade A - Very Good Compliance: Not Supplied	A17SW (NW)	892	2	379832 411166

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
56	River Quality Chemistry Sampling Points Name: Elton Brook Reach: Qsl At Dow Lane To Irwell Estimated Distance: 1.90 Objective: Not Supplied Positional Accuracy: Located by supplier to within 10m Year: 1990 GQA Grade: Not Supplied Compliance: Not Supplied Year: 1993 GQA Grade: River Quality Chemistry GQA Grade C - Fairly Good Compliance: Not Supplied Year: 1994 GQA Grade: River Quality Chemistry GQA Grade C - Fairly Good Compliance: Not Supplied Year: 1995 GQA Grade: River Quality Chemistry GQA Grade C - Fairly Good Compliance: Not Supplied Year: 1996 GQA Grade: River Quality Chemistry GQA Grade C - Fairly Good Compliance: Not Supplied Year: 1997 GQA Grade: River Quality Chemistry GQA Grade C - Fairly Good Compliance: Not Supplied Year: 1998 GQA Grade: River Quality Chemistry GQA Grade C - Fairly Good Compliance: Not Supplied Year: 1999 GQA Grade: River Quality Chemistry GQA Grade C - Fairly Good Compliance: Not Supplied Year: 2000 GQA Grade: River Quality Chemistry GQA Grade C - Fairly Good Compliance: Not Supplied Year: 2001 GQA Grade: River Quality Chemistry GQA Grade C - Fairly Good Compliance: Not Supplied Year: 2002 GQA Grade: River Quality Chemistry GQA Grade C - Fairly Good Compliance: Not Supplied Year: 2003 GQA Grade: River Quality Chemistry GQA Grade B - Good Compliance: Not Supplied Year: 2004 GQA Grade: River Quality Chemistry GQA Grade B - Good Compliance: Not Supplied Year: 2005 GQA Grade: River Quality Chemistry GQA Grade B - Good Compliance: Not Supplied Year: 2006 GQA Grade: River Quality Chemistry GQA Grade B - Good Compliance: Not Supplied Year: 2007 GQA Grade: River Quality Chemistry GQA Grade B - Good Compliance: Not Supplied Year: 2008 GQA Grade: River Quality Chemistry GQA Grade B - Good Compliance: Not Supplied Year: 2009 GQA Grade: River Quality Chemistry GQA Grade B - Good Compliance: Not Supplied	A12NW (W)	894	2	379608 410700
57	Substantiated Pollution Incident Register Authority: Environment Agency - North West Region, South Area Incident Date: 2nd January 2020 Incident Reference: 1766303 Water Impact: Category 3 - Minor Incident Air Impact: Category 1 - Major Incident Land Impact: Category 4 - No Impact Positional Accuracy: Located by supplier to within 10m Pollutant: Atmospheric Pollutants and Effects: Smoke Pollutant: Contaminated Water: Firefighting Run-Off	A14NE (E)	799	2	381478 410587
58	Substantiated Pollution Incident Register Authority: Environment Agency - North West Region, South Area Incident Date: 4th June 2009 Incident Reference: 684555 Water Impact: Category 4 - No Impact Air Impact: Category 4 - No Impact Land Impact: Category 2 - Significant Incident Positional Accuracy: Located by supplier to within 10m Pollutant: Specific Waste Materials: Vehicles And Vehicle Parts	A9NE (SE)	840	2	381439 410208

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
59	Water Abstractions Operator: J R Crompton P.L.C. Licence Number: 2569001140 Permit Version: Not Supplied Location: Premises, BURY Authority: Environment Agency, North West Region Abstraction: Manufacturing Abstraction Type: Not Supplied Source: Surface Daily Rate (m3): 4787 Yearly Rate (m3): 1436536 Details: River Irwell Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A12NW (W)	793	2	379700 410600
60	Water Abstractions Operator: Cemex Uk Materials Ltd Licence Number: 2569001285r01 Permit Version: 2 Location: River Irwell At Rmc Northernt Bury Canal Wharf Authority: Environment Agency, North West Region Abstraction: Construction: General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Not Supplied Authorised Start: 01 April Authorised End: 31 March Permit Start Date: 21st December 2018 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A12NW (W)	797	2	379706 410696
60	Water Abstractions Operator: Cemex Uk Materials Ltd Licence Number: 2569001285r01 Permit Version: 1 Location: River Irwell At Rmc Northernt Bury Canal Wharf Authority: Environment Agency, North West Region Abstraction: Construction: General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Not Supplied Authorised Start: 01 April Authorised End: 31 March Permit Start Date: 1st April 2015 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A12NW (W)	797	2	379706 410696
60	Water Abstractions Operator: Cemex Uk Materials Ltd Licence Number: 2569001285 Permit Version: 2 Location: River Irwell At Rmc Northernt Bury Canal Wharf Authority: Environment Agency, North West Region Abstraction: Construction: General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land At Rmc Northern Bury Canal Wharf Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st April 2008 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A12NW (W)	797	2	379706 410696

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
60	Water Abstractions Operator: Rmc Materials Ltd Licence Number: 2569001285 Permit Version: 1 Location: River Irwell At Rmc Northernt Bury Canal Wharf Authority: Environment Agency, North West Region Abstraction: Construction: General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land At Rmc Northern Bury Canal Wharf Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 23rd March 2005 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A12NW (W)	797	2	379706 410696
61	Water Abstractions Operator: Dorron Roller Ltd Licence Number: 2569001211 Permit Version: Not Supplied Location: Un-Named Tributary Of River Irwell, BURY Authority: Environment Agency, North West Region Abstraction: Cooling Abstraction Type: Not Supplied Source: Surface Daily Rate (m3): 145 Yearly Rate (m3): 45460 Details: Licence Status: Revoked Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A12NW (W)	922	2	379600 410800
62	Water Abstractions Operator: Bury Council Licence Number: Nw/069/0001/007 Permit Version: 1 Location: River Irwell At Chamber Hall Weir Authority: Environment Agency, North West Region Abstraction: Production Of Energy: Hydroelectric Power Generation Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Chamber Hall Weir, Bury Authorised Start: 01 April Authorised End: 31 March Permit Start Date: 10th June 2016 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A17NE (NW)	967	2	380014 411406
	Water Abstractions Operator: P & S Textiles Ltd Licence Number: 2569001015 Permit Version: Not Supplied Location: Fernhill Mill, Shornby Street, BURY, Lancashire Authority: Environment Agency, North West Region Abstraction: Manufacturing Abstraction Type: Not Supplied Source: Groundwater Daily Rate (m3): 227 Yearly Rate (m3): 81828 Details: Not Supplied Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A23SE (N)	1042	2	380700 411700

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: Bury Cooper Whitehead Ltd. Licence Number: 2569001107 Permit Version: Not Supplied Location: Borehole, Hudcar Mills, BURY Authority: Environment Agency, North West Region Abstraction: Manufacturing Abstraction Type: Not Supplied Source: Groundwater Daily Rate (m3): 86 Yearly Rate (m3): 9092 Details: Licence Status: Revoked Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A19NE (NE)	1045	2	381300 411500
	Water Abstractions Operator: Wilcox Drums Ltd Licence Number: 2569001014 Permit Version: 100 Location: Borehole At Premises, Bury Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Cooling (Existing Licences Only) (Low Loss) Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): 114 Yearly Rate (m3): 27276 Details: Premises At Bury, Lancs Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st April 1993 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A23SW (N)	1108	2	380300 411700
	Water Abstractions Operator: Wilcox Drums Ltd Licence Number: 2569001014 Permit Version: 100 Location: Borehole At Premises, Bury Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: Process Water Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Premises At Bury, Lancs Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st April 1993 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A23SW (N)	1108	2	380300 411700
	Water Abstractions Operator: Bury Cooper Whitehead Ltd Licence Number: 2569002212 Permit Version: Not Supplied Location: Springfield Mills, BURY Authority: Environment Agency, North West Region Abstraction: Manufacturing Abstraction Type: Not Supplied Source: River Daily Rate (m3): 9728 Yearly Rate (m3): 86400 Details: Gypsy Brook A Tributary Of Barn Brook Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A24SE (NE)	1127	2	381300 411600

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: Bury Cooper Whitehead Ltd. Licence Number: 2569002211 Permit Version: Not Supplied Location: Bury, BURY, Lancashire Authority: Environment Agency, North West Region Abstraction: Manufacturing Abstraction Type: Not Supplied Source: River Daily Rate (m3): 546 Yearly Rate (m3): 50006 Details: Green Brook A Tributary Of Barn Brook Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A24SW (NE)	1164	2	381200 411700
	Water Abstractions Operator: J K Industries Limited Licence Number: 2569002103 Permit Version: Not Supplied Location: River Roch, BURY, Lancashire Authority: Environment Agency, North West Region Abstraction: Cooling & Boiler Feed & Manufacturing Abstraction Type: Not Supplied Source: Surface Daily Rate (m3): 5455 Yearly Rate (m3): 490968 Details: Additional Purposes: Manufacturing; Boiler feed; Licence Status: Revoked Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A9SE (SE)	1186	2	381400 409600
	Water Abstractions Operator: J R Crompton P.L.C. Licence Number: 2569001138 Permit Version: Not Supplied Location: Known As Deardens Lodge, BURY Authority: Environment Agency, North West Region Abstraction: Manufacturing Abstraction Type: Not Supplied Source: River Daily Rate (m3): 1091 Yearly Rate (m3): 136380 Details: Reservoir Fed By Surface Drainage Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A11SE (W)	1221	2	379300 410300
	Water Abstractions Operator: J B Skips & Services Ltd Licence Number: 2569001056 Permit Version: 100 Location: The River Irwell At Hinds Lane, Bury Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: Dust Suppression Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): 9 Yearly Rate (m3): 909 Details: Premises, Hinds Mill, Bury, Lancs Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st April 1997 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A6SE (SW)	1251	2	379450 409850

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: J R Crompton P.L.C. Licence Number: 2569001139 Permit Version: Not Supplied Location: Bury Authority: Environment Agency, North West Region Abstraction: Manufacturing Abstraction Type: Not Supplied Source: Groundwater Daily Rate (m3): 391 Yearly Rate (m3): 118196 Details: Borehole Near Premises Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A11SW (W)	1319	2	379200 410300
	Water Abstractions Operator: Activecraft Limited; Papermakers Licence Number: 2569001170 Permit Version: Not Supplied Location: Kirklees Brk And Reservoir Fed By Kirkle, Woolford Paper Mills Authority: Environment Agency, North West Region Abstraction: Manufacturing Abstraction Type: Not Supplied Source: River Daily Rate (m3): 0 Yearly Rate (m3): 0 Details: Licence Status : Current Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A16NE (NW)	1359	2	379500 411495
	Water Abstractions Operator: J K Industries Licence Number: 2569002104 Permit Version: Not Supplied Location: Two Reservoirs Fed By Surface Drainage, BURY, Lancashire Authority: Environment Agency, North West Region Abstraction: Boiler Feed & Manufacturing Abstraction Type: Not Supplied Source: River Daily Rate (m3): 2909 Yearly Rate (m3): 909200 Details: Additional Purpose: Boiler feed; Licence Status: Revoked Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A5NW (SE)	1394	2	381600 409500
	Water Abstractions Operator: R Wilkinson Licence Number: 2569002085 Permit Version: 100 Location: Well At Waterfold Farm, Heap Bridge, Near Bury Authority: Environment Agency, North West Region Abstraction: General Agriculture; General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): 7 Yearly Rate (m3): 2489 Details: Waterfold Farm, Heap Bridge, Nr Bury Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 15th February 1966 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A10NE (E)	1403	2	382000 410100

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: T S Fish Licence Number: 2569002063 Permit Version: 100 Location: Well At Water Farm, Heap Bridge, Bury Authority: Environment Agency, North West Region Abstraction: General Agriculture; General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): 6 Yearly Rate (m3): 2159 Details: Water Farm, Heap Bridge, Bury, Lancs Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 14th February 1966 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A10SW (SE)	1411	2	381800 409700
	Water Abstractions Operator: Totallinaelf Uk Ltd Licence Number: 2569001258 Permit Version: 1 Location: Well Point System At Manchester Road, Bury Authority: Environment Agency, North West Region Abstraction: Environmental: Pump & Treat: Pollution Remediation Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Not Supplied Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 12th June 2002 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	(S)	1641	2	380450 408850
	Water Abstractions Operator: T S Fish Licence Number: 2569002059 Permit Version: 100 Location: Well At Spout Bank Farm, Heap Bridgebury, Lancashire Authority: Environment Agency, North West Region Abstraction: General Agriculture; General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): 10 Yearly Rate (m3): 3487 Details: Spout Bank Farm, Heap Bridge, Bury Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 15th February 1966 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	(E)	1666	2	382300 410200
	Water Abstractions Operator: Bury Metropolitan Borough Council Licence Number: 2569001289r01 Permit Version: 1 Location: Tributary Of The River Irwell, At Clarence Park Lido Authority: Environment Agency, North West Region Abstraction: Amenity: Lake And Pond Throughflow Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Not Supplied Authorised Start: 01 April Authorised End: 31 March Permit Start Date: 1st April 2015 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	(N)	1746	2	381211 412322

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: Bury Metropolitan Borough Council Licence Number: 2569001289 Permit Version: 1 Location: Tributary Of The River Irwell, At Clarence Park Lido Authority: Environment Agency, North West Region Abstraction: Amenity: Lake And Pond Throughflow Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Not Supplied Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 22nd December 2008 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	(N)	1746	2	381211 412322
	Water Abstractions Operator: The Elton Cop Dyeing Co Ltd Licence Number: 2569001160 Permit Version: 100 Location: Reservoirs Fed By Elton Brk At Bury [10 Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: Process Water Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): 0 Yearly Rate (m3): 0 Details: Premises At Walshaw Road, Bury Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 25th February 1975 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	(W)	1747	2	378800 411000
	Water Abstractions Operator: Resolution Hydro Limited Licence Number: Nw/069/0001/004 Permit Version: 1 Location: River Irwell At Bealey'S Weir Authority: Environment Agency, North West Region Abstraction: Production Of Energy: Hydroelectric Power Generation Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Not Supplied Authorised Start: 01 April Authorised End: 31 March Permit Start Date: 1st April 2019 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A2SW (SW)	1748	2	379607 409015
	Water Abstractions Operator: St Regis Paper Company U K Ltd Licence Number: 2569001158 Permit Version: 101 Location: R Irwell At Radcliffe, Manchester Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Cooling (Existing Licences Only) (Low Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Premises At Radcliffe, Manchester Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 5th May 2001 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A1SE (SW)	1796	2	379400 409100

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: St Regis Paper Company U K Ltd Licence Number: 2569001158 Permit Version: 101 Location: R Inwell At Radcliffe, Manchester Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: Process Water Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Premises At Radcliffe, Manchester Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 5th May 2001 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A1SE (SW)	1796	2	379400 409100
	Water Abstractions Operator: The East Lancashire Paper Mill Co Licence Number: 2569001158 Permit Version: 100 Location: R Inwell At Radcliffe, Manchester Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: Process Water Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Premises At Radcliffe, Manchester Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 29th March 1966 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A1SE (SW)	1796	2	379400 409100
	Water Abstractions Operator: The East Lancashire Paper Mill Co Licence Number: 2569001158 Permit Version: 100 Location: R Inwell At Radcliffe, Manchester Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Cooling (Existing Licences Only) (Low Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): 14184 Yearly Rate (m3): 3636800 Details: Premises At Radcliffe, Manchester Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 29th March 1966 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A1SE (SW)	1796	2	379400 409100
	Water Abstractions Operator: C V H F Limited Licence Number: 2569002030 Permit Version: Not Supplied Location: River Roch, Bridge Hall Dye Works, BURY Authority: Environment Agency, North West Region Abstraction: Boiler Feed & Manufacturing Abstraction Type: Not Supplied Source: Surface Daily Rate (m3): 2618 Yearly Rate (m3): 436416 Details: Additional Purpose: Manufacturing; Licence Status: Revoked Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	(E)	1820	2	382500 410600

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: Brother Investments Ltd Licence Number: Nw/069/0002/002 Permit Version: 2 Location: River Roch At Heap Bridge Weir Authority: Environment Agency, North West Region Abstraction: Production Of Energy: Hydroelectric Power Generation Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Heap Bridge Weir, Bury Authorised Start: 01 April Authorised End: 31 March Permit Start Date: 18th September 2015 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	(E)	1855	2	382536 410666
	Water Abstractions Operator: Brother Investments Ltd Licence Number: Nw/069/0002/002 Permit Version: 1 Location: River Roch At Heap Bridge Weir Authority: Environment Agency, North West Region Abstraction: Production Of Energy: Hydroelectric Power Generation Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Heap Bridge Weir, Bury Authorised Start: 01 April Authorised End: 31 March Permit Start Date: 17th September 2010 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	(E)	1855	2	382536 410666
	Water Abstractions Operator: Intex Yarns Ltd Licence Number: 2569001245 Permit Version: 100 Location: River Irwell At Radcliffe, Manchester Authority: Environment Agency, North West Region Abstraction: Textiles & Leather: Boiler Feed Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): 274 Yearly Rate (m3): 100000 Details: Land & Premises At Intex Yarns Ltd Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 18th April 1998 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	(S)	1873	2	380001 408701
	Water Abstractions Operator: Unifi Dyed Yarns Ltd Licence Number: 2569001245 Permit Version: 101 Location: River Irwell At Radcliffe, Manchester Authority: Environment Agency, North West Region Abstraction: Textiles & Leather: Boiler Feed Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land & Premises At Intex Yarns Ltd Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st March 2000 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	(S)	1874	2	380000 408700

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: Unifi Dyed Yarns Ltd Licence Number: 2569001245 Permit Version: 101 Location: River Irwell At Radcliffe, Manchester Authority: Environment Agency, North West Region Abstraction: Textiles & Leather: General Cooling (Existing Licences Only) (Low Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land & Premises At Intex Yarns Ltd Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st March 2000 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	(S)	1874	2	380000 408700
	Water Abstractions Operator: Unifi Dyed Yarns Ltd Licence Number: 2569001245 Permit Version: 101 Location: River Irwell At Radcliffe, Manchester Authority: Environment Agency, North West Region Abstraction: Textiles And Leather: Process Water Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land & Premises At Intex Yarns Ltd Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st March 2000 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	(S)	1874	2	380000 408700
	Water Abstractions Operator: Intex Yarns Ltd Licence Number: 2569001245 Permit Version: 100 Location: River Irwell At Radcliffe, Manchester Authority: Environment Agency, North West Region Abstraction: Textiles & Leather: General Cooling (Existing Licences Only) (Low Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land & Premises At Intex Yarns Ltd Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 18th April 1998 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	(S)	1874	2	380000 408700
	Water Abstractions Operator: Intex Yarns Ltd Licence Number: 2569001245 Permit Version: 100 Location: River Irwell At Radcliffe, Manchester Authority: Environment Agency, North West Region Abstraction: Textiles And Leather: Process Water Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land & Premises At Intex Yarns Ltd Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 18th April 1998 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	(S)	1874	2	380000 408700

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: Bonar, Bibby & Baron Licence Number: 2569002191 Permit Version: Not Supplied Location: Borehole, Hampson Mills, BURY Authority: Environment Agency, North West Region Abstraction: Manufacturing Abstraction Type: Not Supplied Source: Groundwater Daily Rate (m3): 546 Yearly Rate (m3): 109104 Details: Licence Status: Revoked Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	(S)	1890	2	380700 408600
	Water Abstractions Operator: Curtain Styling Ltd Licence Number: 2569001155 Permit Version: 100 Location: Reservoir Fed By Surface Drainage Atbury, (Known As Parkers Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: Boiler Feed Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): 20 Yearly Rate (m3): 8300 Details: Elton Vale Bleachworks At Bury Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 3rd January 1975 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	(W)	1941	2	378600 411000
	Water Abstractions Operator: Curtain Styling Ltd Licence Number: 2569001155 Permit Version: 100 Location: Reservoir Fed By Surface Drainage Atbury, (Known As Parkers Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Elton Vale Bleachworks At Bury Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 3rd January 1975 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	(W)	1941	2	378600 411000
	Water Abstractions Operator: Terry Adams Ltd. Licence Number: 2569002239 Permit Version: Not Supplied Location: BURY Authority: Environment Agency, North West Region Abstraction: Industrial: Sand And Gravel Washing Abstraction Type: Not Supplied Source: Surface Daily Rate (m3): 2273 Yearly Rate (m3): 45460 Details: Additional Purpose - Sand And Gravel Washing. Gigg Brook Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	(SE)	1992	2	382300 409400

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Groundwater Vulnerability Map Combined Classification: Secondary Superficial Aquifer - Medium Vulnerability Combined Vulnerability: Medium Combined Aquifer: Productive Bedrock Aquifer, Productive Superficial Aquifer Pollutant Speed: High Bedrock Flow: Well Connected Fractures Dilution: >550 mm/year Baseflow Index: <40% Superficial: >90% Patchiness: 3-10m Superficial Thickness: High Superficial Recharge: High	A13NE (E)	0	4	380598 410573
	Groundwater Vulnerability - Soluble Rock Risk None				
	Bedrock Aquifer Designations Aquifer Designation: Secondary Aquifer - A	A13NE (E)	0	4	380598 410573
	Superficial Aquifer Designations Aquifer Designation: Secondary Aquifer - A	A13NE (E)	0	4	380598 410573
	Extreme Flooding from Rivers or Sea without Defences None				
	Flooding from Rivers or Sea without Defences None				
	Areas Benefiting from Flood Defences None				
	Flood Water Storage Areas None				
	Flood Defences None				
63	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 1040.1 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A14NW (NE)	347	5	381012 410767
64	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 42.2 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A19SW (NE)	589	5	381098 411075
65	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 18.5 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A19SW (NE)	622	5	381091 411127
66	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 227.0 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A19SW (NE)	624	5	381087 411133

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
67	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 7.7 Watercourse Level: Underground Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A19SW (NE)	624	5	381105 411116
68	OS Water Network Lines Watercourse Form: Lake Watercourse Length: 119.5 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A17SE (NW)	660	5	380147 411129
69	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 119.6 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A17SE (NW)	758	5	379924 411067
70	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 40.7 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A17SE (NW)	761	5	380151 411247
71	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 561.0 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irwell Catchment Name: Mersey Primacy: 1	A12NW (W)	768	5	379746 410748
72	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 143.6 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irwell Catchment Name: Mersey Primacy: 1	A12SW (W)	817	5	379676 410523
73	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 16.4 Watercourse Level: Underground Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A12SW (W)	817	5	379676 410523
74	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 711.0 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irwell Catchment Name: Mersey Primacy: 1	A17SE (NW)	821	5	379966 411196
75	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 6.0 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A19NW (NE)	827	5	381173 411323

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
76	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 1.7 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A19NW (NE)	830	5	381172 411328
77	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 46.0 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A19NW (NE)	831	5	381171 411330
78	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 8.3 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A12SW (W)	831	5	379662 410531
79	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 65.2 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irwell Catchment Name: Mersey Primacy: 1	A17SW (NW)	832	5	379813 411047
80	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 11.1 Watercourse Level: On ground surface Permanent: True Watercourse Name: Kirklees Brook Catchment Name: Mersey Primacy: 1	A17SW (NW)	852	5	379835 411108
81	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 4.3 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A19NW (NE)	861	5	381161 411373
82	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 9.8 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A19NW (NE)	863	5	381159 411377
83	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 57.3 Watercourse Level: On ground surface Permanent: True Watercourse Name: Kirklees Brook Catchment Name: Mersey Primacy: 1	A17SW (NW)	863	5	379826 411114
84	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 176.0 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A9NE (E)	869	5	381475 410221

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
85	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 195.8 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A19NW (NE)	870	5	381158 411387
86	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 462.7 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Roch Catchment Name: Mersey Primacy: 1	A9NE (SE)	882	5	381406 410060
87	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 146.5 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irwell Catchment Name: Mersey Primacy: 1	A12SW (W)	894	5	379615 410395
88	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 12.5 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A12SW (W)	894	5	379615 410395
89	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 97.2 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A12NW (W)	895	5	379607 410699
90	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 31.4 Watercourse Level: Underground Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A9NE (SE)	899	5	381481 410158
91	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 5.4 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A17SW (NW)	903	5	379821 411170
92	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 13.7 Watercourse Level: On ground surface Permanent: True Watercourse Name: Kirklees Brook Catchment Name: Mersey Primacy: 1	A17SW (NW)	903	5	379821 411170
93	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 91.4 Watercourse Level: On ground surface Permanent: True Watercourse Name: Barn Brook Catchment Name: Mersey Primacy: 1	A9NE (SE)	910	5	381478 410127

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
94	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 54.2 Watercourse Level: Underground Permanent: True Watercourse Name: Kirklees Brook Catchment Name: Mersey Primacy: 1	A17SW (NW)	915	5	379817 411183
95	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 1120.5 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Roch Catchment Name: Mersey Primacy: 1	A9NE (SE)	959	5	381486 410042
96	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 144.1 Watercourse Level: On ground surface Permanent: True Watercourse Name: Kirklees Brook Catchment Name: Mersey Primacy: 1	A17SW (NW)	969	5	379782 411225
97	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 270.5 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irwell Catchment Name: Mersey Primacy: 2	A11SE (W)	1000	5	379536 410273
98	OS Water Network Lines Watercourse Form: Inland river Watercourse Length: 34.8 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irwell Catchment Name: Mersey Primacy: 1	A11SE (W)	1000	5	379536 410273

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
99	BGS Recorded Landfill Sites Site Name: Woodfields Location: BURY, Gt Manchester Authority: British Geological Survey, National Geoscience Information Service Ground Water: Information not available Surface Water: Information not available Geology: N/A Positional Accuracy: Positioned by the supplier Boundary Accuracy: Good	A18SE (N)	446	-	380600 411098
100	BGS Recorded Landfill Sites Site Name: Wellington Rd Location: BURY, Gt Manchester Authority: British Geological Survey, National Geoscience Information Service Ground Water: Information not available Surface Water: Information not available Geology: N/A Positional Accuracy: Positioned by the supplier Boundary Accuracy: Good	A8NE (S)	484	-	380754 410031
101	Historical Landfill Sites Licence Holder: Not Supplied Location: Greater Manchester Name: Peel College Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD15808 First Input Date: Not Supplied Last Input Date: Not Supplied Specified Waste: Not Supplied Type: EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: Not Supplied BGS Ref: Not Supplied Other Ref: C087	A13SW (S)	242	2	380534 410247
102	Historical Landfill Sites Licence Holder: Bury Metropolitan Borough Council Location: Town Hall, Manchester Road, Bury, Greater Manchester Name: Railway Cuttings East and West Of Manchester Road Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD15805 First Input Date: 1st February 1988 Last Input Date: 30th June 1988 Specified Waste: Deposited Waste included Inert Waste Type: EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: 4200/9357 BGS Ref: Not Supplied Other Ref: RD/LIC/503/88, C077	A12SE (SW)	306	2	380237 410378
103	Historical Landfill Sites Licence Holder: Bury Metropolitan Borough Council Location: Town Hall, Manchester Road, Bury, Greater Manchester Name: Railway Cuttings East and West Of Manchester Road Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD15802 First Input Date: 1st February 1988 Last Input Date: 30th June 1988 Specified Waste: Deposited Waste included Inert Waste Type: EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: 4200/9357 BGS Ref: Not Supplied Other Ref: RD/LIC/503/88, C077	A12SE (W)	350	2	380172 410422

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
104	Historical Landfill Sites Licence Holder: Not Supplied Location: Bury, Greater Manchester Name: Woodfields Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD15774 First Input Date: 31st October 1971 Last Input Date: Not Supplied Specified Waste: Deposited Waste included Industrial, Commercial and Household Waste, and Type: Liquid Sludge EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: Not Supplied BGS Ref: 1084 Other Ref: C079	A18SW (N)	390	2	380436 410983
105	Historical Landfill Sites Licence Holder: Not Supplied Location: Bury, Greater Manchester Name: Wellington Road Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD15821 First Input Date: 30th June 1971 Last Input Date: 31st October 1971 Specified Waste: Deposited Waste included Industrial, Commercial and Household Waste, and Type: Liquid Sludge EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: Not Supplied BGS Ref: 1083 Other Ref: C085	A8NE (S)	479	2	380752 410035
106	Historical Landfill Sites Licence Holder: Bury Metropolitan Borough Council Location: Bridge Road-Bellvue Terrace, Bury, Greater Manchester Name: Railway Cutting Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD15490 First Input Date: 31st March 1991 Last Input Date: 30th September 1992 Specified Waste: Deposited Waste included Inert Waste Type: EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: 4200/9330 BGS Ref: Not Supplied Other Ref: RD/LIC/650/90,C093	A12SE (W)	490	2	380014 410455
107	Historical Landfill Sites Licence Holder: Not Supplied Location: Bury, Greater Manchester Name: Wellington Street Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD15801 First Input Date: Not Supplied Last Input Date: Not Supplied Specified Waste: Not Supplied Type: EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: Not Supplied BGS Ref: Not Supplied Other Ref: C117	A12SW (W)	893	2	379601 410505
108	Licensed Waste Management Facilities (Locations) Licence Number: 102063 Location: York Street Recycling Centre, York Street, Bury, Lancashire, BL9 7AR Operator Name: Mr Richard Roberts & Mr Ian Marshall Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: HCl Waste TS + treatment Licence Status: Modified Issued: 21st October 2010 Last Modified: 7th March 2011 Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14NW (NE)	501	2	381135 410870

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
109	Licensed Waste Management Facilities (Locations) Licence Number: 53921 Location: York Street Mill, York Street, Bury, Lancashire, BL9 7AR Operator Name: Swinnerton Bros Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations Licence Status: Revoked Issued: 22nd September 1983 Last Modified: 17th May 2002 Expires: Not Supplied Suspended: Not Supplied Revoked: 23rd January 2006 Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A19SW (NE)	568	2	381158 410968
110	Licensed Waste Management Facilities (Locations) Licence Number: 100427 Location: Land / Premises At, Manor Street, Bury, Lancashire, BL9 7BL Operator Name: Lewis Miss Nicola Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations Licence Status: Transferred Issued: 29th September 2008 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14NW (NE)	594	2	381223 410903
110	Licensed Waste Management Facilities (Locations) Licence Number: 50015 Location: Manor Street, Bury, Lancashire, BL9 7BL Operator Name: Briggs Susan Ann Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations Licence Status: Revoked Issued: 7th August 1998 Last Modified: 2nd November 2001 Expires: Not Supplied Suspended: Not Supplied Revoked: 14th December 2006 Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14NE (NE)	631	2	381264 410902
111	Licensed Waste Management Facilities (Locations) Licence Number: 53669 Location: 7 James Street, Bury, Lancashire, BL9 7EG Operator Name: J S M Contract Salvage Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Metal Recycling Sites (Vehicle Dismantlers) Licence Status: Surrendered Issued: 17th March 1995 Last Modified: Not Supplied Expires: Not Supplied Suspended: 01/07/2002 Revoked: Not Supplied Surrendered: 26th September 2002 IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	655	2	381276 410299
112	Licensed Waste Management Facilities (Locations) Licence Number: 50372 Location: Gate 2, Tile Street, Woodfields, Bury, Lancashire, BL9 5BR Operator Name: Smith Ian Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles Licence Status: Issued Issued: 25th April 2005 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A18NW (N)	700	2	380547 411346

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
112	Licensed Waste Management Facilities (Locations) Licence Number: 53469 Location: 2 Tile Street, Bury, Lancashire, BL9 5BR Operator Name: Recycle Motor Spares Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Metal Recycling Sites (Mixed) Licence Status: Transferred Issued: 20th September 1996 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A18NW (N)	733	2	380573 411384
113	Licensed Waste Management Facilities (Locations) Licence Number: 50315 Location: Unit 14, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: Hawk Auto Stripper Limited Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles Licence Status: Transferred Issued: 21st June 2004 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	707	2	381365 410412
113	Licensed Waste Management Facilities (Locations) Licence Number: 50286 Location: Gate 4, Pimhole Fold, Bury, Lancashire, BL9 7EY Operator Name: Khan Iyaaz Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles Licence Status: Expired Issued: 1st July 2004 Last Modified: 1st July 2005 Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	715	2	381379 410437
113	Licensed Waste Management Facilities (Locations) Licence Number: 400432 Location: Unit 13, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: North West Waste Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: HCI Waste TS + treatment Licence Status: Issued Issued: 17th June 2013 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	717	2	381369 410383
113	Licensed Waste Management Facilities (Locations) Licence Number: 50268 Location: Gate 4, Pimhole Fold, Bury, Lancashire, BL9 7ES Operator Name: J S M Contract Salvage Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles Licence Status: Revoked Issued: 1st July 2004 Last Modified: 1st July 2005 Expires: Not Supplied Suspended: Not Supplied Revoked: 7th August 2014 Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	723	2	381380 410405

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
113	Licensed Waste Management Facilities (Locations) Licence Number: 103559 Location: Unit 14a Pimhole Ind Est, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: Auto Breakers (Uk) Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Vehicle Depollution Facility <5000 tps Licence Status: Transferred Issued: 5th January 2012 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	727	2	381388 410424
113	Licensed Waste Management Facilities (Locations) Licence Number: 50406 Location: Unit 13, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: J S M Contract Salvage Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles Licence Status: Issued Issued: 1st July 2005 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	728	2	381383 410395
114	Licensed Waste Management Facilities (Locations) Licence Number: 400704 Location: Unit 11 Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: Select Motor Spares (Bury) Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Vehicle Depollution Facility <5000 tps Licence Status: Issued Issued: 23rd October 2013 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	716	2	381354 410333
114	Licensed Waste Management Facilities (Locations) Licence Number: 50414 Location: Unit 12, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: Ahmad Shaki Barkat Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles Licence Status: Transferred Issued: 1st July 2005 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	740	2	381387 410362
115	Licensed Waste Management Facilities (Locations) Licence Number: 104296 Location: Gate 2, Tile Street, Bury, Lancashire, BL9 5BR Operator Name: M60 Skip Hire Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: HCl Waste TS + treatment Licence Status: Issued Issued: 15th August 2012 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A18NW (N)	720	2	380502 411357

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
115	Licensed Waste Management Facilities (Locations) Licence Number: 101963 Location: Gate 3, Tile St, Bury, Lancashire, BL9 5BR Operator Name: Laycock Christopher Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Vehicle depollution facility Licence Status: Issued Issued: 28th September 2010 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A18NW (N)	733	2	380465 411360
116	Licensed Waste Management Facilities (Locations) Licence Number: 404508 Location: Birch Street, Bury, Lancashire, BL9 5AL Operator Name: Recycling Lives Limited Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Metal Recycling Sites (Mixed) Licence Status: Issued Issued: 21st May 2018 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A18NE (N)	747	2	380775 411399
117	Licensed Waste Management Facilities (Locations) Licence Number: 101126 Location: Unit 8/9, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: Iqbal Shabaz Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Vehicle Depollution Facility <5000 tps Licence Status: Modified Issued: 30th November 2009 Last Modified: 12th October 2012 Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	752	2	381376 410286
117	Licensed Waste Management Facilities (Locations) Licence Number: 50407 Location: Unit 10, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: Crompton Mark Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles Licence Status: Issued Issued: 1st July 2005 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	753	2	381390 410324
117	Licensed Waste Management Facilities (Locations) Licence Number: 104661 Location: Unit 5, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: Iqbal Shabaz Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Vehicle Depollution Facility <5000 tps Licence Status: Issued Issued: 10th October 2012 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	761	2	381404 410344

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
117	Licensed Waste Management Facilities (Locations) Licence Number: 53427 Location: Unit 6, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: Amberdeal Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Vehicle depollution facility Licence Status: Modified Issued: 29th March 1996 Last Modified: 17th December 2010 Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	776	2	381411 410315
118	Licensed Waste Management Facilities (Locations) Licence Number: 50272 Location: Gate 4a, Pimhole Fold, Bury, Lancashire, BL9 7ET Operator Name: Crompton Mark Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles Licence Status: Expired Issued: 25th June 2004 Last Modified: 1st July 2005 Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	785	2	381452 410450
118	Licensed Waste Management Facilities (Locations) Licence Number: 53502 Location: Pimhole Fold, Bury, Lancashire, BL9 7ET Operator Name: Mills Janet Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Metal Recycling Sites (Vehicle Dismantlers) Licence Status: Expired Issued: 21st May 1998 Last Modified: Not Supplied Expires: Not Supplied Suspended: 01/01/2002 Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	785	2	381452 410450
118	Licensed Waste Management Facilities (Locations) Licence Number: 50359 Location: Unit 2, Pimhole Business Park, Pimhole, Bury, Lancashire, BL9 7ET Operator Name: Amberdeal Limited Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles Licence Status: Transferred Issued: 1st August 2005 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	819	2	381480 410416
118	Licensed Waste Management Facilities (Locations) Licence Number: 53578 Location: Unit 1, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: Holt Anthony Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Metal Recycling Sites (Vehicle Dismantlers) Licence Status: Transferred Issued: 7th November 1996 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SE (E)	832	2	381497 410432

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
119	Licensed Waste Management Facilities (Locations) Licence Number: 50366 Location: Unit 7, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: Adnan Mohammad Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles Licence Status: Transferred Issued: 6th June 2005 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A9NE (SE)	794	2	381400 410234
120	Licensed Waste Management Facilities (Locations) Licence Number: 50420 Location: 19 Arden Close, Bury, Lancashire, BL9 0UA Operator Name: The Land Clinic Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Mobile Plant Licence Status: Revoked Issued: 28th October 2005 Last Modified: 7th April 2006 Expires: Not Supplied Suspended: Not Supplied Revoked: 17th September 2015 Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A7SE (SW)	810	2	380113 409806
121	Licensed Waste Management Facilities (Locations) Licence Number: 101913 Location: Gate 2, Tile Street, Bury, Lancashire, BL9 5BR Operator Name: M & A Skip Hire Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: HCl Waste TS + treatment Licence Status: Revoked Issued: 26th January 2011 Last Modified: 11th April 2012 Expires: Not Supplied Suspended: Not Supplied Revoked: 1st June 2015 Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A18NW (N)	829	2	380468 411461
121	Licensed Waste Management Facilities (Locations) Licence Number: 102616 Location: Auto Spares World, Park Road, Bury, Lancashire, BL9 5BQ Operator Name: Autospares World Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Vehicle depollution facility Licence Status: Revoked Issued: 8th September 2011 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A18NW (N)	855	2	380473 411489
122	Licensed Waste Management Facilities (Locations) Licence Number: 50413 Location: Unit 7a, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Operator Name: O'Tache George Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles Licence Status: Revoked Issued: 30th November 2005 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: 16th August 2010 Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A9NE (SE)	854	2	381436 410170

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
123	Licensed Waste Management Facilities (Locations) Licence Number: 53713 Location: Peel Mills, Gordon Street, Bury, Lancashire, BL9 0LS Operator Name: Dearden Bernard Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations Licence Status: Issued Issued: 15th September 1994 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A18NW (N)	903	2	380320 411490
124	Licensed Waste Management Facilities (Locations) Licence Number: 53473 Location: Land/premises At, Bridge Street, Bury, Lancashire, BL9 6HH Operator Name: Sims Group U K Limited Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Metal Recycling Sites (Mixed) Licence Status: Surrendered Issued: 13th November 1998 Last Modified: 1st July 2015 Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: 24th June 2020 IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A19NW (NE)	933	2	381179 411448
	Local Authority Landfill Coverage Name: Bury Metropolitan Borough Council - Has not been able to supply Landfill data		0	6	380598 410573
	Local Authority Landfill Coverage Name: Rochdale Metropolitan Borough Council - Has no landfill data to supply		882	7	381411 410068
125	Registered Landfill Sites Licence Holder: Bury M.B.C. Licence Reference: 00503/88/M1 Site Location: East & West Of Manchester Road, Bury, Lancashire Licence Easting: 380140 Licence Northing: 410380 Operator Location: Lester House, 21 Broad Street, BURY, Lancashire, BL9 0DA Authority: Environment Agency - North West Region, South Area Site Category: Landfill - Railway cutting Max Input Rate: Very Large (Equal to or greater than 250,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Status: Licence lapsed/cancelled/defunct/not applicable/surrenderedCancelled Dated: 1st April 1988 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the address or location Boundary Accuracy: Not Applicable Authorised Waste Constr'N Ind. Wastes Containing Only Fibreglass Glass Metals Plastics Similar Non Leachate Forming Materials Soil,Clay,Sand, Stone,Brick,Concrete,Slate Wood Prohibited Waste Animal Flesh Chemical Waste Of Any Nature Foodstuffs Paper/Cardboard Plasterboard Sawdust Textiles Vegetable Matter Waste Forming Polluting Leachate Waste In Liquid Or Sludge Form	A12SE (SW)	395	2	380140 410380

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
126	Registered Landfill Sites Licence Holder: Bury M.B.C. Licence Reference: 00650/90 Site Location: Bridge Road, Bury, Lancashire Licence Easting: 380000 Licence Northing: 410430 Operator Location: Lester House, 21 Broad Street, BURY, Lancashire, BL9 0DA Authority: Environment Agency - North West Region, South Area Site Category: Landfill - Railway cutting Max Input Rate: Medium (Equal to or greater than 25,000 and less than 75,000 tonnes per year) Waste Source: Waste produced/controlled by licence holder Restrictions: Status: Licence lapsed/cancelled/defunct/not applicable/surrenderedCancelled Dated: 1st March 1991 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the address or location Boundary Accuracy: Not Applicable Authorised Waste: GmwdA Group 1 - Non Decomp.W -But Not Max.Waste Permitted By Licence- Stated Prohibited Waste: All Other Waste N.O.S. Liquid/Sludge Wastes Mineral Processing Wastes Waste In Drums Waste In Skips	A12SE (W)	511	2	380000 410430
127	Registered Landfill Sites Licence Holder: Clough Mill Ltd Licence Reference: 00615/90 Site Location: Clough Mill Reservoir, Pimhole Fold, Pimhole, Bury, Lancashire Licence Easting: 381500 Licence Northing: 410350 Operator Location: James Street, BURY, Lancashire, BL9 7EQ Authority: Environment Agency - North West Region, South Area Site Category: Landfill Max Input Rate: Medium (Equal to or greater than 25,000 and less than 75,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Status: Licence lapsed/cancelled/defunct/not applicable/surrenderedCancelled Dated: 1st October 1990 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the road within the address or location Boundary Accuracy: Not Applicable Authorised Waste: Max.Waste Permitted By Licence- Stated Nat.Occ. Uncontam. Excav'N Spoil Prohibited Waste: All Other Waste N.O.S. Waste In Skips	A14SE (E)	752	2	381403 410374
128	Registered Landfill Sites Licence Holder: British Gas Corp (N.W. Region) Licence Reference: 00345/84 Site Location: Elton Works, Victoria Street, Bury, Lancashire Licence Easting: 379450 Licence Northing: 410850 Operator Location: Welman House, Altrincham, Cheshire Authority: Environment Agency - North West Region, South Area Site Category: Landfill Max Input Rate: Large (Equal to or greater than 75,000 and less than 250,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Status: Licence known to be surrenderedSurrendered Dated: 1st October 1984 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the road within the address or location Boundary Accuracy: Not Applicable Authorised Waste: Construction And Demolition Wastes	A11NE (W)	980	2	379547 410826

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
129	Registered Waste Transfer Sites Licence Holder: A Murray t/a Andrew Murray Ltd Licence Reference: 00695/91 Site Location: Unit 1 Millett Street Industrial Estate, Bury, Lancashire Operator Location: 8 Chapeltown Road, Outwood, Radcliffe, Bury, Lancashire Authority: Environment Agency - North West Region, South Area Site Category: Transfer Max Input Rate: Very Small (Less than 10,000 tonnes per year) Waste Source: Some restriction on source of waste Restrictions: Licence Status: Site exempt from licenceExempt Dated: 1st May 1993 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the address or location Boundary Quality: Not Supplied Authorised Waste: Max.Storage In Licence Solvents & Thinners Prohibited Waste: Explosive Waste Malodorous Waste Pressurized Containers/Waste Therein Violently Reactive Wastes Waste N.O.S.	A12NW (W)	767	2	379780 410850
130	Registered Waste Transfer Sites Licence Holder: Auto-Col Ltd Licence Reference: 00656/90 Site Location: Badger Street, BURY, Lancashire, BL9 6AD Operator Location: Norfield Works, Richmond Street, ACCRINGTON, Lancashire, BB5 0RH Authority: Environment Agency - North West Region, South Area Site Category: Transfer Max Input Rate: Very Small (Less than 10,000 tonnes per year) Waste Source: Some restriction on source of waste Restrictions: Licence Status: Site exempt from licenceExempt Dated: 1st May 1993 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the road within the address or location Boundary Quality: Not Supplied Authorised Waste: Max.Storage In Licence Solvents & Thinners Prohibited Waste: Explosive Waste Malodorous Waste Pressurized Contain. Or Waste Therein Violently Reactive Wastes Waste N.O.S.	A19NW (NE)	803	2	381150 411310

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
131	Registered Waste Transfer Sites Licence Holder: B Dearden Licence Reference: 00901 Site Location: Peel Mills, Gordon Street, Castlecroft Road, Bury, Lancashire Operator Location: 19 Walnut Avenue, BURY, Lancashire, BL9 7QR Authority: Environment Agency - North West Region, South Area Site Category: Transfer Max Input Rate: Small (Equal to or greater than 10,000 and less than 25,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Licence Status: Operational as far as is knownOperational Dated: 1st September 1994 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Approximate location provided by supplier Boundary Quality: Not Supplied Authorised Waste Elect. Fittings/Fixtures/Appliances Empty Used Containers Glass,Pottery,China,Enamel,Ceram.Mica Gmwda Group 2 - Slow Decomp./Slight So Max.Waste Permitted By Licence Rubble,Harcore,Stone,Brickwvk,Concrete Scrap Mach'Y/Equip. - Ferrous Scrap Mach'Y/Equip. - Non-Ferrous Soil Weathered Tar/Bitumen Aggregate Prohibited Waste Explosive Waste Liquid Wastes Press'D Containers Or Waste Therein Putrescible Waste Sludge Wastes Special Wastes N.O.S. Waste In Drums Waste N.O.S Whether/Not Pack./Pre-Trt Waste Reacting Violently With Water	A18NW (N)	826	2	380300 411400
132	Registered Waste Treatment or Disposal Sites Licence Holder: Bury M.B.C. Licence Reference: 00071/CO1 Site Location: Market Hall, Princess, Bury, Lancashire Operator Location: Town Hall, BURY, Lancashire, BL9 0SW Authority: Environment Agency - North West Region, South Area Site Category: Incineration Max Input Rate: Small (Equal to or greater than 10,000 and less than 25,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Licence Status: Licence has completion certificateSurrendered Dated: 13th June 1978 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the road within the address or location Boundary Quality: Not Supplied Authorised Waste House. + Com. Untreated Waste Medical, Surgical, Veterinary Wastes	A13NE (N)	54	2	380620 410690
133	Registered Waste Treatment or Disposal Sites Licence Holder: Swinnerton Bros Ltd Licence Reference: 00166/M04 Site Location: York Street, BURY, Lancashire, BL9 7AR Operator Location: As Site Address Authority: Environment Agency - North West Region, South Area Site Category: Baling - Compaction Max Input Rate: Very Large (Equal to or greater than 250,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Licence Status: Operational as far as is knownOperational Dated: 22nd September 1983 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the address or location Boundary Quality: Not Supplied Authorised Waste Construction And Demolition Wastes Empty Used Containers Household + Commercial Waste Ind. Non-Haz. Waste Metal Scrap Polymeric Material, Products/Scrap	A19SW (NE)	571	2	381160 410970

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
134	Registered Waste Treatment or Disposal Sites Licence Holder: K.M.A. Skiphire & Planthire Ltd Licence Reference: 50015 Site Location: Manor Street, BURY, Lancashire, BL9 7BL Operator Location: As Site Address Authority: Environment Agency - North West Region, South Area Site Category: Transfer - with treatment Max Input Rate: Small (Equal to or greater than 10,000 and less than 25,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Licence Status: Operational as far as is knownOperational Dated: 1st August 1998 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the address or location Boundary Quality: Not Supplied Authorised Waste Prohibited Waste	A19SW (NE)	604	2	381230 410910
135	Registered Waste Treatment or Disposal Sites Licence Holder: B Dawson t/a J.S.M Contract (Salvage) Licence Reference: 01121 Site Location: 7 James Street, BURY, Lancashire, BL9 7EG Operator Location: As Site Address Authority: Environment Agency - North West Region, South Area Site Category: Scrapyard Max Input Rate: Medium (Equal to or greater than 25,000 and less than 75,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Licence Status: Operational as far as is knownOperational Dated: 1st March 1995 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the road within the address or location Boundary Quality: Not Supplied Authorised Waste Prohibited Waste	A14SE (E)	646	2	381300 410400

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
136	Registered Waste Treatment or Disposal Sites Licence Holder: R & M Stansfield Enterprises Ltd Licence Reference: 01007/T01 Site Location: The Yard; Tile Street, Woodsfield Street, Fernhill, Bury, Lancashire, BL9 5BU Operator Location: Tile Street, BURY, Lancashire, BL6 5BU Authority: Environment Agency - North West Region, South Area Site Category: Scrapyard Max Input Rate: Very Small (Less than 10,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Licence Status: Operational as far as is knownOperational Dated: 1st September 1996 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the road within the address or location Boundary Quality: Not Supplied Authorised Waste: Associated Non-Scrap Max.Storage Pre-Sorted Scrap Metal Incl. Scrap Vehicles Prohibited Waste: Asbestos (Other Than Integral To Veh.) Bulk Powders Clinical Wastes Explosive Waste Highly Reactive Wastes Pcbs And Analogues Pressurised Wastes Or Cont'Rs Special Wastes N.O.S. Waste Drums (Unless Pre-Cleaned) Waste N.O.S.	A18NW (N)	703	2	380550 411350
137	Registered Waste Treatment or Disposal Sites Licence Holder: S & J Salvage (Mrs J Mills) Licence Reference: 80025 Site Location: Pimhole Field, Hurst Street, Bury, Lancashire Operator Location: 208 Ainsworth Hall Road, BOLTON, Lancashire, BL2 6QR Authority: Environment Agency - North West Region, South Area Site Category: Scrapyard Max Input Rate: Very Small (Less than 10,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Licence Status: Operational as far as is knownOperational Dated: 1st May 1998 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Located by supplier to within 100m Boundary Quality: Not Supplied Authorised Waste: Fibreglass Max.Storage Of Batteries Max.Storage Of Drained Liquids Max.Storage Of Non Oil-Contam.Parts Max.Storage Of Oil-Contam.Parts Max.Storage Of Tyres Max.Storage Of Vehicles Max.Waste Permitted By Licence Paper/Cardboard Plastics Rubber Scrap Vehicles Textiles Wood Prohibited Waste: Asbestos Bulk Powders Clinical Wastes Explosive Waste Pressurised Wastes Spec.Waste (Epa'90:S62/1996 Regs)N.O.S Violently Reactive Waste Waste Containing/Contam.With Pcbs Waste Drums (Unless Pre-Cleaned) Waste In Pressurised Cont'Rs Waste N.O.S.	A14SE (E)	744	2	381400 410400

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
137	Registered Waste Treatment or Disposal Sites Licence Holder: Amberdeal Ltd T/A Autosave Used Motor Licence Reference: 00946 Site Location: Pimhole Fold, Pimhole Road, BURY, Lancashire, BL9 7ET Operator Location: As Site Address Authority: Environment Agency - North West Region, South Area Site Category: Scrapyard Max Input Rate: Very Small (Less than 10,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Licence Status: Operational as far as is knownOperational Dated: 29th March 1996 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the road within the address or location Boundary Quality: Not Supplied Authorised Waste Ferroous Metal Scrap Fibreglass Max.Waste Permitted By Licence Non-Ferrous Metal Scrap Paper/Cardboard Plastics Presorted Scrap Metal Restricted To Rubber Scrap Vehicles Textiles Wood Prohibited Waste Asbestos (Other Than Parts Of Vehicles Bulk Powders Clinical Wastes Explosive Waste Pcbs Pressurised Wastes Special Wastes N.O.S. Violently Reactive Waste Waste Drums (Unless Pre-Cleaned) Waste N.O.S.	A14SE (E)	783	2	381440 410400
138	Registered Waste Treatment or Disposal Sites Licence Holder: Messrs Dawson,Whittle,Egerton t/a Bury Salva Licence Reference: 00958 Site Location: Gate 1 Pinhole Road, BURY, Lancashire, BL9 7ET Operator Location: 7 James Street, BURY, Lancashire, BL9 7EG Authority: Environment Agency - North West Region, South Area Site Category: Scrapyard Max Input Rate: Very Small (Less than 10,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Licence Status: Operational as far as is knownOperational Dated: 1st November 1996 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the address or location Boundary Quality: Not Supplied Authorised Waste Max.Storage In Licence Max.Waste Permitted By Licence Scrap Vehicles Asbestos (Other Than Normal Part Veh.) Bulk Powders Clinical Wastes Explosive Waste Pcbs Pressurised Waste Or Containers Spec.Waste (Epa'90:S62/1996 Regs)N.O.S Violently Reactive Wastes Waste In Drums Waste N.O.S.	A14SE (E)	783	2	381450 410450

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
139	Registered Waste Treatment or Disposal Sites Licence Holder: Brook Street Metal Co Ltd Licence Reference: 00561 Site Location: Bridge Street, BURY, Lancashire, BL9 6HH Operator Location: As Site Address Authority: Environment Agency - North West Region, South Area Site Category: Scrapyard Max Input Rate: Very Small (Less than 10,000 tonnes per year) Waste Source: No known restriction on source of waste Restrictions: Licence Status: Operational as far as is knownOperational Dated: 1st November 1998 Preceded By: Not Given Licence: Superseded By: Not Given Licence: Positional Accuracy: Manually positioned to the address or location Boundary Quality: Not Supplied Authorised Waste Any Non-Haz. Ferrous Metal Scrap Any Non-Haz. Non-Ferrous Metal Scrap Clean Drums Max.Waste Permitted By Licence Scrap Vehicles Prohibited Waste Pcbs/Pcts Spec.Waste (Epa'90:S62/1996 Regs)N.O.S Waste N.O.S.	A19NW (NE)	906	2	381140 411440

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
140	Control of Major Accident Hazards Sites (COMAH) Name: Cussons (UK) Limited Location: Bury Warehouse, Alfred Street, BURY, Lancashire, BL9 9DT Reference: Not Supplied Type: Lower Tier Status: Record Ceased To Be Supplied Under COMAH Regulations Positional Accuracy: Manually positioned to the road within the address or location	A9NW (SE)	756	8	381197 409997
141	Control of Major Accident Hazards Sites (COMAH) Name: T W Tyson Location: Calor House, Webb Street, BURY, Lancashire, BL8 1AF Reference: Not Supplied Type: Lower Tier Status: Record Ceased To Be Supplied Under COMAH Regulations Positional Accuracy: Manually positioned to the road within the address or location	A17SW (NW)	981	8	379736 411191
142	Notification of Installations Handling Hazardous Substances (NIHHS) Name: Cussons (UK) Ltd Location: Alfred Street, Bury, BL9 9QT Status: Not Active Positional Accuracy: Manually positioned to the road within the address or location	A9NW (SE)	727	8	381202 410046
143	Notification of Installations Handling Hazardous Substances (NIHHS) Name: T W Tyson Location: Calor House, Webb Street, BURY, Lancashire, BL8 1AF Status: Not Active Positional Accuracy: Automatically positioned in the proximity of the address	A17SW (NW)	978	8	379736 411187
144	Planning Hazardous Substance Consents Name: T W Tyson Location: Webb Street, BURY, Lancashire, BL8 1AK Authority: Bury Metropolitan Borough Council Application Ref: C/27664/92 Hazardous: Part C, Flammable Substance (Not in Parts A&B), Liquefied petroleum gas Substance: held at >1.4 bar where amount held is greater than or equal to 25 tonnes Maximum Quantity: 25 Application date: Not Supplied Decision: Deemed consent granted between June 1992 and November 1992 Granted Positional Accuracy: Manually positioned to the road within the address or location	A17SW (NW)	978	9	379740 411191

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS 1:625,000 Solid Geology Description: Pennine Lower Coal Measures Formation And South Wales Lower Coal Measures Formation (Undifferentiated)	A13NE (E)	0	1	380598 410573
	Coal Mining Affected Areas Description: In an area which may be affected by coal mining activity. It is recommended that a coal mining report is obtained from the Coal Authority. Contact details are included in the Useful Contacts section of this report.	A13NE (E)	0	10	380598 410573
	Mining Instability Mining Evidence: Inconclusive Coal Mining Source: Ove Arup & Partners Boundary Quality: As Supplied	A13NE (E)	0	-	380598 410573
	Man-Made Mining Cavities Easting: 380000 Northing: 410001 Distance: 723 Quadrant Reference: A7 Quadrant Reference: NE Bearing Ref: SW Cavity Type: Not supplied Commodity: Sandstone Solid Geology Detail: No Details Superficial Geology: No Details Detail:	A7NE (SW)	723	11	380000 410001
	Non Coal Mining Areas of Great Britain No Hazard				
	Potential for Collapsible Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NE (E)	0	1	380598 410573
	Potential for Compressible Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NE (E)	0	1	380598 410573
	Potential for Ground Dissolution Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NE (E)	0	1	380598 410573
	Potential for Landslide Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NE (E)	0	1	380598 410573
	Potential for Running Sand Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NE (E)	0	1	380598 410573
	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NE (E)	0	1	380598 410573
	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (W)	44	1	380458 410532
	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NW (NW)	116	1	380479 410688
	Radon Potential - Radon Affected Areas Affected Area: The property is in a Lower probability radon area (less than 1% of homes are estimated to be at or above the Action Level). Source: British Geological Survey, National Geoscience Information Service	A13NE (E)	0	1	380598 410573
	Radon Potential - Radon Protection Measures Protection Measure: No radon protective measures are necessary in the construction of new dwellings or extensions Source: British Geological Survey, National Geoscience Information Service	A13NE (E)	0	1	380598 410573

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
145	Contemporary Trade Directory Entries Name: Johnson Cleaners Uk Ltd Location: 4, Princess Parade, Bury, Lancashire, BL9 0QL Classification: Dry Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A13SW (W)	0	-	380529 410564
145	Contemporary Trade Directory Entries Name: Perdons Cheese Stall Location: Murray Road, Bury, Lancashire, BL9 0BJ Classification: Cheese Makers & Suppliers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A13SW (SW)	0	-	380569 410546
146	Contemporary Trade Directory Entries Name: Cheese Plus Location: 10-11 Toulmin Block, The Open Market, Bury, Lancashire, BL9 0QQ Classification: Dairies Status: Inactive Positional Accuracy: Manually positioned to the address or location	A13NE (NE)	0	-	380656 410611
147	Contemporary Trade Directory Entries Name: Klick Photopoint Location: 17, Princess Parade, Bury, Lancashire, BL9 0QL Classification: Photographic Processors Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (NW)	12	-	380559 410606
147	Contemporary Trade Directory Entries Name: Klick Location: 17, Princess Parade, Bury, Lancashire, BL9 0QL Classification: Photographic Processors Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (NW)	12	-	380559 410606
148	Contemporary Trade Directory Entries Name: Bury Bacon & Cooked Meat Co Location: Market Parade, Bury, Lancashire, BL9 0BD Classification: Meat - Wholesale Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NE (N)	33	-	380636 410667
148	Contemporary Trade Directory Entries Name: James Lawless & Sons Ltd Location: Market Parade, Bury, Lancashire, BL9 0BD Classification: Electrical Goods Sales, Manufacturers & Wholesalers Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NE (N)	33	-	380636 410667
148	Contemporary Trade Directory Entries Name: Willie'S Wall Papers & Paints Location: Market Parade, Bury, Lancashire, BL9 0BD Classification: Wallpapers & Wall Coverings Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NE (N)	33	-	380636 410667
148	Contemporary Trade Directory Entries Name: Puffin Food Centre Location: Market Hall, Market Parade, Bury, Lancashire, BL9 0BD Classification: Frozen Food Processors & Distributors Status: Inactive Positional Accuracy: Manually positioned to the address or location	A13NE (N)	33	-	380636 410667
148	Contemporary Trade Directory Entries Name: Max Spielmann Location: 29, The Mall, Bury, Lancashire, BL9 0QQ Classification: Photographic Processors Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NE (N)	43	-	380596 410675
148	Contemporary Trade Directory Entries Name: T Shirt Printing Location: Unit 2 The Gable, Market Parade, Bury, Lancashire, BL9 0BD Classification: T-Shirts Status: Active Positional Accuracy: Manually positioned to the road within the address or location	A13NE (NE)	54	-	380654 410708
148	Contemporary Trade Directory Entries Name: Dr Herbs Location: Unit 1 Minden Parade, Bury, Lancashire, BL9 0QG Classification: Lighting Manufacturers Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A13NE (N)	78	-	380621 410714

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
149	Contemporary Trade Directory Entries Name: Ashton Photographics Location: 25, Minden Parade, Bury, Lancashire, BL9 0QG Classification: Photographic Processors Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NE (N)	85	-	380608 410722
150	Contemporary Trade Directory Entries Name: Shopmobility Location: 34, Minden Parade, Bury, Lancashire, BL9 0QG Classification: Disability Equipment - Manufacturers & Suppliers Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NE (NE)	94	-	380697 410751
151	Contemporary Trade Directory Entries Name: Dixons Location: 21-23, The Haymarket, Bury, Lancashire, BL9 0BX Classification: Electrical Goods Sales, Manufacturers & Wholesalers Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (N)	119	-	380559 410742
151	Contemporary Trade Directory Entries Name: Currys Digital Location: 21-23, The Haymarket, Bury, Lancashire, BL9 0BX Classification: Electrical Goods Sales, Manufacturers & Wholesalers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A13NW (N)	119	-	380559 410742
152	Contemporary Trade Directory Entries Name: The Fragrance Shop Location: 2b, The Mall, Bury, Lancashire, BL9 0QQ Classification: Perfume Suppliers Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (NW)	134	-	380512 410724
153	Contemporary Trade Directory Entries Name: Perfume Point Location: 4 Union Arcade, Bury, Lancashire, BL9 0QF Classification: Perfume Suppliers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A13NE (N)	156	-	380588 410790
154	Contemporary Trade Directory Entries Name: BI9 Location: 44, The Haymarket, Bury, Lancashire, BL9 0BX Classification: Bags, Belts & Accessories - Manufacturers & Suppliers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A13NW (NW)	157	-	380454 410719
155	Contemporary Trade Directory Entries Name: Cheshire Fireplaces Of Bury Location: George St, Bury, Lancashire, BL9 0QT Classification: Fireplaces & Mantelpieces Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A13NE (NE)	159	-	380835 410700
155	Contemporary Trade Directory Entries Name: Diton Clothing Location: D R M Mill, South Cross Street, Bury, Lancashire, BL9 0RS Classification: Clothing & Fabrics - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NE (NE)	163	-	380841 410688
156	Contemporary Trade Directory Entries Name: Supasnaps Location: 36, Market Street, Bury, Lancashire, BL9 0AJ Classification: Photographic Processors Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (NW)	164	-	380408 410706
156	Contemporary Trade Directory Entries Name: Geldard'S Location: 17, Broad Street, Bury, Lancashire, BL9 0DA Classification: Dry Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (NW)	181	-	380385 410712
157	Contemporary Trade Directory Entries Name: Bury Crafts Location: Unit 10,Arts & Craft Centre,Broad St, Bury, Lancashire, BL9 0DA Classification: Jewellery Manufacturers & Repairers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A13NW (W)	173	-	380352 410668

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
158	Contemporary Trade Directory Entries Name: Instore Location: Angouleme Way Retail Park, George Street, Bury, Lancashire, BL9 0BZ Classification: Homefurnishings - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NE (NE)	180	-	380808 410786
159	Contemporary Trade Directory Entries Name: K J Plumbing Factors & Heating Spares Ltd Location: Mowe House, 34, Margaret Street, Bury, Lancashire, BL9 0SA Classification: Central Heating Supplies & Equipment Status: Inactive Positional Accuracy: Automatically positioned to the address	A13SE (SE)	209	-	380810 410385
159	Contemporary Trade Directory Entries Name: K J Plumbing Location: Mowe House, 34, Margaret Street, Bury, Lancashire, BL9 0SA Classification: Central Heating Supplies & Equipment Status: Inactive Positional Accuracy: Automatically positioned to the address	A13SE (SE)	209	-	380810 410385
160	Contemporary Trade Directory Entries Name: W H Winterburn Location: South Back Rock, Off Crompton St, Bury, Lancashire, BL9 0NS Classification: Printers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A13NW (NW)	222	-	380462 410797
160	Contemporary Trade Directory Entries Name: Nextrom Location: Derby Chambers, 6, The Rock, Bury, Lancashire, BL9 0NT Classification: Machinery - Industrial & Commercial Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (NW)	254	-	380429 410814
160	Contemporary Trade Directory Entries Name: Hunterskil Howard Projects Ltd Location: Derby Chambers, 6, The Rock, Bury, Lancashire, BL9 0NT Classification: Printed Circuit Services Status: Inactive Positional Accuracy: Manually positioned to the address or location	A13NW (NW)	254	-	380429 410814
160	Contemporary Trade Directory Entries Name: Mels Cleaning Services Location: Derby Chambers, 6, The Rock, Bury, Lancashire, BL9 0NT Classification: Commercial Cleaning Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (NW)	254	-	380429 410814
161	Contemporary Trade Directory Entries Name: Burning Desire (Uk) Ltd Location: 9, Silver Street, Bury, Lancashire, BL9 0EU Classification: Fireplaces & Mantelpieces Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (NW)	233	-	380363 410761
162	Contemporary Trade Directory Entries Name: Why Pay More Location: 58, The Rock, Bury, Lancashire, BL9 0PB Classification: Toiletries Status: Inactive Positional Accuracy: Manually positioned to the address or location	A13NW (N)	233	-	380560 410863
162	Contemporary Trade Directory Entries Name: Robert Daniels Jewellery Location: 47, The Rock, Bury, BL9 0JP Classification: Jewellery Manufacturers & Repairers Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (N)	264	-	380550 410893
163	Contemporary Trade Directory Entries Name: Blackford Bridge Service Station Location: Manchester rd, Bury, Lancashire, BL9 9ST Classification: Petrol Filling Stations Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A13SW (W)	235	-	380257 410557
164	Contemporary Trade Directory Entries Name: P C World Location: Angouleme Way Retail Park, George Street, Bury, Lancashire, BL9 0BZ Classification: Electrical Goods Sales, Manufacturers & Wholesalers Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NE (NE)	237	-	380885 410781

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
165	Contemporary Trade Directory Entries Name: Cleaners Bury Location: 2-6, Bank Street, Bury, BL9 0DL Classification: Carpet, Curtain & Upholstery Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (W)	253	-	380278 410702
165	Contemporary Trade Directory Entries Name: Vega Machinery (Uk) Ltd Location: 8, Bank Street, Bury, Lancashire, BL9 0DL Classification: Packaging & Wrapping Equipment & Supplies Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (NW)	278	-	380259 410718
165	Contemporary Trade Directory Entries Name: Transit Plus Location: 8, Bank Street, Bury, Lancashire, BL9 0DL Classification: Freight Forwarders Status: Inactive Positional Accuracy: Manually positioned to the address or location	A13NW (NW)	278	-	380259 410718
165	Contemporary Trade Directory Entries Name: A2b Office Supplies & Technology Location: The Exchange, 5 Bank Street, Bury, Lancashire, BL9 0DN Classification: Office Equipment Servicing & Maintenance Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NE (W)	279	-	380236 410676
166	Contemporary Trade Directory Entries Name: B W Cleaning Services Location: 14-16 Silver Street, Bury, Lancashire, BL9 0EX Classification: Commercial Cleaning Services Status: Active Positional Accuracy: Automatically positioned to the address	A13NW (NW)	255	-	380318 410753
166	Contemporary Trade Directory Entries Name: Rrg (Bury) Location: 7, Bolton Street, Bury, Lancashire, BL9 0EY Classification: Car Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (NW)	282	-	380323 410792
166	Contemporary Trade Directory Entries Name: Dale Fireplaces Location: 23, Bolton Street, Bury, Lancashire, BL9 0EY Classification: Fireplaces & Mantelpieces Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NW (NW)	311	-	380283 410796
167	Contemporary Trade Directory Entries Name: Stephen Harris & Co Location: Belgrave Place, 8, Manchester Road, Bury, Lancashire, BL9 0ED Classification: Storage & Shelving Systems Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12SE (W)	259	-	380233 410554
167	Contemporary Trade Directory Entries Name: James Hamer Ltd Location: 1-3, St. Marys Place, Bury, Lancashire, BL9 0DZ Classification: Painting & Decorating Supplies Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NE (W)	274	-	380219 410590
167	Contemporary Trade Directory Entries Name: Essential Hygiene Location: 10-12, St. Marys Place, Bury, Lancashire, BL9 0DZ Classification: Commercial Cleaning Services Status: Active Positional Accuracy: Automatically positioned to the address	A12NE (W)	274	-	380224 410619
167	Contemporary Trade Directory Entries Name: Indace Ltd Location: 7-9, St. Marys Place, BURY, Lancashire, BL9 0DZ Classification: Chemists' & Pharmacists' Suppliers & Wholesalers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NE (W)	288	-	380204 410581
168	Contemporary Trade Directory Entries Name: Anglebase Ltd Location: 23, Rochdale Road, Bury, Lancashire, BL9 0QB Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NE (NE)	261	-	380839 410866

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
168	Contemporary Trade Directory Entries Name: Bury Exhausts & Tyres Location: Unit 7 Kwik Save Shopping Precinct, Rochdale Rd, Bury, Lancashire, BL9 0PR Classification: Tyre Dealers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A13NE (NE)	265	-	380870 410844
168	Contemporary Trade Directory Entries Name: Portwood Colour Co Ltd Location: 17-19, Rochdale Road, Bury, Lancashire, BL9 0QB Classification: Colour Manufacturers & Suppliers Status: Inactive Positional Accuracy: Automatically positioned to the address	A13NE (NE)	266	-	380828 410881
169	Contemporary Trade Directory Entries Name: Eric Bradley (Woodworker) Ltd Location: 40, South Cross Street, Bury, Lancashire, BL9 0RS Classification: Joinery Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SW (E)	271	-	380941 410515
170	Contemporary Trade Directory Entries Name: Millennium Blinds Location: 124, The Rock, Bury, Lancashire, BL9 0PJ Classification: Blinds, Awnings & Canopies Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (N)	275	-	380670 410933
171	Contemporary Trade Directory Entries Name: R M C Systems Location: 73, The Rock, Bury, Lancashire, BL9 0NB Classification: Computer Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (N)	281	-	380603 410930
171	Contemporary Trade Directory Entries Name: Brighthouse Location: 101, The Rock, Bury, Lancashire, BL9 0NB Classification: Electrical Goods Sales, Manufacturers & Wholesalers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (N)	302	-	380641 410958
172	Contemporary Trade Directory Entries Name: Chevron Motors Location: Unit 6, 7, South Cross Street, Bury, Lancashire, BL9 0RS Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SW (E)	289	-	380967 410559
172	Contemporary Trade Directory Entries Name: Wallwork Location: Lord Street, BURY, Lancashire, BL9 0RE Classification: Heat Treatment - Metals Status: Active Positional Accuracy: Automatically positioned to the address	A14SW (E)	289	-	380967 410559
172	Contemporary Trade Directory Entries Name: Ace Mots Location: Unit 1, 7, South Cross Street, Bury, Lancashire, BL9 0RS Classification: Mot Testing Centres Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SW (E)	289	-	380967 410559
172	Contemporary Trade Directory Entries Name: South Cross Street M O T Centre Location: Unit 2, 7, South Cross Street, Bury, BL9 0RS Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A14SW (E)	290	-	380967 410559
173	Contemporary Trade Directory Entries Name: Tudor Glass Ltd Location: Lord Street, Bury, Lancashire, BL9 0SD Classification: Glass Products - Manufacturers Status: Active Positional Accuracy: Automatically positioned to the address	A14NW (E)	307	-	380987 410618
174	Contemporary Trade Directory Entries Name: East Lancashire Railway Location: Bolton Street Station, Bolton Street, Bury, Lancashire, BL9 0EY Classification: Railways Status: Active Positional Accuracy: Automatically positioned to the address	A13NW (NW)	326	-	380259 410794

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
174	Contemporary Trade Directory Entries Name: R M S Location: 24a, Bolton Street, Bury, Lancashire, BL9 0LQ Classification: Jewellery Manufacturers & Repairers Status: Active Positional Accuracy: Automatically positioned to the address	A13NW (NW)	342	-	380282 410836
175	Contemporary Trade Directory Entries Name: Gas Appliance Services Location: Foundry Street, Bury, Lancashire, BL9 7AZ Classification: Gas Appliances - Sales & Service Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	328	-	380992 410763
175	Contemporary Trade Directory Entries Name: Shell (Uk) Ltd Location: Rochdale Rd, Bury, Lancashire, BL9 7AX Classification: Petrol Filling Stations - 24 Hour Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14NW (NE)	360	-	381012 410802
176	Contemporary Trade Directory Entries Name: The Perfume Shop Location: 9, Central Street, Bury, Lancashire, BL9 0JN Classification: Perfume Suppliers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (NE)	335	-	380767 410982
176	Contemporary Trade Directory Entries Name: The Perfume Shop Location: Unit 13b The Rock, Bury, Lancashire, BL9 0JN Classification: Perfume Suppliers Status: Active Positional Accuracy: Manually positioned to the address or location	A18SE (NE)	338	-	380807 410972
177	Contemporary Trade Directory Entries Name: First Manchester Bury Depot Location: 55, Rochdale Road, Bury, Lancashire, BL9 0QZ Classification: Bus & Coach Operators & Stations Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	335	-	380963 410839
178	Contemporary Trade Directory Entries Name: Trans International Forwarders Ltd Location: 3, Frecheville Court, Bury, Lancashire, BL9 0UF Classification: Freight Forwarders Status: Inactive Positional Accuracy: Automatically positioned to the address	A13SW (SW)	341	-	380268 410273
178	Contemporary Trade Directory Entries Name: Norman Wordsworth & Co Ltd Location: 15, Knowsley Street, Bury, Lancashire, BL9 0ST Classification: Engineers - General Status: Inactive Positional Accuracy: Automatically positioned to the address	A12SE (SW)	360	-	380225 410293
179	Contemporary Trade Directory Entries Name: Pos Media Displays Solutions Location: Unit 6, East Street Sawmills, East Street, Bury, Lancashire, BL9 0RU Classification: Manufacturers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A13SE (SE)	352	-	380873 410246
179	Contemporary Trade Directory Entries Name: Air Vane Compressors Location: Unit 1, East Street, Bury, Lancashire, BL9 0RU Classification: Air Compressors Status: Inactive Positional Accuracy: Automatically positioned to the address	A13SE (SE)	364	-	380914 410268
179	Contemporary Trade Directory Entries Name: Air Vane Compressors Ltd Location: Unit 1, East Street Sawmills, East Street, Bury, Lancashire, BL9 0RU Classification: Air Compressors Status: Inactive Positional Accuracy: Automatically positioned to the address	A13SE (SE)	364	-	380914 410268
180	Contemporary Trade Directory Entries Name: Pearl Car Care Products Ltd Location: 36, Bolton Street, Bury, BL9 0LL Classification: Car Washing & Polishing Equipment & Supplies Status: Active Positional Accuracy: Automatically positioned to the address	A12NE (NW)	367	-	380246 410838

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
180	Contemporary Trade Directory Entries Name: Prontaprint Location: 40, Bolton Street, Bury, Lancashire, BL9 0LL Classification: Printers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NE (NW)	377	-	380237 410843
180	Contemporary Trade Directory Entries Name: Alenco Location: 44, Bolton Street, Bury, Lancashire, BL9 0LL Classification: Dry Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NE (NW)	384	-	380225 410842
180	Contemporary Trade Directory Entries Name: Allens Location: 44, Bolton Street, Bury, Lancashire, BL9 0LL Classification: Dry Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NE (NW)	384	-	380225 410842
180	Contemporary Trade Directory Entries Name: Alenco Dry Cleaners Location: 44, Bolton Street, Bury, Lancashire, BL9 0LL Classification: Dry Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NE (NW)	384	-	380225 410842
180	Contemporary Trade Directory Entries Name: K & N Upholstery Location: 50, Bolton Street, Bury, Lancashire, BL9 0LL Classification: Leather Garments & Products Status: Inactive Positional Accuracy: Manually positioned to an adjacent address or location	A12NE (NW)	399	-	380222 410861
180	Contemporary Trade Directory Entries Name: Rosehill Printers Ltd Location: A, 50, Bolton Street, Bury, Lancashire, BL9 0LL Classification: Printers Status: Active Positional Accuracy: Automatically positioned to the address	A12NE (NW)	399	-	380222 410861
180	Contemporary Trade Directory Entries Name: Printing.Com Location: 56, Bolton Street, Bury, Lancashire, BL9 0LL Classification: Printers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NE (NW)	404	-	380198 410843
181	Contemporary Trade Directory Entries Name: Adams Fireplaces Location: 159, The Rock, Bury, Lancashire, BL9 0ND Classification: Fireplaces & Mantelpieces Status: Inactive Positional Accuracy: Automatically positioned in the proximity of the address	A18SE (N)	368	-	380732 411023
181	Contemporary Trade Directory Entries Name: Newtons Of Bury Location: 149-151, The Rock, Bury, Lancashire, BL9 0ND Classification: Furniture - Reproduction Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (N)	380	-	380746 411033
181	Contemporary Trade Directory Entries Name: Wilds Table Care Location: 151, The Rock, Bury, Lancashire, BL9 0ND Classification: Tableware Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (N)	380	-	380746 411033
182	Contemporary Trade Directory Entries Name: Horizon Window Blinds Location: 69b Rochdale Road, Bury, Lancashire, BL9 7AX Classification: Blinds, Awnings & Canopies Status: Active Positional Accuracy: Automatically positioned to the address	A14NW (NE)	378	-	381030 410805
182	Contemporary Trade Directory Entries Name: T Yates & Co Location: 2, Fletcher Street, Bury, Lancashire, BL9 7AT Classification: Engineers - General Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	411	-	381053 410835

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
183	Contemporary Trade Directory Entries Name: Gorebrook Location: Derby St, Bury, Lancashire, BL9 0NW Classification: Pattern Makers - Industrial Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19SW (NE)	380	-	380943 410934
184	Contemporary Trade Directory Entries Name: G T Motors Location: 2, York Street, Bury, Lancashire, BL9 7AR Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	417	-	381067 410818
184	Contemporary Trade Directory Entries Name: A S Motors Location: 2, York Street, Bury, Lancashire, BL9 7AR Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	417	-	381067 410818
184	Contemporary Trade Directory Entries Name: As Motors Location: 2, York Street, Bury, Lancashire, BL9 7AR Classification: Mechanical Engineers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	417	-	381067 410818
184	Contemporary Trade Directory Entries Name: A S Motors Location: 2, York Street, Bury, Lancashire, BL9 7AR Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	417	-	381067 410818
184	Contemporary Trade Directory Entries Name: Euro Location: 4a, Fletcher Street, Bury, Lancashire, BL9 7AT Classification: Tyre Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	428	-	381072 410832
184	Contemporary Trade Directory Entries Name: D & J Auto Electrical Services Ltd Location: 1, York Street, Bury, BL9 7AR Classification: Mot Testing Centres Status: Active Positional Accuracy: Automatically positioned to the address	A14NW (NE)	436	-	381090 410812
184	Contemporary Trade Directory Entries Name: JI Autobodies Location: 3, York Street, Bury, Lancashire, BL9 7AR Classification: Car Body Repairs Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	440	-	381090 410821
184	Contemporary Trade Directory Entries Name: Bury Gas Showrooms & Spares Centre Location: 33, Fletcher Street, Bury, Lancashire, BL9 7AT Classification: Gas Appliances - Sales & Service Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	463	-	381102 410850
184	Contemporary Trade Directory Entries Name: Lakeland Leather Furniture Ltd Location: York Street Mill, York Street, Bury, Lancashire, BL9 7AR Classification: Furniture Manufacturers - Home & Office Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	485	-	381137 410825
185	Contemporary Trade Directory Entries Name: Bury Auto Centres Ltd Location: Barlow Street, Bury, Lancashire, BL9 7AA Classification: Tyre Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (NE)	418	-	380912 411007
186	Contemporary Trade Directory Entries Name: Rowe Hankins Ltd Location: Power House, 25, Parker Street, Bury, Lancashire, BL9 0RJ Classification: Electronic Component Manufacturers & Distributors Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	419	-	381100 410646

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
187	Contemporary Trade Directory Entries Name: Bury Engine Centre Location: Cook Street, Bury, Lancashire, BL9 0RP Classification: Engine Rebuilding & Reconditioning Status: Active Positional Accuracy: Automatically positioned to the address	A14SW (E)	422	-	381094 410506
188	Contemporary Trade Directory Entries Name: Kwik Fit Location: John Street, Bury, BL9 0NH Classification: Tyre Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A18SE (N)	429	-	380739 411083
188	Contemporary Trade Directory Entries Name: Kwik-Fit Location: John Street, Bury, Lancashire, BL9 0NH Classification: Tyre Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (N)	429	-	380739 411083
188	Contemporary Trade Directory Entries Name: Kwik-Fit Location: John Street, Bury, Lancashire, BL9 0NH Classification: Tyre Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (N)	429	-	380739 411083
188	Contemporary Trade Directory Entries Name: Ats Euromaster Ltd Location: John Street, Bury, BL9 0NH Classification: Tyre Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A18SE (N)	442	-	380728 411098
188	Contemporary Trade Directory Entries Name: Ats Euromaster Ltd Location: John Street, Bury, Lancashire, BL9 0NH Classification: Tyre Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (N)	442	-	380728 411098
188	Contemporary Trade Directory Entries Name: Ats Euromaster Ltd Location: John Street, Bury, Lancashire, BL9 0NH Classification: Tyre Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (N)	442	-	380728 411098
189	Contemporary Trade Directory Entries Name: Gasco Location: 86, Rochdale Road, Bury, Lancashire, BL9 7AY Classification: Heating Equipment - Sales & Service Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	431	-	381106 410733
189	Contemporary Trade Directory Entries Name: Bury Gunroom Location: 97, Rochdale Road, Bury, Lancashire, BL9 7BA Classification: Gunsmiths Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	443	-	381110 410773
189	Contemporary Trade Directory Entries Name: G W F Services Ltd Location: A, 97, Rochdale Road, Bury, Lancashire, BL9 7BA Classification: Fire Escapes & Evacuation Equipment Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	443	-	381110 410773
190	Contemporary Trade Directory Entries Name: Kinsey Jones Ltd Location: 181-183, The Rock, Bury, Lancashire, BL9 0NE Classification: Car Dealers Status: Inactive Positional Accuracy: Automatically positioned in the proximity of the address	A18SE (N)	434	-	380805 411074
191	Contemporary Trade Directory Entries Name: Tesco Petrol Station Location: Petrol Station, Woodfields Retail Park, Peel Way, Bury, BL9 5BY Classification: Petrol Filling Stations Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SW (N)	436	-	380526 411068

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
192	Contemporary Trade Directory Entries Name: Ace Cars Ltd Location: 32, Heywood Street, Bury, BL9 7EA Classification: Car Dealers - Used Status: Active Positional Accuracy: Automatically positioned to the address	A14SW (SE)	441	-	381069 410360
193	Contemporary Trade Directory Entries Name: R R G Toyota Bury Location: 1 Bolton Street, Bury, Lancashire, BL9 0EY Classification: Car Dealers Status: Active Positional Accuracy: Manually positioned to the road within the address or location	A12NE (NW)	455	-	380133 410846
193	Contemporary Trade Directory Entries Name: Lgc Standards Proficiency Testing Location: 1, Chamberhall Business Park, Chamberhall Green, Bury, Lancashire, BL9 0AP Classification: Laboratories Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A12NE (NW)	480	-	380109 410856
194	Contemporary Trade Directory Entries Name: Castlecroft Motors Location: Bury, BL9 0LN Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A12NE (NW)	456	-	380158 410876
195	Contemporary Trade Directory Entries Name: Motor Claim Guru Ltd Location: 102, Rochdale Road, Bury, BL9 7AY Classification: Vehicle Inspection Services Status: Active Positional Accuracy: Automatically positioned to the address	A14NW (E)	475	-	381150 410736
195	Contemporary Trade Directory Entries Name: Alloy Junction Location: 111, Rochdale Road, Bury, Lancashire, BL9 7BA Classification: Alloys Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	496	-	381166 410767
195	Contemporary Trade Directory Entries Name: Bury Location: 113, Rochdale Road, Bury, Lancashire, BL9 7BA Classification: Air Conditioning Equipment & Systems Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	499	-	381169 410766
196	Contemporary Trade Directory Entries Name: Beldam Lascar Seals Ltd Location: Lascar Works, Tanpits Road, Bury, Lancashire, BL9 0LX Classification: Seal & Joint Manufacturers Status: Inactive Positional Accuracy: Automatically positioned in the proximity of the address	A18SW (NW)	486	-	380285 411005
197	Contemporary Trade Directory Entries Name: W H Tracey Location: Paradise Mill, John Street, Bury, Lancashire, BL9 0NH Classification: Recycling Centres Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SE (N)	491	-	380804 411134
198	Contemporary Trade Directory Entries Name: Horners Bury Ltd Location: Heywood Street, Bury, Lancashire, BL9 7DZ Classification: Car Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	500	-	381182 410646
198	Contemporary Trade Directory Entries Name: Boss Performance Location: Performance House, Heywood Street, Bury, Lancashire, BL9 7DZ Classification: Car Dealers - Used Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	500	-	381182 410646

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
198	Contemporary Trade Directory Entries Name: Carbargains.Co.Uk Location: Performance House, Heywood Street, Bury, Lancashire, BL9 7DZ Classification: Car Dealers - Used Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	500	-	381182 410646
198	Contemporary Trade Directory Entries Name: M V P Vehicle Solutions Ltd Location: Performance House, Heywood Street, Bury, BL9 7DZ Classification: Car Dealers - Used Status: Active Positional Accuracy: Automatically positioned to the address	A14NW (E)	501	-	381182 410659
199	Contemporary Trade Directory Entries Name: Bury Van Spares Location: 16b Queen St, Bury, Lancashire, BL9 7BF Classification: Commercial Vehicle Servicing, Repairs, Parts & Accessories Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A14NW (NE)	519	-	381173 410824
199	Contemporary Trade Directory Entries Name: Fisher Textiles Location: 18, Queen Street, Bury, Lancashire, BL9 7BF Classification: Textile Manufacturing Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	519	-	381173 410824
199	Contemporary Trade Directory Entries Name: Woodlands Garage Location: 16, Queen Street, Bury, Lancashire, BL9 7BF Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	519	-	381173 410824
199	Contemporary Trade Directory Entries Name: A P Scanlon Location: Croft Street Garage, Croft Street, Bury, Lancashire, BL9 7BG Classification: Mot Testing Centres Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	534	-	381190 410821
199	Contemporary Trade Directory Entries Name: Hygienix Services Location: Brenton Business Complex, Bond St, Bury, Lancashire, BL9 7BE Classification: Laboratories Status: Inactive Positional Accuracy: Manually positioned to the address or location	A14NW (E)	545	-	381210 410790
199	Contemporary Trade Directory Entries Name: Print Express International Ltd Location: Unit 6, Brenton Business Complex, Bond Street, Bury, Lancashire, BL9 7BE Classification: Printers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A14NW (E)	548	-	381212 410797
199	Contemporary Trade Directory Entries Name: D R M Industrial Fabrics Ltd Location: Bond Street, Bury, Lancashire, BL9 7BE Classification: Filter Manufacturers & Suppliers Status: Active Positional Accuracy: Automatically positioned to the address	A14NW (E)	549	-	381212 410797
199	Contemporary Trade Directory Entries Name: Bentwoods Location: Bond Street, Bury, Lancashire, BL9 7BE Classification: Clothing & Fabrics - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	549	-	381212 410797
199	Contemporary Trade Directory Entries Name: Trenslo Ltd Location: Bond Street, Bury, Lancashire, BL9 7BE Classification: Textile Manufacturing Status: Inactive Positional Accuracy: Manually positioned to the address or location	A14NW (E)	549	-	381212 410797
199	Contemporary Trade Directory Entries Name: Chase Connect Ltd Location: 12 Croft St, Bury, Lancashire, BL9 7BG Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14NW (NE)	560	-	381212 410836

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
199	Contemporary Trade Directory Entries Name: N A Tyres Location: Croft Street, Bury, Lancashire, BL9 7BG Classification: Tyre Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	581	-	381239 410821
199	Contemporary Trade Directory Entries Name: V W Auto Location: Croft Street, Bury, Lancashire, BL9 7BG Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	581	-	381239 410821
200	Contemporary Trade Directory Entries Name: Fishpool Gas & Bathroom Centre Location: Unit 2, York Street Mill, York Street, Bury, BL9 7AR Classification: Boilers - Servicing, Replacements & Repairs Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	519	-	381132 410916
200	Contemporary Trade Directory Entries Name: Swinnerton Bros Ltd Location: York Street Mill, York Street, Bury, Lancashire, BL9 7AR Classification: Recycling Centres Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	519	-	381132 410916
200	Contemporary Trade Directory Entries Name: Swinnerton Environmental Ltd Location: York Street Mill, York Street, BURY, Lancashire, BL9 7AR Classification: Recycling Centres Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	519	-	381132 410916
201	Contemporary Trade Directory Entries Name: One Athletic Location: Inwood House, 5, Castlecroft Road, Bury, BL9 0LN Classification: Textile Manufacturing Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NE (NW)	531	-	380071 410890
202	Contemporary Trade Directory Entries Name: Rothwell Creative Print Location: Heywood St, Bury, Lancashire, BL9 7DY Classification: Printers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14NW (E)	536	-	381217 410686
203	Contemporary Trade Directory Entries Name: Horological Solvents Location: 194, Wellington Road, Bury, Lancashire, BL9 9AH Classification: Chemical Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A9NW (SE)	539	-	380929 410055
204	Contemporary Trade Directory Entries Name: Comet Group Plc Location: Unit D, Moorgate Retail Park, Bury, Lancashire, BL9 7AQ Classification: Electrical Goods Sales, Manufacturers & Wholesalers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	541	-	381001 411095
204	Contemporary Trade Directory Entries Name: Comet Location: Unit D, Moorgate Retail Park, Bury, Lancashire, BL9 7AQ Classification: Electrical Goods Sales, Manufacturers & Wholesalers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	541	-	381001 411095
205	Contemporary Trade Directory Entries Name: Currys Location: Woodfields Retail Park, Peel Way, BURY, Lancashire, BL9 5BY Classification: Electrical Goods Sales, Manufacturers & Wholesalers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18SW (N)	541	-	380545 411183
206	Contemporary Trade Directory Entries Name: Riley Location: Locomotive Works, Baron Street, Bury, Lancashire, BL9 0TY Classification: Railways Status: Inactive Positional Accuracy: Automatically positioned to the address	A12SE (SW)	555	-	380009 410276

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
207	Contemporary Trade Directory Entries Name: Phil Swire Ltd Location: Britannia Foundry, Croft Street, Bury, Lancashire, BL9 7BG Classification: Woodworking Machinery Status: Inactive Positional Accuracy: Manually positioned to the address or location	A14NW (NE)	562	-	381209 410854
207	Contemporary Trade Directory Entries Name: Impact Location: 3 Fountain Street North, Bury, Lancashire, BL9 7AN Classification: Garage Services Status: Active Positional Accuracy: Manually positioned to the address or location	A14NW (NE)	564	-	381197 410885
207	Contemporary Trade Directory Entries Name: M A M O T Centre Location: Manor Street, Bury, Lancashire, BL9 7BL Classification: Mot Testing Centres Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	613	-	381242 410907
207	Contemporary Trade Directory Entries Name: B M S Precision Engineering Ltd Location: Back Manor Street, Bury, Lancashire, BL9 7BN Classification: Precision Engineers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	613	-	381242 410907
207	Contemporary Trade Directory Entries Name: M A Auto Centres Ltd Location: Manor Street, Bury, Lancashire, BL9 7BL Classification: Mot Testing Centres Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (NE)	613	-	381242 410907
208	Contemporary Trade Directory Entries Name: Currys Pc World Location: Unit 5, Woodfields Retail Park, Peel Way, BURY, Lancashire, BL9 5BY Classification: Electrical Goods Sales, Manufacturers & Wholesalers Status: Active Positional Accuracy: Manually positioned to the address or location	A18SW (N)	565	-	380438 411173
209	Contemporary Trade Directory Entries Name: Sultan Style Location: The Warehouse, 53, Ormrod Street, Bury, BL9 7HF Classification: Clothing & Fabrics - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NW (E)	566	-	381247 410644
209	Contemporary Trade Directory Entries Name: Polytex Location: The Warehouse, 53, Ormrod Street, Bury, Lancashire, BL9 7HF Classification: Machine Shops Status: Active Positional Accuracy: Automatically positioned to the address	A14NW (E)	566	-	381247 410644
210	Contemporary Trade Directory Entries Name: Riley & Son Engineering Location: East Lancs Loco Works, Baron Street, Bury, Lancashire, BL9 0TY Classification: Engineers - General Status: Active Positional Accuracy: Manually positioned within the geographical locality	A7NE (SW)	571	-	380053 410172
211	Contemporary Trade Directory Entries Name: G T Motors Location: 2, York Street, Bury, Lancashire, BL9 7AR Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned in the proximity of the address	A19SW (NE)	577	-	381137 411013
212	Contemporary Trade Directory Entries Name: All Glass & Mirrors Location: Acorn Business Centre, Fountain St North, Bury, Lancashire, BL9 7HL Classification: Mirrors & Decorative Glass Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19SW (NE)	584	-	381182 410960
212	Contemporary Trade Directory Entries Name: James Street Motors Location: Unit 3, Fountain St North, Bury, Lancashire, BL9 7AN Classification: Mot Testing Centres Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19SW (NE)	604	-	381187 410988

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
212	Contemporary Trade Directory Entries Name: J S M M O T & Servicing Centre Location: Unit 3 Britannia Mill, Fountain Street North, Bury, Lancashire, BL9 7AN Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality	A19SW (NE)	617	-	381200 410993
212	Contemporary Trade Directory Entries Name: The Tyre Yard Location: The Tyre Yard, Fountain Street North, Bury, Lancashire, BL9 7AN Classification: Tyre Dealers Status: Active Positional Accuracy: Manually positioned within the geographical locality	A19SW (NE)	617	-	381200 410993
212	Contemporary Trade Directory Entries Name: Atlantis Traders Uk Ltd Location: Office 2 Acorn Business Centre, Fountain Street North, Bury, Lancashire, BL9 7AN Classification: Car Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A19SW (NE)	620	-	381198 411001
213	Contemporary Trade Directory Entries Name: The Cleaning Machine Ltd Location: 16, Prestbury Close, Bury, Lancashire, BL9 9DY Classification: Carpet, Curtain & Upholstery Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A9NW (SE)	587	-	381022 410065
214	Contemporary Trade Directory Entries Name: Bury Diesels Location: Manor St, Bury, Lancashire, BL9 7BL Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14NW (NE)	604	-	381238 410892
214	Contemporary Trade Directory Entries Name: Fine Line Engineering Location: Manor St, Bury, Lancashire, BL9 7BL Classification: Engineering Machine Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14NW (NE)	607	-	381242 410892
214	Contemporary Trade Directory Entries Name: Swire Location: Manor Street, Bury, Lancashire, BL9 7BG Classification: Woodworking Machinery Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14NW (NE)	616	-	381251 410892
214	Contemporary Trade Directory Entries Name: James G Carrick & Co Ltd Location: Manor Street, BURY, Lancashire, BL9 7BL Classification: Steel Manufacturers Status: Active Positional Accuracy: Automatically positioned to the address	A14NE (NE)	618	-	381267 410854
214	Contemporary Trade Directory Entries Name: Tyre Station Bury Location: Manor Street, Bury, Lancashire, BL9 7BL Classification: Tyre Dealers Status: Active Positional Accuracy: Manually positioned to the road within the address or location	A14NW (NE)	619	-	381255 410891
214	Contemporary Trade Directory Entries Name: Starider Cars Location: Unit 2, Manor St, Bury, Lancashire, BL9 7BL Classification: Breakdown and Recovery Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14NW (NE)	624	-	381261 410890
214	Contemporary Trade Directory Entries Name: Bury Diesels Location: Manor Street, Bury, Lancashire, BL9 7BL Classification: Diesel Engine Equipment & Services Status: Active Positional Accuracy: Automatically positioned to the address	A14NE (NE)	631	-	381264 410902

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
214	Contemporary Trade Directory Entries Name: Bury Diesels Location: Manor Street, Bury, Lancashire, BL9 7BL Classification: Diesel Engine Equipment & Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NE (NE)	631	-	381264 410902
215	Contemporary Trade Directory Entries Name: Victorian Gates Location: 45, Kershaw Street, Bury, Lancashire, BL9 7HH Classification: Gate Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NE (E)	606	-	381286 410691
215	Contemporary Trade Directory Entries Name: Rothwell Creative Print Location: 61a, Kershaw Street, Bury, Lancashire, BL9 7HH Classification: Printers Status: Inactive Positional Accuracy: Automatically positioned in the proximity of the address	A14NE (E)	619	-	381299 410691
216	Contemporary Trade Directory Entries Name: Tesco Garage Location: Woodfields Retail Park, Peel Way, Bury, Lancashire, BL9 5BY Classification: Petrol Filling Stations - 24 Hour Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	606	-	380570 411256
217	Contemporary Trade Directory Entries Name: J Rigg Location: Carlyle St, Bury, Lancashire, BL9 0JJ Classification: Car Painters & Sprayers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A17SE (NW)	622	-	380042 410995
218	Contemporary Trade Directory Entries Name: Kih Design Location: Flat 9, Ferndale Mews, 1, Marsden Street, Bury, Lancashire, BL9 5BX Classification: Greeting Card Publishers & Wholesalers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	628	-	380714 411286
218	Contemporary Trade Directory Entries Name: Wickes Location: Moor Street, Bury, Lancashire, BL9 5AQ Classification: Builders' Merchants Status: Active Positional Accuracy: Automatically positioned to the address	A18NE (N)	640	-	380740 411295
219	Contemporary Trade Directory Entries Name: Fosters Blinds Location: 48, Moorgate, Bury, Lancashire, BL9 7AF Classification: Blinds, Awnings & Canopies Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	634	-	381040 411182
220	Contemporary Trade Directory Entries Name: Bike Tyres 247 Location: 15, James Street, Bury, BL9 7EG Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	643	-	381304 410433
220	Contemporary Trade Directory Entries Name: Tyre Base Location: 15, James Street, Bury, Lancashire, BL9 7EG Classification: Tyre Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	645	-	381310 410450
220	Contemporary Trade Directory Entries Name: Bury Body Centre Location: 27-29, JAMES STREET, BURY, BL9 7EG Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	650	-	381305 410405
220	Contemporary Trade Directory Entries Name: Waste Recycling Management Location: 50 Hurst St, Bury, Lancashire, BL9 7ES Classification: Reclaiming - Waste Products Status: Inactive Positional Accuracy: Manually positioned to the address or location	A14SE (E)	670	-	381337 410460

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
221	Contemporary Trade Directory Entries Name: Stendown Composites Ltd Location: James St, Bury, Lancashire, BL9 7EG Classification: Packaging & Wrapping Equipment & Supplies Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	646	-	381290 410364
221	Contemporary Trade Directory Entries Name: Jill Location: Unit 7 James St, Bury, Lancashire, BL9 7EG Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	647	-	381290 410360
221	Contemporary Trade Directory Entries Name: Eas Technology Ltd Location: James St, Bury, Lancashire, BL9 7EG Classification: Electronic Equipment - Manufacturers & Assemblers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	653	-	381286 410330
221	Contemporary Trade Directory Entries Name: Surestart Motors Location: James Street, Bury, BL9 7EG Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	672	-	381312 410345
221	Contemporary Trade Directory Entries Name: The Car Repair Centre Location: Beach House, James Street, Bury, Lancashire, BL9 7EG Classification: Car Breakdown & Recovery Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	694	-	381330 410331
221	Contemporary Trade Directory Entries Name: A One Distribution Location: Hardware House, James Street, Bury, Lancashire, BL9 7EG Classification: Electronic Component Manufacturers & Distributors Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	694	-	381330 410331
221	Contemporary Trade Directory Entries Name: Clough Mill Ltd Location: Beech Mill, James Street, Bury, Lancashire, BL9 7EQ Classification: Textile Manufacturing Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	694	-	381330 410331
221	Contemporary Trade Directory Entries Name: A One Distributions (Uk) Ltd Location: Hardware House, James Street, Bury, Lancashire, BL9 7EG Classification: Hardware Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	694	-	381330 410331
221	Contemporary Trade Directory Entries Name: Software Solutions Location: Hardware House, James Street, BURY, Lancashire, BL9 7EG Classification: Cash Registers & Check-Out Equipment Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	694	-	381330 410331
221	Contemporary Trade Directory Entries Name: Select Motor Spares Bury Ltd Location: Unit 11, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Car Breakers & Dismantlers Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	721	-	381358 410331
222	Contemporary Trade Directory Entries Name: Abbico Ltd Location: Woodstreet Mill, Bury, Lancashire, BL9 7EG Classification: Commercial Cleaning Services Status: Active Positional Accuracy: Manually positioned within the geographical locality	A14SE (E)	648	-	381270 410302
222	Contemporary Trade Directory Entries Name: Design A Frame Location: James St, Bury, Lancashire, BL9 7EG Classification: Window Frame Manufacturers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14SE (SE)	670	-	381283 410276

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
223	Contemporary Trade Directory Entries Name: D2d Xpress Location: Europa House, Barcroft Street, Bury, Lancashire, BL9 5BT Classification: Freight Forwarders Status: Inactive Positional Accuracy: Manually positioned to the address or location	A18NE (N)	655	-	380616 411311
223	Contemporary Trade Directory Entries Name: John Caunt Scientific Ltd Location: Europa House, 79-81, Barcroft Street, Bury, BL9 5BT Classification: Scientific Apparatus & Instruments - Manufacturers Status: Active Positional Accuracy: Automatically positioned to the address	A18NE (N)	655	-	380616 411311
223	Contemporary Trade Directory Entries Name: Brand Idol Location: Europa House, 79-81, Barcroft Street, Bury, BL9 5BT Classification: Printers Status: Active Positional Accuracy: Automatically positioned to the address	A18NE (N)	655	-	380616 411311
223	Contemporary Trade Directory Entries Name: Senior Waste Removals Ltd Location: EUROPA HOUSE, BARCROFT STREET, BURY, BL9 5BT Classification: Waste Disposal Services Status: Active Positional Accuracy: Automatically positioned to the address	A18NE (N)	655	-	380616 411311
223	Contemporary Trade Directory Entries Name: American & Efird (Gb) Ltd Location: Suite 34, Europa House, 79-81, Barcroft Street, Bury, BL9 5BT Classification: Sewing Thread Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	655	-	380616 411311
223	Contemporary Trade Directory Entries Name: Spectrum Automation Ltd Location: Europa House, Barcroft Street, Bury, Lancashire, BL9 5BT Classification: Automation Systems & Equipment Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	655	-	380616 411311
223	Contemporary Trade Directory Entries Name: United Global Services Ltd Location: Europa House, Barcroft Street, Bury, Lancashire, BL9 5BT Classification: Freight Forwarders Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	656	-	380616 411311
223	Contemporary Trade Directory Entries Name: The Moseley Rubber Co Ltd Location: Europa House, Barcroft Street, Bury, Lancashire, BL9 5BT Classification: Rubber & Plastic Products - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	656	-	380616 411311
223	Contemporary Trade Directory Entries Name: Global Telecom & Technology Ltd Location: Europa House, Barcroft Street, Bury, Lancashire, BL9 5BT Classification: Telecommunications Equipment & Systems Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	656	-	380616 411311
223	Contemporary Trade Directory Entries Name: Wells Water Treatment Services Location: Europa House, Barcroft Street, Bury, Lancashire, BL9 5BT Classification: Hygiene & Cleansing Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	656	-	380616 411311
223	Contemporary Trade Directory Entries Name: Easy Care Ltd Location: Europa House, Barcroft Street, Bury, Lancashire, BL9 5BT Classification: Cleaning Services - Domestic Status: Inactive Positional Accuracy: Manually positioned to the address or location	A18NE (N)	656	-	380616 411311
223	Contemporary Trade Directory Entries Name: Haywood Materials Handling Ltd Location: Europa House, Barcroft Street, Bury, Lancashire, BL9 5BT Classification: Plastics - Machinery & Equipment Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	656	-	380616 411311

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
223	Contemporary Trade Directory Entries Name: Dealerprint Location: Europa House, Barcroft Street, Bury, Lancashire, BL9 5BT Classification: Printers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	656	-	380616 411311
224	Contemporary Trade Directory Entries Name: P & F Motors Location: Cork Street, Bury, BL9 7BW Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A19SE (NE)	660	-	381286 410923
225	Contemporary Trade Directory Entries Name: A1 Cavity Wall Ties Location: 175, Rochdale Road, Bury, Lancashire, BL9 7BB Classification: Damp & Dry Rot Control Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NE (E)	662	-	381336 410756
226	Contemporary Trade Directory Entries Name: Norwest Environmental Ltd Location: Peter Street, Bury, Lancashire, BL9 6AB Classification: Air Conditioning & Refrigeration Contractors Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	673	-	380968 411268
226	Contemporary Trade Directory Entries Name: Craffity Location: 5-7 Peter Street, Bury, Lancashire, BL9 6AB Classification: Ceramic Manufacturers, Supplies & Services Status: Active Positional Accuracy: Manually positioned within the geographical locality	A19NW (NE)	697	-	381009 411274
227	Contemporary Trade Directory Entries Name: Heselwood Garage Location: Buckley St, Bury, Lancashire, BL9 5BZ Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A18NE (N)	673	-	380832 411314
228	Contemporary Trade Directory Entries Name: Harrison Sorrell & Co Location: 86, Tenterden Street, Bury, Lancashire, BL9 0HQ Classification: Meat - Wholesale Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	674	-	379826 410672
229	Contemporary Trade Directory Entries Name: Belec Location: 39, Walmersley Road, Bury, Lancashire, BL9 5AE Classification: Domestic Appliances - Servicing, Repairs & Parts Status: Active Positional Accuracy: Automatically positioned to the address	A18NE (NE)	675	-	380908 411294
229	Contemporary Trade Directory Entries Name: Walmersley Trade Centre Location: Buckley Street, Bury, BL9 5AF Classification: Car Dealers - Used Status: Active Positional Accuracy: Automatically positioned to the address	A18NE (N)	707	-	380869 411340
229	Contemporary Trade Directory Entries Name: Rs Commercials Location: Washington Street, Bury, Lancashire, BL9 5BZ Classification: Commercial Vehicle Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	711	-	380890 411338
229	Contemporary Trade Directory Entries Name: Charisma Shades Location: 55-57, Walmersley Road, Bury, Lancashire, BL9 5AE Classification: Blinds, Awnings & Canopies Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	718	-	380903 411341
229	Contemporary Trade Directory Entries Name: Geldard'S Location: 60, Walmersley Road, Bury, Lancashire, BL9 6DP Classification: Dry Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	731	-	380937 411343

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
229	Contemporary Trade Directory Entries Name: Geldard'S Location: 60, Walmersley Road, Bury, Lancashire, BL9 6DP Classification: Dry Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	731	-	380937 411343
230	Contemporary Trade Directory Entries Name: D S Commercials Location: Unit 1, Britannia Warehouse, Ormond Street, Bury, BL9 7AJ Classification: Caravans - Servicing & Repairs Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	677	-	381203 411090
230	Contemporary Trade Directory Entries Name: Acethorn Ltd Location: Unit 2, Britannia Warehouse, Ormond Street, Bury, Lancashire, BL9 7AJ Classification: Chemicals - Distributors & Wholesalers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	677	-	381203 411090
230	Contemporary Trade Directory Entries Name: F 1 M O T Centre Location: Unit 4, Britannia Warehouse, Ormond Street, Bury, Lancashire, BL9 7AJ Classification: Tyre Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	677	-	381203 411090
230	Contemporary Trade Directory Entries Name: Bury Renault Centre Location: Unit 1, Britannia Warehouse, Ormond Street, Bury, Lancashire, BL9 7AJ Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	677	-	381203 411090
230	Contemporary Trade Directory Entries Name: Bury Renault Centre Location: Unit 1, Britannia Warehouse, Ormond Street, Bury, Lancashire, BL9 7AJ Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	677	-	381203 411090
230	Contemporary Trade Directory Entries Name: D S Commercials Location: Unit 1, Britannia Warehouse, Ormond Street, Bury, Lancashire, BL9 7AJ Classification: Commercial Vehicle Bodybuilders & Repairers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	677	-	381203 411090
230	Contemporary Trade Directory Entries Name: Tommy'S Location: Britannia Warehouse, Ormond Street, Bury, Lancashire, BL9 7AJ Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	677	-	381203 411090
230	Contemporary Trade Directory Entries Name: The M O T Centre Location: Unit 4, Britannia Warehouse, Ormond Street, Bury, BL9 7AJ Classification: Mot Testing Centres Status: Active Positional Accuracy: Automatically positioned to the address	A19SW (NE)	677	-	381203 411090
230	Contemporary Trade Directory Entries Name: F 1 Mot Centre Location: Unit 4, Britannia Warehouse, Ormond Street, Bury, BL9 7AJ Classification: Mot Testing Centres Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	677	-	381203 411090
231	Contemporary Trade Directory Entries Name: Zena - Holistic Therapist Location: 62, Andrew Street, Bury, Lancashire, BL9 7HB Classification: Pest & Vermin Control Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	680	-	381357 410529
232	Contemporary Trade Directory Entries Name: C & M Engineering Location: Workshop, Brook Street, Bury, BL9 6AH Classification: Precision Engineers Status: Active Positional Accuracy: Automatically positioned to the address	A19SW (NE)	683	-	381097 411200

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
232	Contemporary Trade Directory Entries Name: Reece Autobodies Location: Unit 1-2, Albert Works, Brook Street, Bury, Lancashire, BL9 6AH Classification: Car Body Repairs Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	723	-	381098 411249
232	Contemporary Trade Directory Entries Name: M & M Auto Centre Ltd Location: Unit 3, Albert Works, Brook Street, Bury, Lancashire, BL9 6AH Classification: Tyre Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	728	-	381125 411236
232	Contemporary Trade Directory Entries Name: Bury'S Finest Bin Cleaning Location: 14 Brook Street, Bury, Lancashire, BL9 6AH Classification: Hygiene & Cleansing Services Status: Active Positional Accuracy: Automatically positioned to the address	A19NW (NE)	758	-	381110 411283
232	Contemporary Trade Directory Entries Name: Moorside Garage Location: Moorside Garage, Brook Street, Bury, Lancashire, BL9 6AH Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	759	-	381120 411278
232	Contemporary Trade Directory Entries Name: Krupa Bros & Son Location: 14, Brook Street, Bury, Lancashire, BL9 6AH Classification: Wrought Ironwork Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	759	-	381120 411278
233	Contemporary Trade Directory Entries Name: Meggitt Electronics Location: Barcroft St, Bury, Lancashire, BL9 5BT Classification: Electronic Equipment - Manufacturers & Assemblers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A18NE (N)	685	-	380670 411344
233	Contemporary Trade Directory Entries Name: Kast Installations Location: Barcroft St, Bury, Lancashire, BL9 5BT Classification: Telecommunications Equipment & Systems Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A18NE (N)	685	-	380676 411344
233	Contemporary Trade Directory Entries Name: D M C Media Solutions Location: Charles Taylor General Adjusting Services Ltd, Imperial House, 79-81, Hornby Street, Bury, BL9 5BN Classification: Office Equipment Servicing & Maintenance Status: Active Positional Accuracy: Automatically positioned to the address	A18NE (N)	714	-	380675 411373
233	Contemporary Trade Directory Entries Name: Scrap Cars Vans Caravans Buyer Location: Imperial House, 79-81, Hornby Street, Bury, Lancashire, BL9 5BN Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	715	-	380657 411373
233	Contemporary Trade Directory Entries Name: Simarco International Location: 79-81, Hornby Street, Bury, BL9 5BN Classification: Freight Forwarders Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	715	-	380657 411373
233	Contemporary Trade Directory Entries Name: Kodak Location: Tile Street, Bury, Lancashire, BL9 5BR Classification: Photographic Processors Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	715	-	380657 411373

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
234	Contemporary Trade Directory Entries Name: Bury Vehicle Repair & Tyre Centre Ltd Location: 50, Wash Lane, Bury, Lancashire, BL9 6AS Classification: Mot Testing Centres Status: Active Positional Accuracy: Manually positioned to the address or location	A19SW (NE)	688	-	381255 411038
234	Contemporary Trade Directory Entries Name: Finesse Chemdry Location: 50a, Wash Lane, Bury, Lancashire, BL9 6AS Classification: Carpet, Curtain & Upholstery Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	688	-	381255 411038
234	Contemporary Trade Directory Entries Name: Ck Plastics Location: 50a, Wash Lane, Bury, Lancashire, BL9 6AS Classification: Builders' Merchants Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	688	-	381255 411038
234	Contemporary Trade Directory Entries Name: Wash Lane Car Sales Location: Topley House, 52, Wash Lane, Bury, BL9 6AS Classification: Car Dealers - Used Status: Active Positional Accuracy: Automatically positioned to the address	A19SE (NE)	692	-	381275 411013
234	Contemporary Trade Directory Entries Name: A L Bio Services Location: Topley House, 52, Wash Lane, Bury, BL9 6AS Classification: Laboratories Status: Active Positional Accuracy: Automatically positioned to the address	A19SE (NE)	698	-	381287 411006
234	Contemporary Trade Directory Entries Name: Bury Office Furniture Location: Topley House, 52, Wash Lane, Bury, BL9 6AS Classification: Office Furniture & Equipment Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SE (NE)	698	-	381287 411006
235	Contemporary Trade Directory Entries Name: L Mortimer (Bury) Ltd Location: Birch St, Bury, Lancs, BL9 5AL Classification: Crane Hire, Sales & Service Status: Inactive Positional Accuracy: Manually positioned to the address or location	A18NE (N)	696	-	380776 411348
235	Contemporary Trade Directory Entries Name: Advanced Automotive Location: Charles Street, Bury, Lancashire, BL9 5AJ Classification: Commercial Vehicle Servicing, Repairs, Parts & Accessories Status: Active Positional Accuracy: Manually positioned within the geographical locality	A18NE (N)	697	-	380777 411349
235	Contemporary Trade Directory Entries Name: D W Fabrications Ltd Location: Charles Street, Bury, Lancashire, BL9 5AJ Classification: Sheet Metal Work Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	697	-	380777 411349
235	Contemporary Trade Directory Entries Name: Recycling Lives Location: Birch Street, Bury, Lancashire, BL9 5AL Classification: Recycling Services Status: Active Positional Accuracy: Manually positioned to the address or location	A18NE (N)	742	-	380793 411392
235	Contemporary Trade Directory Entries Name: L Mortimer (Bury) Ltd Location: Birch Street, Bury, BL9 5AL Classification: Crane Hire, Sales & Service Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	746	-	380788 411396
236	Contemporary Trade Directory Entries Name: Highgrove Contract Furniture Location: Unit 3, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Seating Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	701	-	380384 411298

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
236	Contemporary Trade Directory Entries Name: Bainbridge G R P Location: Unit 3, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Glass Fibre Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	701	-	380384 411298
236	Contemporary Trade Directory Entries Name: Excel Trade Frames Ltd Location: Unit 3, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Window Frame Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	701	-	380384 411298
236	Contemporary Trade Directory Entries Name: P M Hardware Ltd Location: Unit 2, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Builders' Merchants Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	703	-	380376 411297
236	Contemporary Trade Directory Entries Name: Alfred W Perry (Printers) Ltd Location: Unit 1, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Printers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	707	-	380369 411299
236	Contemporary Trade Directory Entries Name: Bury Optical Services Ltd Location: Unit 4, Peel Ind Est, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Optical Goods - Manufacturers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A18NW (N)	736	-	380381 411334
237	Contemporary Trade Directory Entries Name: Clean A Blind Location: 8, Bell Lane, Bury, Lancashire, BL9 6AR Classification: Blinds, Awnings & Canopies Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	702	-	381148 411183
238	Contemporary Trade Directory Entries Name: International Car Breakers Location: Unit 14, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Car Breakdown & Recovery Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	703	-	381360 410410
238	Contemporary Trade Directory Entries Name: J K Car Parts Location: Unit 14, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	703	-	381360 410410
238	Contemporary Trade Directory Entries Name: Northern Car Storage Ltd Location: Unit 15, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Breakdown and Recovery Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	704	-	381369 410448
238	Contemporary Trade Directory Entries Name: J S M Contracts Salvage Ltd Location: Unit 15, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Salvage Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	705	-	381369 410438
238	Contemporary Trade Directory Entries Name: International Breakers Location: Unit 14, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Salvage Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	723	-	381379 410401
239	Contemporary Trade Directory Entries Name: Robs Autos Location: Hornby Street, Bury, Lancashire, BL9 5AB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality	A18NE (N)	706	-	380722 411363

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
239	Contemporary Trade Directory Entries Name: Washington Garage Location: Hornby Street, Bury, BL9 5AB Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A18NE (N)	706	-	380722 411363
240	Contemporary Trade Directory Entries Name: T C R Supplies Ltd Location: Woodstreet Mill, James Street, Bury, BL9 7EG Classification: Commercial Vehicle Servicing, Repairs, Parts & Accessories Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	707	-	381332 410298
240	Contemporary Trade Directory Entries Name: Khan Auto Spares Location: Unit 12, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	729	-	381375 410357
240	Contemporary Trade Directory Entries Name: A 1 Marks Motor Spares Location: Unit 10, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	742	-	381376 410314
240	Contemporary Trade Directory Entries Name: 1st Call Breakers Location: Unit 10, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Classification: Car Breakers & Dismantlers Status: Active Positional Accuracy: Manually positioned to the address or location	A14SE (E)	742	-	381376 410314
240	Contemporary Trade Directory Entries Name: Breaking Toyota'S Location: Unit 8, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Car Breakers & Dismantlers Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	751	-	381373 410282
241	Contemporary Trade Directory Entries Name: S B T Gears Location: Barnbrook Gear Works, Bury, Lancashire, BL9 6AF Classification: Electronic Component Manufacturers & Distributors Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	707	-	381049 411262
241	Contemporary Trade Directory Entries Name: D G Steel & Son Ltd Location: Barnbrook Boiler Works, Brook Street, Bury, Lancashire, BL9 6AF Classification: Engineers - General Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	723	-	381059 411275
241	Contemporary Trade Directory Entries Name: J & J Industrial Location: Barnbrook Boiler Works, Brook Street, Bury, Lancashire, BL9 6AF Classification: Gearboxes Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	723	-	381059 411275
242	Contemporary Trade Directory Entries Name: 4hands Cleaning Location: 27, Parkhills Road, Bury, Lancashire, BL9 9AS Classification: Commercial Cleaning Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A8SW (S)	713	-	380496 409777
242	Contemporary Trade Directory Entries Name: A J F Express Location: 24a, Parkhills Road, Bury, Lancashire, BL9 9AT Classification: Road Haulage Services Status: Inactive Positional Accuracy: Automatically positioned in the proximity of the address	A8SW (S)	760	-	380503 409729
243	Contemporary Trade Directory Entries Name: B M Auto Bodies Location: Church Street, Bury, BL9 6BN Classification: Car Body Repairs Status: Active Positional Accuracy: Automatically positioned to the address	A19SW (NE)	715	-	381204 411147

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
243	Contemporary Trade Directory Entries Name: Vivid Wheels Location: Star Works, Church Street, Bury, Lancashire, BL9 6BN Classification: Alloys Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	715	-	381204 411147
243	Contemporary Trade Directory Entries Name: Callaghan'S Location: Star Works, Church Street, Bury, BL9 6BN Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SW (NE)	723	-	381210 411152
243	Contemporary Trade Directory Entries Name: Cartime Location: Bell Lane, Bury, Lancashire, BL9 6AR Classification: Car Dealers - Used Status: Active Positional Accuracy: Automatically positioned to the address	A19SW (NE)	757	-	381233 411177
243	Contemporary Trade Directory Entries Name: Tdi Location: Star Houes, Bury, Lancashire, BL9 6BN Classification: Digital Printing Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A19SW (NE)	758	-	381245 411166
243	Contemporary Trade Directory Entries Name: J D M Garage Ltd Location: Church St, Bury, Lancashire, BL9 6BN Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A19SW (NE)	758	-	381245 411166
244	Contemporary Trade Directory Entries Name: Ola Cleaning Services Location: Unit 14, Brenton Business Complex, Bond Street, Bury, Lancashire, BL9 7BE Classification: Commercial Cleaning Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SE (NE)	721	-	381331 410971
244	Contemporary Trade Directory Entries Name: Business Utilities Uk Location: Unit 4, Brenton Business Complex, Bond Street, Bury, BL9 7BE Classification: Electricity Companies Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SE (NE)	721	-	381331 410971
244	Contemporary Trade Directory Entries Name: F W Engineering Ltd Location: Unit 13/15, Brenton Business Complex, Bond Street, Bury, Lancashire, BL9 7BE Classification: Electrical Engineers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SE (NE)	721	-	381331 410971
244	Contemporary Trade Directory Entries Name: Impact Automotive Services Ltd Location: Unit 1, Brenton Business Complex, Bond Street, Bury, Lancashire, BL9 7BE Classification: Electronic Equipment - Manufacturers & Assemblers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SE (NE)	721	-	381331 410971
245	Contemporary Trade Directory Entries Name: Rrg Toyota Location: Bolton Street, Bury, Lancashire, BL9 0EY Classification: Car Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (NW)	729	-	379847 410907
245	Contemporary Trade Directory Entries Name: R R G Bury Location: 1, Bolton Street, Bury, Lancashire, BL9 0EY Classification: Car Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A12NW (NW)	729	-	379847 410907

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
246	Contemporary Trade Directory Entries Name: Autospare Location: Tile Street, Bury, Lancashire, BL9 5BR Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	730	-	380594 411384
246	Contemporary Trade Directory Entries Name: A1 Van Breakers Location: Tile Street, Bury, Lancashire, BL9 5BR Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	730	-	380594 411384
246	Contemporary Trade Directory Entries Name: A1 4x4 Breakers Location: Yard 3, Tile St, Bury, Lancashire, BL9 5BR Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A18NE (N)	736	-	380597 411390
246	Contemporary Trade Directory Entries Name: Autospare Location: Woodfield Mill, 2, Tile Street, Bury, Lancashire, BL9 5BR Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned in the proximity of the address	A18NE (N)	741	-	380593 411395
246	Contemporary Trade Directory Entries Name: Recycled Motor Salvage Ltd Location: Tile Street, Bury, Lancashire, BL9 5BR Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	743	-	380564 411393
246	Contemporary Trade Directory Entries Name: Agfachrome Processing Location: Tile St, Bury, Lancashire, BL9 5BR Classification: Photographic Processors Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A18NE (N)	745	-	380606 411400
246	Contemporary Trade Directory Entries Name: Autospare Location: Tile St, Bury, Lancashire, BL9 5BR Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A18NE (N)	747	-	380607 411402
246	Contemporary Trade Directory Entries Name: Recycle Motor Spares Ltd Location: Unit 2, Tile Street, Bury, BL9 5BR Classification: Salvage Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	757	-	380567 411407
246	Contemporary Trade Directory Entries Name: A1 4x4 Breakers Location: Tile St, Bury, Lancashire, BL9 5BR Classification: Commercial Vehicle Servicing, Repairs, Parts & Accessories Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A18NW (N)	765	-	380575 411417
246	Contemporary Trade Directory Entries Name: Ian Smith A 1 Vans Location: Woodfield Mill, 2, Tile Street, Bury, BL9 5BR Classification: Salvage Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	765	-	380574 411417
246	Contemporary Trade Directory Entries Name: Peel Garage Location: Woodfield Mill, 2, Tile Street, Bury, Lancashire, BL9 5BR Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the address or location	A18NW (N)	765	-	380575 411417
246	Contemporary Trade Directory Entries Name: Origin Printing Ltd Location: 6, Fernhill Street, Bury, Lancashire, BL9 5BG Classification: Printers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	765	-	380575 411417

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
246	Contemporary Trade Directory Entries Name: A1 British 4x4 Specialists Location: Unit 4 Fernhill Street, Bury, Lancashire, BL9 5BG Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality	A18NW (N)	765	-	380575 411417
246	Contemporary Trade Directory Entries Name: A1 Landrover Breakers Location: Tile St, Bury, Lancashire, BL9 5BR Classification: Scrap Yards Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A18NW (N)	765	-	380575 411417
247	Contemporary Trade Directory Entries Name: Charisma Cars Location: Millett St, Bury, Lancashire, BL9 0JA Classification: Classic Car Specialists Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A12NW (W)	730	-	379803 410808
247	Contemporary Trade Directory Entries Name: Triple R Tuning Location: Millett St, Bury, Lancs, BL9 0JA Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A12NW (W)	734	-	379802 410816
248	Contemporary Trade Directory Entries Name: Regency Gates & Railings Location: Badger St, Bury, Lancashire, BL9 6AD Classification: Gate Manufacturers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19NW (NE)	730	-	381018 411306
249	Contemporary Trade Directory Entries Name: Polyfilm Manufacturing Location: 1, Fountain Street, Bury, Lancashire, BL9 7HL Classification: Packaging & Wrapping Equipment & Supplies Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	733	-	381412 410563
249	Contemporary Trade Directory Entries Name: Star Breakers Of Bury Location: Scrap Yard, Pimhole Road, Bury, Lancashire, BL9 7EY Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned in the proximity of the address	A14NE (E)	747	-	381427 410575
250	Contemporary Trade Directory Entries Name: Qualisure Location: Birch St, Bury, Lancashire, BL9 5AL Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A18NE (N)	751	-	380774 411404
250	Contemporary Trade Directory Entries Name: T S H Garden Machinery Location: 104, Hornby Street, Bury, BL9 5BB Classification: Lawnmowers & Garden Machinery - Sales & Service Status: Active Positional Accuracy: Automatically positioned to the address	A18NE (N)	757	-	380716 411415
250	Contemporary Trade Directory Entries Name: Re-Trac Services Location: 40, Birch Street, Bury, Lancashire, BL9 5AL Classification: Waste Disposal Services Status: Inactive Positional Accuracy: Manually positioned to the address or location	A18NE (N)	761	-	380752 411416
251	Contemporary Trade Directory Entries Name: United Breakers Location: Roach Bank Mill, Pimhole Road, Bury, Lancashire, BL9 7EY Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	752	-	381429 410537
251	Contemporary Trade Directory Entries Name: Buster Cases Location: Unit 16/C, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Classification: Case Manufacturers Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	766	-	381441 410508

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
252	Contemporary Trade Directory Entries Name: Bury Auto Parts Location: Pimhole Fold, Bury, Lancashire, BL9 7ET Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A14SE (E)	752	-	381420 410459
252	Contemporary Trade Directory Entries Name: Breaking Toyotas Ltd Location: Pimhole Fold, Bury, Lancashire, BL9 7ET Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A14SE (E)	752	-	381420 410459
252	Contemporary Trade Directory Entries Name: A C C S Ltd Location: Unit 3a, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Chemicals & Allied Products Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	782	-	381452 410470
252	Contemporary Trade Directory Entries Name: Discount Jap Spares Location: Pimhole Fold, Bury, Lancashire, BL9 7ET Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	784	-	381452 410450
252	Contemporary Trade Directory Entries Name: Bury Autowreckers Location: Pimhole Fold, Bury, Lancashire, BL9 7ET Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	784	-	381452 410450
252	Contemporary Trade Directory Entries Name: Khan Auto Spares Location: Pimhole Fold, Bury, Lancashire, BL9 7ET Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	784	-	381452 410450
252	Contemporary Trade Directory Entries Name: A1 Marks Motor Spares Location: Unit 10, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	784	-	381452 410450
252	Contemporary Trade Directory Entries Name: Walker Bros Services Ltd Location: Unit 3, Pimhole Business Park, Pimhole Road, BURY, Lancashire, BL9 7ET Classification: Cleaning Materials & Equipment Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	784	-	381452 410450
252	Contemporary Trade Directory Entries Name: Star Autos Transport Location: Pimhole Fold, Bury, Lancashire, BL9 7ET Classification: Road Haulage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	784	-	381452 410450
252	Contemporary Trade Directory Entries Name: Select Motor Spares Location: Pimhole Fold, Bury, Lancashire, BL9 7ET Classification: Salvage Dealers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A14SE (E)	785	-	381452 410450
253	Contemporary Trade Directory Entries Name: Agro Motors Location: Bottle Yard, Pimhole Rd, Bury, Lancashire, BL9 7EY Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14NE (E)	756	-	381436 410619
253	Contemporary Trade Directory Entries Name: Agro Motors Location: Pimhole Rd, Bury, Lancashire, BL9 7EY Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14NE (E)	759	-	381439 410612

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
253	Contemporary Trade Directory Entries Name: M G Salvage Location: Pimhole Fold, Bury, Lancashire, BL9 7ET Classification: Salvage Dealers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A14NE (E)	762	-	381442 410607
253	Contemporary Trade Directory Entries Name: Bury Salvage Location: 1, Pimhole Road, Bury, BL9 7EY Classification: Car Breakers & Dismantlers Status: Active Positional Accuracy: Automatically positioned to the address	A14NE (E)	767	-	381448 410642
254	Contemporary Trade Directory Entries Name: L & D Mortimer Location: Birch St, Bury, Lancashire, BL9 5AL Classification: Scrap Metal Merchants Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A18NE (N)	757	-	380802 411406
255	Contemporary Trade Directory Entries Name: Chips Away Location: Unit 8, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Car Body Repairs Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	760	-	380379 411359
255	Contemporary Trade Directory Entries Name: Reaction Design Location: Unit 10, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Tile Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	785	-	380378 411385
255	Contemporary Trade Directory Entries Name: Jg Fabrications Location: Unit 10, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Wrought Ironwork Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	785	-	380378 411385
256	Contemporary Trade Directory Entries Name: The Car Sales Company Location: Unit 2, Beech Mill, James Street, Bury, BL9 7EG Classification: Car Dealers - Used Status: Active Positional Accuracy: Automatically positioned to the address	A9NE (SE)	761	-	381359 410224
257	Contemporary Trade Directory Entries Name: Autobreakers Uk Location: Unit 14a, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Scrap Metal Merchants Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	761	-	381408 410358
258	Contemporary Trade Directory Entries Name: Volksmaster Location: Unit 3, Millett Street, Bury, Lancashire, BL9 0JA Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A12NW (W)	767	-	379780 410850
258	Contemporary Trade Directory Entries Name: Wipe Out All Round Location: Unit 3, Millett Street, Bury, BL9 0JA Classification: Alloys Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	767	-	379780 410850
258	Contemporary Trade Directory Entries Name: Prestige Auto Tints Location: Unit 3, Millett Street, Bury, Lancashire, BL9 0JA Classification: Window Tinting Status: Inactive Positional Accuracy: Manually positioned to the address or location	A12NW (W)	767	-	379780 410850

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
258	Contemporary Trade Directory Entries Name: M Brearley Motor Body Repairs Location: Unit 2, Millett Street, Bury, Lancashire, BL9 0JA Classification: Car Body Repairs Status: Active Positional Accuracy: Automatically positioned to the address	A12NW (W)	791	-	379773 410895
258	Contemporary Trade Directory Entries Name: Supertune Automotive Ltd Location: Millett House, Millett Street, Bury, Lancashire, BL9 0JA Classification: Car Body Repairs Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	791	-	379773 410895
258	Contemporary Trade Directory Entries Name: Charlie Browns Autocentres Location: Bolton Street, Bury, Lancashire, BL9 0HY Classification: Tyre Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A17SW (NW)	803	-	379777 410931
259	Contemporary Trade Directory Entries Name: Donisthorpe & Co Ltd Location: Peel Mills, Gordon Street, Bury, Lancashire, BL9 0LS Classification: Sewing Thread Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	772	-	380299 411340
259	Contemporary Trade Directory Entries Name: Astro Ltd Location: Peel Mills, Gordon Street, Bury, Lancashire, BL9 0LS Classification: Electronic Engineers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	772	-	380299 411340
259	Contemporary Trade Directory Entries Name: Astro Medical Systems Ltd Location: Peel Mills, Gordon Street, Bury, Lancashire, BL9 0LS Classification: X-Ray Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	772	-	380299 411340
259	Contemporary Trade Directory Entries Name: Mayplas Ltd Location: Peel Mills, Gordon Street, Bury, Lancashire, BL9 0LS Classification: Insulation Materials Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	772	-	380299 411340
260	Contemporary Trade Directory Entries Name: Car Sales Factory Location: Unit 3 Fern Street, Bury, Lancashire, BL9 5BP Classification: Car Dealers - Used Status: Active Positional Accuracy: Automatically positioned to the address	A18NE (N)	775	-	380634 411433
261	Contemporary Trade Directory Entries Name: Stanlan Roller Engineering (1987) Ltd Location: Badger Street, Bury, Lancashire, BL9 6AD Classification: Precision Engineers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	777	-	381136 411288
262	Contemporary Trade Directory Entries Name: G T Autospares Location: Unit 5, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Car Breakers & Dismantlers Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	788	-	381432 410342
262	Contemporary Trade Directory Entries Name: Autosave Location: Unit 6, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Scrap Metal Merchants Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	802	-	381438 410317
263	Contemporary Trade Directory Entries Name: Heap Bridge Garage Location: Bridge St, Bury, Lancashire, BL9 6HH Classification: Engine Rebuilding & Reconditioning Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19NW (NE)	796	-	381208 411255

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
264	Contemporary Trade Directory Entries Name: Carpet Maid Location: 57, Rutland Drive, Bury, Lancashire, BL9 9DR Classification: Carpet, Curtain & Upholstery Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A9SW (SE)	797	-	381149 409897
265	Contemporary Trade Directory Entries Name: Xtreme Breakers Location: Unit 7, Pimhole Business Park, Pimhole Road, Bury, Lancashire, BL9 7ET Classification: Car Breakers & Dismantlers Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	797	-	381408 410247
266	Contemporary Trade Directory Entries Name: J Clemishaw 1870 Ltd Location: 2 Fernhill Street, Bury, Lancashire, BL9 5BG Classification: Tarpaulins Status: Active Positional Accuracy: Manually positioned to the road within the address or location	A18NE (N)	799	-	380597 411454
266	Contemporary Trade Directory Entries Name: Wilcox Drums Ltd Location: Fernhill Works, Park Road, Bury, Lancashire, BL9 5BQ Classification: Drums, Kegs, Barrels & Casks Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	827	-	380580 411480
266	Contemporary Trade Directory Entries Name: J & M Location: Fernhill Works, Park Road, Bury, Lancashire, BL9 5BQ Classification: Waste Disposal Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	827	-	380580 411480
266	Contemporary Trade Directory Entries Name: N W T Service Centre Location: Unit 3 Fernhill Street, Bury, Lancashire, BL9 5BG Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality	A18NW (N)	828	-	380564 411479
266	Contemporary Trade Directory Entries Name: Scrap Your Car Bury Location: 4, Fernhill Street, Bury, BL9 5BG Classification: Car Breakers & Dismantlers Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	844	-	380558 411495
267	Contemporary Trade Directory Entries Name: Wyko Industrial Services Location: 1-7, Taylor Street, Bury, Lancashire, BL9 6DT Classification: Power Transmission Equipment Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	801	-	381069 411359
267	Contemporary Trade Directory Entries Name: Pest-Man.Com Location: Alexandra House, Suite 2, 1-7 Taylor St, Bury, Lancashire, BL9 6DT Classification: Pest & Vermin Control Status: Inactive Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	802	-	381075 411357
267	Contemporary Trade Directory Entries Name: Brook Street Motors Location: Taylor Street, Bury, Lancashire, BL9 6DT Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality	A19NW (NE)	820	-	381048 411392
268	Contemporary Trade Directory Entries Name: John Hesketh & Son Ltd Location: Castlecroft Ironworks, Bury Ground, Bury, Lancashire, BL9 0HU Classification: Blacksmiths & Forgemasters Status: Inactive Positional Accuracy: Automatically positioned to the address	A17SE (NW)	803	-	379985 411188
268	Contemporary Trade Directory Entries Name: James Cage Location: Castlecroft Ironworks, Bury Ground, Bury, Lancashire, BL9 0HU Classification: Road Haulage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A17SE (NW)	803	-	379985 411188

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
269	Contemporary Trade Directory Entries Name: Trumeter Location: Floor 4 Pilot Mill, Alfred Street, Bury, Lancashire, BL9 9EF Classification: Electronic Component Manufacturers & Distributors Status: Active Positional Accuracy: Manually positioned to the address or location	A9NW (SE)	803	-	381245 409980
270	Contemporary Trade Directory Entries Name: Parkhills Location: Manchester Road, BURY, Lancashire, BL9 9AZ Classification: Car Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A8SW (S)	813	-	380336 409706
270	Contemporary Trade Directory Entries Name: Ward Motor Bodies Location: Packhorse Garage, Rear Of Parkhills Rd, Bury, Lancashire, BL9 9AX Classification: Car Body Repairs Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A8SW (S)	816	-	380383 409692
270	Contemporary Trade Directory Entries Name: Johnsons Gas Services Ltd Location: 4b, Parkhills Road, Bury, Lancashire, BL9 9AX Classification: Fireplaces & Mantelpieces Status: Inactive Positional Accuracy: Automatically positioned to the address	A8SW (S)	843	-	380366 409669
270	Contemporary Trade Directory Entries Name: Fishpool Laundry Service Location: 2-4, Parkhills Road, Bury, Lancashire, BL9 9AX Classification: Laundries & Launderettes Status: Inactive Positional Accuracy: Automatically positioned to the address	A8SW (S)	846	-	380363 409666
271	Contemporary Trade Directory Entries Name: Parkhills Location: 18, Parkhills Road, Bury, Lancashire, BL9 9AX Classification: Laundries & Launderettes Status: Inactive Positional Accuracy: Automatically positioned to the address	A8SW (S)	821	-	380399 409684
272	Contemporary Trade Directory Entries Name: Carrick Signs Location: Unit 8, Bridge Trading Estate, Bolton Road, Bury, Lancashire, BL8 2AQ Classification: Printers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	824	-	379687 410742
272	Contemporary Trade Directory Entries Name: Archmaker Ltd Location: Unit 8, Bridge Trading Estate, Bolton Road, Bury, Lancashire, BL8 2AQ Classification: PVC-U Products - Manufacturers & Suppliers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	824	-	379687 410742
272	Contemporary Trade Directory Entries Name: Cemex Bury Plant Location: Bridge Trading Estate, Bolton Road, Ramsbottom, Bury, Lancashire, BL0 9NA Classification: Sand, Gravel & Other Aggregates Status: Active Positional Accuracy: Manually positioned within the geographical locality	A12NW (W)	830	-	379676 410717
272	Contemporary Trade Directory Entries Name: Ancora Associates Ltd Location: Albion Street, Bury, Lancashire, BL8 2AD Classification: Clothing & Fabrics - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	860	-	379647 410724
272	Contemporary Trade Directory Entries Name: Dition Corporate Clothing Ltd Location: Albion Street, Bury, Lancashire, BL8 2AD Classification: Clothing & Fabrics - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	860	-	379647 410724
272	Contemporary Trade Directory Entries Name: Bury Office Furniture Location: Albion Works, Albion Street, Bury, Lancashire, BL8 2AD Classification: Office Furniture & Equipment Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	860	-	379647 410724

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
273	Contemporary Trade Directory Entries Name: Tim Howarth Commercials Ltd Location: Richard Burch St, Bury, Lancashire, BL9 6DU Classification: Commercial Vehicle Dealers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19NW (NE)	827	-	381014 411416
274	Contemporary Trade Directory Entries Name: Bury Salvage Location: Unit 1, Pimhole Business Park, Pimhole Road, Bury, BL9 7ET Classification: Car Breakers & Dismantlers Status: Active Positional Accuracy: Automatically positioned to the address	A14SE (E)	834	-	381494 410406
274	Contemporary Trade Directory Entries Name: Star Breakers Of Bury Location: Unit 2 Pimhole Fold, Pimhole Road, Bury, Lancashire, BL9 7ET Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A14SE (E)	834	-	381494 410406
275	Contemporary Trade Directory Entries Name: Any Old Iron Location: 1, Brick Street, Bury, Lancashire, BL9 6AY Classification: Scrap Metal Merchants Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SE (NE)	835	-	381321 411195
275	Contemporary Trade Directory Entries Name: Swan Finishing Systems Location: Crescent Works, Bell La, Bury, Lancashire, BL9 6BA Classification: Oven Manufacturers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19SE (NE)	844	-	381316 411215
275	Contemporary Trade Directory Entries Name: Hobin Of Bury Location: Bell Lane, Bury, Lancashire, BL9 6HH Classification: Car Dealers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19SE (NE)	845	-	381315 411218
276	Contemporary Trade Directory Entries Name: Edma Location: Unit 16, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Builders' Tools & Equipment Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	836	-	380344 411427
276	Contemporary Trade Directory Entries Name: Fairway Products Location: Unit 17, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Sports Equipment Manufacturers & Distributors Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	860	-	380358 411457
276	Contemporary Trade Directory Entries Name: Callaghan'S Classics Location: Unit 17, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Classic Car Specialists Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	860	-	380358 411457
276	Contemporary Trade Directory Entries Name: Hy-Ram Engineering Location: Unit 18, Peel Industrial Estate, Chamberhall Street, Bury, BL9 0LU Classification: Engineers - General Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	871	-	380348 411466
276	Contemporary Trade Directory Entries Name: D B Cellular Products Ltd Location: Unit 18, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Distribution Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	872	-	380353 411468

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
276	Contemporary Trade Directory Entries Name: Rainbow International Location: Unit 18, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Carpet, Curtain & Upholstery Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	872	-	380353 411468
277	Contemporary Trade Directory Entries Name: Farnell Land Rover Location: Bell Lane, Bury, Lancashire, BL9 6DJ Classification: Car Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A19NE (NE)	837	-	381269 411255
277	Contemporary Trade Directory Entries Name: Bell Lane Car Centre Ltd Location: Bell Lane, Bury, Lancashire, BL9 6DJ Classification: Car Dealers - Used Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NE (NE)	837	-	381269 411255
277	Contemporary Trade Directory Entries Name: Mark Anthony Services Ltd Location: 61-65, Bell Lane, Bury, BL9 6BB Classification: Commercial Vehicle Servicing, Repairs, Parts & Accessories Status: Inactive Positional Accuracy: Automatically positioned to the address	A19SE (NE)	844	-	381300 411232
278	Contemporary Trade Directory Entries Name: Cemex Uk Location: Bridge Trading Estate, Bolton Road, Bury, Lancashire, BL8 2AQ Classification: Concrete & Mortar Ready Mixed Status: Active Positional Accuracy: Manually positioned within the geographical locality	A12NW (W)	844	-	379691 410832
279	Contemporary Trade Directory Entries Name: Auto Spares World Location: Park Road, Bury, Lancashire, BL9 5BQ Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	847	-	380498 411487
280	Contemporary Trade Directory Entries Name: Walkden Group Ltd Location: Unit 3, Bridge Trading Estate, Bolton Road, Bury, Lancashire, BL8 2AQ Classification: Commercial Cleaning Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	852	-	379690 410853
280	Contemporary Trade Directory Entries Name: Walkden Group Ltd Location: Unit 3, Bridge Trading Estate, Bolton Road, Bury, Lancashire, BL8 2AQ Classification: Commercial Cleaning Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	852	-	379690 410853
280	Contemporary Trade Directory Entries Name: Uk Sprinklers Ltd Location: Unit 1, Bridge Trading Estate, Bolton Road, Bury, Lancashire, BL8 2AQ Classification: Firefighting Equipment Status: Active Positional Accuracy: Automatically positioned to the address	A12NW (W)	864	-	379688 410883
280	Contemporary Trade Directory Entries Name: Office Equipment Services Location: 13, Bolton Road, Bury, BL8 2AB Classification: Office Equipment Servicing & Maintenance Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	899	-	379647 410873
281	Contemporary Trade Directory Entries Name: Georgian Gates Location: Lower Woodhill Rd, Bury, Lancashire, BL8 1AA Classification: Wrought Ironwork Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A17SW (NW)	854	-	379773 411026

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
281	Contemporary Trade Directory Entries Name: The Cleaning Fairy Location: 3, Lower Woodhill Road, Bury, BL8 1AA Classification: Cleaning Services - Domestic Status: Inactive Positional Accuracy: Automatically positioned to the address	A17SW (NW)	855	-	379746 410985
281	Contemporary Trade Directory Entries Name: Veolia Location: 3, Lower Woodhill Road, Bury, BL8 1AA Classification: Waste Disposal Services Status: Active Positional Accuracy: Automatically positioned to the address	A17SW (NW)	855	-	379746 410985
281	Contemporary Trade Directory Entries Name: The Cleaning Fairy (Uk) Ltd Location: 3, Lower Woodhill Road, Bury, Lancashire, BL8 1AA Classification: Cleaning Services - Domestic Status: Inactive Positional Accuracy: Manually positioned to the address or location	A17SW (NW)	855	-	379746 410985
281	Contemporary Trade Directory Entries Name: G Bennett (Transport) Ltd Location: Lower Woodhill Road, Bury, Lancashire, BL8 1AA Classification: Road Haulage Services Status: Inactive Positional Accuracy: Automatically positioned in the proximity of the address	A17SW (NW)	873	-	379751 411028
281	Contemporary Trade Directory Entries Name: Excelsior Case & Container Ltd Location: Unit 1/2, Irwell Works, Lower Woodhill Road, Bury, Lancashire, BL8 1AA Classification: Materials Handling Equipment Status: Inactive Positional Accuracy: Automatically positioned in the proximity of the address	A17SW (NW)	873	-	379751 411028
281	Contemporary Trade Directory Entries Name: Apollo Pharma Ltd Location: Unit 1 Irwell Works, Lower Woodhill Road, Bury, Lancashire, BL8 1AA Classification: Pharmaceutical Manufacturers & Distributors Status: Active Positional Accuracy: Automatically positioned to the address	A17SW (NW)	873	-	379751 411028
281	Contemporary Trade Directory Entries Name: Georgian Gates Location: Unit 2, Irwell Works, Lower Woodhill Road, Bury, BL8 1AA Classification: Wrought Ironwork Status: Active Positional Accuracy: Automatically positioned to the address	A17SW (NW)	873	-	379751 411028
281	Contemporary Trade Directory Entries Name: Eden Fashions Ltd Location: Irwell Bridge Mills, Lower Woodhill Rd, Bury, Lancashire, BL8 1AA Classification: Clothing & Fabrics - Manufacturers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A17SW (NW)	874	-	379750 411027
281	Contemporary Trade Directory Entries Name: Fortis Mouldings Ltd Location: Unit 2 Irwell Works, Lower Woodhill Rd, Bury, Lancashire, BL8 1AA Classification: Plastics - Injection Moulding Status: Inactive Positional Accuracy: Manually positioned to the address or location	A17SW (NW)	874	-	379750 411028
281	Contemporary Trade Directory Entries Name: Lati Uk Ltd Location: Unit 2 Irwell Works, Lower Woodhill Rd, Bury, Lancashire, BL8 1AA Classification: Plastics - Raw Materials Status: Inactive Positional Accuracy: Manually positioned to the address or location	A17SW (NW)	874	-	379750 411028
281	Contemporary Trade Directory Entries Name: Evans Halshaw Ford Location: Evans Halshaw, Crostons Road, Bury, BL8 1AA Classification: Car Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A17SW (NW)	880	-	379737 411017
281	Contemporary Trade Directory Entries Name: Dixon Ford Berry Location: Lower Woodhill Rd, Bury, Lancashire, BL8 1AA Classification: Car Dealers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A17SW (NW)	884	-	379718 410992

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
282	Contemporary Trade Directory Entries Name: Good Mix Concrete Location: UNIT 3, PARK ROAD, BURY, BL9 5BQ Classification: Concrete & Mortar Ready Mixed Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	858	-	380434 411482
283	Contemporary Trade Directory Entries Name: Silver Street Brewery Ltd Location: Britannia Mill, Cobden Street, Bury, Lancashire, BL9 6AW Classification: Brewers Status: Active Positional Accuracy: Automatically positioned to the address	A19NW (NE)	870	-	381232 411332
283	Contemporary Trade Directory Entries Name: D B A Location: Britannia Mill, Cobden Street, Bury, Lancashire, BL9 6AW Classification: Washing Machines - Servicing & Repairs Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A19NW (NE)	892	-	381254 411342
283	Contemporary Trade Directory Entries Name: Gk Bio Products Ltd Location: Unit 12b, Britannia Mill, Cobden Street, Bury, Lancashire, BL9 6AW Classification: Laboratories Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	892	-	381254 411342
283	Contemporary Trade Directory Entries Name: Tasklake Ltd Location: Unit 14a Britannia Mill, Cobden St, Bury, Lancashire, BL9 6AW Classification: Bags, Belts & Accessories - Manufacturers & Suppliers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	892	-	381254 411342
283	Contemporary Trade Directory Entries Name: Aspect Glass Location: Unit 7, Britannia Mill, Cobden Street, Bury, Lancashire, BL9 6AW Classification: Glass Products - Manufacturers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	892	-	381254 411342
283	Contemporary Trade Directory Entries Name: Diamond Product Uk Ltd Location: Unit 15, Britannia Mill, Cobden Street, Bury, Lancashire, BL9 6AW Classification: Textile Manufacturing Status: Inactive Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	892	-	381254 411342
283	Contemporary Trade Directory Entries Name: N J F Grinding Location: Unit 15, Britannia Mill, Cobden Street, Bury, Lancashire, BL9 6AW Classification: Tool Sharpening, Repairing & Servicing Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	892	-	381254 411342
283	Contemporary Trade Directory Entries Name: D A S Bury Ltd Location: Unit 1, Britannia Mill, Samuel Street, Bury, Lancashire, BL9 6AG Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A19NW (NE)	892	-	381254 411342
283	Contemporary Trade Directory Entries Name: Carrera 2000 Location: Unit 9a, Britannia Mill, Cobden Street, Bury, BL9 6AW Classification: Screen Process Printers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	892	-	381254 411342
283	Contemporary Trade Directory Entries Name: Outstanding Beers Location: Unit 4/B, Britannia Mill, Cobden Street, Bury, Lancashire, BL9 6AW Classification: Brewers Status: Active Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	892	-	381254 411342
283	Contemporary Trade Directory Entries Name: Auto Privacy Glass Location: Unit 4/A, Britannia Mill, Cobden Street, Bury, Lancashire, BL9 6AW Classification: Window Tinting Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	892	-	381254 411342

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
283	Contemporary Trade Directory Entries Name: I S I Location: 31 Samuel Street, Bury, Lancashire, BL9 6AG Classification: Catering Equipment Status: Active Positional Accuracy: Manually positioned to the road within the address or location	A19NW (NE)	905	-	381254 411359
283	Contemporary Trade Directory Entries Name: Auto Privacy Glass Location: 4a, Samuel Street, Bury, Lancashire, BL9 6AG Classification: Window Tinting Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	911	-	381248 411372
283	Contemporary Trade Directory Entries Name: Motor Restore Ltd Location: 4a, Samuel Street, Bury, Lancashire, BL9 6AG Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	911	-	381248 411372
283	Contemporary Trade Directory Entries Name: Auto Privacy Glass Location: 4 Samuel st, Bury, Lancashire, BL9 6AG Classification: Window Tinting Status: Inactive Positional Accuracy: Manually positioned to the address or location	A19NE (NE)	941	-	381280 411385
283	Contemporary Trade Directory Entries Name: Carrick Leather Goods Co Ltd Location: 1, Samuel Street, BURY, Lancashire, BL9 6AG Classification: Leather Garments & Products Status: Active Positional Accuracy: Automatically positioned to the address	A19NE (NE)	942	-	381280 411385
284	Contemporary Trade Directory Entries Name: B & M Location: Pimhole Road, Bury, Lancashire, BL9 7EY Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	874	-	381541 410447
284	Contemporary Trade Directory Entries Name: Steve'S Auto Spares Location: Pimhole Road, Bury, Lancashire, BL9 7EY Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14SE (E)	874	-	381541 410447
285	Contemporary Trade Directory Entries Name: Hi Way Motors Location: Taylor Street, Bury, BL9 6DT Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A19NW (NE)	878	-	381062 411449
285	Contemporary Trade Directory Entries Name: Gourmet Food Co Ltd Location: Taylor Street, Bury, Lancashire, BL9 6DW Classification: Food Products - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	909	-	381045 411491
285	Contemporary Trade Directory Entries Name: Arla Foods Location: Taylor Street, Bury, Lancashire, BL9 6DT Classification: Dairies Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	909	-	381045 411491
285	Contemporary Trade Directory Entries Name: Cleansafe Location: Remar House, Geoffrey Street, Bury, Lancashire, BL9 6FT Classification: Cleaning Materials & Equipment Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	925	-	381039 411511
286	Contemporary Trade Directory Entries Name: J S T Fabrication Location: Unit 3 Kenyon Street, Bury, Lancashire, BL9 6DQ Classification: Sheet Metal Work Status: Active Positional Accuracy: Manually positioned to the road within the address or location	A19NW (NE)	880	-	381082 411442

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
287	Contemporary Trade Directory Entries Name: Re Build Location: Unit 4, Park Road, Bury, Lancashire, BL9 5BQ Classification: Furniture - Reproduction Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	880	-	380507 411522
287	Contemporary Trade Directory Entries Name: Apex Auto Repairs Location: Unit 5 Park Road, Bury, Lancashire, BL9 5BQ Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A18NW (N)	886	-	380552 411536
287	Contemporary Trade Directory Entries Name: G & M Venditti Compressors Ltd Location: Unit 1, Park Road, Bury, BL9 5BQ Classification: Air Compressors Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	886	-	380552 411536
287	Contemporary Trade Directory Entries Name: M J Howard Technical Services Ltd Location: Unit 6 Birch Business Park, Todd Street, Bury, Lancashire, BL9 5BQ Classification: Engineers - General Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	889	-	380531 411536
287	Contemporary Trade Directory Entries Name: Rainbow International Location: Unit 6, Park Road, Bury, Lancashire, BL9 5BQ Classification: Carpet, Curtain & Upholstery Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	890	-	380531 411536
287	Contemporary Trade Directory Entries Name: Whitefield Accident Repair Centre Location: Unit 3, Park Road, Bury, BL9 5BQ Classification: Car Body Repairs Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	906	-	380507 411548
287	Contemporary Trade Directory Entries Name: Whitefield Accident Repair Ltd Location: Unit 3, Park Road, Bury, BL9 5BQ Classification: Car Body Repairs Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	906	-	380507 411548
288	Contemporary Trade Directory Entries Name: R E Performance Centre Location: Bridge St, Bury, Lancs, BL9 6HH Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19NW (NE)	881	-	381204 411368
289	Contemporary Trade Directory Entries Name: Greenbrook Garage Location: Unit 1, Albion Street, Bury, Lancashire, BL8 2AD Classification: Car Engine Tuning & Diagnostic Services Status: Active Positional Accuracy: Manually positioned to the road within the address or location	A12NW (W)	888	-	379636 410800
289	Contemporary Trade Directory Entries Name: Deltatex (Uk) Services Location: Albion St, Bury, Lancashire, BL8 2AD Classification: Photocopiers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A12NW (W)	889	-	379636 410806
290	Contemporary Trade Directory Entries Name: K B Supplies Location: Albion Works, Albion Street, Bury, Lancashire, BL8 2AD Classification: Builders' Merchants Status: Inactive Positional Accuracy: Automatically positioned in the proximity of the address	A12NW (W)	889	-	379638 410814
290	Contemporary Trade Directory Entries Name: Tony Hilton Location: Unit 1, Albion Street, Bury, Lancashire, BL8 2AD Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	891	-	379646 410844

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
290	Contemporary Trade Directory Entries Name: J Alan Autos Location: Unit 5 Albion Street, Bury, Lancashire, BL8 2AD Classification: Garage Services Status: Active Positional Accuracy: Manually positioned to the address or location	A12NW (W)	891	-	379646 410844
290	Contemporary Trade Directory Entries Name: Reliable Upholstery Location: Albion House, Albion Street, Bury, Lancashire, BL8 2AD Classification: Furniture - Repairing & Restoring Status: Active Positional Accuracy: Automatically positioned to the address	A12NW (W)	891	-	379646 410844
290	Contemporary Trade Directory Entries Name: Aquasure Location: Albion House, Albion Street, Bury, Lancashire, BL8 2AD Classification: Distribution Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	891	-	379646 410844
290	Contemporary Trade Directory Entries Name: Bp Garage Services Location: Albion St, Bury, Lancashire, BL8 2AD Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A12NW (W)	896	-	379636 410832
290	Contemporary Trade Directory Entries Name: Domestic Discount Appliances Location: 31, Bolton Road, Bury, Lancashire, BL8 2AB Classification: Washing Machines - Servicing & Repairs Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	933	-	379600 410842
290	Contemporary Trade Directory Entries Name: National Tyres & Autocare Location: 24, Bolton Road, Bury, BL8 2QR Classification: Tyre Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A12NW (W)	956	-	379592 410888
290	Contemporary Trade Directory Entries Name: Bridge End Paint Shop Location: Unit 1 Broom St, Off Bolton Rd, Bury, Lancashire, BL8 2AB Classification: Car Body Repairs Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A11NE (W)	972	-	379556 410827
291	Contemporary Trade Directory Entries Name: Ace High Customs Location: 154, Hornby Street, Bury, Lancashire, BL9 5BB Classification: Motor Cycle Repairs Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	890	-	380710 411548
291	Contemporary Trade Directory Entries Name: Cts Location: Unit 6-7, Hornby St, Bury, Lancashire, BL9 5EF Classification: Tyre Disposal Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A23SE (N)	933	-	380695 411592
292	Contemporary Trade Directory Entries Name: The Ironing Board Location: 127, Alfred Street, Bury, Lancashire, BL9 9EQ Classification: Ironing & Home Laundry Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A9SW (SE)	893	-	381201 409816
293	Contemporary Trade Directory Entries Name: Carpet Cleaning Bury Location: 12, Vernon Street, Bury, Lancashire, BL9 5AR Classification: Carpet, Curtain & Upholstery Cleaners Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	894	-	380849 411536
294	Contemporary Trade Directory Entries Name: Inchcape Volkswagen Location: Bell Lane, Bury, Lancashire, BL9 6DL Classification: Car Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A19NE (NE)	898	-	381358 411249

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
295	Contemporary Trade Directory Entries Name: C C Motors Location: Bright St, Bury, Lancashire, BL9 6AQ Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19NE (NE)	905	-	381316 411304
296	Contemporary Trade Directory Entries Name: Burgaflex Location: Block C Chamberhall Business Park, Harvard Road, Bury, Lancashire, BL9 0FU Classification: Air Conditioning Equipment & Systems Status: Inactive Positional Accuracy: Automatically positioned to the address	A17NE (NW)	906	-	380132 411403
297	Contemporary Trade Directory Entries Name: Pro Lifts Location: 149, Wash Lane, Bury, Lancashire, BL9 7DP Classification: Stairlifts - Manufacturers & Installers Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NE (E)	908	-	381562 410879
298	Contemporary Trade Directory Entries Name: E & S Services Location: 28, Worcester Close, Bury, Lancashire, BL9 9DB Classification: Refrigerators & Freezers - Servicing & Repairs Status: Inactive Positional Accuracy: Automatically positioned to the address	A9SW (SE)	912	-	381074 409707
299	Contemporary Trade Directory Entries Name: Insulslab Location: Peel Industrial Estate, Chamberhall Street, Bury, BL9 0LU Classification: Insulation Materials Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	913	-	380304 411495
299	Contemporary Trade Directory Entries Name: Mayplas Location: Bury, BL9 0LU Classification: Insulation Materials Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	913	-	380304 411495
299	Contemporary Trade Directory Entries Name: S P Air Ltd Location: Unit 21, Peel Industrial Estate, Chamberhall Street, Bury, Lancashire, BL9 0LU Classification: Pneumatic Systems & Equipment Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	915	-	380323 411504
299	Contemporary Trade Directory Entries Name: Andrew'S Courier Services Ltd Location: Unit 23, Peel Industrial Estate, Chamberhall Street, Bury, BL9 0LU Classification: Freight Forwarders Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	924	-	380315 411511
299	Contemporary Trade Directory Entries Name: G & M Venditti Compressors Ltd Location: Unit 24, Peel Industrial Estate, Chamberhall Street, Bury, BL9 0LU Classification: Air Compressors Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	930	-	380312 411515
299	Contemporary Trade Directory Entries Name: Deeply Vale Brewery Ltd Location: Unit 25, Peel Industrial Estate, Chamberhall Street, Bury, BL9 0LU Classification: Brewers Status: Active Positional Accuracy: Automatically positioned to the address	A18NW (N)	939	-	380309 411524
300	Contemporary Trade Directory Entries Name: A1 Waste Location: 57, Pine Street, Bury, Lancashire, BL9 7QQ Classification: Waste Disposal Services Status: Active Positional Accuracy: Automatically positioned to the address	A19SE (NE)	913	-	381536 410979

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
301	Contemporary Trade Directory Entries Name: Purr O Lux Within Albion Mill Location: Purr O Lux, Albion Mill, Albion Street, Bury, BL8 2AE Classification: Homefurnishings - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	914	-	379600 410765
301	Contemporary Trade Directory Entries Name: Albion Mill Location: Albion Mill, Albion Street, Bury, BL8 2AE Classification: Homefurnishings - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	914	-	379600 410765
301	Contemporary Trade Directory Entries Name: Purrolux Location: Purr O Lux, Albion Mill, Albion Street, Bury, BL8 2AE Classification: Bed & Mattress Manufacturers Status: Active Positional Accuracy: Automatically positioned to the address	A12NW (W)	914	-	379600 410765
301	Contemporary Trade Directory Entries Name: Heritage Reproductions Ltd Location: Unit 30, Albion Street, Bury, BL8 2AD Classification: Furniture - Reproduction Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	914	-	379600 410765
301	Contemporary Trade Directory Entries Name: Purr O Lux Location: Albion Mill, Albion Street, Bury, Lancashire, BL8 2AE Classification: Homefurnishings - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	931	-	379583 410768
301	Contemporary Trade Directory Entries Name: Storm Clouds Location: Albion Works, Albion Street, Bury, Lancashire, BL8 2AD Classification: Waterproof Clothing & Rainwear Status: Inactive Positional Accuracy: Automatically positioned to the address	A12NW (W)	931	-	379583 410768
301	Contemporary Trade Directory Entries Name: Bump & Grind Motorcycle Breakers Location: Unit 32, Albion Street, Bury, Lancashire, BL8 2AD Classification: Motor Cycle Breakers & Dismantlers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A12NW (W)	932	-	379582 410768
302	Contemporary Trade Directory Entries Name: Britmix Ltd Location: Unit 1, Town Gate, Every St, Bury, Lancashire, BL9 5BE Classification: Concrete & Mortar Ready Mixed Status: Inactive Positional Accuracy: Manually positioned to the address or location	A18NE (N)	916	-	380610 411572
302	Contemporary Trade Directory Entries Name: Falcon Asphalt Construction Co Ltd Location: Town Gate, Every Street, Bury, Lancashire, BL9 5BE Classification: Asphalt & Coated Macadam Laying Contractors Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	917	-	380610 411573
302	Contemporary Trade Directory Entries Name: R Platt & Son (Building Contractors) Ltd Location: Town Gate, Every Street, Bury, Lancashire, BL9 5BE Classification: Concrete & Mortar Ready Mixed Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	917	-	380610 411573
302	Contemporary Trade Directory Entries Name: Lj Motors Location: Town Gate, Every Street, Bury, Lancashire, BL9 5BE Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the address or location	A18NE (N)	917	-	380610 411573
302	Contemporary Trade Directory Entries Name: T'S Autosolutions Location: Town Gate, Every Street, Bury, BL9 5BE Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NE (N)	917	-	380610 411573

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
302	Contemporary Trade Directory Entries Name: Every Street Garage Location: Every Street, Bury, Lancashire, BL9 5BE Classification: Tyre Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A23SE (N)	928	-	380620 411585
302	Contemporary Trade Directory Entries Name: Shack Wrap Location: Fern Hill Business Centre, Todd Street, Bury, BL9 5BJ Classification: Insulation Materials Status: Active Positional Accuracy: Automatically positioned to the address	A23SE (N)	935	-	380611 411592
302	Contemporary Trade Directory Entries Name: Super Poly Ltd Location: Fern Hill Business Centre, Todd Street, Bury, BL9 5BJ Classification: Polythene & Plastic Sheeting Supplies Status: Inactive Positional Accuracy: Automatically positioned to the address	A23SE (N)	965	-	380595 411620
302	Contemporary Trade Directory Entries Name: North West Catering Engineers Location: Suite 1, Fernhill Business Centre, Todd Street, Bury, BL9 5BJ Classification: Catering Equipment - Servicing & Repairs Status: Active Positional Accuracy: Automatically positioned to the address	A23SE (N)	965	-	380595 411620
302	Contemporary Trade Directory Entries Name: Sioen (UK) Location: Fern Hill Business Centre, Todd Street, Bury, BL9 5BJ Classification: Waterproof Clothing & Rainwear Status: Inactive Positional Accuracy: Automatically positioned to the address	A23SE (N)	965	-	380595 411620
303	Contemporary Trade Directory Entries Name: Steelwood Door Centre Location: 110, Wash Lane, Bury, Lancashire, BL9 7DJ Classification: Door Manufacturers - Domestic Status: Inactive Positional Accuracy: Automatically positioned to the address	A14NE (E)	920	-	381586 410826
304	Contemporary Trade Directory Entries Name: Tie Wire Northwest Location: 221, Manchester Road, Bury, Lancashire, BL9 9HJ Classification: Damp & Dry Rot Control Status: Inactive Positional Accuracy: Automatically positioned to the address	A8SW (S)	921	-	380354 409590
305	Contemporary Trade Directory Entries Name: Jewson Location: Higher Mills, Bridge Street, Bury, BL9 6HH Classification: Builders' Merchants Status: Active Positional Accuracy: Automatically positioned to the address	A19NW (NE)	923	-	381126 411467
306	Contemporary Trade Directory Entries Name: J K'Z Services Ltd Location: Bury, Lancashire, BL9 6bg Classification: Cleaning Services - Domestic Status: Active Positional Accuracy: Manually positioned within the geographical locality	A19SE (NE)	925	-	381465 411150
307	Contemporary Trade Directory Entries Name: Howarth Timber & Building Supplies Location: Bright Street, Bury, Lancashire, BL9 6AQ Classification: Builders' Merchants Status: Active Positional Accuracy: Automatically positioned to the address	A19NE (NE)	927	-	381336 411315
307	Contemporary Trade Directory Entries Name: Almodale (UK) Ltd Location: Unit 15 Bright Street Works, Bright St, Bury, Lancashire, BL9 6AQ Classification: Textile Manufacturing Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19NE (NE)	943	-	381309 411362
307	Contemporary Trade Directory Entries Name: H2o Bathrooms Location: Unit 7, Bright Street Mill, Bright St, Bury, Lancashire, BL9 6AQ Classification: Bathroom Fixtures - Manufacturers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A19NE (NE)	947	-	381320 411358

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
307	Contemporary Trade Directory Entries Name: Supertech Location: Unit 14 Bright Street Works, Bright Street, Bury, Lancashire, BL9 6AQ Classification: Computer Manufacturers Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A19NE (NE)	949	-	381321 411359
307	Contemporary Trade Directory Entries Name: Piston & Rotor Location: Unit 17, Bright Street Mill, Bright Street, Bury, BL9 6AQ Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A19NE (NE)	949	-	381321 411359
307	Contemporary Trade Directory Entries Name: Bright Fabrications Location: Unit 7, Bright Street Mill, Bright Street, Bury, Lancashire, BL9 6AQ Classification: Metal Products - Fabricated Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NE (NE)	949	-	381321 411359
307	Contemporary Trade Directory Entries Name: Arch Point Engineering Ltd Location: Unit 18, Bright Street Works, Bright Street, Bury, Lancashire, BL9 6AQ Classification: Engineers - General Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NE (NE)	949	-	381321 411359
307	Contemporary Trade Directory Entries Name: Chemical & Supplies Direct Location: Unit 9, Bright Street Mill, Bright Street, Bury, Lancashire, BL9 6AQ Classification: Cleaning Materials & Equipment Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NE (NE)	949	-	381321 411359
307	Contemporary Trade Directory Entries Name: Ashgrove Engineering Projects Ltd Location: Unit 4a, Bright Street Mill, Bright Street, Bury, Lancashire, BL9 6AQ Classification: Engineers - General Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NE (NE)	972	-	381352 411362
307	Contemporary Trade Directory Entries Name: Latem Location: Unit 19, Bright Street Mill, Bright Street, Bury, Lancashire, BL9 6AQ Classification: Sheet Metal Work Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NE (NE)	972	-	381352 411362
307	Contemporary Trade Directory Entries Name: Uk Chairs Ltd Location: Unit 1, Bright Street Mill, Bright Street, Bury, Lancashire, BL9 6AQ Classification: Furniture Manufacturers - Home & Office Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NE (NE)	1000	-	381349 411404
307	Contemporary Trade Directory Entries Name: Golfs-R-Us Location: Unit 6, Bright Street Mill, Bright Street, Bury, Lancashire, BL9 6AQ Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NE (NE)	1000	-	381349 411404
307	Contemporary Trade Directory Entries Name: Oakfern Ltd Location: Bright Street Mill, Bright Street, Bury, Lancashire, BL9 6AQ Classification: Frozen Food Processors & Distributors Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NE (NE)	1000	-	381349 411404
308	Contemporary Trade Directory Entries Name: Perrys Of Bury Location: Crostons Road, Bury, Lancashire, BL8 1AJ Classification: Car Dealers Status: Active Positional Accuracy: Automatically positioned to the address	A17SW (NW)	931	-	379702 411058
309	Contemporary Trade Directory Entries Name: Hillmar Products Location: New Victoria Mills, Wellington Street, Bury, Lancashire, BL8 2AL Classification: Leather Garments & Products Status: Inactive Positional Accuracy: Manually positioned to the address or location	A11SE (W)	934	-	379562 410480

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
310	Contemporary Trade Directory Entries Name: R R G Kia Bury Location: Wellington Street, Bury, Lancashire, BL8 2AX Classification: Car Dealers Status: Inactive Positional Accuracy: Automatically positioned to the address	A11NE (W)	935	-	379564 410678
310	Contemporary Trade Directory Entries Name: R R G Kia Location: Wellington Street, Bury, Lancashire, BL8 2AX Classification: Car Dealers Status: Active Positional Accuracy: Manually positioned to the address or location	A11NE (W)	937	-	379562 410680
310	Contemporary Trade Directory Entries Name: Merlin Gates Location: Castle House, 7, Wellington Street, Bury, Lancashire, BL8 2AL Classification: Wrought Ironwork Status: Inactive Positional Accuracy: Automatically positioned to the address	A11NE (W)	970	-	379527 410658
311	Contemporary Trade Directory Entries Name: Hmr Autos Location: Unit 2-5, Hornby Street, Bury, Lancashire, BL9 5EF Classification: Car Dealers - Used Status: Inactive Positional Accuracy: Automatically positioned to the address	A23SE (N)	937	-	380670 411596
311	Contemporary Trade Directory Entries Name: Rdx Sports Location: Unit 2-5, Hornby Street, Bury, Lancashire, BL9 5EF Classification: Sports Equipment Manufacturers & Distributors Status: Inactive Positional Accuracy: Automatically positioned to the address	A23SE (N)	937	-	380670 411596
311	Contemporary Trade Directory Entries Name: Hmr Auto Solutions Location: Unit 2-5, Hornby Street, Bury, Lancashire, BL9 5EF Classification: Car Body Repairs Status: Inactive Positional Accuracy: Automatically positioned to the address	A23SE (N)	937	-	380670 411596
311	Contemporary Trade Directory Entries Name: Northwest Landrovers Location: Unit 8, Hornby St, Bury, Lancashire, BL9 5EF Classification: Car Breakers & Dismantlers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A23SE (N)	937	-	380670 411596
311	Contemporary Trade Directory Entries Name: Thomas Hardman & Sons Ltd Location: Fernhill Mill, Hornby St, Bury, Lancashire, BL9 5BD Classification: Textile Manufacturing Status: Inactive Positional Accuracy: Automatically positioned to the address	A23SE (N)	980	-	380670 411639
311	Contemporary Trade Directory Entries Name: Arville Location: Fernhill Mills, Hornby Street, Bury, Lancashire, BL9 5BL Classification: Textile Manufacturing Status: Active Positional Accuracy: Automatically positioned to the address	A23SE (N)	980	-	380670 411639
311	Contemporary Trade Directory Entries Name: Bury M O T Centre Ltd Location: Bury, BL9 5BL Classification: Mot Testing Centres Status: Active Positional Accuracy: Automatically positioned to the address	A23SE (N)	980	-	380670 411639
311	Contemporary Trade Directory Entries Name: Bury Autobodies Location: Bury, BL9 5BL Classification: Car Body Repairs Status: Inactive Positional Accuracy: Automatically positioned to the address	A23SE (N)	980	-	380670 411639
312	Contemporary Trade Directory Entries Name: Valves & Engineered Products Ltd Location: Kay Buildings, Kay Street, Bury, Lancashire, BL9 6BQ Classification: Engineers - General Status: Active Positional Accuracy: Automatically positioned to the address	A19NE (NE)	942	-	381270 411395

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
312	Contemporary Trade Directory Entries Name: Today'S Specials Location: 17 Bright St, Bury, Lancashire, BL9 6AQ Classification: Food Products - Manufacturers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19NE (NE)	961	-	381305 411389
313	Contemporary Trade Directory Entries Name: Heap Bridge Garage Location: Power Ho,Bridge St, Bury, Lancashire, BL9 6HH Classification: Engine Rebuilding & Reconditioning Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19NW (NE)	949	-	381186 411462
313	Contemporary Trade Directory Entries Name: Marsh & Jeffrey Location: Bridge St, Bury, Lancashire, BL9 6HH Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19NW (NE)	950	-	381185 411464
313	Contemporary Trade Directory Entries Name: Rally Equipe Location: Power House, Bridge Street, Bury, BL9 6HH Classification: Car Engine Tuning & Diagnostic Services Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A19NW (NE)	959	-	381203 411463
313	Contemporary Trade Directory Entries Name: A C Packaging Co Ltd Location: Porritt Street, BURY, Lancashire, BL9 6HJ Classification: Packaging & Wrapping Equipment & Supplies Status: Active Positional Accuracy: Automatically positioned to the address	A19NW (NE)	962	-	381216 411458
313	Contemporary Trade Directory Entries Name: West Coast Racing Ltd Location: Power House,Bridge St, Bury, Lancashire, BL9 6HH Classification: Car Dealers Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A19NW (NE)	962	-	381181 411480
313	Contemporary Trade Directory Entries Name: Ironing Board Location: 48, Bridge Street, Bury, Lancashire, BL9 6HH Classification: Ironing & Home Laundry Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	971	-	381193 411484
314	Contemporary Trade Directory Entries Name: Chbc Bird & Pest Location: 5, Worcester Close, Bury, Lancashire, BL9 9DB Classification: Pest & Vermin Control Status: Active Positional Accuracy: Automatically positioned to the address	A9SW (SE)	953	-	381058 409651
315	Contemporary Trade Directory Entries Name: Beldite Location: Puma House,Lower Woodhill Rd, Bury, Lancashire, BL8 1AA Classification: Toiletries Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A17NW (NW)	955	-	379844 411268
316	Contemporary Trade Directory Entries Name: Tygas Ltd Location: Webb Street, Bury, Lancashire, BL8 1AF Classification: Gas Suppliers Status: Active Positional Accuracy: Automatically positioned to the address	A17SW (NW)	957	-	379744 411163
317	Contemporary Trade Directory Entries Name: Coloured Glass Location: Unit 2 Remar Industrial Estate,Geoffrey Street, Bury, Lancashire, BL9 6FT Classification: Glass Products - Manufacturers Status: Active Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	958	-	381077 411531
318	Contemporary Trade Directory Entries Name: G A P Location: Unit 4, Kay Street, Bury, Lancashire, BL9 6BU Classification: PVC-U Products - Manufacturers & Suppliers Status: Active Positional Accuracy: Automatically positioned to the address	A19NW (NE)	966	-	381249 411441

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
318	Contemporary Trade Directory Entries Name: Gap Ltd Location: Unit 4, Kay Street, Bury, Lancashire, BL9 6BU Classification: Cladding Suppliers & Installers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	966	-	381249 411441
318	Contemporary Trade Directory Entries Name: Central Motors Location: Unit 7, Kay Street, Bury, BL9 6BU Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A19NE (NE)	995	-	381281 411452
319	Contemporary Trade Directory Entries Name: Chadwicks Of Bury Ltd Location: Villiers Street, Bury, Lancashire, BL9 6BS Classification: Seal & Joint Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NE (NE)	967	-	381424 411277
320	Contemporary Trade Directory Entries Name: Bricktec Location: Fern Hill Business Centre, Todd Street, Bury, Lancashire, BL9 5BJ Classification: Blast Cleaning Equipment Manufacturers Status: Active Positional Accuracy: Automatically positioned to the address	A23SE (N)	967	-	380599 411622
320	Contemporary Trade Directory Entries Name: Barbe Uk Ltd Location: Fern Hill Business Centre, Todd Street, Bury, Lancashire, BL9 5BJ Classification: Chemicals & Allied Products Status: Inactive Positional Accuracy: Automatically positioned to the address	A23SE (N)	982	-	380618 411639
320	Contemporary Trade Directory Entries Name: Prep-Tec Systems Location: Fern Hill Business Centre, Todd Street, BURY, Lancashire, BL9 5BJ Classification: Sheet Metal Work Status: Inactive Positional Accuracy: Automatically positioned to the address	A23SE (N)	982	-	380618 411639
320	Contemporary Trade Directory Entries Name: Aggregate Industries Ltd Location: Every St, Bury, Lancashire, BL9 5BE Classification: Concrete Contractors Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A23SE (N)	986	-	380649 411644
321	Contemporary Trade Directory Entries Name: Adapt Recycling Ltd Location: Warth Park, 10 Radcliffe Rd, Bury, Lancashire, BL9 9NB Classification: Recycling Centres Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A7SE (S)	969	-	380236 409575
322	Contemporary Trade Directory Entries Name: Johnston Industries Inc Location: Fern Hill Business Centre, Todd Street, Bury, Lancashire, BL9 5BJ Classification: Clothing & Fabrics - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A23SW (N)	974	-	380554 411625
323	Contemporary Trade Directory Entries Name: Good Motors Location: Wellington St, Bury, Lancashire, BL8 2AL Classification: Car Dealers - Used Status: Inactive Positional Accuracy: Manually positioned within the geographical locality	A11SE (W)	981	-	379519 410441
323	Contemporary Trade Directory Entries Name: Imperial Leather Designs Location: New Victoria Mills, Wellington Street, Bury, BL8 2AL Classification: Homefurnishings - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A11SE (W)	981	-	379519 410441
323	Contemporary Trade Directory Entries Name: Vizards Location: New Victoria Mills, Wellington Street, Bury, BL8 2AL Classification: French Polishing Status: Inactive Positional Accuracy: Automatically positioned to the address	A11SE (W)	981	-	379519 410441

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
323	Contemporary Trade Directory Entries Name: Naz Upholstery Service Location: New Victoria Mills, Wellington Street, Bury, Lancashire, BL8 2AL Classification: Furniture Manufacturers - Home & Office Status: Inactive Positional Accuracy: Manually positioned to the address or location	A11SE (W)	981	-	379519 410441
323	Contemporary Trade Directory Entries Name: Suite Leather Uk Location: New Victoria Mills, Wellington Street, Bury, Lancashire, BL8 2AL Classification: Leather Merchants & Wholesalers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A11SE (W)	981	-	379519 410440
323	Contemporary Trade Directory Entries Name: N L G Ltd Location: New Victoria Mills, Wellington Street, Bury, BL8 2AL Classification: Homefurnishings - Manufacturers Status: Inactive Positional Accuracy: Automatically positioned to the address	A11SE (W)	981	-	379519 410441
323	Contemporary Trade Directory Entries Name: Hendricks & Howcroft Ltd Location: New Victoria Mills, Wellington Street, Bury, Lancashire, BL8 2AL Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the address or location	A11SE (W)	981	-	379519 410441
323	Contemporary Trade Directory Entries Name: Neumann Leathers Location: New Victoria Mills, Wellington Street, Bury, Lancashire, BL8 2AL Classification: Leather Garments & Products Status: Inactive Positional Accuracy: Automatically positioned to the address	A11SE (W)	981	-	379519 410441
323	Contemporary Trade Directory Entries Name: Naz Upholstery Services Location: New Victoria Mills, Wellington Street, Bury, Lancashire, BL8 2AL Classification: Upholstery Manufacturers Status: Inactive Positional Accuracy: Manually positioned to the address or location	A11SE (W)	981	-	379519 410441
323	Contemporary Trade Directory Entries Name: Imperial Leather Designs Location: New Victoria Mills, Wellington Street, BURY, Lancashire, BL8 2AL Classification: Seating Manufacturers Status: Active Positional Accuracy: Automatically positioned to the address	A11SE (W)	981	-	379519 410441
324	Contemporary Trade Directory Entries Name: Daisyfield Foods Ltd Location: Wellington St, Bury, Lancashire, BL8 2XX Classification: Bacon & Ham Curers & Merchants Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A11NE (W)	982	-	379513 410644
325	Contemporary Trade Directory Entries Name: Superior Fire Surrounds Location: Unit 1 Excel Works, Regent St, Bury, Lancashire, BL9 5AT Classification: Fireplaces & Mantelpieces Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location	A23SE (N)	985	-	380798 411636
325	Contemporary Trade Directory Entries Name: Heritage Gates & Railings Location: 14, Regent Street, Bury, Lancashire, BL9 5AT Classification: Wrought Ironwork Status: Inactive Positional Accuracy: Automatically positioned to the address	A23SE (N)	990	-	380763 411645
326	Contemporary Trade Directory Entries Name: Chipsaway Location: Unit 28, Peel Industrial Estate, Chamberhall Street, Bury, BL9 0LU Classification: Car Breakdown & Recovery Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A18NW (N)	987	-	380286 411567
327	Contemporary Trade Directory Entries Name: R E Performance Centre Location: Power House, Bridge Street, Bury, Lancashire, BL9 6HH Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A19NW (NE)	991	-	381136 411539

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
327	Contemporary Trade Directory Entries Name: R.E Performance Centre Location: Power House, Bridge Street, Bury, Lancashire, BL9 6HH Classification: Car Engine Tuning & Diagnostic Services Status: Inactive Positional Accuracy: Automatically positioned to the address	A19NW (NE)	991	-	381136 411539
328	Fuel Station Entries Name: Angouleme Way Service Station Location: Angouleme Way , , Bury, Greater Manchester, BL9 0BZ Brand: Obsolete Premises Type: Not Applicable Status: Obsolete Positional Accuracy: Automatically positioned to the address	A13NE (NE)	101	-	380722 410751
328	Fuel Station Entries Name: Save Bury Location: Angouleme Way , , Bury, Greater Manchester, BL9 0BZ Brand: Save Premises Type: Not Applicable Status: Obsolete Positional Accuracy: Automatically positioned to the address	A13NE (NE)	101	-	380722 410751
329	Fuel Station Entries Name: Shell Bury Rock Location: Rochdale Road Derby Street, , Bury, Greater Manchester, BL9 7AX Brand: Shell Premises Type: Not Applicable Status: Obsolete Positional Accuracy: Manually positioned to the address or location	A13NE (NE)	293	-	380894 410860
330	Fuel Station Entries Name: Tesco Bury Location: Peel Way , Woodfield Retail Park, Bury, Greater Manchester, BL9 5BY Brand: TESCO Premises Type: Hypermarket Status: Open Positional Accuracy: Manually positioned to the address or location	A18SW (N)	436	-	380525 411067
331	Fuel Station Entries Name: Kingsway Location: Heywood Street , , Bury, Greater Manchester, BL9 7DZ Brand: OBSOLETE Premises Type: Not Applicable Status: Obsolete Positional Accuracy: Approximate location provided by supplier	A14SW (E)	480	-	381153 410510
332	Fuel Station Entries Name: Castlecroft Garage Location: Castlecroft Road , , Bury, Greater Manchester, BL9 0LN Brand: OBSOLETE Premises Type: Not Applicable Status: Obsolete Positional Accuracy: Located by supplier to within 100m	A17SE (NW)	535	-	380182 411002

Agency & Hydrological	Version	Update Cycle
Contaminated Land Register Entries and Notices Environment Agency - Head Office Rossendale Borough Council - Environmental Health Department Rochdale Metropolitan Borough Council - Environmental Health Department Bolton Metropolitan Borough Council - Environmental Health Department Bury Metropolitan Borough Council - Environmental Health Department	June 2020 October 2017 October 2017 September 2017 September 2017	Annually Annual Rolling Update Annually Annual Rolling Update Annual Rolling Update
Discharge Consents Environment Agency - North West Region	July 2021	Quarterly
Enforcement and Prohibition Notices Environment Agency - North West Region	March 2013	
Integrated Pollution Controls Environment Agency - North West Region	January 2009	
Integrated Pollution Prevention And Control Environment Agency - North West Region	July 2021	Quarterly
Local Authority Integrated Pollution Prevention And Control Bury Metropolitan Borough Council - Environmental Health Department Bolton Metropolitan Borough Council - Environmental Health Department Rochdale Metropolitan Borough Council - Environmental Health Department Rossendale Borough Council - Environmental Health Department	February 2015 July 2014 July 2014 May 2016	Variable Variable Variable Variable
Local Authority Pollution Prevention and Controls Bury Metropolitan Borough Council - Environmental Health Department Rochdale Metropolitan Borough Council - Environmental Health Department Bolton Metropolitan Borough Council - Environmental Health Department Rossendale Borough Council - Environmental Health Department	February 2015 July 2014 July 2014 May 2016	Not Applicable Annual Rolling Update Not Applicable Annual Rolling Update
Local Authority Pollution Prevention and Control Enforcements Bury Metropolitan Borough Council - Environmental Health Department Bolton Metropolitan Borough Council - Environmental Health Department Rochdale Metropolitan Borough Council - Environmental Health Department Rossendale Borough Council - Environmental Health Department	February 2015 July 2014 July 2014 May 2016	Variable Variable Variable Variable
Nearest Surface Water Feature Ordnance Survey	August 2021	
Pollution Incidents to Controlled Waters Environment Agency - North West Region	January 2000	
Prosecutions Relating to Authorised Processes Environment Agency - North West Region	July 2015	
Prosecutions Relating to Controlled Waters Environment Agency - North West Region	March 2013	
Registered Radioactive Substances Environment Agency - North West Region	June 2016	Annually
River Quality Environment Agency - Head Office	November 2001	Not Applicable
River Quality Biology Sampling Points Environment Agency - Head Office	April 2012	Annually
River Quality Chemistry Sampling Points Environment Agency - Head Office	April 2012	Annually
Substantiated Pollution Incident Register Environment Agency - North West Region - Central Area Environment Agency - North West Region - North Area Environment Agency - North West Region - South Area	July 2021 July 2021 July 2021	Quarterly Quarterly Quarterly
Water Abstractions Environment Agency - North West Region	July 2021	Quarterly

Agency & Hydrological	Version	Update Cycle
Water Industry Act Referrals Environment Agency - North West Region	October 2017	Quarterly
Groundwater Vulnerability Map Environment Agency - Head Office	June 2018	As notified
Bedrock Aquifer Designations Environment Agency - Head Office	January 2018	Annually
Superficial Aquifer Designations Environment Agency - Head Office	January 2018	Annually
Source Protection Zones Environment Agency - Head Office	May 2021	Bi-Annually
Extreme Flooding from Rivers or Sea without Defences Environment Agency - Head Office	September 2021	Quarterly
Flooding from Rivers or Sea without Defences Environment Agency - Head Office	September 2021	Quarterly
Areas Benefiting from Flood Defences Environment Agency - Head Office	September 2021	Quarterly
Flood Water Storage Areas Environment Agency - Head Office	September 2021	Quarterly
Flood Defences Environment Agency - Head Office	September 2021	Quarterly
OS Water Network Lines Ordnance Survey	July 2021	Quarterly
BGS Groundwater Flooding Susceptibility British Geological Survey - National Geoscience Information Service	May 2013	Annually

Waste	Version	Update Cycle
BGS Recorded Landfill Sites British Geological Survey - National Geoscience Information Service	November 2002	Not Applicable
Historical Landfill Sites Environment Agency - Head Office	May 2021	Quarterly
Integrated Pollution Control Registered Waste Sites Environment Agency - North West Region	January 2009	Not Applicable
Licensed Waste Management Facilities (Landfill Boundaries) Environment Agency - North West Region - Central Area Environment Agency - North West Region - North Area Environment Agency - North West Region - South Area	October 2021 October 2021 October 2021	Quarterly Quarterly Quarterly
Licensed Waste Management Facilities (Locations) Environment Agency - North West Region - Central Area Environment Agency - North West Region - North Area Environment Agency - North West Region - South Area	July 2021 July 2021 July 2021	Quarterly Quarterly Quarterly
Local Authority Landfill Coverage Bolton Metropolitan Borough Council Bury Metropolitan Borough Council Lancashire County Council - Waste Management Group Rochdale Metropolitan Borough Council - Environmental Health Department Rossendale Borough Council - Environmental Health Department	February 2003 February 2003 February 2003 February 2003 February 2003	Not Applicable Not Applicable Not Applicable Not Applicable Not Applicable
Local Authority Recorded Landfill Sites Bolton Metropolitan Borough Council Bury Metropolitan Borough Council Lancashire County Council - Waste Management Group Rochdale Metropolitan Borough Council - Environmental Health Department Rossendale Borough Council - Environmental Health Department	October 2018 October 2018 October 2018 October 2018 October 2018	
Registered Landfill Sites Environment Agency - North West Region - Central Area Environment Agency - North West Region - North Area Environment Agency - North West Region - South Area	March 2006 March 2006 March 2006	Not Applicable Not Applicable Not Applicable
Registered Waste Transfer Sites Environment Agency - North West Region - Central Area Environment Agency - North West Region - North Area Environment Agency - North West Region - South Area	April 2018 April 2018 April 2018	
Registered Waste Treatment or Disposal Sites Environment Agency - North West Region - Central Area Environment Agency - North West Region - North Area Environment Agency - North West Region - South Area	June 2015 June 2015 June 2015	

Hazardous Substances	Version	Update Cycle
Control of Major Accident Hazards Sites (COMAH) Health and Safety Executive	April 2018	Bi-Annually
Explosive Sites Health and Safety Executive	March 2017	Annually
Notification of Installations Handling Hazardous Substances (NIHHS) Health and Safety Executive	August 2001	
Planning Hazardous Substance Enforcements Bolton Metropolitan Borough Council - Planning Department Bury Metropolitan Borough Council Lancashire County Council Rochdale Metropolitan Borough Council Rossendale Borough Council - Planning Department	February 2016 February 2016 February 2016 February 2016 February 2016	Variable Variable Variable Variable Variable
Planning Hazardous Substance Consents Bolton Metropolitan Borough Council - Planning Department Bury Metropolitan Borough Council Lancashire County Council Rochdale Metropolitan Borough Council Rossendale Borough Council - Planning Department	February 2016 February 2016 February 2016 February 2016 February 2016	Variable Variable Variable Variable Variable
Geological	Version	Update Cycle
BGS 1:625,000 Solid Geology British Geological Survey - National Geoscience Information Service	January 2009	Not Applicable
BGS Recorded Mineral Sites British Geological Survey - National Geoscience Information Service	November 2021	Bi-Annually
CBSCB Compensation District Cheshire Brine Subsidence Compensation Board (CBSCB)	August 2011	As notified
Coal Mining Affected Areas The Coal Authority - Property Searches	March 2014	Annual Rolling Update
Mining Instability Ove Arup & Partners	June 1998	Not Applicable
Non Coal Mining Areas of Great Britain British Geological Survey - National Geoscience Information Service	May 2015	Not Applicable
Potential for Collapsible Ground Stability Hazards British Geological Survey - National Geoscience Information Service	April 2020	Annually
Potential for Compressible Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Ground Dissolution Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Landslide Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Running Sand Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Shrinking or Swelling Clay Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	Annually
Radon Potential - Radon Affected Areas British Geological Survey - National Geoscience Information Service	July 2011	Annually
Radon Potential - Radon Protection Measures British Geological Survey - National Geoscience Information Service	July 2011	Annually


Industrial Land Use	Version	Update Cycle
Contemporary Trade Directory Entries Thomson Directories	October 2021	Quarterly
Fuel Station Entries Catalist Ltd - Experian	August 2021	Quarterly
Gas Pipelines National Grid	October 2021	Annually
Underground Electrical Cables National Grid	May 2021	Annually
Sensitive Land Use	Version	Update Cycle
Ancient Woodland Natural England	February 2021	Bi-Annually
Areas of Adopted Green Belt Bolton Metropolitan Borough Council Bury Metropolitan Borough Council Rochdale Metropolitan Borough Council Rossendale Borough Council - Planning Department	October 2020 October 2020 October 2020 October 2020	Quarterly Quarterly Quarterly Quarterly
Areas of Unadopted Green Belt Bolton Metropolitan Borough Council Bury Metropolitan Borough Council Rochdale Metropolitan Borough Council Rossendale Borough Council - Planning Department	October 2020 October 2020 October 2020 October 2020	Quarterly Quarterly Quarterly Quarterly
Areas of Outstanding Natural Beauty Natural England	January 2021	Bi-Annually
Environmentally Sensitive Areas Natural England	January 2017	
Forest Parks Forestry Commission	April 1997	Not Applicable
Local Nature Reserves Natural England	February 2021	Bi-Annually
Marine Nature Reserves Natural England	July 2019	Bi-Annually
National Nature Reserves Natural England	January 2021	Bi-Annually
National Parks Natural England	February 2018	Bi-Annually
Nitrate Sensitive Areas Natural England	April 2016	Not Applicable
Nitrate Vulnerable Zones Department for Environment, Food and Rural Affairs (DEFRA - formerly FRCA) Environment Agency - Head Office	April 2016 June 2017	Bi-Annually
Ramsar Sites Natural England	August 2020	Bi-Annually
Sites of Special Scientific Interest Natural England	February 2021	Bi-Annually
Special Areas of Conservation Natural England	July 2020	Bi-Annually
Special Protection Areas Natural England	February 2021	Bi-Annually

A selection of organisations who provide data within this report

Data Supplier	Data Supplier Logo
Ordnance Survey	
Environment Agency	
Scottish Environment Protection Agency	
The Coal Authority	
British Geological Survey	 British Geological Survey NATURAL ENVIRONMENT RESEARCH COUNCIL
Centre for Ecology and Hydrology	 Centre for Ecology & Hydrology NATURAL ENVIRONMENT RESEARCH COUNCIL
Natural Resources Wales	
Scottish Natural Heritage	
Natural England	
Public Health England	
Ove Arup	
Stantec UK Ltd	

Contact	Name and Address	Contact Details
1	British Geological Survey - Enquiry Service British Geological Survey, Environmental Science Centre, Keyworth, Nottingham, Nottinghamshire, NG12 5GG	Telephone: 0115 936 3143 Fax: 0115 936 3276 Email: enquiries@bgs.ac.uk Website: www.bgs.ac.uk
2	Environment Agency - National Customer Contact Centre (NCCC) PO Box 544, Templeborough, Rotherham, S60 1BY	Telephone: 03708 506 506 Email: enquiries@environment-agency.gov.uk
3	Bury Metropolitan Borough Council - Environmental Health Department 3 Knowsley Place, Duke Street, Bury, Lancashire, BL9 0EJ	Telephone: 0161 253 5000 Fax: 0161 253 5563 Website: www.bury.gov.uk
4	Environment Agency - Head Office Rio House, Waterside Drive, Aztec West, Almondsbury, Bristol, Avon, BS32 4UD	Telephone: 01454 624400 Fax: 01454 624409
5	Ordnance Survey Adanac Drive, Southampton, Hampshire, SO16 0AS	Telephone: 03456 05 05 05 Email: customerservices@ordnancesurvey.co.uk Website: www.ordnancesurvey.gov.uk
6	Bury Metropolitan Borough Council Craig House, Bank Street, Bury, Lancashire, BL9 0DN	Telephone: 0161 253 5000 Fax: 0161 705 5290 Website: www.bury.gov.uk
7	Rochdale Metropolitan Borough Council - Environmental Health Department P O Box 32, Telegraph House, Ballie Street, Rochdale, Greater Manchester, OL16 1JH	Telephone: 01706 864139 Fax: 01706 864185 Website: www.rochdale.gov.uk
8	Health and Safety Executive 5S.2 Redgrave Court, Merton Road, Bootle, L20 7HS	Website: www.hse.gov.uk
9	Bury Metropolitan Borough Council Maple House, 8 Haymarket Street, Bury, BL9 0PD	Telephone: 0161 253 5000 Fax: 0161 705 5290 Website: www.bury.gov.uk
10	The Coal Authority - Property Searches 200 Lichfield Lane, Mansfield, Nottinghamshire, NG18 4RG	Telephone: 0345 762 6848 Fax: 01623 637 338 Email: groundstability@coal.gov.uk Website: www2.groundstability.com
11	Stantec UK Ltd Caversham Bridge House, Waterman Place, Reading, RG1 8DN	Telephone: 0118 950 0761 Email: pba.reading@stantec.com Website: www.stantec.com
12	Rochdale Metropolitan Borough Council PO Box 15, Town Hall, Rochdale, Greater Manchester, OL16 1AB	Telephone: 01706 647474 Fax: 01706 59475 Website: www.rochdale.gov.uk
13	Natural England County Hall, Spetchley Road, Worcester, WR5 2NP	Telephone: 0300 060 3900 Email: enquiries@naturalengland.org.uk Website: www.naturalengland.org.uk
-	Public Health England - Radon Survey, Centre for Radiation, Chemical and Environmental Hazards Chilton, Didcot, Oxfordshire, OX11 0RQ	Telephone: 01235 822622 Fax: 01235 833891 Email: radon@phe.gov.uk Website: www.ukradon.org
-	Landmark Information Group Limited Imperium, Imperial Way, Reading, Berkshire, RG2 0TD	Telephone: 0844 844 9952 Fax: 0844 844 9951 Email: customerservices@landmarkinfo.co.uk Website: www.landmarkinfo.co.uk

Please note that the Environment Agency / Natural Resources Wales / SEPA have a charging policy in place for enquiries.



Index Map

For ease of identification, your site and buffer have been split into Slices, Segments and Quadrants. These are illustrated on the Index Map opposite and explained further below.

Slice

Each slice represents a 1:10,000 plot area (2.7km x 2.7km) for your site and buffer. A large site and buffer may be made up of several slices (represented by a red outline), that are referenced by letters of the alphabet, starting from the bottom left corner of the slice "grid". This grid does not relate to National Grid lines but is designed to give best fit over the site and buffer.

Segment

A segment represents a 1:2,500 plot area. Segments that have plot files associated with them are shown in dark green, others in light blue. These are numbered from the bottom left hand corner within each slice.

Quadrant

A quadrant is a quarter of a segment. These are labelled as NW, NE, SW, SE and are referenced in the datasheet to allow features to be quickly located on plots. Therefore a feature that has a quadrant reference of A7NW will be in Slice A, Segment 7 and the NW Quadrant.

A selection of organisations who provide data within this report:



Envirocheck reports are compiled from 136 different sources of data.

Client Details

Dr B Rice-Birchall, iD GeoEnvironmental Ltd, Caledonian House, Tatton Street, Knutsford, Cheshire, WA16 6AG

Order Details

Order Number: 287800372_1_1
Customer Ref: 5237
National Grid Reference: 380600, 410560
Site Area (Ha): 1.89
Search Buffer (m): 1000

Site Details

Bury Market, Murray Road, BURY, BL9 0BJ

Full Terms and Conditions can be found on the following link:
<http://www.landmarkinfo.co.uk/Terms/Show/515>



Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



The Coal
Authority

CON29M

coal mining report

BURY MARKET, MURRAY ROAD, BURY, BL9 0BD



Known or potential coal mining risks

Past underground coal mining	Page 4
Future underground coal mining	Page 4
Mine entries	Page 5



Further action

No further reports from the Coal Authority are required. Further information on any next steps can be found in our Professional opinion.

For more information on our reports please visit
www.groundstability.com



Professional opinion

According to the official mining information records held by the Coal Authority at the time of this search, evidence of, or the potential for, coal mining related features have been identified. In view of the coal mining circumstances we would recommend that any planned or future development should follow detailed technical advice before beginning work on site. Please see **page 3** for further details on **Future development**.

Your reference: **5237**
Our reference: **51002715802001**
Date: **17 November 2021**

Client name:
**ID GEOENVIRONMENTAL
LIMITED**

If you require any further assistance please
contact our experts on:
0345 762 6848
groundstability@coal.gov.uk



The Law
Society

Enquiry boundary

Key

Approximate position of enquiry boundary shown



We can confirm that the location is
on the coalfield



Reproduced by permission of Ordnance Survey on behalf of HMSO. © Crown copyright and database right 2018. All rights reserved.
Ordnance Survey Licence number: 100020315.

This report is prepared in accordance with the latest Law Society's Guidance Notes 2018, the User Guide 2018 and the Coal Authority's Terms and Conditions applicable at the time the report was produced.



Accessibility

If you would like this information in an alternative format, please contact our communications team on 0345 762 6848 or email communications@coal.gov.uk.

Professional opinion



Future development

If development proposals are being considered, technical advice relating to both the investigation of coal and former coal mines and their treatment should be obtained before beginning work on site. All proposals should apply specialist engineering practice required for former mining areas. No development should be undertaken that intersects, disturbs or interferes with any coal or coal mines without first obtaining the permission of the Coal Authority. Developers should be aware that the investigation of coal seams, mine workings or mine entries may have the potential to generate and/or displace underground gases. Associated risks both to the development site and any neighbouring land or properties should be fully considered when undertaking any ground works. The need for effective measures to prevent gases migrating onto any land or into any properties, either during investigation or remediation work, or after development must also be assessed and properly addressed.

If you are looking to develop, or undertake works, within a coal mining development high risk area your Local Authority planning department may require a Coal Mining Risk Assessment to be undertaken by a qualified mining geologist or engineer. Should you require any additional information then please contact the Coal Authority on **0345 762 6848** or email **cmra@coal.gov.uk**.

Detailed findings

Information provided by the Coal Authority in this report is compiled in response to the Law Society's CON29M Coal Mining enquiries. The said enquiries are protected by copyright owned by the Law Society of 113 Chancery Lane, London WC2A 1PL.

The Coal Authority owns the copyright in this report and the information used to produce this report is protected by our database rights. All rights are reserved and unauthorised use is prohibited. If we provide a report for you, this does not mean that copyright and any other rights will pass to you. However, you can use the report for your own purposes.

1 Past underground coal mining

The property is not within a surface area that could be affected by any past recorded underground coal mining.

However the property is in an area where the Coal Authority believes there is coal at or close to the surface. This coal may have been worked at some time in the past. The potential presence of coal workings at or close to the surface should be considered, particularly prior to any site works or future development activity, as ground movement could still be a risk. Your attention is drawn to the Professional opinion sections of the report.

2 Present underground coal mining

The property is not within a surface area that could be affected by present underground mining.

3 Future underground coal mining

The property is not in an area where the Coal Authority has received an application for, and is currently considering whether to grant a licence to remove or work coal by underground methods.

The property is not in an area where a licence has been granted to remove or otherwise work coal using underground methods.

The property is not in an area likely to be affected from any planned future underground coal mining.

However, reserves of coal exist in the local area which could be worked at some time in the future.

No notices have been given, under section 46 of the Coal Mining Subsidence Act 1991, stating that the land is at risk of subsidence.

4 Mine entries

There are no recorded coal mine entries known to the Coal Authority within, or within 20 metres, of the boundary of the property.

This information is based on the information that the Coal Authority has at the time of this enquiry.

Based on the Coal Authority's knowledge of the mining circumstances at the time of this enquiry, there may be unrecorded mine entries in the local area that do not appear on Coal Authority records.

5 Coal mining geology

The Coal Authority is not aware of any damage due to geological faults or other lines of weakness that have been affected by coal mining.

6 Past opencast coal mining

The property is not within the boundary of an opencast site from which coal has been removed by opencast methods.

7 Present opencast coal mining

The property does not lie within 200 metres of the boundary of an opencast site from which coal is being removed by opencast methods.

8 Future opencast coal mining

There are no licence requests outstanding to remove coal by opencast methods within 800 metres of the boundary.

The property is not within 800 metres of the boundary of an opencast site for which a licence to remove coal by opencast methods has been granted.

9 Coal mining subsidence

The Coal Authority has not received a damage notice or claim for the subject property, or any property within 50 metres of the enquiry boundary, since 31 October 1994.

There is no current Stop Notice delaying the start of remedial works or repairs to the property.

The Coal Authority is not aware of any request having been made to carry out preventive works before coal is worked under section 33 of the Coal Mining Subsidence Act 1991.

10 Mine gas

The Coal Authority has no record of a mine gas emission requiring action.

11 Hazards related to coal mining

The property has not been subject to remedial works, by or on behalf of the Coal Authority, under its Emergency Surface Hazard Call Out procedures.

12 Withdrawal of support

The property is not in an area where a notice to withdraw support has been given.

The property is not in an area where a notice has been given under section 41 of the Coal Industry Act 1994, cancelling the entitlement to withdraw support.

13 Working facilities order

The property is not in an area where an order has been made, under the provisions of the Mines (Working Facilities and Support) Acts 1923 and 1966 or any statutory modification or amendment thereof.

14 Payments to owners of former copyhold land

The property is not in an area where a relevant notice has been published under the Coal Industry Act 1975/Coal Industry Act 1994.

Statutory cover



Coal mining subsidence

In the unlikely event of any coal mining related subsidence damage, the Coal Authority or the mine operator has a duty to take remedial action in respect of subsidence caused by the withdrawal of support from land or property in connection with lawful coal mining operations.

When the works are the responsibility of the Coal Authority, our dedicated public safety and subsidence team will manage the claim. The house or land owner ("the owner") is covered for these works under the terms of the Coal Mining Subsidence Act 1991 (as amended by the Coal Industry Act 1994). Please note, this Act does not apply where coal was worked or gotten by virtue of the grant of a gale in the Forest of Dean, or any other part of the Hundred of St. Briavels in the county of Gloucester.

If you believe your land or property is suffering from coal mining subsidence damage and you need more information on what to do next, please use the following link to our website which sets out what your rights are and what you need to consider before making a claim.

www.gov.uk/government/publications/coal-mining-subsidence-damage-notice-form



Coal mining hazards

Our public safety and subsidence team provide a 24 hour a day, 7 days a week hazard reporting service, to help protect the public from hazards caused by past coal workings, such as a mine shaft or shallow working collapse. To report any hazards please call **01623 646 333**. Further information can be found on our website: www.gov.uk/coalauthority.

Glossary



Key terms

adit - horizontal or sloped entrance to a mine

coal mining subsidence - ground movement caused by the removal of coal by underground mining

Coal Mining Subsidence Act 1991 - the Act setting out the duties of the Coal Authority to repair damage caused by coal mining subsidence

coal mining subsidence damage - damage to land, buildings or structures caused by the removal of coal by underground mining

coal seams - bed of coal of varying thickness

future opencast coal mining - a licence granted, or licence application received, by the Coal Authority to excavate coal from the surface

future underground coal mining - a licence granted, or licence application received, by the Coal Authority to excavate coal underground. Although it is unlikely, remaining coal reserves could create a possibility for future mining, which would be licensed by the Coal Authority

mine entries - collective name for shafts and adits

payments to owners of former copyhold land - historically, copyhold land gave rights to coal to the copyholder. Legislation was set up to allow others to work this coal, but they had to issue a notice and pay compensation if a copyholder came forward

shaft - vertical entry into a mine

site investigation - investigations of coal mining risks carried out with the Coal Authority's permission


stop notice - a delay to repairs because further coal mining subsidence damage may occur and it would be unwise to carry out permanent repairs

subsidence claim - a formal notice of subsidence damage to the Coal Authority since it was established on 31 October 1994

withdrawal of support - a historic notice informing landowners that the coal beneath their property was going to be worked



working facilities orders - a court order which gave permission, restricted or prevented coal mine workings

Appendix D



 iD GeoEnvironmental Limited			Project Title: Bury Market				BH01																																														
			Project Number: 5237		Client: Bury Council					Sheet 1 Of 2																																											
			GL (mAOD): 94.10		N Coord: 410561.5		E Coord: 380633.1																																														
Date: 28/02/2022-01/03/2022			Method: Cable Percussion		Driller: Lundy SI		Logged By: MJ																																														
Depth (m)	Type	Test Result	Level	Legend	Depth (m)	Description	Water	Standpipe																																													
1.30 - 2.00	B	N=6	93.95		0.15	MADE GROUND: Black macadam																																															
			93.50		0.60	MADE GROUND: Grey sandy gravel and cobble.																																															
			92.80		1.30	MADE GROUND: Brown very gravelly cobbly sand. Gravel and cobble is of sandstone and brick																																															
						MADE GROUND: Brown very sandy gravelly cobbly clay with boulders																																															
2.00 - 2.45 2.00 - 2.40 2.30 - 2.80 2.40 - 2.50	SPT T B T		91.80		2.30	Reddish brown silty sandy PEAT																																															
3.00 - 3.45 3.00 - 3.45	SPT T	N=11	91.30		2.80	Grey brown gravelly SAND with cobbles.																																															
4.00 - 4.50 4.00 - 4.45 4.00 - 4.45	B SPT T	N=20																																																			
5.00 - 5.50 5.00 - 5.45 5.00 - 5.45	B SPT T	N=35																																																			
6.00	T																																																				
7.00 - 7.50 7.00 - 7.45 7.00 - 7.45	B SPT T	N=8	87.20		6.90	Brown sandy gravelly CLAY																																															
8.00 - 8.45	U	V=100 blows, 0% rec				Borehole Continues																																															
KEY D - Disturbed Sample B - Bulk Sample U - Undisturbed W - Water Sample S - Standard Penetration Test C - Cone Penetration Test N - Penetration Test 'N' Value V - Hand Shear Vane kPa ▽ - Groundwater Strike ▼ - Groundwater Level			REMARKS Vacuum excavation used to clear services in starter pit to a depth of 1.3m. SPT N values corrected where taken in granular deposits. BH coordinates and elevation estimated from topographic survey information Scale: 1:50			Water Strikes <table><tr><th>Date</th><th>Strike</th><th>Level</th><th>Minutes</th><th>Casing</th><th>Sealed</th></tr><tr><td>28/02/2022</td><td>5</td><td>4.5</td><td></td><td></td><td></td></tr><tr><td>01/03/2022</td><td>11.8</td><td>6.9</td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td></tr></table> Daily Log Of Depths <table><tr><th>Date</th><th>Casing</th><th>Water</th><th>From</th><th>To</th><th>Hours</th></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td></tr></table> Chiselling						Date	Strike	Level	Minutes	Casing	Sealed	28/02/2022	5	4.5				01/03/2022	11.8	6.9										Date	Casing	Water	From	To	Hours												
						Date	Strike	Level	Minutes	Casing	Sealed																																										
						28/02/2022	5	4.5																																													
						01/03/2022	11.8	6.9																																													
						Date	Casing	Water	From	To	Hours																																										

			Project Title: Bury Market			BH01		
			Project Number: 5237		Client: Bury Council			
			GL (mAOD): 94.10		N Coord: 410561.5	E Coord: 380633.1		
Date: 28/02/2022-01/03/2022			Method: Cable Percussion		Driller: Lundy SI	Logged By: MJ		
Depth (m)	Type	Test Result	Level	Legend	Depth (m)	Description	Water	Standpipe
9.30 - 9.80	B					Brown sandy gravelly CLAY		
10.00 - 10.45	SPT	N=50	83.90		10.20			
10.00 - 10.45	T					Brown fine SAND		
11.20 - 11.65	SPT	N=50						
11.50 - 11.95	T							
12.20 - 12.70	B		82.00		12.10			
12.40	T					Green brown silty slightly gravelly CLAY		
13.00 - 13.50	B	N=35						
13.00 - 13.45	SPT							
13.00 - 13.45	T							
14.40 - 14.80	B	N=50	80.00		14.10			
14.40	T					Grey MUDSTONE		
14.50 - 14.95	SPT	N=50						
14.50 - 14.95	T							
14.90 - 15.20	SPT							
14.90 - 15.20	T		78.90		15.20			
						End Of Borehole At 15.20 m		
KEY D - Disturbed Sample B - Bulk Sample U - Undisturbed W - Water Sample S - Standard Penetration Test C - Cone Penetration Test N - Penetration Test 'N' Value V - Hand Shear Vane kPa ▽ - Groundwater Strike ▼ - Groundwater Level			REMARKS Vacuum excavation used to clear services in starter pit to a depth of 1.3m. SPT N values corrected where taken in granular deposits. BH coordinates and elevation estimated from topographic survey information Scale: 1:50			Water Strikes		
						Date	Strike	Level
						28/02/2022	5	4.5
						01/03/2022	11.8	6.9
						Daily Log Of Depths		
						Chiselling		
						Date	Casing	Water

 iD GeoEnvironmental Limited			Project Title: Bury Market				BH02		
			Project Number: 5237		Client: Bury Council				
			GL (mAOD): 93.70		N Coord: 410537.1		E Coord: 380546.2		
Date: 02/03/2022-03/03/2022			Method: Cable Percussion		Driller: Lundy SI		Logged By: MJ		
Depth (m)	Type	Test Result	Level	Legend	Depth (m)	Description	Water	Standpipe	
1.00 1.00 1.00 1.40 - 1.80 1.40 - 1.80 1.50 - 2.00 2.00 - 2.45 2.00 - 2.45 2.30 - 2.80 2.50 2.50 2.50 3.00 - 3.45 3.00 - 3.45 4.00 - 4.45 4.00 - 4.45 5.00 - 5.45 5.00 - 5.45 5.50 5.50 6.00 6.50 - 6.95 7.00 - 7.50 8.00 - 8.50 8.00 - 8.45 8.00 - 8.45	J T V SPT T B SPT T B J T V SPT T SPT T J V T U B B SPT T	N=18 <							

 iD GeoEnvironmental Limited			Project Title: Bury Market				BH02						
			Project Number: 5237		Client: Bury Council								
			GL (mAOD): 93.70		N Coord: 410537.1		E Coord: 380546.2						
Date: 02/03/2022-03/03/2022			Method: Cable Percussion		Driller: Lundy SI		Logged By: MJ						
Depth (m)	Type	Test Result	Level	Legend	Depth (m)	Description	Water	Standpipe					
9.50 - 9.95 9.50 - 9.95	SPT T	N=50			10.30	Brown fine SAND							
11.00 - 11.50 11.00 - 11.45 11.00 - 11.45	B SPT T	N=30				Green brown slightly gravelly CLAY with cobbles							
12.00	T												
12.40 12.50 - 12.95	T U	V=100 blows, 60% rec											
13.00	T												
13.50	T												
14.00 - 14.45 14.00 - 14.45	SPT T	N=50											
14.40 - 14.90	B				79.20	14.50			Grey MUDSTONE				
15.40 - 15.80 15.40 - 15.85	SPT T	N=50			77.90	15.80			End Of Borehole At 15.80 m				
KEY					REMARKS				Water Strikes				
D - Disturbed Sample B - Bulk Sample U - Undisturbed W - Water Sample S - Standard Penetration Test C - Cone Penetration Test N - Penetration Test 'N' Value V - Hand Shear Vane kPa ▽ - Groundwater Strike ▼ - Groundwater Level			Vacuum excavation used to clear services in starter pit to a depth of 1.3m. SPT N values corrected where taken in granular deposits. BH coordinates and elevation estimated from topographic survey information Scale: 1:50			Date			Strike	Level	Minutes	Casing	Sealed
						02/03/2022			4.8	4.1			
			Daily Log Of Depths			Chiselling							
			Date	Casing	Water	From	To	Hours					

 iD GeoEnvironmental Limited			Project Title: Bury Market				WS01				
			Project Number: 5237		Client: Bury Council		Sheet 1 Of 1				
			GL (mAOD): 94.00		N Coord: 410630.7		E Coord: 380671.4				
Date: 21/02/2022			Method: Window Sampler		Driller: Earth Engineering		Logged By: MJ				
Depth (m)	Type	Test Result	Level	Legend	Depth (m)	Description	Water	Standpipe			
0.50 0.50	J T	N=5	93.91 93.75 93.50		0.09 0.25 0.50	MADE GROUND: Black macadam					
1.20 1.20 - 1.65 1.20	J SPT T		93.00		1.00	MADE GROUND: Grey sandy gravel and cobble.					
2.00 - 2.45	SPT					MADE GROUND: Red sandy gravel with cobbles of brick					
2.90 3.00 - 3.45	T SPT	N=15	91.50 91.20 90.80		2.50 2.80 3.20	MADE GROUND: Black gravelly sand of ash and clinker with occasional brick cobble.					
3.70	T		90.00		4.00	MADE GROUND: Grey brown very gravelly cobbly sand. Strata is wet from 2.1m					
4.00 - 5.00 4.00 - 4.45 4.20	B SPT T		89.00		5.00	MADE GROUND: Black silty SAND with much organic matter.					
						Brown very silty SAND with organic matter noted					
						Grey very clayey gravelly cobbly SAND. Sand is damp from 3.6m					
						Brown SAND and GRAVEL with occasional cobble. Strata is wet.					
						End Of Borehole At 5.00 m					
KEY D - Disturbed Sample B - Bulk Sample U - Undisturbed W - Water Sample S - Standard Penetration Test C - Cone Penetration Test N - Penetration Test 'N' Value V - Hand Shear Vane kPa ▽ - Groundwater Strike ▼ - Groundwater Level			REMARKS No Groundwater Encountered No visual or olfactory evidence of hydrocarbon contamination encountered. WS coordinates and elevation estimated from topographic survey information Scale: 1:40			Water Strikes					
						Date	Strike	Level	Minutes	Casing	Sealed
						Daily Log Of Depths			Chiselling		
						Date	Casing	Water	From	To	Hours

 iD GeoEnvironmental Limited			Project Title: Bury Market				WS02				
			Project Number: 5237		Client: Bury Council						
			GL (mAOD): 94.00		N Coord: 410573.3		Sheet 1 Of 1		E Coord: 380657.7		
Date: 21/02/2022			Method: Window Sampler		Driller: Earth Engineering		Logged By: MJ				
Depth (m)	Type	Test Result	Level	Legend	Depth (m)	Description	Water	Standpipe			
0.60	J T		93.85		0.15	MADE GROUND: Black macadam					
0.60			93.60		0.40	MADE GROUND: Grey sandy gravel and cobble.					
1.00 - 1.50	B	N=6	92.90		1.10	MADE GROUND: Brown very gravelly cobbly sand. Gravel and cobble is of sandstone and brick					
1.20 - 1.65	SPT										
1.50	T	N=4				Yellow brown very gravelly cobbly SAND					
2.00 - 2.45	SPT										
3.00 - 4.00	B	N=11	91.20		2.80	Grey clayey gravelly SAND with cobbles. Sand is wet from 3.2m. Band of brown sandy gravelly clay from 4.3-4.7m.					
3.00 - 3.45	SPT										
3.50	T	N=8									
4.00 - 4.45	SPT										
			89.00		5.00	End Of Borehole At 5.00 m					
KEY D - Disturbed Sample B - Bulk Sample U - Undisturbed W - Water Sample S - Standard Penetration Test C - Cone Penetration Test N - Penetration Test 'N' Value V - Hand Shear Vane kPa ▽ - Groundwater Strike ▼ - Groundwater Level			REMARKS No Groundwater Encountered No visual or olfactory evidence of hydrocarbon contamination encountered. WS coordinates and elevation estimated from topographic survey information Scale: 1:40			Water Strikes					
						Date	Strike	Level	Minutes	Casing	Sealed
						Daily Log Of Depths			Chiselling		
						Date	Casing	Water	From	To	Hours

 iD GeoEnvironmental Limited			Project Title: Bury Market				WS03				
			Project Number: 5237		Client: Bury Council						
			GL (mAOD): 93.90		N Coord: 410563.4		Sheet 1 Of 1		E Coord: 380594.2		
Date: 24/02/2022			Method: Window Sampler		Driller: Earth Engineering		Logged By: MJ				
Depth (m)	Type	Test Result	Level	Legend	Depth (m)	Description	Water	Standpipe			
0.50 0.50	J T		93.80 93.50		0.10 0.40	MADE GROUND: Black macadam MADE GROUND: Brown very sandy gravel and cobble. MADE GROUND: Brown very gravelly cobbly sand with some fragments of clinker noted.					
1.20 - 1.65	SPT	N=9	92.70		1.20	MADE GROUND: Brown and grey very clayey gravelly sand. Fragments of ceramic tile noted.					
2.00 - 2.45	SPT	N=22	92.10 92.00		1.80 1.90	Reddish brown SAND with some organic matter noted. Yellow brown with grey patches slightly clayey very gravelly cobbly SAND. Strata is wet from 4.3m.					
2.50 - 3.50	B										
2.80	T										
3.00 - 3.45	SPT	N=30									
4.00 - 4.45	SPT	N=23									
4.70 4.70	J V		88.90		5.00	End Of Borehole At 5.00 m					
KEY D - Disturbed Sample B - Bulk Sample U - Undisturbed W - Water Sample S - Standard Penetration Test C - Cone Penetration Test N - Penetration Test 'N' Value V - Hand Shear Vane kPa ▽ - Groundwater Strike ▼ - Groundwater Level			REMARKS No Groundwater Encountered No visual or olfactory evidence of hydrocarbon contamination encountered. WS coordinates and elevation estimated from topographic survey information Scale: 1:40			Water Strikes					
						Date	Strike	Level	Minutes	Casing	Sealed
						Daily Log Of Depths			Chiselling		
						Date	Casing	Water	From	To	Hours

 iD GeoEnvironmental Limited			Project Title: Bury Market				WS04A				
			Project Number: 5237		Client: Bury Council					Sheet 1 Of 1	
			GL (mAOD): 94.20		N Coord: 410527.7		E Coord: 380635.1				
Date: 22/02/2022			Method: Window Sampler		Driller: Earth Engineering		Logged By: MJ				
Depth (m)	Type	Test Result	Level	Legend	Depth (m)	Description	Water	Standpipe			
0.50 0.50	J T	N=4	94.10		0.10	MADE GROUND: Black macadam					
1.20 1.20 - 1.65 1.20	J SPT T		93.90		0.30	MADE GROUND: Grey sandy gravel and cobble.					
2.00 - 2.45	SPT	N=14	93.30		0.90	MADE GROUND: Brown very gravelly cobbly sand. Gravel and cobble is of sandstone and brick					
3.00 - 3.45	SPT	N=17	92.00		2.20	0.70 - 0.80 Electricity brick and asbestos pipe encountered in hand pit. Pit extended to the north and progressed to 1.2m MADE GROUND: Brown very gravelly sand with rare brick cobble.					
4.00 - 4.45	SPT	N=8	90.30		3.90	Orange brown with black patches slightly clayey very gravelly SAND with occasional sandstone cobbles.					
4.50	T		89.20		5.00	Orange brown very gravelly cobbly SAND. Strata is wet from 4.0m					
						End Of Borehole At 5.00 m					
KEY D - Disturbed Sample B - Bulk Sample U - Undisturbed W - Water Sample S - Standard Penetration Test C - Cone Penetration Test N - Penetration Test 'N' Value V - Hand Shear Vane kPa ▽ - Groundwater Strike ▼ - Groundwater Level			REMARKS No Groundwater Encountered No visual or olfactory evidence of hydrocarbon contamination encountered. WS coordinates and elevation estimated from topographic survey information Scale: 1:40			Water Strikes					
						Date	Strike	Level	Minutes	Casing	Sealed
						Daily Log Of Depths			Chiselling		
						Date	Casing	Water	From	To	Hours

 iD GeoEnvironmental Limited			Project Title: Bury Market				WS05				
			Project Number: 5237		Client: Bury Council				Sheet 1 Of 1		
			GL (mAOD): 94.20		N Coord: 410509.1		E Coord: 380604.3				
Date: 22/02/2022			Method: Window Sampler		Driller: Earth Engineering		Logged By: MJ				
Depth (m)	Type	Test Result	Level	Legend	Depth (m)	Description	Water	Standpipe			
0.70 0.70	J T	N=6	94.10		0.10	MADE GROUND: Black macadam					
1.20 1.20 - 1.65	J SPT		93.80		0.40	MADE GROUND: Brown very sandy gravel and cobble.					
2.00 - 2.45	SPT	N=15	92.50		1.70	MADE GROUND: Black gravelly sand of ash with occasional brick gravel and cobble.					
2.50	T	N=20	92.00		2.20	Brown mottled grey sandy gravelly CLAY with occasional sandstone and quartz cobble.					
3.00 - 3.45	SPT		91.00		3.20	Dark brown with black patches very cobbly SAND and GRAVEL. Strata is wet from 4.0m					
4.00 - 4.45	SPT	N=15	89.20		5.00	End Of Borehole At 5.00 m					
4.50 4.50	J V										
KEY D - Disturbed Sample B - Bulk Sample U - Undisturbed W - Water Sample S - Standard Penetration Test C - Cone Penetration Test N - Penetration Test 'N' Value V - Hand Shear Vane kPa ▽ - Groundwater Strike ▼ - Groundwater Level			REMARKS No Groundwater Encountered No visual or olfactory evidence of hydrocarbon contamination encountered. WS coordinates and elevation estimated from topographic survey information Scale: 1:40			Water Strikes					
						Date	Strike	Level	Minutes	Casing	Sealed
						Daily Log Of Depths		Chiselling			
						Date	Casing	Water	From	To	Hours

DYNAMIC PROBE TEST RESULT

Project Title: Bury Market

Project No: 5237

Client: Bury Council

Date: 21/02/2022


WS01

N Coord: 380671.4

E Coord: 410630.7

GL (mAOD): 94.00

Depth (m)	DP Blows/100mm
5.0	0
5.1	2
5.2	3
5.3	3
5.4	3
5.5	2
5.6	3
5.7	2
5.8	2
5.9	3
6.0	3
6.1	3
6.2	3
6.3	3
6.4	3
6.5	2
6.6	3
6.7	2
6.8	2
6.9	1
7.0	2
7.1	1
7.2	2
7.3	3
7.4	3
7.5	4
7.6	4
7.7	4
7.8	5
7.9	7
8.0	6
8.1	6
8.2	5
8.3	5
8.4	5
8.5	5
8.6	4
8.7	3
8.8	3
8.9	4
9.0	4
9.1	5
9.2	5
9.3	6
9.4	6
9.5	7
9.6	10
9.7	12
9.8	13
9.9	0
10.0	0



DYNAMIC PROBE TEST RESULT

Project Title: Bury Market

Project No: 5237

Client: Bury Council

Date: 21/02/2022


WS02

E Coord: 380657.7

N Coord: 410573.3

GL (mAOD): 94.00

Depth (m)	DP Blows/100mm
5.0	15 13 16 16 1
5.5	9 10 11 13 12
6.0	12 12 13 15 12
6.5	15 9 7 4 13
7.0	3 4 6 7 3
7.5	6 3 2 2 7
8.0	4 4 4 5 2
8.5	7 8 7 7 5
9.0	9 12 11 11 8
9.5	13 14 15 15 13
10.0	0



DYNAMIC PROBE TEST RESULT

Project Title: Bury Market

Project No: 5237

Client: Bury Council

Date: 24/02/2022


WS03

E Coord: 380594.2

N Coord: 410563.4

GL (mAOD): 93.90

Depth (m)	DP Blows/100mm
5.0	2
5.2	2
5.4	2
5.6	2
5.8	1
6.0	1
6.2	2
6.4	3
6.6	2
6.8	3
7.0	3
7.2	3
7.4	3
7.6	3
7.8	4
8.0	3
8.2	3
8.4	8
8.6	8
8.8	8
9.0	8
9.2	10
9.4	12
9.6	13
9.8	13
10.0	13
10.2	14
10.4	14
10.6	15
10.8	15
11.0	16
11.2	18
11.4	18
11.6	20
11.8	21
12.0	22
12.2	24
12.4	32
12.6	33
12.8	33
13.0	0



DYNAMIC PROBE TEST RESULT

Project Title: Bury Market

Project No: 5237

Client: Bury Council

Date: 22/02/2022


WS04A

E Coord: 380635.1

N Coord: 410527.7

GL (mAOD): 94.20

Depth (m)	DP Blows/100mm
5.0	0
5.1	4
5.2	4
5.3	3
5.4	4
5.5	4
5.6	3
5.7	5
5.8	5
5.9	6
6.0	7
6.1	7
6.2	5
6.3	4
6.4	5
6.5	3
6.6	5
6.7	3
6.8	3
6.9	4
7.0	5
7.1	6
7.2	7
7.3	6
7.4	7
7.5	8
7.6	10
7.7	10
7.8	11
7.9	10
8.0	11
8.1	11
8.2	12
8.3	12
8.4	14
8.5	13
8.6	22
8.7	20
8.8	20
8.9	29
9.0	50
9.1	0
9.2	0
9.3	0
9.4	0
9.5	0
9.6	0
9.7	0
9.8	0
9.9	0
10.0	0



DYNAMIC PROBE TEST RESULT

Project Title: Bury Market

Project No: 5237

Client: Bury Council

Date: 22/02/2022


WS05

E Coord: 380604.3

N Coord: 410509.1

GL (mAOD): 94.20

Depth (m)	DP Blows/100mm
5.0	0
5.1	1
5.2	2
5.3	6
5.4	7
5.5	11
5.6	8
5.7	4
5.8	5
5.9	9
6.0	4
6.1	3
6.2	3
6.3	3
6.4	3
6.5	3
6.6	5
6.7	5
6.8	6
6.9	8
7.0	7
7.1	8
7.2	8
7.3	7
7.4	11
7.5	13
7.6	12
7.7	11
7.8	12
7.9	9
8.0	10
8.1	9
8.2	9
8.3	10
8.4	17
8.5	23
8.6	21
8.7	23
8.8	26
8.9	27
9.0	20
9.1	24
9.2	50
9.3	0
9.4	0
9.5	0
9.6	0
9.7	0
9.8	0
9.9	0
10.0	0



Appendix E

Hole ID	Depth (m)	Material	Table 1: Inorganic Determinands - Concentrations in mg/kg unless otherwise stated. Critical Concentrations (GAC) are shown below											
			pH	As	Cd	Cr (III)	Cu	Pb	Hg	Ni	Se	Zn	SO ₄ (g/l)	Asbestos
S4UL Commerical Land		640		190	8600	68000	2330	1100	980	12000	730000			
WS01	0.50	Ash & Clinker	8.6	16	13	25	2490	268	<0.35	70	<2	266	0.03	NAD
WS01	1.20	Granular Made Ground	8.9	3.0	1.4	6.0	219	68	<0.35	11	<2	37	0.02	NAD
WS01	3.70	Sand	5.8	-	-	-	-	-	-	-	-	-	0.02	-
WS01	4.20	Sand & Gravel	7.3	-	-	-	-	-	-	-	-	-	0.03	-
WS02	0.60	Granular Made Ground	9.5	<1	<0.5	11	28	16	<0.17	18	<1	32	0.02	NAD
WS02	3.50	Sand	8.9	-	-	-	-	-	-	-	-	-	0.06	-
WS03	0.50	Granular Made Ground	8.2	4.0	0.6	13	27	27	<0.17	14	<1	44	0.07	NAD
WS04A	0.50	Granular Made Ground	10.0	<2	1.4	17	21	17	<0.35	25	<2	54	0.02	NAD
WS04A	1.20	Granular Made Ground	9.6	<2	1.3	18	17	49	<0.35	23	<2	65	0.03	NAD
WS05	0.70	Granular Made Ground	9.4	5.0	<1.0	12	13	463	0.93	7.0	<2	23	0.03	NAD
WS05	4.50	Sand & Gravel	8.3	-	-	-	-	-	-	-	-	-	0.02	-
BH01	5.00	Sand	8.7	-	-	-	-	-	-	-	-	-	0.02	-
BH01	7.00	Cohesive Superfical Deposits	8.9	-	-	-	-	-	-	-	-	-	0.03	-
BH01	11.50	Sand	8.9	-	-	-	-	-	-	-	-	-	0.02	-
BH01	13.00	Cohesive Superfical Deposits	8.6	-	-	-	-	-	-	-	-	-	0.03	-
BH01	14.90	Mudstone	8.9	-	-	-	-	-	-	-	-	-	<0.01	-
BH02	1.00	Gravelly Sand - Possibly Reworked	6.4	<1	<0.5	13	7.0	11	<0.17	10	<1	27	0.06	NAD
BH02	1.40	Gravelly Sand - Possibly Reworked	5.7	-	-	-	-	-	-	-	-	-	0.04	-
BH02	6.00	Cohesive Superfical Deposits	8.9	-	-	-	-	-	-	-	-	-	0.02	-
BH02	8.00	Sand	9.0	-	-	-	-	-	-	-	-	-	0.04	-
BH02	11.00	Cohesive Superfical Deposits	9.0	-	-	-	-	-	-	-	-	-	0.02	-
BH02	13.50	Cohesive Superfical Deposits	8.9	-	-	-	-	-	-	-	-	-	0.02	-
BH02	15.40	Mudstone	8.8	-	-	-	-	-	-	-	-	-	<0.01	-

Key		Source of Critical Concentration
BOLD	Determinand in excess of critical concentration	For source of Generic Assessment Criteria refer to Generic Notes 4 "Contamination Assessment"
-	Determinand not tested for	
<	Determinand concentration is below indicated "method" level of detection	
NAD	Abestos not detected	

Hole ID	Depth (m)	Material	Table 2: Speciated Polycyclic Aromatic Hydrocarbons - Concentrations in mg/kg unless otherwise stated. Critical Concentrations (GAC) are shown below																	
			TOC	SOM	Acenaphthene	Acenaphthylene	Anthracene	Benzo(a)anthracene	Benzo(a)pyrene	Benzo(b)fluoranthene	Benzo(g,h,i)perylene	Benzo(k)fluoranthene	Chrysene	Dibenz(a,h)anthracene	Fluoranthene	Fluorene	Indeno(123-cd)pyrene	Naphthalene	Phenanthrene	Pyrene
S4UL Commercial Land (1% SOM)			%	%	84000	83000	520000	170	35	44	3900	1200	350	3.5	23000	63000	500	190	22000	54000
WS01	0.50	Ash & Clinker	7.2	12.4	<0.01	<0.01	<0.02	<0.04	<0.04	<0.05	<0.05	<0.07	<0.06	<0.04	<0.08	<0.01	<0.03	<0.03	<0.03	<0.07
WS01	1.20	Granular Made Ground	2.2	3.8	<0.01	<0.01	<0.02	<0.04	<0.04	<0.05	<0.05	<0.07	<0.06	<0.04	<0.08	<0.01	<0.03	<0.03	<0.03	<0.07
WS02	0.60	Granular Made Ground	0.7	1.2	0.47	<0.01	0.54	0.94	0.89	0.97	0.31	0.35	0.96	0.08	2.66	0.26	0.44	0.22	2.33	2.17
WS03	0.50	Granular Made Ground	1.4	2.4	<0.01	<0.01	<0.02	0.04	0.04	0.06	<0.05	<0.07	<0.06	<0.04	0.08	<0.01	<0.03	<0.03	0.07	0.08
WS04A	0.50	Granular Made Ground	0.4	0.7	0.06	<0.01	0.09	0.19	0.21	0.24	0.12	0.08	0.24	<0.04	0.53	0.04	0.13	<0.03	0.37	0.47
WS04A	1.20	Granular Made Ground	1.1	1.9	0.06	<0.01	0.12	0.26	0.21	0.25	0.08	0.08	0.28	<0.04	0.63	0.05	0.11	<0.03	0.46	0.52
WS05	0.70	Granular Made Ground	1.8	3.1	0.04	<0.01	0.06	0.09	0.10	0.11	0.07	<0.07	0.10	<0.04	0.22	0.03	0.07	<0.03	0.21	0.19
BH02	1.00	Gravelly Sand - Possibly Reworked	0.4	0.7	<0.01	<0.01	<0.02	<0.04	<0.04	<0.05	<0.05	<0.07	<0.06	<0.04	<0.08	<0.01	<0.03	<0.03	<0.03	<0.07

Key		Source of Critical Concentration
BOLD	Determinand in excess of critical concentration	For source of Generic Assessment Criteria refer to Generic Notes 4 "Contamination Assessment"
-	Determinand not tested for	
<	Determinand concentration is below indicated "method" level of detection	

Hole ID	Depth (m)	Material	Table 3: Speciated Total Petroleum Hydrocarbons - Concentrations in mg/kg unless otherwise stated. Critical Concentrations (GAC) are shown below																			
			TOC	SOM	BTEX				Aliphatic TPH Bandings							Aromatic TPH Bandings						
					Benzene	Toluene	Ethyl Benzene	Xylenes	C ₅ -C ₆	C ₆ -C ₈	C ₈ -C ₁₀	C ₁₀ -C ₁₂	C ₁₂ -C ₁₆	C ₁₆ -C ₂₁	C ₂₁ -C ₃₅	EC ₅ -EC ₇	EC ₇ -EC ₈	EC ₈ -EC ₁₀	EC ₁₀ -EC ₁₂	EC ₁₂ -EC ₁₆	EC ₁₆ -EC ₂₁	EC ₂₁ -EC ₃₅
S4UL Commerial (1% SOM)			%	%	27	56000	5700	5900	3200	7800	2000	9700	59000	1600000	1600000	26000	56000	3500	16000	36000	28000	28000
WS03	4.7	Sand	0.44	0.8	<0.01	0.04	<0.01	0.05	<0.01	0.02	<1	<1	2	2	20	<0.01	0.04	<1	<1	2	2	9
WS05	4.5	Sand & Gravel	0.32	0.6	<0.01	<0.01	<0.01	<0.02	<0.01	<0.01	<1	<1	2	2	47	<0.01	<0.01	<1	<1	2	2	2
BH02	1.0	Gravelly Sand - Possibly Reworked	0.42	0.7	<0.01	<0.01	<0.01	0.04	<0.01	<0.01	<1	<1	<1	<1	3	<0.01	<0.01	<1	<1	<1	<1	2
BH02	2.5	Sand	0.72	1.2	<0.01	<0.01	<0.01	<0.02	<0.01	<0.01	<1	<1	<1	<1	6	<0.01	<0.01	<1	<1	<1	<1	2
BH02	5.5	Sand & Gravel	0.15	0.3	<0.01	<0.01	<0.01	<0.02	<0.01	<0.01	<1	<1	<1	<1	3	<0.01	<0.01	<1	<1	<1	<1	1

Key		Source of Critical Concentration
BOLD	Parameter tested and found to be in excess of critical concentration	For source of Generic Assessment Criteria refer to Generic Notes 4 "Contamination Assessment"
-	Determinand not tested for	
<	Determinand concentration is below indicated "method" level of detection	

Hole ID	Water Body	Table 4: Concentrations in µg/l unless otherwise stated. Critical Concentrations (GAC) are shown below. ¹																
		PAH				BTEX				Aliphatic TPH Bandings				Aromatic TPH Bandings ³				
		Acenaphthene	Acenaphthylene	Fluorene	Naphthalene	Benzene	Toluene	Ethyl Benzene	Xylenes ⁴	C ₅ -C ₆	C ₆ -C ₈	C ₈ -C ₁₀	C ₁₀ -C ₁₂	EC ₅ -EC ₇	EC ₇ -EC ₈	EC ₈ -EC ₁₀	EC ₁₀ -EC ₁₂	EC ₁₂ -EC ₁₆
SoBRA GAC _{gwvap} Commerical ²		15,000,000	20,000,000	18,000,000	23,000	20,000	21,000,000	960,000	940,000	190,000	150,000	5,700	3,600	20,000,000	21,000,000	190,000	660,000	3,700,000
BH02	Lower groundwater body	<1	<1	<1	<1	<1	<1	<1	<2	<1	<1	5	5	<1	<1	8	6	<5
WS05	Upper groundwater body	<1	<1	<1	<1	<1	<1	<1	<2	<1	<1	<5	<5	<1	<1	5	<5	5

Key		Source of Critical Concentration	
BOLD	Parameter tested and found to be in excess of critical concentration	1	SoBRA "Development of Generic Assessment Criteria from volatile contaminants in groundwater" ver. 1.0.
-	Determinand not tested for	Selected Notes	
<	Determinand concentration is below indicated "method" level of detection	Within SoBRA's GAC _{gwvap} derivation methodology:	

Hole ID	Material	Table 5: Groundwater Organic Assessment - Concentrations in µg/l unless otherwise stated. Results are quoted to 4 significant figures. Critical Concentrations are shown below												
		Benzene	Toluene	Ethylbenzene	Xylene	Phenols	Dissolved TPH	PAH	Benzo(a)pyrene	Anthracene	Fluoranthene	Benzo(b,k)fluoranthene	Benzo(g,h,i)perylene & Indeno(1,2,3-cd)pyrene	Naphthalene
	GW General Quality 2015	0.75^	-	-	-	-	-	-	-	-	0.075^	-	-	0.075^
BH02	Lower groundwater body	<1	<1	<1	<1	-	36	-	<1	<1	<1	<2	<2	<1
WS05	Upper groundwater body	<1	<1	<1	<1	-	110	-	<1	<1	<1	<2	<2	<1

Key		Source of Critical Concentration	
BOLD	Determinand in excess of critical concentration	∞	Annual Average EQS for Priority Substances & other Pollutants - Inland Surface Waters, Table 1, Schedule 3, Part 3 – Water Framework Directive (England and Wales) Directions 2015
-	Determinand not tested for	#	Threshold Values for Groundwater - Table 1, Schedule 5, Groundwater Impacts on: Surface Waters, Water Framework Directive (England and Wales) Directions 2015
<	Determinand concentration is below indicated “method” level of detection	#	Threshold Values for Groundwater - Table 1, Schedule 5, GW Drinking Water Protected Areas, Water Framework Directive (England and Wales) Directions 2015
*	EQS for Specific Pollutants - Table 1, Schedule 3, Part 2, Water Framework Directive (England and Wales) Directions 2015		Threshold Values for Groundwater - Table 1, Schedule 5, General Quality of GW Body, Water Framework Directive (England and Wales) Directions 2015

FINAL ANALYTICAL TEST REPORT


Envirolab Job Number:
Issue Number:

Date:

Client:

Project Manager:
Project Name:
Project Ref:
Order No:
Date Samples Received:
Date Instructions Received:
Date Analysis Completed:

Approved by:



Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/1	22/02082/2	22/02082/4	22/02082/5	22/02082/6	22/02082/8	22/02082/9	Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	WS01	WS01	WS01	WS01	WS02	WS02	WS03			
Depth to Top	5.00	1.20	3.70	4.20	0.60	3.50	0.50			
Depth To Bottom										
Date Sampled	21-Feb-22	21-Feb-22	21-Feb-22	21-Feb-22	21-Feb-22	21-Feb-22	24-Feb-22			
Sample Type	Soil	Soil	Soil	Soil	Soil	Soil	Soil			
Sample Matrix Code	4A	4A	6A	4A	4A	6A	4A			
% Stones >10mm _A	<0.1	12.2	9.5	22.0	21.2	28.0	25.8	% w/w	0.1	A-T-044
pH _D ^{M#}	8.60	8.85	5.84	7.30	9.47	8.88	8.18	pH	0.01	A-T-031s
Sulphate (water sol 2:1) _D ^{M#}	0.03	0.02	0.02	0.03	0.02	0.06	0.07	g/l	0.01	A-T-026s
Total Organic Carbon _D ^{M#}	7.21	2.20	-	-	0.69	-	1.39	% w/w	0.03	A-T-032s
Arsenic _D ^{M#}	16	3	-	-	<1	-	4	mg/kg	1	A-T-024s
Cadmium _D ^{M#}	13.1	1.4	-	-	<0.5	-	0.6	mg/kg	0.5	A-T-024s
Copper _D ^{M#}	2490	219	-	-	28	-	27	mg/kg	1	A-T-024s
Chromium _D ^{M#}	25	6	-	-	11	-	13	mg/kg	1	A-T-024s
Lead _D ^{M#}	268	68	-	-	16	-	27	mg/kg	1	A-T-024s
Mercury _D	<0.35	<0.35	-	-	<0.17	-	<0.17	mg/kg	0.17	A-T-024s
Nickel _D ^{M#}	70	11	-	-	18	-	14	mg/kg	1	A-T-024s
Selenium _D ^{M#}	<2	<2	-	-	<1	-	<1	mg/kg	1	A-T-024s
Zinc _D ^{M#}	266	37	-	-	32	-	44	mg/kg	5	A-T-024s

Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/1	22/02082/2	22/02082/4	22/02082/5	22/02082/6	22/02082/8	22/02082/9	Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	WS01	WS01	WS01	WS01	WS02	WS02	WS03			
Depth to Top	5.00	1.20	3.70	4.20	0.60	3.50	0.50			
Depth To Bottom										
Date Sampled	21-Feb-22	21-Feb-22	21-Feb-22	21-Feb-22	21-Feb-22	21-Feb-22	24-Feb-22			
Sample Type	Soil	Soil	Soil	Soil	Soil	Soil	Soil			
Sample Matrix Code	4A	4A	6A	4A	4A	6A	4A			
Asbestos in Soil (inc. matrix)										
Asbestos in soil [#]	NAD	NAD	-	-	NAD	-	NAD			A-T-045
Asbestos Matrix (visual) _D	-	-	-	-	-	-	-			A-T-045
Asbestos Matrix (microscope) _D	-	-	-	-	-	-	-			A-T-045
Asbestos ACM - Suitable for Water Absorption Test? _D	N/A	N/A	-	-	N/A	-	N/A			A-T-045

Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/1	22/02082/2	22/02082/4	22/02082/5	22/02082/6	22/02082/8	22/02082/9	Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	WS01	WS01	WS01	WS01	WS02	WS02	WS03			
Depth to Top	5.00	1.20	3.70	4.20	0.60	3.50	0.50			
Depth To Bottom										
Date Sampled	21-Feb-22	21-Feb-22	21-Feb-22	21-Feb-22	21-Feb-22	21-Feb-22	24-Feb-22			
Sample Type	Soil	Soil	Soil	Soil	Soil	Soil	Soil			
Sample Matrix Code	4A	4A	6A	4A	4A	6A	4A			
PAH-16MS										
Acenaphthene _A ^{M#}	<0.01	<0.01	-	-	0.47	-	<0.01	mg/kg	0.01	A-T-019s
Acenaphthylene _A ^{M#}	<0.01	<0.01	-	-	<0.01	-	<0.01	mg/kg	0.01	A-T-019s
Anthracene _A ^{M#}	<0.02	<0.02	-	-	0.54	-	<0.02	mg/kg	0.02	A-T-019s
Benzo(a)anthracene _A ^{M#}	<0.04	<0.04	-	-	0.94	-	0.04	mg/kg	0.04	A-T-019s
Benzo(a)pyrene _A ^{M#}	<0.04	<0.04	-	-	0.89	-	0.04	mg/kg	0.04	A-T-019s
Benzo(b)fluoranthene _A ^{M#}	<0.05	<0.05	-	-	0.97	-	0.06	mg/kg	0.05	A-T-019s
Benzo(ghi)perylene _A ^{M#}	<0.05	<0.05	-	-	0.31	-	<0.05	mg/kg	0.05	A-T-019s
Benzo(k)fluoranthene _A ^{M#}	<0.07	<0.07	-	-	0.35	-	<0.07	mg/kg	0.07	A-T-019s
Chrysene _A ^{M#}	<0.06	<0.06	-	-	0.96	-	<0.06	mg/kg	0.06	A-T-019s
Dibenzo(ah)anthracene _A ^{M#}	<0.04	<0.04	-	-	0.08	-	<0.04	mg/kg	0.04	A-T-019s
Fluoranthene _A ^{M#}	<0.08	<0.08	-	-	2.66	-	0.08	mg/kg	0.08	A-T-019s
Fluorene _A ^{M#}	<0.01	<0.01	-	-	0.26	-	<0.01	mg/kg	0.01	A-T-019s
Indeno(123-cd)pyrene _A ^{M#}	<0.03	<0.03	-	-	0.44	-	<0.03	mg/kg	0.03	A-T-019s
Naphthalene _A ^{M#}	<0.03	<0.03	-	-	0.22	-	<0.03	mg/kg	0.03	A-T-019s
Phenanthrene _A ^{M#}	<0.03	<0.03	-	-	2.33	-	0.07	mg/kg	0.03	A-T-019s
Pyrene _A ^{M#}	<0.07	<0.07	-	-	2.17	-	0.08	mg/kg	0.07	A-T-019s
Total PAH-16MS _A ^{M#}	<0.08	<0.08	-	-	13.6	-	0.37	mg/kg	0.01	A-T-019s

Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/11	22/02082/12	22/02082/13	22/02082/15	22/02082/17	22/02082/21	22/02082/23	Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	WS03	WS04A	WS04A	WS05	WS05	BH01	BH01			
Depth to Top	4.70	0.50	1.20	0.70	4.50	5.00	7.00			
Depth To Bottom						5.45	7.45			
Date Sampled	24-Feb-22	22-Feb-22	22-Feb-22	22-Feb-22	22-Feb-22	28-Feb-22	28-Feb-22			
Sample Type	Soil	Soil	Soil	Soil	Soil	Soil	Soil			
Sample Matrix Code	4A	4A	4A	4AB	4A	4A	6A			
% Stones >10mm _A	28.6	25.6	16.2	13.4	27.7	17.5	10.4	% w/w	0.1	A-T-044
pH _D ^{M#}	-	9.99	9.58	9.42	8.33	8.69	8.85	pH	0.01	A-T-031s
Sulphate (water sol 2:1) _D ^{M#}	-	0.02	0.03	0.03	0.02	0.02	0.03	g/l	0.01	A-T-026s
Total Organic Carbon _D ^{M#}	0.44	0.40	1.12	1.78	0.32	-	-	% w/w	0.03	A-T-032s
Arsenic _D ^{M#}	-	<2	<2	5	-	-	-	mg/kg	1	A-T-024s
Cadmium _D ^{M#}	-	1.4	1.3	<1.0	-	-	-	mg/kg	0.5	A-T-024s
Copper _D ^{M#}	-	21	17	13	-	-	-	mg/kg	1	A-T-024s
Chromium _D ^{M#}	-	17	18	12	-	-	-	mg/kg	1	A-T-024s
Lead _D ^{M#}	-	17	49	463	-	-	-	mg/kg	1	A-T-024s
Mercury _D	-	<0.35	<0.35	0.93	-	-	-	mg/kg	0.17	A-T-024s
Nickel _D ^{M#}	-	25	23	7	-	-	-	mg/kg	1	A-T-024s
Selenium _D ^{M#}	-	<2	<2	<2	-	-	-	mg/kg	1	A-T-024s
Zinc _D ^{M#}	-	54	65	23	-	-	-	mg/kg	5	A-T-024s

Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/11	22/02082/12	22/02082/13	22/02082/15	22/02082/17	22/02082/21	22/02082/23	Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	WS03	WS04A	WS04A	WS05	WS05	BH01	BH01			
Depth to Top	4.70	0.50	1.20	0.70	4.50	5.00	7.00			
Depth To Bottom						5.45	7.45			
Date Sampled	24-Feb-22	22-Feb-22	22-Feb-22	22-Feb-22	22-Feb-22	28-Feb-22	28-Feb-22			
Sample Type	Soil	Soil	Soil	Soil	Soil	Soil	Soil			
Sample Matrix Code	4A	4A	4A	4AB	4A	4A	6A			
Asbestos in Soil (inc. matrix)										
Asbestos in soil [#]	-	NAD	NAD	NAD	-	-	-			A-T-045
Asbestos Matrix (visual) _D	-	-	-	-	-	-	-			A-T-045
Asbestos Matrix (microscope) _D	-	-	-	-	-	-	-			A-T-045
Asbestos ACM - Suitable for Water Absorption Test? _D	-	N/A	N/A	N/A	-	-	-			A-T-045

Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/11	22/02082/12	22/02082/13	22/02082/15	22/02082/17	22/02082/21	22/02082/23	Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	WS03	WS04A	WS04A	WS05	WS05	BH01	BH01			
Depth to Top	4.70	0.50	1.20	0.70	4.50	5.00	7.00			
Depth To Bottom						5.45	7.45			
Date Sampled	24-Feb-22	22-Feb-22	22-Feb-22	22-Feb-22	22-Feb-22	28-Feb-22	28-Feb-22			
Sample Type	Soil	Soil	Soil	Soil	Soil	Soil	Soil			
Sample Matrix Code	4A	4A	4A	4AB	4A	4A	6A			
PAH-16MS										
Acenaphthene _A ^{M#}	-	0.06	0.06	0.04	-	-	-	mg/kg	0.01	A-T-019s
Acenaphthylene _A ^{M#}	-	<0.01	<0.01	<0.01	-	-	-	mg/kg	0.01	A-T-019s
Anthracene _A ^{M#}	-	0.09	0.12	0.06	-	-	-	mg/kg	0.02	A-T-019s
Benzo(a)anthracene _A ^{M#}	-	0.19	0.26	0.09	-	-	-	mg/kg	0.04	A-T-019s
Benzo(a)pyrene _A ^{M#}	-	0.21	0.21	0.10	-	-	-	mg/kg	0.04	A-T-019s
Benzo(b)fluoranthene _A ^{M#}	-	0.24	0.25	0.11	-	-	-	mg/kg	0.05	A-T-019s
Benzo(ghi)perylene _A ^{M#}	-	0.12	0.08	0.07	-	-	-	mg/kg	0.05	A-T-019s
Benzo(k)fluoranthene _A ^{M#}	-	0.08	0.08	<0.07	-	-	-	mg/kg	0.07	A-T-019s
Chrysene _A ^{M#}	-	0.24	0.28	0.10	-	-	-	mg/kg	0.06	A-T-019s
Dibenzo(ah)anthracene _A ^{M#}	-	<0.04	<0.04	<0.04	-	-	-	mg/kg	0.04	A-T-019s
Fluoranthene _A ^{M#}	-	0.53	0.63	0.22	-	-	-	mg/kg	0.08	A-T-019s
Fluorene _A ^{M#}	-	0.04	0.05	0.03	-	-	-	mg/kg	0.01	A-T-019s
Indeno(123-cd)pyrene _A ^{M#}	-	0.13	0.11	0.07	-	-	-	mg/kg	0.03	A-T-019s
Naphthalene _A ^{M#}	-	<0.03	<0.03	<0.03	-	-	-	mg/kg	0.03	A-T-019s
Phenanthrene _A ^{M#}	-	0.37	0.46	0.21	-	-	-	mg/kg	0.03	A-T-019s
Pyrene _A ^{M#}	-	0.47	0.52	0.19	-	-	-	mg/kg	0.07	A-T-019s
Total PAH-16MS _A ^{M#}	-	2.77	3.11	1.29	-	-	-	mg/kg	0.01	A-T-019s

Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/11	22/02082/12	22/02082/13	22/02082/15	22/02082/17	22/02082/21	22/02082/23	Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	WS03	WS04A	WS04A	WS05	WS05	BH01	BH01			
Depth to Top	4.70	0.50	1.20	0.70	4.50	5.00	7.00			
Depth To Bottom						5.45	7.45			
Date Sampled	24-Feb-22	22-Feb-22	22-Feb-22	22-Feb-22	22-Feb-22	28-Feb-22	28-Feb-22			
Sample Type	Soil	Soil	Soil	Soil	Soil	Soil	Soil			
Sample Matrix Code	4A	4A	4A	4AB	4A	4A	6A			
TPH CWG with Clean Up *C1										
Ali >C5-C6 _A [#]	<0.01	-	-	-	<0.01	-	-	mg/kg	0.01	A-T-022s
Ali >C6-C8 _A [#]	0.02	-	-	-	<0.01	-	-	mg/kg	0.01	A-T-022s
Ali >C8-C10 _A	<1	-	-	-	<1	-	-	mg/kg	1	A-T-055s
Ali >C10-C12 _A ^{M#}	<1	-	-	-	<1	-	-	mg/kg	1	A-T-055s
Ali >C12-C16 _A ^{M#}	2	-	-	-	2	-	-	mg/kg	1	A-T-055s
Ali >C16-C21 _A ^{M#}	2	-	-	-	2	-	-	mg/kg	1	A-T-055s
Ali >C21-C35 _A ^{M#}	20	-	-	-	47	-	-	mg/kg	1	A-T-055s
Total Aliphatics _A	23	-	-	-	52	-	-	mg/kg	1	A-T-055s
Aro >C5-C7 _A [#]	<0.01	-	-	-	<0.01	-	-	mg/kg	0.01	A-T-022s
Aro >C7-C8 _A [#]	0.04	-	-	-	<0.01	-	-	mg/kg	0.01	A-T-022s
Aro >C8-C10 _A	<1	-	-	-	<1	-	-	mg/kg	1	A-T-055s
Aro >C10-C12 _A	<1	-	-	-	<1	-	-	mg/kg	1	A-T-055s
Aro >C12-C16 _A	2	-	-	-	2	-	-	mg/kg	1	A-T-055s
Aro >C16-C21 _A ^{M#}	2	-	-	-	2	-	-	mg/kg	1	A-T-055s
Aro >C21-C35 _A	9	-	-	-	2	-	-	mg/kg	1	A-T-055s
Total Aromatics _A	12	-	-	-	6	-	-	mg/kg	1	A-T-055s
TPH (Ali & Aro >C5-C35) _A	35	-	-	-	57	-	-	mg/kg	1	A-T-055s
BTEX - Benzene _A [#]	<0.01	-	-	-	<0.01	-	-	mg/kg	0.01	A-T-022s
BTEX - Toluene _A [#]	0.04	-	-	-	<0.01	-	-	mg/kg	0.01	A-T-022s
BTEX - Ethyl Benzene _A [#]	<0.01	-	-	-	<0.01	-	-	mg/kg	0.01	A-T-022s
BTEX - m & p Xylene _A [#]	0.03	-	-	-	<0.01	-	-	mg/kg	0.01	A-T-022s
BTEX - o Xylene _A [#]	0.02	-	-	-	<0.01	-	-	mg/kg	0.01	A-T-022s
MTBE _A [#]	<0.01	-	-	-	<0.01	-	-	mg/kg	0.01	A-T-022s

Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/25	22/02082/27	22/02082/30	22/02082/31	22/02082/32	22/02082/34	22/02082/35	Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH01	BH01	BH01	BH02	BH02	BH02	BH02			
Depth to Top	11.50	13.00	14.90	1.00	1.40	2.50	5.50			
Depth To Bottom	11.95	13.45	15.20		1.80					
Date Sampled	01-Mar-22	01-Mar-22	01-Mar-22	02-Mar-22	02-Mar-22	02-Mar-22	02-Mar-22			
Sample Type	Soil	Soil	Soil	Soil	Soil	Soil	Solid			
Sample Matrix Code	4A	6A	5A	5A	5A	6A	7			
% Stones >10mm _A	<0.1	7.0	14.3	4.4	32.6	14.3	<0.1	% w/w	0.1	A-T-044
pH _D ^{M#}	8.88	8.58	8.86	6.40	5.65	-	-	pH	0.01	A-T-031s
Sulphate (water sol 2:1) _D ^{M#}	0.02	0.03	<0.01	0.06	0.04	-	-	g/l	0.01	A-T-026s
Total Organic Carbon _D ^{M#}	-	-	-	0.42	-	0.72	0.15	% w/w	0.03	A-T-032s
Arsenic _D ^{M#}	-	-	-	<1	-	-	-	mg/kg	1	A-T-024s
Cadmium _D ^{M#}	-	-	-	<0.5	-	-	-	mg/kg	0.5	A-T-024s
Copper _D ^{M#}	-	-	-	7	-	-	-	mg/kg	1	A-T-024s
Chromium _D ^{M#}	-	-	-	13	-	-	-	mg/kg	1	A-T-024s
Lead _D ^{M#}	-	-	-	11	-	-	-	mg/kg	1	A-T-024s
Mercury _D	-	-	-	<0.17	-	-	-	mg/kg	0.17	A-T-024s
Nickel _D ^{M#}	-	-	-	10	-	-	-	mg/kg	1	A-T-024s
Selenium _D ^{M#}	-	-	-	<1	-	-	-	mg/kg	1	A-T-024s
Zinc _D ^{M#}	-	-	-	27	-	-	-	mg/kg	5	A-T-024s

Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/25	22/02082/27	22/02082/30	22/02082/31	22/02082/32	22/02082/34	22/02082/35	Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH01	BH01	BH01	BH02	BH02	BH02	BH02			
Depth to Top	11.50	13.00	14.90	1.00	1.40	2.50	5.50			
Depth To Bottom	11.95	13.45	15.20		1.80					
Date Sampled	01-Mar-22	01-Mar-22	01-Mar-22	02-Mar-22	02-Mar-22	02-Mar-22	02-Mar-22			
Sample Type	Soil	Soil	Soil	Soil	Soil	Soil	Solid			
Sample Matrix Code	4A	6A	5A	5A	5A	6A	7			
Asbestos in Soil (inc. matrix)										
Asbestos in soil [#]	-	-	-	NAD	-	-	-			A-T-045
Asbestos Matrix (visual) _D	-	-	-	-	-	-	-			A-T-045
Asbestos Matrix (microscope) _D	-	-	-	-	-	-	-			A-T-045
Asbestos ACM - Suitable for Water Absorption Test? _D	-	-	-	N/A	-	-	-			A-T-045

Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/25	22/02082/27	22/02082/30	22/02082/31	22/02082/32	22/02082/34	22/02082/35	Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH01	BH01	BH01	BH02	BH02	BH02	BH02			
Depth to Top	11.50	13.00	14.90	1.00	1.40	2.50	5.50			
Depth To Bottom	11.95	13.45	15.20		1.80					
Date Sampled	01-Mar-22	01-Mar-22	01-Mar-22	02-Mar-22	02-Mar-22	02-Mar-22	02-Mar-22			
Sample Type	Soil	Soil	Soil	Soil	Soil	Soil	Solid			
Sample Matrix Code	4A	6A	5A	5A	5A	6A	7			
PAH-16MS										
Acenaphthene _A ^{M#}	-	-	-	<0.01	-	-	-	mg/kg	0.01	A-T-019s
Acenaphthylene _A ^{M#}	-	-	-	<0.01	-	-	-	mg/kg	0.01	A-T-019s
Anthracene _A ^{M#}	-	-	-	<0.02	-	-	-	mg/kg	0.02	A-T-019s
Benzo(a)anthracene _A ^{M#}	-	-	-	<0.04	-	-	-	mg/kg	0.04	A-T-019s
Benzo(a)pyrene _A ^{M#}	-	-	-	<0.04	-	-	-	mg/kg	0.04	A-T-019s
Benzo(b)fluoranthene _A ^{M#}	-	-	-	<0.05	-	-	-	mg/kg	0.05	A-T-019s
Benzo(ghi)perylene _A ^{M#}	-	-	-	<0.05	-	-	-	mg/kg	0.05	A-T-019s
Benzo(k)fluoranthene _A ^{M#}	-	-	-	<0.07	-	-	-	mg/kg	0.07	A-T-019s
Chrysene _A ^{M#}	-	-	-	<0.06	-	-	-	mg/kg	0.06	A-T-019s
Dibenzo(ah)anthracene _A ^{M#}	-	-	-	<0.04	-	-	-	mg/kg	0.04	A-T-019s
Fluoranthene _A ^{M#}	-	-	-	<0.08	-	-	-	mg/kg	0.08	A-T-019s
Fluorene _A ^{M#}	-	-	-	<0.01	-	-	-	mg/kg	0.01	A-T-019s
Indeno(123-cd)pyrene _A ^{M#}	-	-	-	<0.03	-	-	-	mg/kg	0.03	A-T-019s
Naphthalene _A ^{M#}	-	-	-	<0.03	-	-	-	mg/kg	0.03	A-T-019s
Phenanthrene _A ^{M#}	-	-	-	<0.03	-	-	-	mg/kg	0.03	A-T-019s
Pyrene _A ^{M#}	-	-	-	<0.07	-	-	-	mg/kg	0.07	A-T-019s
Total PAH-16MS _A ^{M#}	-	-	-	<0.08	-	-	-	mg/kg	0.01	A-T-019s

Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/25	22/02082/27	22/02082/30	22/02082/31	22/02082/32	22/02082/34	22/02082/35	Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH01	BH01	BH01	BH02	BH02	BH02	BH02			
Depth to Top	11.50	13.00	14.90	1.00	1.40	2.50	5.50			
Depth To Bottom	11.95	13.45	15.20		1.80					
Date Sampled	01-Mar-22	01-Mar-22	01-Mar-22	02-Mar-22	02-Mar-22	02-Mar-22	02-Mar-22			
Sample Type	Soil	Soil	Soil	Soil	Soil	Soil	Solid			
Sample Matrix Code	4A	6A	5A	5A	5A	6A	7			
TPH CWG with Clean Up *C1										
Ali >C5-C6 _A [#]	-	-	-	<0.01	-	<0.01	<0.01	mg/kg	0.01	A-T-022s
Ali >C6-C8 _A [#]	-	-	-	<0.01	-	<0.01	<0.01	mg/kg	0.01	A-T-022s
Ali >C8-C10 _A	-	-	-	<1	-	<1	<1	mg/kg	1	A-T-055s
Ali >C10-C12 _A ^{M#}	-	-	-	<1	-	<1	<1	mg/kg	1	A-T-055s
Ali >C12-C16 _A ^{M#}	-	-	-	<1	-	<1	<1	mg/kg	1	A-T-055s
Ali >C16-C21 _A ^{M#}	-	-	-	<1	-	<1	<1	mg/kg	1	A-T-055s
Ali >C21-C35 _A ^{M#}	-	-	-	3	-	6	3	mg/kg	1	A-T-055s
Total Aliphatics _A	-	-	-	3	-	8	3	mg/kg	1	A-T-055s
Aro >C5-C7 _A [#]	-	-	-	<0.01	-	<0.01	<0.01	mg/kg	0.01	A-T-022s
Aro >C7-C8 _A [#]	-	-	-	<0.01	-	<0.01	<0.01	mg/kg	0.01	A-T-022s
Aro >C8-C10 _A	-	-	-	<1	-	<1	<1	mg/kg	1	A-T-055s
Aro >C10-C12 _A	-	-	-	<1	-	<1	<1	mg/kg	1	A-T-055s
Aro >C12-C16 _A	-	-	-	<1	-	<1	<1	mg/kg	1	A-T-055s
Aro >C16-C21 _A ^{M#}	-	-	-	<1	-	<1	<1	mg/kg	1	A-T-055s
Aro >C21-C35 _A	-	-	-	2	-	2	1	mg/kg	1	A-T-055s
Total Aromatics _A	-	-	-	2	-	3	1	mg/kg	1	A-T-055s
TPH (Ali & Aro >C5-C35) _A	-	-	-	6	-	11	4	mg/kg	1	A-T-055s
BTEX - Benzene _A [#]	-	-	-	<0.01	-	<0.01	<0.01	mg/kg	0.01	A-T-022s
BTEX - Toluene _A [#]	-	-	-	<0.01	-	<0.01	<0.01	mg/kg	0.01	A-T-022s
BTEX - Ethyl Benzene _A [#]	-	-	-	<0.01	-	<0.01	<0.01	mg/kg	0.01	A-T-022s
BTEX - m & p Xylene _A [#]	-	-	-	0.02	-	<0.01	<0.01	mg/kg	0.01	A-T-022s
BTEX - o Xylene _A [#]	-	-	-	0.02	-	<0.01	<0.01	mg/kg	0.01	A-T-022s
MTBE _A [#]	-	-	-	<0.01	-	<0.01	<0.01	mg/kg	0.01	A-T-022s

Envirolab Job Number: 22/02082

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/02082/36	22/02082/37	22/02082/38	22/02082/41	22/02082/43			Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH02	BH02	BH02	BH02	BH02					
Depth to Top	6.00	8.00	11.00	13.50	15.40					
Depth To Bottom		8.45	11.45		15.85					
Date Sampled	02-Mar-22	02-Mar-22	02-Mar-22	03-Mar-22	03-Mar-22					
Sample Type	Soil	Soil	Soil	Soil	Soil					
Sample Matrix Code	6A	6A	6A	6A	6A					
% Stones >10mm _A	5.5	3.0	<0.1	6.7	4.5			% w/w	0.1	A-T-044
pH _D ^{M#}	8.88	8.98	9.03	8.89	8.83			pH	0.01	A-T-031s
Sulphate (water sol 2:1) _D ^{M#}	0.02	0.04	0.02	0.02	<0.01			g/l	0.01	A-T-026s

REPORT NOTES

General

Soil chemical analysis:

TPH analysis of water by method A-T-007:

Electrical Conductivity of water by Method A-T-037:

Asbestos:

Predominant Matrix Codes:

Secondary Matrix Codes:

Key:

EPH CWG GCxGC ID from TPH CWG

Envirolab Deviating Samples Report

Client: iD GeoEnvironmental Ltd (Knutsford), Caledonian House, Tatton Street,
Knutsford, WA16 6AG

Project: Bury Market

Clients Project No: 5237

Project No: 22/02082

Date Received: 07/03/2022 (am)

Cool Box Temperatures (°C): 5.9 & 6.1

Lab Sample ID			
Client Sample No			
Client Sample ID/Depth			
Date Sampled			
Deviation Code			
	✓	✓	✓

Key

F Maximum holding time exceeded between sampling date and analysis for analytes listed below

Lab Sample ID			
Client Sample No			
Client Sample ID/Depth			
Date Sampled			
	✓	✓	✓

Envirolab Analysis Dates

Lab Sample ID												
Client Sample No												
Client Sample ID/Depth												
Date Sampled												

Lab Sample ID											
Client Sample No											
Client Sample ID/Depth											
Date Sampled											

Lab Sample ID			
Client Sample No			
Client Sample ID/Depth			
Date Sampled			

End of Report

FINAL ANALYTICAL TEST REPORT


Envirolab Job Number:
Issue Number:

Date:

Client:

Project Manager:
Project Name:
Project Ref:
Order No:
Date Samples Received:
Date Instructions Received:
Date Analysis Completed:

Approved by:



Envirolab Job Number: 22/03209

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/03209/1	22/03209/2						Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH02	WS05								
Depth to Top										
Depth To Bottom										
Date Sampled	31-Mar-22	31-Mar-22								
Sample Type	Water - EW	Water - EW								
Sample Matrix Code	N/A	N/A								
TPH CWG (w) with Clean Up *C1										
Ali >C5-C6 (w) _A [#]	<1	<1						µg/l	1	A-T-022w
Ali >C6-C8 (w) _A [#]	<1	<1						µg/l	1	A-T-022w
Ali >C8-C10 (w) _A [#]	5	<5						µg/l	5	A-T-055w
Ali >C10-C12 (w) _A [#]	5	<5						µg/l	5	A-T-055w
Ali >C12-C16 (w) _A [#]	<5	<5						µg/l	5	A-T-055w
Ali >C16-C21 (w) _A [#]	<5	<5						µg/l	5	A-T-055w
Ali >C21-C35 (w) _A [#]	12	94						µg/l	5	A-T-055w
Total Aliphatics (w) _A [#]	22	94						µg/l	5	A-T-055w
Aro >C5-C7 (w) _A [#]	<1	<1						µg/l	1	A-T-022w
Aro >C7-C8 (w) _A [#]	<1	<1						µg/l	1	A-T-022w
Aro >C8-C10 (w) _A	8	5						µg/l	5	A-T-055w
Aro >C10-C12 (w) _A [#]	6	<5						µg/l	5	A-T-055w
Aro >C12-C16 (w) _A [#]	<5	5						µg/l	5	A-T-055w
Aro >C16-C21 (w) _A [#]	<5	6						µg/l	5	A-T-055w
Aro >C21-C35 (w) _A	<10	<10						µg/l	10	A-T-055w
Total Aromatics (w) _A	14	16						µg/l	10	A-T-055w
TPH (Ali & Aro >C5-C35) (w) _A	36	110						µg/l	10	A-T-055w
BTEX - Benzene (w) _A [#]	<1	<1						µg/l	1	A-T-022w
BTEX - Toluene (w) _A [#]	<1	<1						µg/l	1	A-T-022w
BTEX - Ethyl Benzene (w) _A [#]	<1	<1						µg/l	1	A-T-022w
BTEX - m & p Xylene (w) _A [#]	<1	<1						µg/l	1	A-T-022w
BTEX - o Xylene (w) _A [#]	<1	<1						µg/l	1	A-T-022w
MTBE (w) _A [#]	<1	<1						µg/l	1	A-T-022w

REPORT NOTES

General

Soil chemical analysis:

TPH analysis of water by method A-T-007:

Electrical Conductivity of water by Method A-T-037:

Asbestos:

Predominant Matrix Codes:

Secondary Matrix Codes:

Key:

EPH CWG GCxGC ID from TPH CWG

Envirolab Deviating Samples Report

Client: iD GeoEnvironmental Ltd (Knutsford), Caledonian House, Tatton Street,
Knutsford, WA16 6AG

Project: Bury Market

Clients Project No: 5237

Project No: 22/03209

Date Received: 04/04/2022 (am)

Cool Box Temperatures (°C): 6.0

NO DEVIATIONS IDENTIFIED

Envirolab Analysis Dates

Lab Sample ID		
Client Sample No		
Client Sample ID/Depth		
Date Sampled		

End of Report

FINAL ANALYTICAL TEST REPORT

Envirolab Job Number:
Issue Number:

Date:

Client:

Project Manager:
Project Name:
Project Ref:
Order No:
Date Samples Received:
Date Instructions Received:
Date Analysis Completed:

Approved by:

Hollybeany-King

Envirolab Job Number: 22/03209

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/03209/1	22/03209/2						Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH02	WS05								
Depth to Top										
Depth To Bottom										
Date Sampled	31-Mar-22	31-Mar-22								
Sample Type	Water - EW	Water - EW								
Sample Matrix Code	N/A	N/A								
pH (w) _A [#]	7.28	7.34						pH	0.01	A-T-031w
Sulphate (w) _A [#]	101	35						mg/l	1	A-T-026w

Envirolab Job Number: 22/03209

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/03209/1	22/03209/2						Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH02	WS05								
Depth to Top										
Depth To Bottom										
Date Sampled	31-Mar-22	31-Mar-22								
Sample Type	Water - EW	Water - EW								
Sample Matrix Code	N/A	N/A								
SVOC (w)										
2,4,5-Trichlorophenol _A	<1	<1						µg/l	1	A-T-052w
2,4,6-Trichlorophenol (w) _A	<1	<1						µg/l	1	A-T-052w
2,4-Dichlorophenol _A	<1	<1						µg/l	1	A-T-052w
2,4-Dimethylphenol _A	<1	<1						µg/l	1	A-T-052w
2,4-Dinitrotoluene _A	<1	<1						µg/l	1	A-T-052w
2,6-Dinitrotoluene _A	<1	<1						µg/l	1	A-T-052w
2-Chloronaphthalene _A	<1	<1						µg/l	1	A-T-052w
2-Chlorophenol _A	<1	<1						µg/l	1	A-T-052w
2-Methylnaphthalene _A	<1	<1						µg/l	1	A-T-052w
2-Methylphenol _A	<1	<1						µg/l	1	A-T-052w
2-Nitrophenol _A	<1	<1						µg/l	1	A-T-052w
4-Bromophenyl phenyl ether _A	<1	<1						µg/l	1	A-T-052w
4-Chloro-3-methylphenol _A	<1	<1						µg/l	1	A-T-052w
Bis(2-chloroisopropyl)ether _A	<1	<1						µg/l	1	A-T-052w
3+4-Methylphenol _A	<1	<1						µg/l	1	A-T-052w
4-Nitrophenol _A	<1	<1						µg/l	1	A-T-052w
Acenaphthene _A	<1	<1						µg/l	1	A-T-052w
Acenaphthylene _A	<1	<1						µg/l	1	A-T-052w
Anthracene _A	<1	<1						µg/l	1	A-T-052w
Bis(2-chloroethyl)ether _A	<1	<1						µg/l	1	A-T-052w
Bis(2-chloroethoxy)methane _A	<1	<1						µg/l	1	A-T-052w
Bis(2-ethylhexyl)phthalate _A	<10	<10						µg/l	10	A-T-052w
Benzo(a)anthracene _A	<1	<1						µg/l	1	A-T-052w
Butylbenzyl phthalate _A	<1	<1						µg/l	1	A-T-052w
Benzo(b)fluoranthene _A	<1	<1						µg/l	1	A-T-052w
Benzo(k)fluoranthene _A	<1	<1						µg/l	1	A-T-052w
Benzo(a)pyrene _A	<1	<1						µg/l	1	A-T-052w
Benzo(ghi)perylene _A	<1	<1						µg/l	1	A-T-052w
Carbazole _A	<1	<1						µg/l	1	A-T-052w
Chrysene _A	<1	<1						µg/l	1	A-T-052w
Dibenzofuran _A	<1	<1						µg/l	1	A-T-052w
n-Dibutylphthalate _A	<1	<1						µg/l	1	A-T-052w

Envirolab Job Number: 22/03209

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/03209/1	22/03209/2						Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH02	WS05								
Depth to Top										
Depth To Bottom										
Date Sampled	31-Mar-22	31-Mar-22								
Sample Type	Water - EW	Water - EW								
Sample Matrix Code	N/A	N/A								
n-Diethylphthalate _A	<10	<10						µg/l	10	A-T-052w
n-Nitroso-n-dipropylamine _A	<1	<1						µg/l	1	A-T-052w
Diethyl phthalate _A	<1	<1						µg/l	1	A-T-052w
Dimethyl phthalate _A	<1	<1						µg/l	1	A-T-052w
Dibenzo(ah)anthracene _A	<1	<1						µg/l	1	A-T-052w
Fluorene _A	<1	<1						µg/l	1	A-T-052w
Fluoranthene _A	<1	<1						µg/l	1	A-T-052w
Hexachlorobenzene _A	<1	<1						µg/l	1	A-T-052w
Pentachlorophenol (SVOC) _A	<1	<1						µg/l	1	A-T-052w
Phenol _A	<1	<1						µg/l	1	A-T-052w
Hexachloroethane _A	<1	<1						µg/l	1	A-T-052w
Nitrobenzene _A	<1	<1						µg/l	1	A-T-052w
Naphthalene _A	<1	<1						µg/l	1	A-T-052w
Isophorone _A	<1	<1						µg/l	1	A-T-052w
Hexachlorocyclopentadiene _A	<1	<1						µg/l	1	A-T-052w
Phenanthrene _A	<1	<1						µg/l	1	A-T-052w
Pyrene _A	<1	<1						µg/l	1	A-T-052w
Indeno(1,2,3-cd)pyrene _A	<1	<1						µg/l	1	A-T-052w
Perylene _A	<1	<1						µg/l	1	A-T-052w

Envirolab Job Number: 22/03209

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/03209/1	22/03209/2						Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH02	WS05								
Depth to Top										
Depth To Bottom										
Date Sampled	31-Mar-22	31-Mar-22								
Sample Type	Water - EW	Water - EW								
Sample Matrix Code	N/A	N/A								
VOC (w)										
Dichlorodifluoromethane _A	<1	<1						µg/l	1	A-T-006w
Chloromethane _A	<10	<10						µg/l	10	A-T-006w
Vinyl Chloride _A [#]	<1	<1						µg/l	1	A-T-006w
Bromomethane _A [#]	<1	<1						µg/l	1	A-T-006w
Chloroethane _A [#]	<1	<1						µg/l	1	A-T-006w
Trichlorofluoromethane _A [#]	<1	<1						µg/l	1	A-T-006w
trans 1,2-Dichloroethene _A [#]	<1	<1						µg/l	1	A-T-006w
Dichloromethane _A	<5	<5						µg/l	5	A-T-006w
Carbon Disulphide _A [#]	<1	<1						µg/l	1	A-T-006w
1,1-Dichloroethene _A [#]	<1	<1						µg/l	1	A-T-006w
1,1-Dichloroethane _A [#]	<1	<1						µg/l	1	A-T-006w
cis 1,2-Dichloroethene _A [#]	<1	<1						µg/l	1	A-T-006w
Bromochloromethane _A [#]	<5	<5						µg/l	5	A-T-006w
Chloroform _A [#]	<1	<1						µg/l	1	A-T-006w
2,2-Dichloropropane _A [#]	<1	<1						µg/l	1	A-T-006w
1,2-Dichloroethane _A [#]	<2	<2						µg/l	2	A-T-006w
1,1,1-Trichloroethane _A [#]	<1	<1						µg/l	1	A-T-006w
1,1-Dichloropropene _A [#]	<1	<1						µg/l	1	A-T-006w
Benzene _A [#]	<1	<1						µg/l	1	A-T-006w
Carbon Tetrachloride _A [#]	<1	<1						µg/l	1	A-T-006w
Dibromomethane _A [#]	<1	<1						µg/l	1	A-T-006w
1,2-Dichloropropane _A [#]	<1	<1						µg/l	1	A-T-006w
Bromodichloromethane _A [#]	<10	<10						µg/l	10	A-T-006w
Trichloroethene _A [#]	<1	<1						µg/l	1	A-T-006w
cis 1,3-Dichloropropene _A [#]	<1	<1						µg/l	1	A-T-006w
trans 1,3-Dichloropropene _A [#]	<1	<1						µg/l	1	A-T-006w
1,1,2-Trichloroethane _A [#]	<1	<1						µg/l	1	A-T-006w
Toluene _A [#]	<1	<1						µg/l	1	A-T-006w
1,3-Dichloropropane _A [#]	<1	<1						µg/l	1	A-T-006w
Dibromochloromethane _A [#]	<3	<3						µg/l	3	A-T-006w
1,2-Dibromoethane _A [#]	<1	<1						µg/l	1	A-T-006w
Tetrachloroethene _A	1	<1						µg/l	1	A-T-006w

Envirolab Job Number: 22/03209

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/03209/1	22/03209/2						Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH02	WS05								
Depth to Top										
Depth To Bottom										
Date Sampled	31-Mar-22	31-Mar-22								
Sample Type	Water - EW	Water - EW								
Sample Matrix Code	N/A	N/A								
1,1,1,2-Tetrachloroethane _A	<1	<1						µg/l	1	A-T-006w
Chlorobenzene _A [#]	<1	<1						µg/l	1	A-T-006w
Ethylbenzene _A [#]	<1	<1						µg/l	1	A-T-006w
m & p Xylene _A [#]	<1	<1						µg/l	1	A-T-006w
Bromoform _A [#]	<1	<1						µg/l	1	A-T-006w
Styrene _A [#]	<1	<1						µg/l	1	A-T-006w
1,1,2,2-Tetrachloroethane _A	<1	<1						µg/l	1	A-T-006w
o-Xylene _A [#]	<1	<1						µg/l	1	A-T-006w
1,2,3-Trichloropropane _A [#]	<1	<1						µg/l	1	A-T-006w
Isopropylbenzene _A [#]	<1	<1						µg/l	1	A-T-006w
Bromobenzene _A [#]	<1	<1						µg/l	1	A-T-006w
2-Chlorotoluene _A [#]	<1	<1						µg/l	1	A-T-006w
n-propylbenzene _A [#]	<1	<1						µg/l	1	A-T-006w
4-Chlorotoluene _A [#]	<1	<1						µg/l	1	A-T-006w
1,2,4-Trimethylbenzene _A [#]	<1	<1						µg/l	1	A-T-006w
4-Isopropyltoluene _A [#]	<1	<1						µg/l	1	A-T-006w
1,3,5-Trimethylbenzene _A [#]	<1	<1						µg/l	1	A-T-006w
1,2-Dichlorobenzene _A [#]	<1	<1						µg/l	1	A-T-006w
1,4-Dichlorobenzene _A [#]	<1	<1						µg/l	1	A-T-006w
sec-Butylbenzene _A [#]	<1	<1						µg/l	1	A-T-006w
tert-Butylbenzene _A [#]	<2	<2						µg/l	2	A-T-006w
1,3-Dichlorobenzene _A [#]	<1	<1						µg/l	1	A-T-006w
n-butylbenzene _A [#]	<1	<1						µg/l	1	A-T-006w
1,2-Dibromo-3-chloropropane _A [#]	<2	<2						µg/l	2	A-T-006w
1,2,4-Trichlorobenzene _A [#]	<3	<3						µg/l	3	A-T-006w
1,2,3-Trichlorobenzene _A [#]	<3	<3						µg/l	3	A-T-006w
Hexachlorobutadiene _A [#]	<1	<1						µg/l	1	A-T-006w

Envirolab Job Number: 22/03209

Client Project Name: Bury Market

Client Project Ref: 5237

Lab Sample ID	22/03209/1	22/03209/2						Units	Limit of Detection	Method ref
Client Sample No										
Client Sample ID	BH02	WS05								
Depth to Top										
Depth To Bottom										
Date Sampled	31-Mar-22	31-Mar-22								
Sample Type	Water - EW	Water - EW								
Sample Matrix Code	N/A	N/A								
TPH CWG (w) with Clean Up *C1										
Ali >C5-C6 (w) _A [#]	<1	<1						µg/l	1	A-T-022w
Ali >C6-C8 (w) _A [#]	<1	<1						µg/l	1	A-T-022w
Ali >C8-C10 (w) _A [#]	5	<5						µg/l	5	A-T-055w
Ali >C10-C12 (w) _A [#]	5	<5						µg/l	5	A-T-055w
Ali >C12-C16 (w) _A [#]	<5	<5						µg/l	5	A-T-055w
Ali >C16-C21 (w) _A [#]	<5	<5						µg/l	5	A-T-055w
Ali >C21-C35 (w) _A [#]	12	94						µg/l	5	A-T-055w
Total Aliphatics (w) _A [#]	22	94						µg/l	5	A-T-055w
Aro >C5-C7 (w) _A [#]	<1	<1						µg/l	1	A-T-022w
Aro >C7-C8 (w) _A [#]	<1	<1						µg/l	1	A-T-022w
Aro >C8-C10 (w) _A	8	5						µg/l	5	A-T-055w
Aro >C10-C12 (w) _A [#]	6	<5						µg/l	5	A-T-055w
Aro >C12-C16 (w) _A [#]	<5	5						µg/l	5	A-T-055w
Aro >C16-C21 (w) _A [#]	<5	6						µg/l	5	A-T-055w
Aro >C21-C35 (w) _A	<10	<10						µg/l	10	A-T-055w
Total Aromatics (w) _A	14	16						µg/l	10	A-T-055w
TPH (Ali & Aro >C5-C35) (w) _A	36	110						µg/l	10	A-T-055w
BTEX - Benzene (w) _A [#]	<1	<1						µg/l	1	A-T-022w
BTEX - Toluene (w) _A [#]	<1	<1						µg/l	1	A-T-022w
BTEX - Ethyl Benzene (w) _A [#]	<1	<1						µg/l	1	A-T-022w
BTEX - m & p Xylene (w) _A [#]	<1	<1						µg/l	1	A-T-022w
BTEX - o Xylene (w) _A [#]	<1	<1						µg/l	1	A-T-022w
MTBE (w) _A [#]	<1	<1						µg/l	1	A-T-022w

REPORT NOTES

General

Soil chemical analysis:

TPH analysis of water by method A-T-007:

Electrical Conductivity of water by Method A-T-037:

Asbestos:

Predominant Matrix Codes:

Secondary Matrix Codes:

Key:

EPH CWG GCxGC ID from TPH CWG

Envirolab Deviating Samples Report

Client: iD GeoEnvironmental Ltd (Knutsford), Caledonian House, Tatton Street,
Knutsford, WA16 6AG

Project: Bury Market

Clients Project No: 5237

Project No: 22/03209

Date Received: 04/04/2022 (am)

Cool Box Temperatures (°C): 6.0

Lab Sample ID		
Client Sample No		
Client Sample ID/Depth		
Date Sampled		
Deviation Code		
	✓	✓

Key

F

Maximum holding time exceeded between sampling date and analysis for analytes listed below

Lab Sample ID		
Client Sample No		
Client Sample ID/Depth		
Date Sampled		
	✓	✓
	✓	✓
	✓	✓

Envirolab Analysis Dates

Lab Sample ID		
Client Sample No		
Client Sample ID/Depth		
Date Sampled		

End of Report

Appendix F

TEST REPORT

Client iD GeoEnvironmental Ltd

Address Caledonian House
Tatton Street
Knutsford
WA16 6AG

Contract 5237 -
Bury Market

Job Number MRN 4296/4
Date of Issue 11 April 2022
Pages 1 of 22

Approved Signatories


S J Hutchings, O P Davies

Notes

- 1 All remaining samples and remnants from this contract will be disposed 28 days from the date of this report unless you notify us to the contrary.
- 2 Result certificates, in this report, not bearing a UKAS mark, are not included in our UKAS accreditation schedule.
- 3 Opinions and interpretations expressed herein are outside the scope of our UKAS accreditation.
- 4 Certified that the samples have been examined and tested in accordance with the terms of the contract/order and unless otherwise stated conform to the standards/specifications quoted.
- 5 The results included within the report are representative of the samples submitted for analysis.
- 6 This certificate should not be reproduced, except in full, without the express permission of the laboratory.

MURRAY RIX

TEST CERTIFICATE



[Handwritten Signature]


MURRAY RIX

TEST CERTIFICATE

[illegible]



TEST CERTIFICATE



[Handwritten signature]


MURRAY RIX

TEST CERTIFICATE

[illegible]



TEST CERTIFICATE



[Handwritten signature]

MURRAY RIX

TEST CERTIFICATE

[illegible]


MURRAY RIX

TEST CERTIFICATE

[illegible]



TEST CERTIFICATE



Handwritten signature



MURRAY RIX

TEST CERTIFICATE

CLIENT	
SITE	
JOB NUMBER	

SAMPLE LABEL		DATE SAMPLED	
LAB SAMPLE No.		DATE RECEIVED	
DATE TESTED		SAMPLED BY	
MATERIAL			
ADVISED SOURCE			

INITIAL CONDITIONS													



[Handwritten Signature]

MURRAY RIX

TEST CERTIFICATE

	iD GeoEnvironmental Ltd
	5237 - Bury Market
	MRN 4296/4

	Oven Dry		None
	28-Mar-22		02-Mar-22

110037	BH02 6.50 U	BH02	Stiff brown silty sandy CLAY	2.67
110038	BH02 12.50 U	BH02	Firm to stiff brown silty sandy CLAY with occasional gravel	2.66

Particle density reported is the average of two determinations



MURRAY RIX


TEST CERTIFICATE

CLIENT	
SITE	
JOB NUMBER	

SAMPLE LABEL		DATE SAMPLED	
LAB SAMPLE No.		DATE RECEIVED	
DATE TESTED		SAMPLED BY	
MATERIAL			
ADVISED SOURCE			


INITIAL CONDITIONS



TEST TYPE

SKETCH OF
SPECIMEN AT
FAILURE



MURRAY RIX

TEST CERTIFICATE

[illegible]

MURRAY RIX

TEST CERTIFICATE

[illegible]


MURRAY RIX

TEST CERTIFICATE

[illegible]



TEST CERTIFICATE



Handwritten signature



MURRAY RIX

TEST CERTIFICATE

CLIENT	
SITE	
JOB NUMBER	

SAMPLE LABEL		DATE SAMPLED	
LAB SAMPLE No.		DATE RECEIVED	
DATE TESTED		SAMPLED BY	
MATERIAL			
ADVISED SOURCE			

	INITIAL CONDITIONS									



[Handwritten signature]

MURRAY RIX


TEST CERTIFICATE

CLIENT	
SITE	
JOB NUMBER	

SAMPLE LABEL		DATE SAMPLED	
LAB SAMPLE No.		DATE RECEIVED	
DATE TESTED		SAMPLED BY	
MATERIAL			
ADVISED SOURCE			


INITIAL CONDITIONS



TEST TYPE


SKETCH OF
SPECIMEN AT
FAILURE





MURRAY RIX

TEST CERTIFICATE

[illegible]

MURRAY RIX

TEST CERTIFICATE

[illegible]

MURRAY RIX

TEST CERTIFICATE

[illegible]

MURRAY RIX

TEST CERTIFICATE

[illegible]

TEST REPORT

Client iD GeoEnvironmental Ltd

Address Caledonian House
Tatton Street
Knutsford
WA16 6AG

Contract 5237 -
Bury Market

Job Number MRN 4296/5
Date of Issue 06 May 2022
Pages 1 of 3

Approved Signatories

S J Hutchings, O P Davies

Notes

- 1 All remaining samples and remnants from this contract will be disposed 28 days from the date of this report unless you notify us to the contrary.
- 2 Result certificates, in this report, not bearing a UKAS mark, are not included in our UKAS accreditation schedule.
- 3 Opinions and interpretations expressed herein are outside the scope of our UKAS accreditation.
- 4 Certified that the samples have been examined and tested in accordance with the terms of the contract/order and unless otherwise stated conform to the standards/specifications quoted.
- 5 The results included within the report are representative of the samples submitted for analysis.
- 6 This certificate should not be reproduced, except in full, without the express permission of the laboratory.


MURRAY RIX

TEST CERTIFICATE

[illegible]



TEST CERTIFICATE



Handwritten signature

Appendix G

Visit	Initials	Borehole Reference	Monitoring Date	Observations	Barometric Pressure - Start (mb)	Barometric Pressure - Finish (mb)	Barometric Pressure Trend	PID ppm	CH ₄ Peak %V/V	CH ₄ Steady %V/V	CO ₂ Peak %V/V	CO ₂ Steady %V/V	O ₂ %V/V	CO ppm	H ₂ S ppm	Flow Peak l/hr	Flow Steady l/hr	Q ₁₀ CH ₄ l/hr	Implied CS	Q ₁₀ CO ₂ l/hr	Implied CS	Max Q ₁₀ CH ₄ l/hr	Implied CS	Max Q ₁₀ CO ₂ l/hr	Implied CS
1	MJ	BH01	28/02/2022		1016	1016	Falling	-	0.0	0.0	0.0	0.0	17.0	0	0	0.0	0.0	0.0001	CS1	0.0001	CS1	0.0001	CS1	0.0006	CS1
2	MJ		28/04/2022		1019	1018	Falling	-	0.0	0.0	0.0	0.0	19.8	0	0	0.0	0.0	0.0001	CS1	0.0001	CS1				
3	MJ		10/05/2022		997	997	Falling	-	0.0	0.0	0.1	0.1	19.7	0	0	0.0	0.0	0.0001	CS1	0.0001	CS1				
4	MJ		27/05/2022		1008	1008	Steady	-	0.0	0.0	0.6	0.5	18.0	0	0	0.0	0.0	0.0001	CS1	0.0005	CS1				
5	MJ		24/06/2022		994	994	Falling	-	0.0	0.0	0.3	0.3	18.6	0	0	0.0	0.0	0.0001	CS1	0.0003	CS1				
6	MJ		12/07/2022		1008	1008	Steady	-	0.0	0.0	0.6	0.6	16.0	0	0	0.0	0.0	0.0001	CS1	0.0006	CS1				
1	MJ	BH02	28/02/2022		1016	1016	Falling	-	0.0	0.0	0.0	0.0	21.0	0	0	0.0	0.0	0.0001	CS1	0.0001	CS1	0.0001	CS1	0.0008	CS1
2	MJ		28/04/2022		1019	1018	Falling	-	0.0	0.0	0.5	0.5	20.1	0	0	0.0	0.0	0.0001	CS1	0.0005	CS1				
3	MJ		10/05/2022		997	997	Falling	-	0.0	0.0	0.4	0.4	20.4	0	0	0.0	0.0	0.0001	CS1	0.0004	CS1				
4	MJ		27/05/2022		1008	1008	Steady	-	0.0	0.0	0.5	0.5	20.6	0	0	0.0	0.0	0.0001	CS1	0.0005	CS1				
5	MJ		24/06/2022		994	994	Falling	-	0.0	0.0	0.7	0.7	20.0	0	0	0.0	0.0	0.0001	CS1	0.0007	CS1				
6	MJ		12/07/2022		1008	1008	Steady	-	0.0	0.0	0.8	0.8	20.0	0	0	0.0	0.0	0.0001	CS1	0.0008	CS1				
1	MJ	WS01	28/02/2022		1016	1016	Falling	-	0.0	0.0	4.1	4.1	14.2	0	0	0.0	0.0	0.0001	CS1	0.0041	CS1	0.0001	CS1	0.0046	CS1
2	MJ		28/04/2022		1019	1018	Falling	-	0.0	0.0	4.0	4.0	12.3	0	0	0.0	0.0	0.0001	CS1	0.004	CS1				
3	MJ		10/05/2022		997	997	Falling	-	0.0	0.0	3.7	3.7	12.4	0	0	0.0	0.0	0.0001	CS1	0.0037	CS1				
4	MJ		27/05/2022		1008	1008	Steady	-	0.0	0.0	4.0	4.0	11.3	0	0	0.0	0.0	0.0001	CS1	0.004	CS1				
5	MJ		24/06/2022		994	994	Falling	-	0.0	0.0	4.4	4.4	10.7	0	0	0.0	0.0	0.0001	CS1	0.0044	CS1				
6	MJ		12/07/2022		1008	1008	Steady	-	0.0	0.0	4.6	4.6	11.7	0	0	0.0	0.0	0.0001	CS1	0.0046	CS1				
1	MJ	WS02	28/02/2022		1016	1016	Falling	-	0.0	0.0	1.4	1.4	19.5	0	0	0.0	0.0	0.0001	CS1	0.0014	CS1	0.0001	CS1	0.0019	CS1
2	MJ		28/04/2022		1019	1018	Falling	-	0.0	0.0	1.5	1.5	19.2	0	0	0.0	0.0	0.0001	CS1	0.0015	CS1				
3	MJ		10/05/2022		997	997	Falling	-	0.0	0.0	1.5	1.5	19.2	0	0	0.0	0.0	0.0001	CS1	0.0015	CS1				
4	MJ		27/05/2022		1008	1008	Steady	-	0.0	0.0	1.5	1.5	19.7	0	0	0.0	0.0	0.0001	CS1	0.0015	CS1				
5	MJ		24/06/2022		994	994	Falling	-	0.0	0.0	1.9	1.9	18.2	0	0	0.0	0.0	0.0001	CS1	0.0019	CS1				
6	MJ		12/07/2022		1008	1008	Steady	-	0.0	0.0	1.9	1.9	18.8	0	0	0.0	0.0	0.0001	CS1	0.0019	CS1				
1	MJ	WS03	28/02/2022		1016	1016	Falling	-	0.0	0.0	1.4	1.4	20.1	0	0	0.0	0.0	0.0001	CS1	0.0014	CS1	0.0001	CS1	0.0043	CS1
2	MJ		28/04/2022		1019	1018	Falling	-	0.0	0.0	3.9	3.9	17.5	0	0	0.0	0.0	0.0001	CS1	0.0039	CS1				
3	MJ		10/05/2022		997	997	Falling	-	0.0	0.0	4.3	4.3	16.8	0	0	0.0	0.0	0.0001	CS1	0.0043	CS1				
4	MJ		27/05/2022		1008	1008	Steady	-	0.0	0.0	3.6	3.6	17.8	0	0	0.0	0.0	0.0001	CS1	0.0036	CS1				
5	MJ		24/06/2022		994	994	Falling	-	0.0	0.0	0.6	0.6	20.7	0	0	0.0	0.0	0.0001	CS1	0.0006	CS1				
6	MJ		12/07/2022		1008	1008	Steady	-	0.0	0.0	4.2	4.2	16.7	0	0	0.0	0.0	0.0001	CS1	0.0042	CS1				
1	MJ	WS04A	28/02/2022		1016	1016	Falling	-	0.0	0.0	2.1	2.1	19.1	0	0	0.0	0.0	0.0001	CS1	0.0021	CS1	0.0001	CS1	0.0037	CS1
2	MJ		28/04/2022		1019	1018	Falling	-	0.0	0.0	2.0	2.0	18.4	0	0	0.0	0.0	0.0001	CS1	0.002	CS1				
3	MJ		10/05/2022		997	997	Falling	-	0.0	0.0	3.3	3.3	11.9	0	0	0.0	0.0	0.0001	CS1	0.0033	CS1				
4	MJ		27/05/2022		1008	1008	Steady	-	0.0	0.0	2.0	2.0	18.5	0	0	0.0	0.0	0.0001	CS1	0.002	CS1				
5	MJ		24/06/2022		994	994	Falling	-	0.0	0.0	3.7	3.7	11.8	0	0	0.0	0.0	0.0001	CS1	0.0037	CS1				
6	MJ		12/07/2022		1008	1008	Steady	-	0.0	0.0	3.6	3.6	13.9	0	0	0.0	0.0	0.0001	CS1	0.0036	CS1				
1	MJ	WS05	28/02/2022		1016	1016	Falling	-	0.0	0.0	1.7	1.7	17.7	0	0	0.0	0.0	0.0001	CS1	0.0017	CS1	0.0001	CS1	0.0024	CS1
2	MJ		28/04/2022		1019	1018	Falling	-	0.0	0.0	2.0	2.0	18.9	0	0	0.0	0.0	0.0001	CS1	0.002	CS1				
3	MJ		10/05/2022		997	997	Falling	-	0.0	0.0	2.4	2.4	17.7	0	0	0.0	0.0	0.0001	CS1	0.0024	CS1				
4	MJ		27/05/2022		1008	1008	Steady	-	0.0	0.0	2.1	2.1	18.0	0	0	0.0	0.0	0.0001	CS1	0.0021	CS1				
5	MJ		24/06/2022		994	994	Falling	-	0.0	0.0	2.2	2.2	18.6	0	0	0.0	0.0	0.0001	CS1	0.0022	CS1				
6	MJ		12/07/2022		1008	1008	Steady	-	0.0	0.0	2.1	2.1	18.8	0	0	0.0	0.0	0.0001	CS1	0.0021	CS1				

Monitoring Assessment

0.0001 CS1 0.0046 CS1

Borehole Worst Case

0.0001 CS1 0.0046 CS1

Sitewide Worst Case

MAXIMUM = 0 0 0 4.6 4.6 10.7 0 0 0 0.0 0.0001 CS1 0.0046 CS1

TEST DATE AND CONDITIONS			
Date		01/11/2021	
Atmospheric Pressure		971	mB
Ambient Temperature		21.7	°C
Envionics Serial No.		5089	

**GFM430 Final Inspection & Calibration
Check Certificate**

GAS DATA LTD

Unit 4, Fairfield Court

Seven Stars Estate

Wheler Rd

Coventry

CV3 4LJ

Tel 02476303311

Fax 02476307711



Customer	ID Geoenvironmental Limited
Certificate Number	122791
Order Number	329623

Serial Number	10165
Software Version	G430-00.0024/0013

Recalibration DUE Date
01/11/22

Instrument Checks					
Keyboard	✓		Display Contrast	✓	
Pump Flow In	450	Accept > 200 cc/min	Pump Flow @ -200mB	250	Accept > 200 cc/min
Clock Set / Running	✓		Labels Fitted	✓	

Gas Checks						
Sensor	CH ₄		CO ₂		O ₂	
	Instrument Gas	True Gas Value %	Instrument Gas	True Gas Value %	Instrument Gas	True Gas Value %
	Readings %		Readings %		Readings %	
	60	60	39.7	40	20.9	20.9
	Accept ±3.0		Accept ±3.0		Accept ±0.5	
	5	5	5	5	6	6
	Accept ±0.3		Accept ±0.3		Accept ±0.3	
Zero Reading 100% N2	0	0	0	0	0	0
	Accept ±0.0		Accept ±0.0		Accept ±0.1	

Optional Gas Checks						
Applied Gas & Range		Concentration Tested @ (ppm)	Instrument Readings (ppm)			
Toxic Gas	Range (ppm)		Zero Reading		Instrument Gas Reading	
H2S	5000	1500	0	Accept ±0.0	1500	Accept ±5.0
CO	2000	1000	0	Accept ±0.0	998	Accept ±5.0

Cross Gas Effects									
Applied Gas (ppm)		Instrument Readings (ppm)							
Toxic Gas	Concentration	Toxic 1:	H2S	Toxic 2:	CO	Toxic 3:			
H2S	1500	1500		0					
CO	1000	38		998					
Pressure Checks									
Atmospheric Pressure [AP] (mB)					Static Pressure [SP] (mB)				
Current Atmospheric		Instrument Atmospheric			Applied Pressure (mB)		Instrument Pressure (mB)		
Pressure (mB)		Pressure Reading (mB)							
All Ports		Open Ports		971	Accept ±2.0	0.0mB		N/A	Accept ±0.0
AP Port (Internal)		+800 mB		800	Accept ±5.0	+50mB		N/A	Accept ±2.0
AP Port (Internal)		+1200mb		1200	Accept ±5.0	-100mB		N/A	Accept ±2.0
Flow Checks									
Borehole Flow				Differential Pressure					
Applied Reading (l/h)		Instrument Reading (l/h)			Applied Pressure (Pa)		Instrument Reading (Pa)		
-30		-29.5	Accept ±3.0		-323		-320	Accept ±50	
-3		-3	Accept ±1.0		-15		-15	Accept ±6.0	
0		0	Accept ±0.0		0		0	Accept ±0.5	
3		3	Accept ±0.5		16		15	Accept ±3.0	
30		29.5	Accept ±3.0		333		327	Accept ±50	
60		59.5	Accept ±6.0		1006		998	Accept ±130	
90		89.7	Accept ±9.0		1999		>>>>	Accept ±250	
		Temperature Checks							
		Calibration Temperature			Instrument Temperature Reading °C				
		Applied Temperature °C							
		-10			-10	Accept ±2.0			
		0			0	Accept ±1.0			
		30			30	Accept ±1.0			
		60			60	Accept ±1.0			
		100			100	Accept ±1.0			

Technician:
<i>Jack Rutland</i>

Date Tested:
<i>02/11/2021</i>

The instrument identified by the serial number stated above has been tested by Gas Data personnel for calibration accuracy on the date and under the ambient conditions stated. Gas Data Ltd internal BS EN ISO9001:2015 compliant workshop procedures were followed to apply known calibration test gases, gas flow rates, pressures and temperatures of the values stated. The results displayed on the instrument at each stage are recorded above.

Appendix H

Generic Notes – ID Geoenvironmental Investigations

Environmental Setting

General

Third party information obtained from the British Geological Survey (BGS), the Coal Authority and the Local Authority etc is presented in the Correspondence Appendix of this Geoenvironmental Report.

Geology, Mining & Quarrying

In order to establish the geological setting of a site, ID Geoenvironmental refer to BGS maps for the area, and the relevant geological memoir.

A coal mining report is obtained from the Coal Authority. Further information is sourced from the Local Authority and by reference to current and historical OS plans.

Landfills and other Historical Land Uses

ID Geoenvironmental obtain data from the Landmark Information Group, the Environment Agency and the Local Authority with respect to known areas of landfilling within 250m of the proposed development site. Reference is also made to historical OS plans, which are inspected for evidence of backfilled quarries, railway cuttings, colliery spoil tips etc.

Historical maps dating from the middle of the nineteenth century are also studied for evidence of historical land uses (i.e. gas works, foundries, chemical works) which may represent potential sources of contamination or ground instability.

Radon

Radon is a colourless, odourless gas, which is radioactive. It is formed in strata that contain uranium and radium (most notably granite), and can move through fissures eventually discharging to atmosphere, or the spaces under and within buildings. Where radon occurs in high concentrations, it can pose a risk to health.

In order to assess potential risks associated with radon gas, ID Geoenvironmental refer to BRE Report BR211, 2007: *"Radon: guidance on protective measures for new buildings"*.

The level of protection needed is site-specific and is determined by reference to the maps contained in Annex A of BR211. These maps are derived from the Radon Atlas of England and Wales (2007), and indicate the highest radon potential within each 1km grid square.

If the site falls within a light grey square on the relevant map in Annex A then basic radon protection should be installed in new buildings; if the site falls within a dark grey square then full radon protection should be installed. If the site is in an un-shaded square then no radon protection is needed.

BR211 provides a preliminary indication of the measures required for a particular site, but it is also often beneficial to request a BR211 Radon Report from the BGS. The Annex A maps indicate the highest geological radon potential within each 1km grid square, but in many cases the radon potential varies considerably within the grid square. The BR211 Radon Report gives definitive guidance on the requirement for radon protective measures, and therefore may allow the adoption of a lower level of protection than that indicated in the Annex A maps.

ID GeoEnvironmental typically obtain a BR211 Radon Report for all sites that fall within a shaded square on the relevant Annex A map.

When requesting a BR211 Radon Report from the BGS ID GeoEnvironmental select the search radius carefully, since too large a search radius may result in the inclusion of areas of higher geological radon potential, and therefore in the recommendation of too high a level of protection.

Further details of the protective measures required, if appropriate, are provided in the Hazardous Gas section of this GeoEnvironmental Report.

Hydrogeology

ID GeoEnvironmental obtain information from the Environment Agency (EA) and the Landmark Information Group with respect to:

- groundwater quality
- recorded pollution incidents
- licensed groundwater abstractions

From 1 April 2010 the Environment Agency's Groundwater Protection Policy uses aquifer designations that are consistent with the Water Framework Directive. These designations reflect the importance of aquifers in terms of groundwater as a resource (drinking water supply) but also their role in supporting surface water flows and wetland ecosystems.

The aquifer designation data is based on geological mapping provided by the British Geological Survey.

These maps are split into two differing aquifer designations:

- Superficial (Drift) – permeable unconsolidated (loose) deposits such as sands and gravels.
- Bedrock – solid permeable formations such as sandstone, chalk or limestone.

The maps display the following aquifer designations:

Principal aquifers: "These are layers of rock or drift deposits that have high intergranular and/or fracture permeability - meaning they usually provide a high level of water storage. They may support water supply and/or river base flow on a strategic scale. In most cases, principal aquifers are aquifers previously designated as major aquifer".

Secondary A – "permeable layers capable of supporting water supplies at a local rather than strategic scale, and in some cases forming an important source of base flow to rivers. These are generally aquifers formerly classified as minor aquifers";

Secondary B - predominantly lower permeability layers which may store and yield limited amounts of groundwater due to localised features such as fissures, thin permeable horizons and weathering. These are generally the water-bearing parts of the former non-aquifers

Unproductive Strata: These are rock layers or drift deposits with low permeability that have negligible significance for water supply or river base flow. However groundwater flow through such rocks, although imperceptible, does take place and needs to be considered in assessing the risk associated with persistent pollutants. Some non-aquifers can yield water in sufficient quantities for domestic use”.

Groundwater vulnerability is determined by 4 variables:

1. The presence and nature of overlying soil (the weathered zone affected by living organisms; soil in the UK can extend up to 2m in depth). Physical properties of the soil affect the downward passage of water and it's ability to attenuate pollutants. The EA make reference to a three-fold classification of soil types:-

Soils of low leaching potential are defined as "soils in which the pollutants are unlikely to penetrate the soil layer because either water movement is largely horizontal, or they have the ability to attenuate diffuse pollutants”.

Soils of intermediate leaching potential are defined as "soils which have a moderate ability to attenuate diffuse source pollutants or in which it is possible that some non-adsorbed diffuse source pollutants and liquid discharges could penetrate the soil layer”.

Soils of high leaching potential are defined as "soils with little ability to attenuate diffuse source pollutants and in which non-adsorbed diffuse source pollutants and liquid discharges have the potential to move rapidly to underlying strata or to shallow groundwater”.

In urban areas and restored mineral workings the soil information is based on fewer observations than elsewhere. A worst-case vulnerability (H) is therefore assumed for these areas and for current mineral workings by the EA. All are given a designation of HU unless proved otherwise.

2. The presence and nature of Drift, which often overlies bedrock. Where Drift is of substantial thickness and low permeability, it can provide an effective barrier to surface pollutant migration. Permeable Drift is classified as a Minor Aquifer except where it is in probable hydraulic continuity with a Major Aquifer, where it is regarded as part of the Major Aquifer unless proven otherwise by site investigation.
3. The nature of the geological strata (bedrock). Rocks that contain groundwater in exploitable quantities are called aquifers.
4. The depth of the unsaturated zone; i.e. that part of the aquifer which lies above the water table

The EA have also designated Source Protection Zones, which are based on proximity to a groundwater source (springs, wells and abstraction boreholes). The size of a Source Protection Zone is a function of the aquifer, volume of groundwater abstracted and the effective rainfall, and may vary from tens to several thousand hectares.

Hydrology

ID GeoEnvironmental obtain information from the Environment Agency and the Landmark Information Group with respect to:

- surface water quality
- recorded pollution incidents
- licensed abstractions (groundwater & surface waters)
- licensed discharge consents
- site susceptibility to flooding

The EA have set water quality targets for all rivers. These targets are known as River Quality Objectives (RQO's). The water quality classification scheme used to set RQO planning targets is known as the River Ecosystem scheme. The scheme comprises five classes (RE1 to RE5) which reflect the chemical quality requirements of communities of plants and animals occurring in our rivers.

General Quality Assessment (GQA) grades reflect actual water quality. They are based on the most recent analytical testing undertaken by the EA. There are six GQA grades (denoted A to F) defined by the concentrations of biochemical oxygen demand, total ammonia and dissolved oxygen.

The susceptibility of a site to flooding is assessed by reference to a Flood Map on the Environment Agency's website. These maps provide show natural floodplains - areas potentially at risk of flooding if a river rises above its banks, or high tides and stormy seas cause flooding in coastal areas.

There are two different kinds of area shown on the Flood Map:

1. Dark blue areas could be flooded by the sea by a flood that has a 0.5% (1 in 200) or greater chance of happening each year, or by a river by a flood that has a 1% (1 in 100) or greater chance of happening each year
2. Light blue areas show the additional extent of an extreme flood from rivers or the sea. These outlying areas are likely to be affected by a major flood, with up to a 0.1% (1 in 1000) chance of occurring each year.

These two colours show the extent of the natural floodplain if there were no flood defences or certain other manmade structures and channel improvements

The maps also show all flood defences built in the last five years to protect against river floods with a 1% (1 in 100) chance of happening each year, or floods from the sea with a 0.5% (1 in 200) chance of happening each year, together with some, but not all, older defences and defences which protect against smaller floods.

The Agency's assessment of the likelihood of flooding from rivers and the sea at any location is based on the presence and effect of all flood defences, predicted flood levels, and ground levels.

It should also be noted that as the floodplain shown is the 1 in 100 year (or 1 in 200 year as appropriate), areas outside this may be flooded by more extreme floods (e.g. the 1 in 1000 year

flood). Also, parts of the areas shown at risk of flooding will be flooded by lesser floods (e.g. the 1 in 5 year flood). In some places due to the shape of the river valley, the smaller floods will flood a very similar extent to larger floods but to a lesser depth.

If a site falls within a floodplain, it is recommended that a flood survey be undertaken by a specialist consultant who can advise on appropriate mitigating measures; ie raising slab levels, provision of storage etc.

Furthermore, as discussed in Planning Policy Statement 25 (PPS25) a consequence of amendment 8 to Article 10 of The Town and Country Planning (General Development Procedure) Order 1995 ("the GDPO"), on 1st October 2006, LPAs are required to consult the Environment Agency on all applications for development in flood risk areas (except minor development), including those in areas with critical drainage problems and for any development on land exceeding 1 hectare outside flood risk areas.

COMAH & Explosive Sites

ID GeoEnvironmental obtain information from the Landmark Information Group with respect to COMAH or explosive sites within 1km of the proposed development site. MMi's report refers to any that are present, and recommends that the Client seeks further advice from the HSE.

Areas around COMAH sites (chemical plants etc) are zoned with respect to the implementation of emergency plans. The HSE are a statutory consultee to the local planning authority for all COMAH sites. The COMAH site may have to revise its emergency action plan if development occurs. This might be quite straightforward or could entail significant expenditure. Consequently, the COMAH site may object to a proposed development (although it is the Local Authority who have final say, and they are likely to place more weight on advice from the HSE).

Preliminary Conceptual Ground Model

The site's environmental setting (and proposed end use) is used by ID GeoEnvironmental to assess the significance of any contamination encountered during the subsequent ground investigation

Assessment of contaminated land is based on an evaluation of pollutant linkages (source-pathway-receptor). Contaminants within the near surface strata represent a potential source of pollution. The environment (most notably groundwater), site workers and end users are potential targets.

Potential pollutant linkages are shown on a preliminary conceptual site model, presented as a Drawing in an Appendix to this GeoEnvironmental Report. The preliminary model is revised in light of data arising from the subsequent ground investigation.

Generic Notes 2.

Ground Investigation Fieldwork

General

IDG Ground Investigations are undertaken in accordance with current UK guidance including:

BS EN 1997-1:2004 Eurocode 7: Geotechnical design — Part 1: General rules

BS EN 1997-2:2007 Eurocode 7: Geotechnical design —Part 2: Ground investigation and testing

NA to BS EN 1997-2:2007 UK National Annex to Eurocode 7. Geotechnical design. Ground investigation and testing

BS 5930:1999 Code of practice for site investigations (partially replaced, under revision).

BS 10175:2011 Investigation of potentially contaminated sites. Code of practice.

BS EN ISO 14688-1:2002 Geotechnical investigation and testing. Identification and classification of soil. Identification and description.

BS EN ISO 14688-2:2004 Geotechnical investigation and testing. Identification and classification of soil. Principles for a classification.

BS EN ISO 14689-1:2003 Geotechnical investigation and testing. Identification and classification of rock. Identification and description.

“Guidance on the protection of housing on contaminated land” – NHBC & EA R&D Publication 66 (2000, 2008) updated 3rd June 2014

“Technical Aspects of Site Investigation” – EA R&D Technical Report P5-065/TR (2000)

“Development of appropriate soil sampling strategies for land contamination” – EA R&D Technical Report P5-066/TR (2001)

AGS: 1996 “Guide to the selection of Geotechnical Soil Laboratory Testing”

Exploratory hole logs are presented in Appendices to this Geoenvironmental Report. These logs include details of the:

Investigation technique adopted

Descriptions of the solid strata, and any groundwater encountered.

Samples taken

Results of any in-situ testing

Any gas\groundwater monitoring well installed

Exploratory Hole Locations

Exploratory hole locations are selected by IDG, prior to commencement of fieldwork, to provide a representative view of the strata beneath the site and to target potential contaminant sources identified during the preliminary investigation (desk study). Additional exploratory locations are often determined by the site engineer in light of the ground conditions actually encountered; this enables better delineation of the depth and lateral extent of organic contamination, poor ground, relict structures etc.

Investigation Techniques

Ground conditions can be investigated by a number of techniques. Techniques most commonly used by IDG include:

Machine excavated trial pits, usually equipped with a backactor and a 0.6m wide bucket.

Cable percussive (Shell & Auger) boreholes, typically using 150mm diameter tools and casing. Cable Percussive drilling is employed to advance boreholes in superficial (made ground and Drift strata).

Window or Windowless Sampling boreholes. Constraints associated with existing buildings, operations and underground service runs can render some sites partly or wholly inaccessible to a mechanical excavator. In such circumstances, window sampling is often the most appropriate technique. A window sampling drilling rig can be manoeuvred in areas of restricted access and results in minimal disturbance of the ground (a 150mm) diameter tarmac/concrete core can be lifted and put to one side). However, it should be noted that window sampling allows only a limited inspection of the ground (especially made ground with a significant proportion of coarse material) and cannot be used in solid strata.

Rotary percussive open-hole probeholes are typically drilled using a tricone rock roller bit with water or air as the flushing medium. Rotary probeholes are generally lined through made ground with temporary steel casing to prevent hole collapse. Rotary boreholes are used to enable progress in solid strata (rockhead) and are commonly drilled to identify the presence of shallow mineworkings or to install deep groundwater monitoring boreholes in the solid strata.

Hazardous ground gas and groundwater monitoring boreholes may be installed in cable percussive boreholes, window sample probeholes and rotary boreholes. Where installed, gas\groundwater monitoring wells typically comprise a lower slotted section, surrounded by a filter pack of 10 mm diameter non-calcareous gravel and an upper plain section surrounded in part by a bentonite seal and in part by gravel or arisings. The top of the plain pipe is cut off below ground level and the monitoring well protected by a circular or square, stopcock type manhole cover set in concrete, or the plain pipe is cut off just above ground level and the well protected by 100mm diameter raised steel helmet set in concrete, which stands approximately 300mm proud of ground level.

Monitoring well details, including the location of the response zone and bentonite seal are presented on the relevant exploratory hole logs.

In-situ Testing

Where relative densities of granular materials given on the trial pit and window sample logs are based on visual inspection only, they do not relate to any specific bearing capacities.

BS EN ISO 22476-3:2005 Geotechnical investigation and testing. Field testing. Standard penetration test

The relative densities of granular materials encountered in cable percussive boreholes are based on Standard Penetration Test (SPT) results. SPTs are carried out boreholes, in accordance with BS EN ISO 22476-3:2005. The sampler is penetrated over an initial seating drive of 150mm. The sampler is then driven for a test drive of 300mm in four increments of 75mm. The total number of blow required to drive the sampler 300mm is recorded as the penetration resistance or N-value. Where full penetration (450mm) is not possible the test is continued up to a maximum of 50 blows and the depth of penetration is recorded in millimetres.

The strength of cohesive deposits is determined using a hand shear vane in general accordance with BS1377-7-1990.

Shear strength test results reported on trial pit logs are considered to be more reliable than those reported on window sample logs. Significant sample disturbance occurs during window sampling and consequently shear strength results on disturbed window samples are generally lower than results obtained during trial pitting, in-situ or in large excavated blocks.

Sampling

Representative soil/fill samples are taken at regular intervals from the exploratory holes to assist in description of the ground and to allow selected laboratory testing to be performed. The type of sample taken is dependent on the nature of the stratum and the purpose of the analysis.

Where the soils encountered contain a significant proportion of coarse grained material, truly representative samples are not typically obtained and only the finer fraction is placed in sample containers. However, a visual estimate of the amount of coarse material is made on site. Note: Coarse constituents not sampled are defined as: coarse gravel, cobble and boulder. (i.e. any 'particles' with an average diameter greater than 20mm).

Occasionally, unrepresentative 'spot' samples are also taken from some exploratory locations for contaminant analysis, typically where unusual, localised pockets of materials are encountered.

Samples of soil for chemical testing are placed into appropriate containers (see below) prior to delivery to the selected laboratory. Samples of water are taken in one litre, brown glass bottles and stored in cool boxes, at a temperature of approximately 4°C, until delivery to the selected laboratory. Soil/fill samples for organic analysis are also stored in cool boxes.

Sample Containers (for geotechnical analysis). The majority of samples are only scheduled for PI and sulphate testing, for which 500g of sample is required (a full 0.5-litre plastic tub). However, bulk bags are taken where scheduling of compaction or grading tests are required.

Containers (for contaminant analysis). In order to comply with MCERTS requirements, labs have to provide a sample description and consequently require sufficient soil sample, and the use of wide-necked containers. For any sample requiring both inorganic & organic analysis, it is necessary to submit both a 1-litre glass jar and a 1 kg plastic tub.

Where scheduling for VOC (including GRO) testing is anticipated, a glass vial is also required. In summary (for contaminant analysis):

Anticipated testing	Container(s)	Remarks
pH & metals only	1 kg plastic tub	
organics (TPH, PAH) etc only	1 litre wide-necked glass jar	Vial required if TPH is to include GRO as well as DRO & LRO, or speciated PAH
VOCs (incl. naphthalene and/or GRO) only	glass vial & 1kg plastic tub	
pH & metals, and organics	1 litre wide-necked glass jar 1kg plastic tub	

pH & metals, and organics (incl. VOCs or GRO)	glass vial 1 litre wide-necked glass jar 1kg plastic tub	
--	---	--

Groundwater

Where encountered during fieldwork, groundwater is recorded on exploratory hole logs. If monitoring wells are installed, groundwater levels are also recorded on one or more occasions after completion of the fieldwork.

It should be borne in mind that the rapid excavation rates used during a ground investigation may not allow the establishment of equilibrium water levels. Water levels are likely to fluctuate with season/rainfall and could be substantially higher at wetter times of the year than those found during the ground investigation.

Long-term monitoring of standpipes or piezometers is always recommended if water levels are likely to have a significant effect on earthworks or foundation design.

Description of Strata

Soils encountered during an IDG investigation are described (logged) in general accordance with EN ISO 14688-1. The descriptions and depth of deposits encountered are presented on the exploratory hole logs and summarised in the Ground Conditions section of the report within the main body of text.

Rocks encountered during an IDG investigation are described (logged) in general accordance with EN ISO 14689-1. The descriptions and depth of strata encountered are presented on the exploratory hole logs and summarised in the Ground Conditions section of the report within the main body of text.

The materials encountered in the trial pits are logged, samples taken, and tests performed on the in-situ materials in the excavation faces, to depths of up to 1.2m; below this depth these operations are conducted at the surface on disturbed samples recovered from the excavation.

Key to Exploratory Hole Logs

Keys to logs are presented in the Appendix(ces) containing the logs. There are two Keys – Symbols & Legends and Terms & Definitions.

Generic Notes – ID Geoenvironmental Investigations

3. Geotechnical Laboratory Tests

General

Soil samples are delivered to the laboratory for testing along with a schedule of testing drawn up by IDG. All tests are carried out in accordance with BS 1377:1990.

The test results are presented as received in an Appendix to this Geoenvironmental Report.

The following laboratory testing are routinely carried out on a selection of samples:

Atterberg limits & moisture contents

Soluble sulphate & pH

The additional tests are typically only scheduled where significant earthworks regrade is anticipated:

Grading.

Compaction tests

Particle density.

Atterberg Limits & Moisture Content

The Liquid and Plastic Limits of samples of natural in-situ clay are determined using the cone penetrometer method and the rolling thread test. These tests enable determination of an average Plasticity Index (PI) for each "type" of clay, although judgement is applied where variable results are reported.

PI can be related to shrinkability (low, medium or high) and then to minimum founding depth. IDG typically only consider a soil to be shrinkable if the proportion finer than 63µm is >35%.

PI results are compared against guidance given in the NHBC Standards, Chapter 4.2 (revised April 2003), which advocates the use of modified Plasticity Index (I'_p), defined as:

$$I'_p = I_p * (\% < 425\mu\text{m} / 100)$$

ie if PI is 30%, but the soil contains 80% < 425µm, then: $I'_p = 30 * 80/100 = 24\%$.

It should be noted that in accordance with the requirements of BS 1377, the % passing the 425µm sieve is routinely reported by testing labs.

IDG apply engineering judgment where PI results are spread over a range of classifications. Consideration is given to:

the average values for each particular soil type (ie differentiate between residual soil and alluvium),

the number of results in each class and

the actual values.

Unless the judgment strongly indicates otherwise, IDG typically adopt a conservative approach and recommend assumption of the higher classification.

Soluble Sulphate and pH

Sulphates in soil and groundwater are the chemical agents most likely to attack sub-surface concrete, resulting in expansion and softening of the concrete to a mush. Another common cause of concrete deterioration is groundwater acidity.

The rate of chemical attack depends on the concentration of aggressive ions and their replenishment at the reaction surface. The rate of replenishment is related to the presence and mobility of groundwater.

IDG refer to BRE Special Digest 1 (SD1) "Concrete in aggressive ground. Part 1: Assessing the aggressive chemical environment" (2005). SD 1 provides definitions of:

- the nature of the site (greenfield, brownfield or pyritic)
- the groundwater regime (static, mobile or highly mobile)
- the Design Sulphate Class (DC Class) and
- the Aggressive Chemical Environment for Concrete (ACEC Class)

IDG reports clearly state each of the above for the site being considered.

The concentrations of sulphate in aqueous soil/fill extracts are determined in the laboratory using the gravimetric method. The results are expressed in terms of SO_4 for direct comparison with BS 5328:1997. The pH value of each sample was determined by the electrometric method.

SD1 also discusses determination of "representative" sulphate concentration from a number of tests. Essentially if <10 samples of a given soil-type have been tested, the highest measured sulphate concentration should be taken. If >10 samples have been tested, the mean of the highest 20% of the sulphate test results can be taken. With respect to groundwater, the highest sulphate concentration should always be taken.

With respect to pH (soil & groundwater) the value used is the lowest value if <10 samples have been tested and the mean of the lowest 20% if >10 samples have been tested.

Generic Notes – ID Geoenvironmental Investigations

4 Contamination Laboratory Analysis & Interpretation (including WAC)

Current UK Guidance

The UK approach to contaminated land is set out in **Land Contamination Risk Management (LCRM)** published on the Gov.uk website. The approach is based upon risk assessment, where risk is defined as the combination of the probability of occurrence of a defined hazard and the magnitude of the consequences of the occurrence.

In the context of land contamination, there are three essential elements to any risk: (1) a contaminant source, (2) a receptor (eg controlled water or people exposed to the contaminants) and (3) a pathway linking (1) and (2). Risk can only exist where all three elements combine to create a pollutant linkage. Risk assessment requires the formulation of a conceptual model which supports the identification and assessment of pollutant linkages.

As recommended by LCRM, IDG adopt a tiered approach to risk assessment, consistent with UK guidance and best practice. In general this comprises the following elements of work:

- A Preliminary Risk Assessment (PRA)
- A Generic Quantitative Risk Assessment (GQRA)
- A Detailed Quantitative Risk Assessment (DQRA)

Preliminary Risk Assessment

A preliminary risk assessment is generally undertaken as part of a “Desk Study” investigation. This investigation collates readily available information including historical land uses, the geological, hydrogeological and hydrological setting of the site, and the proposed end-use which is presented as a “Preliminary Conceptual Model”. Potential pollutant linkages are defined and a preliminary assessment of the risks posed to receptors is stated.

Further information regarding the development of a conceptual model for the site is presented in Generic Notes 1 – Environmental Setting and Preliminary Risk Assessment.

Generic Quantitative Risk Assessment

Where potential pollutant linkages are identified in the preliminary conceptual model a generic quantitative risk assessment (GQRA) generally forms part of an intrusive phase of site investigation, allowing for the sampling of both soil and groundwater. The intrusive investigation should target pollutant linkages identified in the Preliminary Conceptual Model, but should also investigate previously unidentified sources and contaminant pathways encountered during the site investigation works.

Human Health

Detailed guidance on human health risk assessment is available in the following:

INFO-RA2-2: assessing risks to human health

Human health toxicological assessment of contaminants in soil - Science Report: SC050021/SR2

Updated technical background to the CLEA model - Science Report: SC050021/SR3

CLEA Software (Version 1.05) Handbook Science report: SC050021/SR4

Compilation of data for priority organic pollutants for derivation of Soil Guideline Values - Science Report: SC050021/SR7

Guidance on Comparing Soil Contamination Data with a Critical Concentration - CL:AIRE and CIEH, May 2008

Generic Assessment Criteria represent “screening concentrations” devised for a number of standard land-use scenarios. They are based conservative receptor and exposure parameters and provide a useful method of screening out sites where contaminants pose a negligible risk. GACs are available from a number of sources for the following land-use scenarios. These scenarios include:

- Residential end-use with consumption of homegrown produce.
- Residential end-use without consumption of homegrown produce.
- Residential Public Open Space (Landscaped Areas)
- Public Open Space (Parks)
- Allotments
- Commercial Development

The initial step of such a generic quantitative risk assessment is to compare site chemical data with appropriate UK generic assessment criteria. These following GACs are currently appropriate.

Soil Guideline Values (SGVs) (Environment Agency 2009) are based on CLEA “default settings and therefore represent screening criteria based on minimal risk to human health. SGVs are available for arsenic, cadmium, mercury, nickel, selenium, BTEX, phenols and dioxins, furans and dioxin-like PCB substances for residential, allotments and commercial land-uses based on a sandy loam soil and a 6% soil organic matter (SOM) content.

Soil Generic Assessment Criteria for Human Health Risk Assessment (EIC/AGS/CL:AIRE 2009) adopted CLEA default settings and therefore represent screening criteria based on minimal risk to human health. GACs were derived for 3 metals and 32 organic contaminants for four standard land uses at 1%, 2% and 6% SOM content.

Suitable for Use Levels (S4ULs) (LQM/CIEH, Nathanail 2015) represent generic assessment criteria for each of the above standard land-uses, based on updated toxicological assessments and modified exposure parameters. They therefore represent screening criteria based on minimal risk to human health. S4ULs for organic compounds are available for 1%, 2% and 6% SOM. (*S4ULs Copyright Land Quality Management Limited reproduced with permission; Publication Number S4UL3061. All rights Reserved.*)

Category 4 Screening Levels (Defra March 2014) are primarily intended to be used to assist the classification of land under the revised Part 2A Statutory Guidance issued in 2012. The revised guidance introduced the concept of four categories of contaminated land (Category 1 (significant/high risk) – Category 4 (low risk). C4SLs are low risk levels which are not representative of significant possibility of significant harm (SPoSH) and, whilst not intended to mark the top of Category 4, should the C4SLs not be exceeded, land can be demonstrated as being in Category 4 and cannot be determined as contaminated land.

The GAC selected to form the basis of a Generic Risk Assessment are dependent on the existing or proposed land use as defined in the Conceptual Model (which identifies the critical receptor and exposure parameters) and other factors such as the SOM content of the near surface soils at the site.

Soil organic matter (SOM) is the fraction of soil composed of organic matter. It consists principally of decomposed plant remains. The presence of SOM is important in determining the fate and behaviour of a number of organic contaminants. Generally, the greater the SOM content of soil, the greater the sorptive capacity of the soil and the lower the mobility of certain contaminant phases. (Note: $TOC = SOM \times 0.58$; and $FOC = TOC/100$).

Generic Assessment Criteria adopted by IDG available, by regulators, upon request.

The CLEA model assumes a simple linear partitioning between the sorbed, dissolved and vapour phases. The theoretical upper boundaries to this behaviour are represented by the maximum aqueous solubility and pure saturated vapour concentration of the chemical. The CLEA model uses a traffic light system to identify when individual and/or combined assessment criteria exceed the lower of either the aqueous or vapour based saturation limit (the lower saturation limit). Assessment criteria which exceed the lower of the two saturation limits and where the vapour pathway is an important contributor to exposure are highlighted in red in the CLEA model. These values are depicted as shaded values in the IDG GAC Tables. In such cases the exposure from the vapour phase will be over predicted and where the vapour pathway is the only exposure route being considered the risk is likely to be negligible.

IDG Reports will therefore state the applicable land-use scenario, and the SOM content adopted for the assessment. In general, the initial assessment **assumes a low soil organic matter content (1% SOM)** to ensure that the assessment is appropriately conservative. Where contaminant concentrations exceed the adopted GAC, site-specific assessment (for example applying measured SOM contents of soils or development site-specific exposure parameters) will be undertaken to further evaluate the risk. It should be noted that exceedance of GAC does not necessarily mean that remediation will be required.

Interpretation of Results

Prior to undertaking any comparison of soil contamination data, the issue of the averaging area requires further consideration. IDG consider that contamination across the entire site needs to be characterised by reference to the Conceptual Site Model. Consequently, IDG gather and analyse sample results by “soil type”, or by former use in a given sub-area of the site, before undertaking statistical analysis; ie the averaging area is associated with the extent of a particular fill type, or an area affected by spillage/leakage rather than from within a specified depth below the site surface.

In terms of brownfield redevelopment, this is considered an appropriate methodology which provides a representative sample population for statistical analysis which allows for the necessary relocation of soils during site development works.

Should any of the GAC criteria detailed above be exceeded, then three possible courses of action could be considered. (The first is only applicable in terms of human health, but the second and third could also be applied to groundwater or landfill gas).

- Undertake further statistical analysis to determine whether contaminant concentrations of inorganic contaminants within soil/fill actually present a risk (only applicable to assessing the risk to human health).

- Based on a Generic Quantitative Risk Assessment, advocate an appropriate level of remediation to “break” the pollutant linkage - for example the removal/relocation of the contaminated materials or the provision of a clean cover.

- Carry out a more a Detailed Quantitative Risk Assessment in order to further assess the risk.

Controlled Waters Receptors

Where the environmental setting of a site is considered moderately or highly “sensitive” in respect of controlled waters (i.e where a pollutant linkage potentially exists to a controlled waters receptor) a risk assessment will be undertaken. This initially comprises comparison of soil-leachate or groundwater concentrations to the appropriate water quality standard. Depending upon the specific characteristics and environmental setting of the site the appropriate standard is likely to be one of the following:

Water Supply (Water Quality) Regulations 1989

Environmental Quality Standards: The River Basin Districts Typology, Standards and Groundwater threshold values (Water Framework Directive)(England and Wales) Directions 2010.
The Surface Waters (Abstraction for Drinking Water) Regulations

It is not possible to derive generic GAC values for controlled waters, because distance to the receptor, ground permeability and hydraulic gradient are key factors in the assessment, and both are extremely site-specific. As a consequence should groundwater or soil leachate concentrations exceed the adopted water quality standards in a site with moderate or high sensitivity, a detailed quantitative risk assessment may be required.

Phytotoxic Effects

With respect to the assessment of potential **phytotoxic effects** of contaminants, IDG refer to available publications relating to allowable concentrations of heavy metals (copper and zinc) in arable soils which have been set by the Department of Environmentⁱ. These values are detailed in the table below.

Allowable Concentrations of Heavy Metals in Arable Soils

Element	Limit According to pH of soil (mg/kg)			
	5.0 to <5.5	5.5 to <6.0	6.0 to 7.0	>7.0
Copper	80	100	135	200
Nickel	50	60	75	110
Zinc	200	200	200	300

IDG have reviewed the available data on Boron behaviour in soil, plant uptake and the relatively high precipitation rates typical in the UK. In the absence of any definitive value IDG have opted to be relatively conservative and have adopted a Boron Soil Screening Value of 5mg/kg. This value is considered protective of the majority of common landscape plants.

Hazardous Ground Gas

Tier 1 risk assessment of **hazardous gas** is undertaken through reference to the following documents:

Approved Document C, Building Regulations 2000

Boyle & Witherington (2007) – Guidance on evaluation on development proposals on sites where methane and carbon dioxide are present, incorporating “traffic lights”. Report Ref. 10627-R01-(02), for NHBC

CIRIA C665 (2006) – Assessing risks posed by hazardous ground gases to buildings

BS 8485:2007 – Code of Practice for the characterisation & remediation from ground gas in affected developments

Further information is presented in Generic Notes No. 5 – Hazardous Gas.

Waste Classification & WAC

Waste soils to be disposed off-site should be characterised by a general chemical testing for a broad suite to include pH, TOC, metals, speciated PAH and banded hydrocarbons. WAC testing is not required to characterise the waste. Chemical test result should be provided to the waste haulier and receiving landfill who will confirm the classification of the waste soils.

In the context of waste soils generated by remediation and/or groundwork activities on brownfield sites, the following definitions (from the Landfill Regulations 2002) apply:

Inert (e.g. uncontaminated ‘natural’ soil, bricks, concrete, tiles & ceramics).

Non-Hazardous (e.g. soil excavated from a contaminated site which contains dangerous substances, but at concentrations below prescribed thresholds).

Hazardous (e.g. soil excavated from a contaminated site which contains dangerous substances at concentrations above prescribed thresholds).

Dangerous substances include compounds containing a variety of determinants commonly found in contaminated soils on brownfield sites, for example arsenic, lead, chromium, benzene etc.

From 16th July 2005, landfill operators require Waste Acceptance Criteria (WAC) laboratory data, should soil waste be classified as **hazardous**, and such waste must have been subjected to pre-treatment. However, subject to WAC testing it may be possible to classify it as stable, non-reactive hazardous waste, which can be placed within a dedicated cell within the non-hazardous landfill.

It should be noted that where non-hazardous waste is accepted at a non-hazardous landfill facility, WAC testing is not required.

Should off-site disposal of soils classified as hazardous waste be undertaken during redevelopment, then WAC analysis should be scheduled at an early stage in the remediation programme.

However, organic compounds (BTEX, TPH, PAH etc) are the most common contaminants that result in soils being classed as hazardous. These contaminants can often be dealt with by alternative technologies (eg by bioremediation or stabilisation) and consequently retention on site is often possible.

Key References

Environment Agency (2008), "Evaluation of models for predicting plant uptake of chemicals from soil" Science Report – SC050021/SR.

Environment Agency (2008), "Human health toxicological assessment of contaminants in soil". Science Report – SR2.

Environment Agency (2009), "Updated Technical Background to the CLEA Model (as amended 2009)". Science Report - SC050021/SR3.

Environment Agency (2009), "CLEA Software (Version 1.05) Handbook". Science Report - SC050021/SR4.

"Guidance on Comparing Soil Contamination Data with a Critical Concentration". CL:AIRE and CIEH (May 2008).

CL:AIRE (2010), "Soil Generic Assessment Criteria for Human Health Risk Assessment".

CL:AIRE (2013), "Development of Category 4 Screening Levels for Assessment of Land Affected by Contamination. SP1010 Final Project Report.

DEFRA (2014), "Development of Category 4 Screening Levels for Assessment of Land Affected by Contamination –. SP1010 Policy Companion Document.

Nathanial (*et. al.*) (2015). The LQM/S4ULs for Human Health Risk Assessment. Land Quality Press, Nottingham.

Department of Environment (1996), “Code of Practice for Agricultural use of Sewage Sludge”.

Generic Notes – ID Geoenvironmental Investigations

5. Hazardous Gas

General

Hazardous gas is considered to be any mixture of potentially explosive, toxic or asphyxiating gases, most notably methane, carbon dioxide and oxygen (deficiency).

IDG Investigations are undertaken in accordance with the following Standards and Guidance:

BS8576:2013 Guidance on investigations for ground gas – Permanent gases and Volatile Organic Compounds (VOCs).

BS 8485:2015+A1:2019 Code of practice for the design of protective measures for methane and carbon-dioxide ground gases for new buildings.

BS10175:2011 +A2-2017 Investigation of potentially contaminated sites – Code of practice.

CIRIA C665 (2007) Assessing risks posed by hazardous ground gases to buildings.

CIRIA C716 Remediating and mitigating risks from volatile organic compound (VOC) vapours from land affected by contamination.

CIRIA 735 (2014) Good practice on the testing and verification of protection systems for buildings against hazardous ground gases.

In addition, radon, a naturally occurring radioactive gas is also considered. Further information about radon is included in Notes 1. – Environmental Setting.

At preliminary stage, the assessment of potential risks associated with hazardous gas are based on a review of data obtained from the Landmark Information Group/Groundsure Limited, and the Local Authority. Reference is also made to historical OS plans, which are inspected for evidence of backfilled quarries, railway cuttings, colliery spoil tips etc.

Sources

Potential sources of hazardous gas include:

Landfill sites

Made ground, especially where significant depths are present

Shallow mineworkings associated with coal extraction

Geological strata, including peat, organic silts, coal-bearing strata and limestone (reaction with acidic waters), granite (radon)

Groundwater can sometimes act as a “carrier” for hazardous gas.

Leakages from pipelines or storage tanks

Sewers, septic tanks and cess pits

Generation

Wherever biodegradable material is deposited, landfill gas (principally a mixture of methane and carbon dioxide) is likely to be generated by microbial activity. Carbon dioxide is an asphyxiant and toxic; methane is

flammable and a mixture containing between 5% and 15% methane by volume in air is explosive. Landfill gas in the ground is unlikely in itself to pose a significant risk, though it may damage vegetation. However, infiltration of landfill gas into confined spaces (e.g. cellars, services, etc) may give rise to considerable risk.

There is no typical figure for the length of time that landfill gas will be evolved, but at many sites significant gas generation continues for at least 15 years after the last deposit of waste.

Migration

Gas migration from a landfill site may occur in several ways. It may migrate through adjacent strata; the distance of migration being dependent on the pressure gradients, volume of gas and permeability of the strata. Where there are faults, cavities and fissures within the strata, gas may move considerable distances. Other migration pathways for gas include man-made features such as mine shafts, roadways and underground services.

Gas migration is influenced by a number of climatic factors, such as atmospheric pressure variations, water table level variations and the influence of a covering of snow or ice over the surface of the site and surrounding area.

Gas Monitoring Procedure

IDG adopt a standard gas monitoring procedure. This procedure involves the measurement, in the following order of:

- Atmospheric temperature, pressure and ambient oxygen concentration on site immediately prior to and on completion of monitoring.

- Borehole gas emission rate.

- Methane, oxygen and carbon dioxide concentrations using an infra-red gas analyser.

- Standing water level using a dipmeter.

In addition, ground conditions at each sampling location are recorded together with prevailing weather conditions and any other observations such as any vandalism.

Where samples of gas are required for laboratory analysis, Gresham Tubes or Tedlar Bags are used. Gas concentrations in the well are typically recorded immediately before and after retrieval of a sample.

Monitoring Programme

The appropriate length of the monitoring programme is confirmed in accordance with BS8576:2013 (Figure 6).

Site Characterisation

Gas monitoring results are assessed in accordance with BS8485:2015.

Borehole gas flow rates (Q_{hg}) are calculated for each gas at borehole standpipe for each monitoring event. On completion of the monitoring programme a GSV is adopted for the site taking into account the monitoring data, conceptual model, hazardous gas source(s) and nature of pathway. Where the dataset is representative and comprehensive, the GSV should be at the maximum borehole Q_{hg} measured for all the monitoring events.

A worst case check (based on site wide highest flow rate and site wide highest gas concentration) should also be calculated for the site. The worst case Q_{hg} should be compared with the maximum borehole Q_{hg} .

Characteristic gas situation (CS) is determined using the Q_{hg} adopted for the site in accordance with BS8485:2015.

Table 1 – Characteristic Situation BS8485:2015

Characteristic Situation	GSV CH ₄ or CO ₂ (l/hr)	Additional limiting factors	Typical source of generation
1	<0.07	Typically <1% methane concentration and <5% carbon-dioxide concentration (otherwise consider and increase to CS2)	Natural soils with low organic content
2	<0.07 to <0.7	Typical measured flow rate <70 litre/hr)otherwise increase to Characteristic Situation 3)	Natural soil, high peat/organic content
3	0.7 to <3.5	Quantitative Risk Assessment required to evaluate scope of protection measures.	Old landfill, inert waste, mineworking flooded.
4	3.5 to <15		Mineworking – susceptible to flooding, completed landfill, inert waste (WMP 26B criteria)
5	15 to <70		Mineworking unflooded, inactive
6	>70		Recent landfill site

Notes:

Borehole flow rate = volume of gas (regardless of composition) which is escaping from well (l/hr).

Gas Screening Value (litre/hour) = gas concentration (%) / 100 x borehole flow rate (l/hr).

Gas protection measures

A minimum “Gas Protection Score” is allocated for new buildings at the site. This is based on the characteristic situation of the site and the proposed building type. Low rise residential properties are generally classed as “Type A” buildings, whilst managed residential apartments are classed as “Type B buildings”.

The required gas protection measures, taking into account the proposed foundation and floor slab construction methods are selected to meet the required gas protection score. A combination of at least two of the following three types of gas protection measures are required to achieve the minimum gas protection score.

The structural barrier of the floor slab, or of the basement slab and walls if a basement is present (Gas Protection Score 0-2.5).

Ventilation measures (Gas Protection Score 0.5-4.0); and,

Gas resistant membrane (Gas Protection Score 2). It is important to note that there are several requirements (including independent validation) that need to be fulfilled in order to achieve the score of 2.