

72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.

Dilapidation survey.

The applicant proposes to undertake surveys every two months and will submit this to the Council by email.

The location of dilapidation survey will be unadopted section of Knowsley Road classified as Public Footpath No.42, Christ Church, Radcliffe.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.



72375 - Discharge of conditions at Ainsworth Nursing Home, Ainsworth.

Dilapidation photos as part of the condition discharge.

Photos starting at the site on page 1 heading south, each photo is immediately to the south of the preceding photo. Photos taken October 2025.

